

Free 30 Day Trial! SS [Name] [Address] [City] [State] [Zip]

NAME: Hwee Jie


REF: AIG

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHF486E Yr Regn: 30 sep 2014
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Car / Prime Mover /
 Truck / Trailer or
 Make: Toyota Prius C.C. 1797
 Colour: Maroon A/C: Insured / Std / NI / NA
 Sp Reading: 603995 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTDKN36U9057S1865
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65 R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>3/4/19</u>	D.O.I. <u>4/4/19</u>

Survey held at Smk

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooflop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>Lg \$2,700.00</u>
	<u>CRPD \$5,327.17 (66%)</u>
	<u>04/19/2008</u>
	<u>GBH3558Y</u>

Done/Time: File Pass to:

☐ : Preli. Report

Days Of Repair:

☐ : Final Report

Resurvey No. of Trip:

Survey Fee:

Transportation

☐ : Site Insp \$

☐ : Interview \$

☐ : Tech. Invs \$

☐ : Weekend \$

TOTAL



Report Format :

Lump Sum / I.O.I: \$

VIC

Section A - Accident Details

Registration Number	SHF486E
Case Reference Number	TAX/04/19/2008
Registration Date	30/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LIM KEE ENG
Type of Accident	Head to Rear
Accident Date and Time	3/4/2019 9:45 AM
Accident Reported Date and Time	3/4/2019 11:54 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100883
Special Instruction to ARC, if any	TP
Prepared Date and Time	3/4/2019 2:13 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



h/p/s

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$500.00
Total Spray Cost	\$1,476.00	\$450.00
Total Spare Part Cost	\$4,697.17	\$1,519.52
Total Other Cost	\$840.00	\$210.00
TOTAL COST	\$8,027.17	\$2,709.52
Lump Sum Total	\$8,050.00	\$2,700.00 (L/S)
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	04/04/2019 3:56 PM	04/04/2019 2:19 PM
Signature		
Remarks		
		L/S REPAIR, PHOTO AFTER PAINT.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0183	Invoice Number	
Quotation Date	12.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,014.00	\$500.00
Total Labour	\$1,014.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY REAR SPOILER	\$180.00	\$80.00
TO RESPRAY REAR PANEL	\$160.00	\$0.00
Total Spray Painting & Panel Beating	\$1,476.00	\$480.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$50.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$120.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$840.00	\$210.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52158-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52161-18010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check
		52015-47090	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$167.40	0.00	\$0.00	Replace	Check
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given
		76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given

52578-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$84.80	0.00	\$0.00	Replace	Check	X
52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$84.80	0.00	\$0.00	Replace	Check	X
58308-47011	UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Check	X
67005-47241	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace	X
75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	X
75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	X
75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$29.40	25.00	\$22.05	Replace	Replace	X
56117-50140	DAM, BACK DOOR GLASS ADHESIVE, NO.1	1.00	\$27.30	25.00	\$20.48	Replace	Replace	X
58284-47050	DAM, BACK DOOR GLASS ADHESIVE, NO.2	1.00	\$17.40	25.00	\$13.05	Replace	Replace	X
75575-47020	MOULDING, BACK WINDOW, LOWER NO.2	1.00	\$29.40	25.00	\$22.05	Replace	Replace	X
75574-47010	MOULDING, BACK WINDOW, OUTSIDE LH NO.2	1.00	\$29.40	25.00	\$22.05	Replace	Replace	X
75573-47090	MOULDING, BACK WINDOW, OUTSIDE RH NO.2	1.00	\$29.40	25.00	\$22.05	Replace	Replace	X
	SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	X
68810-47010	TAILGATE DOOR HINGE LH/RH	0.00	\$58.30	0.00	\$0.00	Replace	Not Given	X
69350-47030	TAILGATE DOOR LOCK	0.00	\$444.10	0.00	\$0.00	Replace	Check	X
67881-47022	TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	0.00	\$0.00	Replace	Check	X
89415-47020	TAILGATE LOCK, COVER	0.00	\$15.70	0.00	\$0.00	Replace	Not Given	X
76801-47070-80	TAILGATE OUTSIDE GARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Not Given	X
69431-47010	STRIKER, BACK DOOR	0.00	\$48.90	0.00	\$0.00	Replace	Not Given	X
75310-47020	EMBLEM REAR	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X
	NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	X
	NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given	X
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	X
75442-47030	NAME PLATE (PRIUS)	0.00	\$60.80	0.00	\$0.00	Replace	Not Given	X
75443-47030	NAME PLATE (TOYOTA)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X
76085-47910	SPOILER REAR	1.00	\$953.70	100.00	\$0.00	Replace	Repair	X
	SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
	STICKER DECAL 6555 8888	0.00	\$21.80	0.00	\$0.00	Replace	Not Given	X
58307-47080	END PANEL	0.00	\$802.10	0.00	\$0.00	Replace	Check	X
84718-4703180	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Not Given	X
84718-4703180	END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	0.00	\$0.00	Replace	Not Given	X
58336-12090	REINFORCEMENT, RR	0.00	\$34.60	0.00	\$0.00	Replace	Check	X
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Check	X
Total			\$7,387.61		\$1,899.40			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

44
 deleted
 wee
 wee
 wee
 wee
 wee
 wee
 wee
 wee
 wee
 wee
 1899.40
 202
 519.52
 + 500.00
 + 690.00
 2709.52
 45 \$2700/-



Case Details

Case Reference Number : TAX/04/19/2008
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHF486E

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-6339-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 03/04/2019 01:45 AM
 Vehicle Age(In Months) : 55

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	+
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	+
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	+
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	+
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	+
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check	+
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	+
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	+
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	+
									Total Spare Part Cost	5,871.46	Surveyor Total			1,899.38
									Lump Sum Discount (%)	20.00	Lump Sum Dis (%)			20
									Final Spare Part Cost	4,697.17	Final Sur Total			1,519.50

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	*
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace	*
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give	*
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give	*
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check	*
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check	*
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Check	*
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace	*
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	*
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	*
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	*
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.1	1	27.30	27.30	25.00	20.48	Replace	1	20.48	Replace	*
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.2	1	17.40	17.40	25.00	13.05	Replace	1	13.05	Replace	*
One Time Key In	Main			MOULDING, BACK WINDOW, LOWER NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	*

Total Spare Part Cost 5,871.46

Surveyor Total 1,899.38

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 4,697.17

Final Sur Total 1,519.50

BOM Type	Coating Type	Portion	Material Number	SMRT Recommendation								Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
One Time Key In	Main			MOULDING, BACK WINDOW, OUTSIDE LH NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	*	
One Time Key In	Main			MOULDING, BACK WINDOW, OUTSIDE RH NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	*	
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace	*	
One Time Key In	Main			TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Not Give	*	
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Check	*	
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Check	*	
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Not Give	*	
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	0	0	Not Give	*	
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Not Give	*	
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	0	0	Not Give	*	
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0	Not Give	*	
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0	Not Give	*	
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	*	
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	0	0	Not Give	*	

Total Spare Part Cost 5,871.48

Surveyor Total 1,899.38

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 4,697.17

Final Sur Total 1,519.50

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give	+
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	1	0	Repair	+
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	+
One Time Key In	Main			STICKER DECAL 6555 0888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	+
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	+
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	+
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	Not Give	+
One Time Key In	Main			REINFORCEMENT, RR	2	34.60	69.20	25.00	51.90	Replace	0	0	Check	+
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	+
Total Spare Part Cost									5,871.46	Surveyor Total 1,899.38				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									4,697.17	Final Sur Total 1,519.50				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,014.00	500	
Total:			1,014.00	500.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	376.00	200	
Total:			1,476.00	480.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY TAIL GATE	378.00	200	
4	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0	
5	Main	TO RESPRAY REAR SPOILER	180.00	80	
6	Main	TO RESPRAY REAR PANEL	180.00	0	
Total:			1,476.00	480.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	50	
3	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
4	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	120.00	0	
5	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120	
6	Main	TO REPLACE SUNDRY PARTS	100.00	0	
7	Main	TO WASH AND VACUUM	60.00	0	
Total:			840.00	210.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	4,897.17	1,518.50
Total Labour Cost	1,014.00	500.00
Total Spray Painting	1,476.00	480.00
Other	840.00	210.00
Overall Total	7,867.17	2,709.50
Lump Sum Repair Option		

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Lump Sum Total	7,850.00	2,700.00
Surveyor Approved Amount		2,700.00
No of Repair Days*	6	4
Remarks	.	U/S REPAIR, PHOTO AFTER PAINT.
Surveyor Name		Hwee Jie
Signature		
Survey Date	04/04/2019	Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vic (LKKAuto)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>
Sent: Friday, 10 May, 2019 4:17 PM
To: CS A Team; Admin A
Subject: LOD Re: Accident on 3/4/2019 involving SHF 486E & GBH 3558Y (AIG's insured)
Our Ref: TAX/04/19/2008/lg
Attachments: TAX 04 19 2008.pdf

Dear All,

We quantify our claim as follows:-

Cost of Repair	\$2,700.00
Loss of Rental	\$537.70 (5 days x \$107.54)
Loss of Income	\$300.00 (5 day x \$60.00)
LTA Search Fee	\$7.00
Total	\$3,544.70

We enclose the following documents:

- 1) Repair invoice
- 2) Proof of rental rate
- 3) GIA report
- 4) Accident vehicle laid-up report
- 5) LTA search

Please let us have your offer soon. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG19006047/JHA3

11 APRIL 2019

B & I RESOURCES PTE LTD
20 ANG MO KIO INDUSTRIAL PARK 2A
SINGAPORE 567761

Dear Sir/Madam,

ACCIDENT INVOLVING GBH3558Y & SHF486E ALONG/AT TPE ON 03/04/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SHF486E against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

KHANCHNA
Case Handler
DID: 6841-2360
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific - Express Third Party Claim)

I, **SMRT TAXIS PTE LTD** (the third party claimant") of **60 WOODLANDS INDUSTRIAL PARK E4 (S)757705** (address), owner of **SHF 486E** (vehicle no.) hereby authorize **SMRT AUTOMOTIVE SERVICES PTE LTD** ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no **SHF 486E** that was damaged pursuant to the accident which occurred on **03/04/2019** (date) along **TPE TUNNEL** (location) involving vehicle no/s **GBH 3558Y** ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of **SMRT TAXIS PTE LTD**.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 10 (day) of May (month) 2019 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, SMRT AUTOMOTIVE SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3,500.00 (Global Sum – all in) for vehicle no. SHF 486E that was damaged pursuant to the accident which occurred on 03/04/2019 (date) along TPE TUNNEL (location) involving vehicle no/s GBH 3558Y. This is pursuant to the inspection conducted on 04/04/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SMRT TAXIS PTE LTD ("the third party claimant") of vehicle no. SHF 486E make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SHF 486E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 10 (day) of May (month) **2019** (year)


Signed by appointed surveyor


Signed by "the workshop" (with chop)

*** This Discharge Voucher applies only to the claimant's claim or his property damage and will not affect his personal injuries claim and/or uninsured losses claim in a later date. Further, the settlement terms herein should not be used as an evidence to prejudice to the claimant's personal injuries claim and/or other uninsured losses claim arising of the subject matter in this action.



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV190400276
Date : 23.04.2019
Vehicle No. : SHF486E
Your Ref No. : TAX/04/19/2008
Our Ref No. : 24100883
Terms : 30 Days

Description	Qty	Unit Cost	Add / (Discount) Amount	Amount
LUMP SUM AMOUNT FOR REPAIR AS PER SURVEYOR'S RECOMMENDATION	1.00		\$	2,700.00
GRAND TOTAL				\$ 2,700.00

Remark :

Make/Model : TOYOTA PRIUS
Accident Date : 03.04.2019

N.B. Payment by cheque should be crossed and
made payable to 'SMRT Automotive Services Pte Ltd'.
No receipt will be issued unless requested.


Authorized Signature
for SMRT Automotive Services Pte Ltd



SMRT Taxis Pte Ltd

MEMORANDUM

To: Claims Dept

Our Ref: TAX/04/19/2008

From: SMRT Taxis Pte Ltd

Date: 15/04/2019

ACCIDENT INVOLVING SHF 486E & GBH 3558Y ON 3/4/2019 ALONG TPE TUNNEL

This is to confirm that the daily rental rate for SHF 486E is \$107.54 per day.

Please proceed to recover any rental loss from the third party as a result of the above accident.

Thank you.

Yours sincerely
SMRT TAXIS PTE LTD



for Manager



Laid Up Report

Accident Start Date : 01/04/2019

Accident End Date : 08/05/2019

Date Generated : 08/05/2019

User Name : OngHuaYen

Case Reference Number	Vehicle Registration Number	Company Type	Vehicle Make	Vehicle Model	Job Card Number	Date and Time (Accident Repair)	Date and Time (Repair Completed)
TAX/04/16/2008	SHF486E	SMRT Taxi Pte Ltd	TOYOTA	PRIUS	24100863	03/04/2019 11:54 AM	08/04/2019 2:30 PM

4/4/2019

Page 2

Enquire Transaction History

Transaction History Details

Log Date/Time:	04 Apr 2019 / 08:44:31	Transaction Amount:	\$7.49
Asset Type:	Vehicle		
Asset ID:	GBH355BY	Channel:	External Agency
Transaction Type:	18.32 Insurance Enquiry (GIRD Payment)	Business Transaction Reference No.:	20190404084431930510
User ID:	ESASBAHO - BALQISH BINTE ABDUL HALIL		

Search Date / Time: 03 Apr 2019 09:45:00
Insurance Company: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Information displayed is correct as at the log date and time.

Enquire Related Logs

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)
Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Apr 2019 Edit Reg		04 Apr 2019 00:00 Edit Adj Rpt	S\$2,700.00 Edit Estimates	S\$2,700.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	B & I RESOURCES PTE LTD, Co. Reg. No.: 200202782D		
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHF486E	Date of Loss:	03/04/2019 09:00 - :59 [54 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3716824851SG	Policy/Cover Note No.:	1800053322 (Comprehensive) Coverage: 14/05/2018 - 13/05/2019
Vehicle Reg. No. (Insured):	GBH3558Y	Policy No. (Claimant):	D-19093197MFSH
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 16/04/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

• AIG_SG (08/04/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHF486E (3716824851SG)
[GBH3558Y]
TP
SMRT TAXIS PTE LTD
Apr 3 2019 9:00AM
[B & I RESOURCES PTE LTD]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences				
			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit	
Assessment Reports				
			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	08/04/19 11:02	Accident Statement From: SC - Reg. No: GBH3558Y, Claimant: B & I RESOURCES PTE LTD	 Load HTM	
Photos/Images				
			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/04/19 09:03	General View	 Load JPG	☒
2	08/04/19 09:03	General View	 Load JPG	☒
3	08/04/19 09:03	General View	 Load JPG	☒
4	08/04/19 09:03	General View	 Load JPG	☒
5	08/04/19 09:03	General View	 Load JPG	☒
6	08/04/19 09:03	General View	 Load JPG	☒
7	08/04/19 09:03	General View	 Load JPG	☒
8	08/04/19 09:03	General View	 Load JPG	☒
9	08/04/19 09:03	General View	 Load JPG	☒
10	08/04/19 09:03	General View	 Load JPG	☒
11	08/04/19 09:03	General View	 Load JPG	☒
12	08/04/19 09:03	General View	 Load JPG	☒
13	08/04/19 09:03	General View	 Load JPG	☒
14	08/04/19 09:03	General View	 Load JPG	☒
15	08/04/19 09:03	General View	 Load JPG	☒
16	08/04/19 09:03	General View	 Load JPG	☒
17	08/04/19 09:03	General View	 Load JPG	☒
Documentation				
			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/04/19 19:42	TP ESTIMATE - MARKED	 Load PDF	
2	08/04/19 19:42	TP GIA REPORT	 Load PDF	
3	25/04/19 10:05	LETTER TO OI	 Load PDF	
4	20/06/19 11:45	WORKSHOP INVOICE	 Load PDF	
5	20/06/19 11:45	AUTHORISATION TO ACT FORM	 Load PDF	
6	20/06/19 11:45	Release Voucher	 Load PDF	
7	20/06/19 11:45	RENTAL MILEAGE	 Load PDF	
8	20/06/19 11:45	RENTAL RECEIPT	 Load PDF	
9	20/06/19 11:45	LTA SEARCH	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBH3558Y (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHF486E (TP veh)		
Date of Accident:	03/04/2019		

Global Sum Settlement	:	☒ Yes	☐ No	
Repair Estimate	:	\$		10,866.10
Final Repair Cost	:	\$		3,500.00
Loss of Use	:	\$		5.00 days at \$60.00 per day
Rental (if any)	:	\$		5 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		3,500.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	SMRT Taxis Pte Ltd	: \$	3,500.00
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

20 Jun
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19006047/JHA3Q2

Date: 20/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800053322
Claimant Vehicle No : SHF486E **Insured Vehicle No :** GBH3558Y
Date of Loss: 03/04/2019 **Nature of Claim:** TP **Claim No:** 3716824851SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHF486E**
 Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZR1440810
 Reg. Date: 30/09/2014 (Man. Year: 2014) Chassis No: JTDKN36U905751865
 Colour: Maroon Odometer: 603995 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,536.10	1,899.40	5,636.70	74.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	1,190.00	2,140.00	64.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,866.10	3,089.40	7,776.70	71.57
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	10,866.10	2,700.00	8,166.10	75.15
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Car Rental (5.0 x S\$107.54/day) (S\$)		537.70		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		3,544.70		
Global Sum Settlement (S\$)		3,500.00		

INSPECTION

Date of Assignment: 04/04/2019
 Date Inspected: 04/04/2019 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)

60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 4.0 days

Adjuster: ONG HWEE JIE

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER REAR (DISC 25%)	Deformed	458.60 F	*343.95 F
2	1	*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
3	1	*BUMPER LIP REAR (DISC 25%)	Necessary	228.90 F	*171.68 F
4	1	*TAILGATE ASY (DISC 25%)	Dented	1,007.90 F	*755.93 F
5	1	*TAIL GATE DOOR GLASS MOULDING ,LH (DISC 25%)	Necessary	29.40 F	*22.05 F
6	1	*TAIL GATE DOOR GLASS MOULDING ,RH (DISC 25%)	Necessary	29.40 F	*22.05 F
7	1	*MOULDING BACK WINDW,LOWER NO.1 (DISC 25%)	Necessary	29.40 F	*22.05 F
8	1	*DAM BACK DOOR GLASS ADHESIVE NO.1 (DISC 25%)	Necessary	27.30 F	*20.48 F
9	1	*DAM BACK DOOR GLASS ADHESIVE NO.2 (DISC 25%)	Necessary	17.40 F	*13.05 F
10	1	*MOULDING ,BACK WINDOW,LOWER NO.2 (DISC 25%)	Necessary	29.40 F	*22.05 F
11	1	*MOULDING ,BACK WINDOW ,OUTSIDE LH NO.2 (DISC 25%)	Necessary	29.40 F	*22.05 F
12	1	*MOULDING ,BACK WINDOW ,OUTSIDE RH NO.2 (DISC 25%)	Necessary	29.40 F	*22.05 F
13	1	*NAME PLATE (HYBRID) (DISC 25%)	Damaged	51.90 F	*38.93 F
14	1	*SENSOR REVERSE (SN)	Shorted	180.00 F	*180.00 F
15	2	*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
16	3	*SEALANT W/SCREEN (SN)	Necessary	111.00 F	*111.00 F
17	1	*BUMPER REINFORCEMENT REAR	Not Necessary	205.70 F	*- F
18	1	*ARM SUB-ASSY ,RR BUMPER LH	Not Necessary	139.60 F	*- F
19	1	*ARM SUB-ASSY ,RR BUMPER RH	Not Necessary	139.60 F	*- F
20	1	*ANTENNA ,ELECTRICAL LOWER REAR	Not Necessary	157.40 F	*- F
21	1	*BUMPER LIP COVER RR/LH	Not Necessary	72.20 F	*- F
22	1	*BUMPER LIP COVER RR/RH	Not Necessary	118.10 F	*- F
23	1	*BUMPER SEA, RR LH	Not Necessary	88.90 F	*- F
24	1	*BUMPER SEA, RR RH	Not Necessary	65.70 F	*- F
25	1	*BUMPER SIDE RETAINER RR /LH	Not Necessary	94.80 F	*- F
26	1	*BUMPER SIDE RETAINER RR /RH	Not Necessary	94.80 F	*- F
27	1	*UNDER COVER SUBASSY ,RR FLOOR	Not Necessary	514.50 F	*- F
28	2	*TAILGATE DOOR HINGE LH/RH	Not Necessary	58.30 F	*- F
29	1	*TAILGATE DOOR LOCK	Not Necessary	444.10 F	*- F
30	1	*TAILGATE DOOR WEATHERSTRIP	Not Necessary	353.40 F	*- F
31	1	*TAILGATE LOCK ,COVER	Not Necessary	15.70 F	*- F
32	1	*TAILGATE OUTER SIDE GARNISH	Not Necessary	504.90 F	*- F
33	1	*STRIKER BACK DOOR	Not Necessary	48.90 F	*- F
34	1	*EMBLEM REAR	Not Necessary	60.30 F	*- F
35	1	*NUMBER PLATE	Not Necessary	15.00 F	*- F
36	1	*NUMBER PLATE FRAME	Not Necessary	12.00 F	*- F
37	1	*NAME PLATE (PRIUS)	Not Necessary	60.80 F	*- F
38	1	*NAME PLATE (TOYOTA)	Not Necessary	51.90 F	*- F
39	1	*SMRT LOGO	Not Necessary	7.80 F	*- F
40	1	*STICKER DECAL 6555 8888	Not Necessary	21.60 F	*- F
41	1	*END PANEL	Not Necessary	602.10 F	*- F
42	1	*END PANEL COVER ,DECK TRIM HOLE	Not Necessary	46.10 F	*- F
43	1	*END PANEL COVER ,DECK TRIM ,RR	Not Necessary	121.10 F	*- F
44	1	*REINFORCEMENT ,RR	Not Necessary	34.60 F	*- F
45	1	*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
46	1	*SPOILER REAR	Repair	953.70 F	*- F

F=Franchise part.

Total Parts (\$\$) 7,536.10 1,899.40

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.						
---	--	--	--	--	--	--

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANLE BEATING & BODY WORK	New	1,014.00	500.00
2	SPRAY PAINT	New	1,476.00	480.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	50.00
5	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
6	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	0.00
7	TO REMOVE AND REFIX REAR WINDSCREEN	New	240.00	120.00
8	TO REPLACE SUNDRY PARTS	New	100.00	0.00
9	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			3,330.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >