Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19006049/T1GA3Q2

Date: 04/02/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant SMB3521D

Insured Vehicle No: SHC8483B Vehicle No:

Date of Loss: 31/03/2019 Nature of Claim: ΤP Claim No: MCT19030813

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMB3521D Reg No:

Make & Model: ALEXANDER DENNIS ENVIRO500, 8.8 D (A) Engine No: 22117951

Reg. Date: 02/09/2014 (Man. Year: 2014) Chassis No: SFD76CLR5EMTL3450

Odometer: Colour: Green 0 km

Engine Capacity: 8849 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: No Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 305/70 R22.5 Rear Tyre Size: 305/70 R22.5 (D) Michelin 8/8 mm Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8/8 mm Front Right Side: Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00		0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,290.00	965.00	325.00	25.19
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	1,290.00	965.00	325.00	25.19
	+ GST 7.00/7.00% (S\$)	90.30	67.55	22.75	25.19
	Nett Amount (S\$)	1,380.30	1,032.55	347.75	25.19
	+ Loss of Use (1.0 x S\$250.00/day) (S\$)		250.00		
Nett Liability (S\$)		1,282.55			

INSPECTION

05/04/2019 Date of Assignment:

Tower Transit Singapore Pte Ltd (HQ) Date Inspected: 12/04/2019 Inspected At:

21 Bulim Drive, Bulim Bus Depot

Singapore 648170

Estimated Period of Repair: 1.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: Chong Pui Lin Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 21 Dec 2020)

Parts: N/A ALEXANDER DENNIS ENVIRO500 8.8 D (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMB3521D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REPLACE /REPAIR THE DAMAGED PARTS (INCLUDING SPRAY PAINTING)	New	1,290.00	965.00
	Gross Labour Cost (S\$)		1,290.00	965.00
	Report was unsubmitted	during this print-out.		

< END OF ESTIMATES >