



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19006057/Uea3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 09-09-2020



ATTN:PETER

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|--------------|-----------------------|------------|
| Insured Veh. | SHF 754G | Veh. Inspected | SLE 3435R |
| Policy No. | VPX/P1680520 | Coverage (\$) | 0.00 |
| Claim No. | S9M01JBN | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 09/04/2019 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|-----------------|---------------------|------------|
| Make & Model | HONDA VEZEL (A) | c.c | 1496 |
| Engine No. | HIDDEN | Year of Reg. | 2016 |
| Chassis No. | RU11200755 | Colour | BLUE |
| Odometer | 64122 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | | | |
|-----------------------|-------------|-------------|----------------|
| | Size | Make | Balance |
| R/H Front Tyre | 215/60 R16 | GOODYEAR | 6 mm |
| L/H Front Tyre | 215/60 R16 | GOODYEAR | 6 mm |
| R/H Rear Tyre | 215/60 R16 | GOODYEAR | 6 mm |
| L/H Rear Tyre | 215/60 R16 | GOODYEAR | 6 mm |

4. Description of Damages

| |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS. |
|--|

5. General Information

| | | | |
|-----------------------|---|------------------------|------------|
| Accident Date | 03/04/2019 | Inspection Date | 09/04/2019 |
| Survey held at | KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 1 Working Days |
|-------------------------------------|-----------------------|