

ASS. REC. BY:

REF: CS/FCI 19006059/ KS d3 | n2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time: 10:36am @ 5/4/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 5234T

Insured:

SHA 3656M

at Workshop m/s:

Transcab

Tel:

6287 6666

of

No. 2 Amk st. 63

Policy No:

Claim No:

D19002253MFS4

Sum Insured:

Excess:

Make of Vch:

D.O.A 1/4/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:41am @ 5/4/19

Person Contacted:

Amenda

Vehicle: ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 5234T - CC3/11/16021334/CI 99392 D.O.A - 07/11/2016

SHA 3656M - CS3+FCI 19019850 / T1cd3e2 D.O.A - 29/10/2018

30/5 @ 8076.92 Remmt

(\$ 25,123.99 Red - 76%)

ASS. REC. BY:

REF: F021Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Tens Ccb

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S14D5234T Yr Regn: 01.19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Provi c.c. 17.88Colour: M.P. White 1841 A/C: Insured / Std / NI / NASp. Reading 18712 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDK B31410 3079076Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 1/4/19 D.O.I. 5/4/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or8 PM N/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to03/04/19 @ 14:48 p.m. revised in to Karen via email.

RECEIVED

Date/Time, File Pass to?

30/05/191) Type

Date/Time, File Return to?

2) _____

☐ : Prel. Report☒ : Final ReportDays Of Repair: 6

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ - RS. \$

Parking

Others

TOTAL

350

Report Format :

Lump Sum / I.B.I. (\$) 2,076.92 p/p



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002253MFSH

Date: 08 April 2019

Our Ref: CS/FCI19006059/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 5234T .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/04/2019 at the premises of M/s Trans-Cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>33,200.91</u> .
Revised Estimate Amount	: S\$ <u>8,076.92</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the rear & front n/s portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 6 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	03-04-2019	Our Ref No. D19002253MFSH
Accident Date	01-04-2019	Claim Type. Third Party
Insured Vehicle	SHA3656M	Third Party Vehicle. SHD5234T
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	AMANDA TAY	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 8 April 2019 2:48 PM
To: 'Karen Tan'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19002253MFSH/1
Attachments: SHD 5234T - Preli Advise.pdf

Dear Karen,

Enclosed preliminary revised of vehicle SHD 5234T.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 5 April 2019 10:44 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002253MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 5 April 2019 10:36 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002253MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD5234T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	02 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B98195
Chassis No.:	JTDKB3FU103079076
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	17 Jan 2019
First Registration Date:	17 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jan 2027
PARF Rebate Amount:	\$10,685.00

Intended COE Rebate Details

COE Expiry Date:	16 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$20,838.00
COE Rebate Amount:	\$16,670.00
Total Rebate Amount:	\$27,355.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Apr 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5234T**AAD1904-028***Not Notified**Respray B&P paint
88076-98*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5234T

JTDKB3FU103079076

TOYOTA

PRIUS

1.4.2019

FCIL

17/1/2019

PART**LIST**

1	1 REAR BUMPER	\$	<i>Bu/cm</i>	458.60	✓
2	1 REAR BUMPER RE-INFORCEMENT	\$	<i>Bu</i>	318.80	✓
3	1 REAR BUMPER TOWING COVER	\$	<i>Sm</i>	14.70	X
4	1 REAR BUMPER UNDER COVER (BLACK)	\$	<i>nd/cm</i>	552.60	✓
5	1 REAR BUMPER SIDE RETAINER LH	\$	<i>mi</i>	112.70	✓
6	1 REAR BUMPER SIDE RETAINER RH	\$	<i>Sm</i>	112.70	X
7	1 REAR TAILGATE	\$	<i>Bu</i>	1,547.27	✓
8	1 REAR TAILGATE OUTER GARNISH	\$	<i>nd</i>	905.10	✓
9	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>Sm</i>	54.70	X
10	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>Sm</i>	54.70	X
11	1 GARNISH, BACK DOOR SIDE, LH	\$	<i>Sm</i>	93.60	X
12	1 GARNISH, BACK DOOR SIDE, RH	\$	<i>Sm</i>	93.60	X
13	1 BOARD ASSY, BACK DOOR TRIM	\$	<i>Sm</i>	254.40	X
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>Sm</i>	51.20	X
15	1 REAR TAILGATE WEATHERSTRIP	\$	<i>Sm</i>	365.20	X
16	1 REAR END PANEL	\$	<i>Bu</i>	602.10	✓
17	1 TAILLAMP LOWER RH	\$	<i>Sm</i>	548.40	X
18	1 TAILLAMP UPPER RH	\$	<i>Sm</i>	557.90	X
19	1 REAR BUMPER SIDE RH	\$	<i>Sm</i>	232.00	X
20	1 REAR BUMPER SIDE LH	\$	<i>mi</i>	232.00	✓
21	1 TAILLAMP LOWER LH	\$	<i>Bu</i>	548.40	✓
22	1 TAILLAMP UPPER LH	\$	<i>cm</i>	557.90	✓
23	1 PAN, REAR FLOOR	\$	<i>R</i>	572.10	X
24	1 EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	<i>R</i>	77.00	X
25	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	\$	<i>R</i>	192.90	X
26	1 EXTENSION, REAR FLOOR SIDE PANEL, LH	\$	<i>R</i>	77.00	X
27	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	<i>R</i>	192.90	X
28	1 PANEL SUB-ASSY, REAR DOOR, LH	\$	<i>R</i>	1,258.30	X
29	1 PANEL, QUARTER WHEEL HOUSE, OUTER LH	\$	<i>R</i>	290.50	X

Trans-cab Auto Services Pte Ltd

AAD1904-028

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5234T

30	1 REAR FENDER LH	\$	R	817.50	X
31	1 PANEL SUB-ASSY, REAR DOOR, RH	\$	R	1,258.30	X
32	1 REAR FENDER RH	\$	R	817.50	X
33	1 FRONT BUMPER	\$	Bu 100	499.90	✓
34	1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	R	101.20	X

	\$	14,423.67
25%	\$	3,605.92
	\$	10,817.75

Specical Nett

1	1SET PARKING AID	\$	Shot	700.00	250sm
2	1SET REAR BUMPER CLIP	\$	R	22.00	✓
3	2 REAR WINDSCREEN SELANT	\$	R	80.00	40sm
4	1 WINDSCREEN MOULDING	\$	R	100.00	✓
5	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	R	100.00	30sm
6	1 REAR TAILGATE TOYOTA LOGO	\$	R	47.00	✓
7	1 REAR TAILGATE WORDING 'PRIUS'	\$	R	52.90	✓
8	1 REAR TAILGATE WORDING 'HYBRID'	\$	R	53.50	✓
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	R	80.00	30sm
10	1 REAR TAILGATE STICKER '6555-3333'	\$	R	80.00	30sm
11	1 REAR BUMPER PROTECTOR	\$	R	100.00	X

TOTAL \$ 1,415.40

TOTAL PARTS \$ 12,233.15

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00	1320l
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	1000l
To Rust-Proofing Of The Affected Areas.	\$	170.00	60l
To reinstall rear bumper parking sensor.	\$	170.00	50l

Trans-cab Auto Services Pte Ltd

AAD1904-028

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5234T

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	601
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	~ 170.00	X
To repair and realign rear exhaust pipe.	\$	~ 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To transfer of Rear fender fittings, attachments and perform water seepage test.	\$	~ 170.00	X

TOTAL \$ 10,150.00**Over All Total \$ 33,200.91****(PART-BY-PART) Repair Days****28 DAYS**

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19006059/Ksd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 03-06-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3656M	Veh. Inspected	SHD 5234T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002253MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	05/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDKB3FU103079076	Colour	M.PEARL WHITE / RED	
Odometer	18712	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	9 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	9 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/04/2019	Inspection Date	05/04/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5234T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BUCKLED / CRACKED	458.60	458.60
1	REAR BUMPER RE-INFORCEMENT	BENT	318.80	318.80
1	REAR BUMPER TOWING COVER	SERVICEABLE	14.70	-
1	REAR BUMPER UNDER COVER (BLACK)	DENTED / CRACKED	552.60	552.60
1	REAR BUMPER SIDE RETAINER LH	DISTORTED	112.70	112.70
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	112.70	-
1	REAR TAILGATE	BUCKLED	1,547.27	1,547.27
1	REAR TAILGATE OUTER GARNISH	DENTED	905.10	905.10
1	COVER,REAR COMBINATION LAMP,RH	SERVICEABLE	54.70	-
1	COVER,REAR COMBINATION LAMP,RH	SERVICEABLE	54.70	-
1	GARNISH,BACK DOOR SIDE,LH	SERVICEABLE	93.60	-
1	GARNISH,BACK DOOR SIDE,RH	SERVICEABLE	93.60	-
1	BOARD ASSY,BACK DOOR TRIM	SERVICEABLE	254.40	-
1	PANEL ASSY,BACK DOOR TRIM,UPPER	SERVICEABLE	51.20	-
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	365.20	-
1	REAR END PANEL	BENT	602.10	602.10
1	TAILLAMP LOWER RH	SERVICEABLE	548.40	-
1	TAILLAMP UPPER RH	SERVICEABLE	557.90	-
1	REAR BUMPER SIDE RH	SERVICEABLE	232.00	-
1	REAR BUMPER SIDE LH	MISSING	232.00	232.00
1	TAILLAMP LOWER LH	BROKEN	548.40	548.40
1	TAILLAMP UPPER LH	CRACKED	557.90	557.90
1	PAN,REAR FLOOR	TO REPAIR SEE LABOUR ↓	572.10	-
1	EXTENSION,REAR FLOOR SIDE PANEL,RH	TO REPAIR SEE LABOUR ↓	77.00	-
1	EXTENSION,REAR FLOOR PAN TO QUARTER PANEL,LH	TO REPAIR SEE LABOUR ↓	192.90	-
1	EXTENSION,REAR FLOOR SIDE PANEL,LH	TO REPAIR SEE LABOUR ↓	77.00	-

Report Ref No. CS/FCI19006059/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXTENSION,REAR FLOOR PAN TO QUARTER PANEL,RH	TO REPAIR SEE LABOUR ✓	192.90	-
1	PANEL SUB-ASSY,REAR DOOR,LH	TO REPAIR SEE LABOUR ✓	1,258.30	-
1	PANEL,QUARTER WHEEL HOUSE,OUTER LH	TO REPAIR SEE LABOUR ✓	290.50	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR ✓	817.50	-
1	PANEL SUB-ASSY,REAR DOOR,RH	TO REPAIR SEE LABOUR ✓	1,258.30	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR ✓	817.50	-
1	FRONT BUMPER	BUCKLED / DENTED	499.90	499.90
1	BRACKET,FRONT BUMPER EXTENSION MOUNTING LESS 25% DISCOUNT	SERVICEABLE	101.20	-
			-3,605.92	-1,583.85
			10,817.75	4,751.52
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	SHORTED	700.00	250.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	22.00	22.00
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	REAR TAILGATE TOYOTA LOGO (SN)	NECESSARY	47.00	47.00
1	REAR TAILGATE WORDING "PRIUS" (SN)	NECESSARY	52.90	52.90
1	REAR TAILGATE WORDING "HYBRID" (SN)	NECESSARY	53.50	53.50
1	REAR TAILGATE STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	30.00
1	REAR TAILGATE STICKER "6555-3333" (SN)	NECESSARY	80.00	30.00
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	100.00	-
			1,415.40	655.40
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	1,320.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF PAN,REAR FLOOR,EXTENSION,REAR FLOOR SIDE PANEL,RH,EXTENSION,REAR FLOOR PAN TO QUARTER PANEL,LH,EXTENSION,REAR FLOOR SIDE PANEL,LH,EXTENSION,REAR FLOOR PAN TO QUARTER PANEL,RH,PANEL SUB-ASSY,REAR DOOR,LH,PANEL,QUARTER WHEEL HOUSE,OUTER LH,PANEL SUB-ASSY,REAR DOOR,RH,REAR FENDER LH AND REAR FENDER RH.		4,200.00	1,000.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			10,150.00	2,670.00
	GRAND TOTAL		22,383.15	8,076.92
RECOMMENDED COST OF REPAIRS				8,076.92

Report Ref No. CS/FCI19006059/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.