

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AXA16014757/R1GA3Q2-1

**Date:** 24/11/2020

### REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

GA072698

**Claimant**

**Vehicle No :** SJR8431Z

**Insured Vehicle No :**

SGZ5480U

Date of Loss: 06/08/2016

Nature of Claim:

TP

Claim No: C0395086

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR8431Z**

Make & Model: TOYOTA WISH, 1.8 X LIMITED (A)

Engine No: 1NZX914729

Reg. Date: 16/07/2009 (Man. Year: 2009)

Chassis No: MR053HY9305114934

Colour: Grey

Odometer: 192493 km

Engine Capacity: 1497 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size:

185/60 R15

Front Left Side: West Lake 5 mm

Rear Left Side:

West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side:

West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,393.88	1,211.45	1,182.43	49.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	1,050.00	400.00	27.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,843.88</b>	<b>2,261.45</b>	<b>1,582.43</b>	<b>41.17</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>3,843.88</b>	<b>1,800.00</b>	<b>2,043.88</b>	<b>53.17</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b>		200.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,002.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,000.00</b>		

### INSPECTION

Date of Assignment: 08/08/2016

Date Inspected: 10/08/2016 Inspected At:

3A Automobile Pte Ltd (HQ)  
120 Lower Delta Road, #02-15,  
Cendex Centre  
Singapore 169208

Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD RASUL**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2017)
<b>Parts:</b>	M1-MPV	TOYOTA WISH 1.8 X LIMITED (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJR8431Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (CONSISTENT)	Deformed	491.95 FL	*491.95 FL
2	1		*SPARE TYRE PANEL (CONSISTENT)	Serviceable	669.70 FL	*- FL
3	1		*TAIL LAMP -RHS (CONSISTENT)	Cracked	287.90 FL	*287.90 FL
4	1		*BOOT LID LOCK(CONSISTENT)	Bent	95.60 FL	*95.60 FL
5	1		*REAR END PANEL (CONSISTENT)	Repair	513.30 FL	*- FL
6	1		*REAR END PANEL INNER GARNISH (CONSISTENT)	Serviceable	210.75 FL	*- FL
7	1		*REAR BUMPER BRACKET -RHS (BIG) (CONSISTENT)	Necessary	84.90 FL	*84.90 FL
8	1		*REAR BUMPER BRACKET -RHS (SMALL) (CONSISTENT)	Necessary	45.70 FL	*45.70 FL
9	10		*BUMPER CLIPS (CONSISTENT)	Necessary	35.00 FL	*35.00 FL
10	1		*WEATHERSTRIP (CONSISTENT)	Necessary	165.95 FL	*165.95 FL
11	1		*EXHAUST TAIL END (CONSISTENT)	Bent	65.90 FL	*65.90 FL
12	1		*REAR BOOT EMBLEM -TOYOTA LOGO(CONSISTENT)	Necessary	20.20 FL	*20.20 FL
13	1		*REAR BOOT EMBLEM -J (CONSISTENT)	Necessary	35.30 FL	*35.30 FL
14	1		*REAR BOOT EMBLEM -VIOS (CONSISTENT)	Necessary	20.20 FL	*20.20 FL
15	1		*REVERSE SENSOR (CONSISTENT)	Not Working	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,942.35</b>	<b>1,548.60</b>
<b>- List Item Discount on L Items 20.00/25.00% (\$\$)</b>	548.47	337.15
<b>Total Parts (\$\$)</b>	<b>2,393.88</b>	<b>1,211.45</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR CHARGES TO REMOVE AND RENEWING OF REAR BOOT,REAR BUMPER,BRACKETS ETC INCLUDING WELDING ,DISMANTLING, FIXING ,CUTTING OUT OF NECESSARY JOINTS	New	650.00	450.00
2	TO PROVIDE SKILL LABOUR & MATERIAL TO DO SURFACE TREATMENT/ EPOXY TREATMENT AND TO RESPRAY WITH 2K PAINT ON THE AFFECTED AREAS & COMPONENTS WITH OVEN SPRAY BOTH FACILITATES	New	800.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,450.00</b>	<b>1,050.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >