



Your Ref: PCS.CCC.2018.218231.ERGO

Date: 25th June 2019

Our Ref: CS1/LAW19006127/T1qd3s2

M/s ComLaw LLC

64 Cecil ST #03-02

IOB Building

Singapore 049711

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
GW 6046A INSURED VEHICLE: SGF 3898S ACCIDENT DATE: 31/07/2018**

We thank you for your instruction on 03/04/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GW 6046A from M/s Pro Plus Automobile Engineers.
- b) Survey report by Priority Services with colour photographs.
- c) Final Repair Bill of GW 6046A from M/s Kim Service Station.
- d) Singapore Accident Statement of Vehicles GW 6046A and SGF 3898S.
- e) Colour damaged vehicle photographs of GW 6046A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GW 6046A
Make & Model	: Toyota Dyna 150D
Year of Registration	: 2003
Chassis Number	: JTFUF34Y403001563
Engine Capacity	: 2986 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.