



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 5419T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER (CONSISTENT)	DEFORMED	459.80	459.80
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	SERVICEABLE	77.50	-
1	FRONT BUMPER LOWER LID (CONSISTENT)	DEFORMED	381.00	381.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	321.00	-
1	FRONT BUMPER RH FOG LAMP (CONSISTENT)	CRACKED	327.70	327.70
1	FRONT BUMPER RH FOG LAMP BRACKET (CONSISTENT)	CRACKED	22.00	22.00
1	FRONT BUMPER RH FOG LAMP GARNISH (CONSISTENT)	TORN	45.00	45.00
2	FRONT BUMPER SIDE RETAINER L/R (CONSISTENT)	SERVICEABLE	41.20	-
1	FRONT BUMPER TOW HOOK COVER (CONSISTENT)	SERVICEABLE	17.10	-
1	FRONT GRILLE (CONSISTENT)	SERVICEABLE	351.80	-
1	FRONT GRILLE 'LOGO' EMBLEM (CONSISTENT)	SERVICEABLE	23.40	-
1	FRONT GRILLE CENTER BRACKET (CONSISTENT)	SERVICEABLE	76.00	-
1	FRONT GRILLE OUTER COVER (CONSISTENT)	SERVICEABLE	421.00	-
1	FRONT GRILLE TOP GARNISH (CONSISTENT)	SERVICEABLE	85.00	-
1	FRONT RH FENDER (CONSISTENT)	BADLY DENTED	580.00	580.00
1	FRONT RH FENDER ARCH GARNISH (CONSISTENT)	GRAZED	153.00	153.00
1	FRONT RH FENDER INNER SHIELD (CONSISTENT)	DEFORMED	130.00	130.00
1	FRONT RH HEADLAMP (CONSISTENT)	CRACKED	1,784.50	1,784.50
1	FRONT RH HEADLAMP LOWER BRACKET (CONSISTENT)	SERVICEABLE	35.00	-
1	FRONT RH HEADLAMP SIDE BRACKET (CONSISTENT)	SERVICEABLE	35.00	-
1	FRONT RH SPORT RIM (CONSISTENT)	SERVICEABLE	815.00	-
	LESS 20% DISCOUNT		-1,236.40	-776.60
			4,945.60	3,106.40
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	100.00	50.00
1	SET FRONT GRILLE TOP GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
1	SET FRONT RH FENDER ARCH GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-

Report Ref No. CC4/ASM19006129/Uga3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT RH FENDER INNER SHIELD CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	FRONT RH TYRE (SN) (CONSISTENT)	NOT NECESSARY	500.00	-
			740.00	100.00
	<b>LABOUR</b>			
	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING .(TO FR).		100.00	20.00
	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT .		900.00	400.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENT AND DAMAGED CONSISTENT TO THE ACCIDENT .INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT .		900.00	300.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	30.00
			2,020.00	750.00
<b>GRAND TOTAL</b>			<b>7,705.60</b>	<b>3,956.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,150.00</b>

Report Ref No. CC4/ASM19006129/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.