



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 5419T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT FENDER RH (CONSISTENT)	BADLY DENTED	580.00	580.00
1	FRONT FENDER WHEEL ARCH GARNISH RH (CONSISTENT)	GRAZED	153.00	153.00
1	FRONT BUMPER (CONSISTENT)	DEFORMED	459.80	459.80
10	FRONT BUMPER CLIP @\$1.50 (CONSISTENT)	NECESSARY	15.00	15.00
1	FRONT HEADLAMP RH (CONSISTENT)	NOT NECESSARY	1,820.00	-
	LESS 20% DISCOUNT		-605.56	-241.56
			2,422.24	966.24
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING SYSTEM.		30.00	20.00
	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS.		520.00	300.00
	SPRAYPAINTING CHARGES.		620.00	400.00
			1,170.00	720.00
	<b>GRAND TOTAL</b>		<b>3,592.24</b>	<b>1,686.24</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>1,686.24</b>

Report Ref No. CC4/ASM19006129/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.