



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 4912U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HORN COVER (CONSISTENT)	CRACKED	68.00	68.00
1	FRONT FENDER (CONSISTENT)	CRACKED	68.00	68.00
2	FRONT SIGNAL LAMP @\$48.00 (CONSISTENT)	BUCKLED	96.00	96.00
2	SIDE COWLING @\$85.00 (CONSISTENT)	N/S CRACKED	170.00	85.00
1	HEAD LAMP (CONSISTENT)	NOT NECESSARY	108.00	-
2	FOOTREST BAR RUBBER @\$10.00 (CONSISTENT)	SERVICEABLE	20.00	-
1	BRAKE LEVER (CONSISTENT)	CUT	30.00	30.00
1	SIDE MIRROR (CONSISTENT)	SERVICEABLE	48.00	-
1	FRONT FORK ASSY (CONSISTENT)	DAMAGED	250.00	250.00
1	UNDER BRACKET (CONSISTENT)	CRACKED	260.00	260.00
1	STEERING CONE BEARING (CONSISTENT)	DAMAGED	65.00	65.00
1	FRONT FOOTREST BAR (CONSISTENT)	SERVICEABLE	78.00	-
1	FRONT BRAKE DISC (CONSISTENT)	DAMAGED	115.00	115.00
1	FRONT RIM ASSY (CONSISTENT)	DENTED / BENT	240.00	240.00
1	FRONT RIM SHAFT (CONSISTENT)	DAMAGED	30.00	30.00
1	HEAD LAMP COVER (CONSISTENT)	SERVICEABLE	80.00	-
1	HANDLE END (RH) (CONSISTENT)	CUT	30.00	30.00
1	BODY BRACKET (CONSISTENT)	CRACKED	62.00	62.00
1	AIR CLEANER COVER (ADDITIONAL) (CONSISTENT)	CRACKED	55.00	55.00
1	REAR SIDE COWLING LH (ADDITIONAL) (CONSISTENT)	DAMAGED	90.00	90.00
1	BASKET (ADDITIONAL) (CONSISTENT)	DAMAGED	32.00	32.00
1	FRONT FENDER (BLACK) (ADDITIONAL) (CONSISTENT)	CRACKED	50.00	50.00
	LESS 10% DISCOUNT		-204.50	-162.60
			1,840.50	1,463.40
<u>SPECIAL NETT ITEMS</u>				
1	TYRE (CONSISTENT) (SN)	SERVICEABLE	180.00	-
1	FRONT NUMBER PLATE (ADDITIONAL) (CONSISTENT) (SN)	NOT NECESSARY	15.00	-
			195.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TO PRESS FORK ASSY .		250.00	60.00
	REMOVE ALL NECESSARY AFFECTED PARTS FOR REPAIRS ,WELD/CUT PANEL ,BEATING & RENEW PARTS.		250.00	200.00
	SPRAY PAINTING .		200.00	120.00
			700.00	380.00
	GRAND TOTAL		2,735.50	1,843.40
RECOMMENDED COST OF REPAIRS				1,843.40

Report Ref No. CC4/ASM19006133/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.