

(S/S2/III)

INS. CASE OWNER:

Jimmy

CC³ /AIG19006154, J⁸³ 1/1/19

LKK:

IDAC:

Surveyor:

MJ

DOI:

ASSIGNMENT

5/4/19

Date / Time:

5/4/19

Registered in Merimen:

8/4/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKT M8R

Name of Insured:

AN KOK HAN

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

7/4/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

210049K52-04

ANV1

PIB

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final? Yes / No

SKT M8R

SHC 4717P

SUP 1948H

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

SHC 4717P - x

SKT M8R - 10/11/19 10:00 AM / 10/11/19 10:00 AM

BOLA 28, 100%, 3 car chain collision and 02 was the last vehicle, send letter to 02.

pending further LOR

01-11-19

FILE PASS TO TYPIST TO PREPARE REPORT.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by: MJ

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MJ

Repair Cost:

46

SS7,650

(7 days) Reduction:

73

%

Email

Call

FINAL SETTLEMENT

Date/Time: 12.02.20

Confirm with LEE GEX

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 100%

Repair Cost:

SS7,650.00

Loss of Rental (LOR):

SS 1,344.25

(12.5 days) x 107.54

Loss of Use (LOU):

SS -

(S x days)

Loss of Income (LOI):

SS -

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS7.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 9,001.25

Global Sum SS: 9,000

FINAL PAYMENT

Date/Time: 13-02-20

Confirm with: LEE GEX

Email

Call

Payee 1:

SS 9,000.00

Name 1:

SMART TAXIS PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: +320

COPY SENT
8/2/2020

Vehicle: Hwee Jie

REF: ALG

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC4713P Yr Regn: 6 Aug 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798

Colour: maroon A/C: Insured / Std / NI / NA

Sp Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN36U80S747368

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ STD A/Rim or

Tyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or chilles

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 3/4/19 D.O.I. 5/4/19

Survey held at Sumit

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / UIC / Rooflop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>4%: +7,650 (RED: +20,815.35 73%)</u>
	<u>04/19/2011</u>
	<u>SKT2218R</u>
	<u>SLP1948H</u>

Date/Time: File Pass to:

☐ : Prel. Report

1)

☐ : Final Report

Date/Time: File Return to:

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1 \$ + P.S. \$

1 Phone

1 Other

TOTAL

Report Format:

Lump Sum / L.B.L. \$

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)



Case Details

Case Reference Number : TAX/04/19/2011
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4713P

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-6349-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 03/04/2019 09:45 AM
 Vehicle Age(In Months) : 56

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	•	/ 00 ✓
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	•	/ MC ✓
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	1	154.27	Replace	•	/ 00 ✓
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0.00	Check	•	X MM
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	1	104.70	Replace	•	/ 0T ✓
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	1	141.66	Replace	•	/ 0R ✓
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	•	/ 0R ✓
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	•	/ MC ✓
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	1	54.15	Replace	•	/ CRU ✓
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	1	88.57	Replace	•	/ CRU ✓
									Total Spare Part Cost	21,516.24	Surveyor Total				3,805.51
									Lump Sum Discount (%)	0.00	Lump Sum Dis (%)				20.00
									Final Spare Part Cost	21,516.24	Final Sur Total				3,044.41

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace	✓ CR4
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	1	66.68	Replace	✓ CR4
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	1	49.28	Replace	✓ CR4
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	✓ CR
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	✓ CR
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0.00	Check	✗ N/A
One Time Key In	Main			EXHAUST HEAT SHIELD, REAR	1	107.40	107.40	25.00	80.55	Replace	0	0.00	Check	✗ N/A
One Time Key In	Main			EXHAUST TAIL PIPE	1	656.20	656.20	25.00	492.15	Replace	0	0.00	Check	✗ N/A
One Time Key In	Main			SUPPORT, EXHAUST REAR	2	33.60	67.20	25.00	50.40	Replace	0	0.00	Check	✗ N/A
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace	✓ DO
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ N/C
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ N/C
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ N/C
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.1	1	27.30	27.30	25.00	20.48	Replace	1	20.48	Replace	✓ N/C
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.2	1	17.40	17.40	25.00	13.05	Replace	1	13.05	Replace	✓ N/C

Total Spare Part Cost

21,516.24

Surveyor Total

3,805.51

Lump Sum Discount (%)

0.00

Lump Sum Dis (%)

20.00

Final Spare Part Cost

21,516.24

Final Sur Total

3,044.41

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MOULDING, BACK WINDOW, LOWER NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	/ MK ✓
One Time Key In	Main			MOULDING, BACK WINDOW, OUTSIDE LH NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	/ MK ✓
One Time Key In	Main			MOULDING, BACK WINDOW, OUTSIDE RH NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	/ MK ✓
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	25.00	83.25	Replace	3	83.25	Replace	/ MK ✓
One Time Key In	Main			TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0.00	Check	X NAI
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0.00	Check	X NAI
One Time Key In	Main			TAILGATE DOOR STAY LH	1	241.50	241.50	25.00	181.13	Replace	0	0.00	Check	X NAI
One Time Key In	Main			TAILGATE DOOR STAY RH	1	241.50	241.50	25.00	181.13	Replace	0	0.00	Check	X NAI
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0.00	Check	X NAI
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0.00	Check	X NAI
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	1	378.67	Replace	/ GR ✓
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0.00	Check	X NAI
One Time Key In	Main			TAILGATE TRIM, LH	1	85.90	85.90	25.00	64.43	Replace	0	0.00	Check	X NAI
One Time Key In	Main			TAILGATE TRIM, LOWER	1	180.70	180.70	25.00	135.52	Replace	0	0.00	Check	X NAI
One Time Key In	Main			TAILGATE TRIM, RH	1	88.30	88.30	25.00	66.22	Replace	0	0.00	Check	X NAI
Total Spare Part Cost									21,516.24	Surveyor Total				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				
Final Spare Part Cost									21,516.24	Final Sur Total				
										3,805.51				
										20.00				
										3,044.41				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAILGATE TRIM, UPPER	1	49.60	49.60	25.00	37.20	Replace	0	0.00	Check	* X NAI
One Time Key In	Main			TAILGATE, BOARD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0.00	Check	* X NAI
One Time Key In	Main			WIRE, BACK DOOR, NO.1	1	582.40	582.40	25.00	436.80	Replace	0	0.00	Not Givr	* X NAI
One Time Key In	Main			SWITCH ASSY, BACK DOOR OPENER	1	146.10	146.10	10.00	131.49	Replace	0	0.00	Check	* X NAI
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	1	45.22	Replace	* / MC ✓
One Time Key In	Main			LICENSE PLATE LAMP	1	35.70	35.70	10.00	32.13	Replace	0	0.00	Check	* X NAI
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0.00	Not Givr	* X NAI
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0.00	Not Givr	* X NAI
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	* / MC ✓
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	1	45.60	Replace	* / MC ✓
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	* / MC ✓
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	0	0.00	Check	* X NAI
One Time Key In	Main			3RD BRAKE LAMP	1	231.30	231.30	10.00	208.17	Replace	0	0.00	Check	* X NAI
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	* / MC ✓
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	* / MC ✓

Total Spare Part Cost

21,516.24

Surveyor Total

3,805.51

Lump Sum Discount (%)

0.00

Lump Sum Dis (%)

20.00

Final Spare Part Cost

21,516.24

Final Sur Total

3,044.41

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	1	451.58	Replace	✓
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0.00	Check	✗ N/A
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0.00	Check	✗ N/A
One Time Key In	Main			REINFORCEMENT, RR	2	34.60	69.20	25.00	51.90	Replace	0	0.00	Check	✗ N/A
One Time Key In	Main		4006314	SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	✓
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0.00	Not Give	✗ N/A
One Time Key In	Main			MEMBER SUB-ASSY, RR LH	1	174.10	174.10	25.00	130.57	Replace	0	0.00	Check	✗ N/A
One Time Key In	Main			MEMBER SUB-ASSY, RR RH	1	174.10	174.10	25.00	130.57	Replace	0	0.00	Check	✗ N/A
One Time Key In	Main			FLOOR PANEL RR/LH	1	102.00	102.00	25.00	76.50	Replace	0	0.00	Check	✗ N/A
One Time Key In	Main			FLOOR PANEL RR/RH	1	209.90	209.90	25.00	157.43	Replace	0	0.00	Check	✗ N/A
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0.00	Not Give	✗ N/A
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	0	0.00	Not Give	✗ N/A
One Time Key In	Main			BOARD, RR FLOOR	1	392.30	392.30	25.00	294.23	Replace	0	0.00	Not Give	✗ N/A
One Time Key In	Main			BOARD ASSY, RR RH	1	379.20	379.20	25.00	284.40	Replace	0	0.00	Not Give	✗ N/A
One Time Key In	Main			SPACER, RR FLOOR	1	130.60	130.60	25.00	97.95	Replace	0	0.00	Not Give	✗ N/A
Total Spare Part Cost									21,516.24	Surveyor Total 3,805.51				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 20.00				
Final Spare Part Cost									21,516.24	Final Sur Total 3,044.41				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BOX, DECK FLOOR, COVER LH	1	230.10	230.10	25.00	172.57	Replace	0	0.00	Not Givr	* X NN
One Time Key In	Main			BOX, DECK FLOOR, LH	1	196.80	196.80	25.00	147.60	Replace	0	0.00	Not Givr	* X NN
One Time Key In	Main			COVER ASSY, TONNEAU	1	602.10	602.10	25.00	451.58	Replace	0	0.00	Not Givr	* X NN
One Time Key In	Main			CUSHION, SPARE WHEEL	1	230.80	230.80	25.00	173.10	Replace	0	0.00	Check	* X NN
One Time Key In	Main			PROTECTOR, SPARE	1	143.70	143.70	25.00	107.77	Replace	0	0.00	Check	* X NN
One Time Key In	Main			CARRIER, SPARE	1	19.70	19.70	25.00	14.77	Replace	0	0.00	Check	* X NN
One Time Key In	Main		6503707	TYRE	1	126.74	126.74	25.00	95.05	Replace	0	0.00	Not Givr	* X NN
One Time Key In	Main			WHEEL, DISC	1	1,490.20	1,490.20	25.00	1,117.65	Replace	0	0.00	Not Givr	* X NN
One Time Key In	Main			BREAKDOWN SIGN	1	35.00	35.00	0.00	35.00	Replace	0	0.00	Check	* X NN
One Time Key In	Main			PANEL ASSY, DECK LH	1	307.00	307.00	25.00	230.25	Replace	0	0.00	Check	* X NN
One Time Key In	Main			PANEL ASSY, DECK RH	1	307.00	307.00	25.00	230.25	Replace	0	0.00	Check	* X NN
One Time Key In	Main			BATTERY	1	278.00	278.00	10.00	250.20	Replace	0	0.00	Check	* X NN
One Time Key In	Main			BATTERY CLAMP	1	16.10	16.10	25.00	12.08	Replace	0	0.00	Check	* X NN
One Time Key In	Main			BATTERY TRAY	1	42.80	42.80	25.00	32.10	Replace	0	0.00	Check	* X NN
One Time Key In	Main			WIRE, FLOOR	1	1,675.00	1,675.00	10.00	1,507.50	Replace	0	0.00	Not Givr	* X NN

Total Spare Part Cost

21,516.24

Surveyor Total

3,805.51

Lump Sum Discount (%)

0.00

Lump Sum Dis (%)

20.00

Final Spare Part Cost

21,516.24

Final Sur Total

3,044.41

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			WIRE, FLOOR, NO.2	1	1,305.40	1,305.40	10.00	1,174.86	Replace	0	0.00	Not Give	* X N/A
One Time Key In	Main			PANEL SUB-ASSY, QTR	1	588.40	588.40	25.00	441.30	Replace	0	0.00	Not Give	* X N/A
One Time Key In	Main			PANEL SUB-ASSY, QTR WHEEL HOUSE	1	588.40	588.40	25.00	441.30	Replace	0	0.00	Not Give	* X N/A
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.02	Replace	0	0.00	Check	* X N/A
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	0	0.00	Check	* X N/A
One Time Key In	Main			TROUGH, BACK DOOR LH	1	110.90	110.90	25.00	83.18	Replace	0	0.00	Not Give	* X N/A
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	0	0.00	Not Give	* X N/A
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0.00	Not Give	* X N/A
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0.00	Not Give	* X N/A
One Time Key In	Main			FENDER LINER RR/LH	1	141.30	141.30	25.00	105.98	Replace	0	0.00	Not Give	* X N/A
One Time Key In	Main			QUARTER GLASS RR/LH	1	168.10	168.10	25.00	126.07	Replace	0	0.00	Not Give	* X N/A
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0.00	Not Give	* X N/A
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0.00	Check	* X N/A
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0.00	Check	* X N/A
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	0	0.00	Not Give	* X N/A
Total Spare Part Cost									21,516.24	Surveyor Total			3,805.51	
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)			20.00	
Final Spare Part Cost									21,516.24	Final Sur Total			3,044.41	

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	0	0.00	Not Give	X NAI
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0.00	Not Give	X NAI
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0.00	Not Give	X NN
One Time Key In	Main			FENDER LINER RR/RH	1	141.30	141.30	25.00	105.98	Replace	1	105.98	Replace	/ CUT ✓
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0	Repair	X R
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give	X NAI
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Not Give	X NAI
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	X NAI
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	X NAI
One Time Key In	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	1	82.80 0.00	Replace	/ OR ✓
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00 0.00	Replace	/ CUT ✓
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00 0.00	Replace	/ CUT ✓
One Time Key In	Main			COVER, FR BUMPER HOLE RH	1	18.50	18.50	25.00	13.88	Replace	1	13.88 0.00	Replace	/ CR ✓
Total Spare Part Cost									21,516.24	Surveyor Total 3,805.51				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 20.00				
Final Spare Part Cost									21,516.24	Final Sur Total 3,044.41				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			2,028.00	1,000.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,690.00	800.00 ✓	
2	Main	TO REPAIR FRONT PORTION	338.00	200 ✓	
Total:			2,028.00	1,000.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200 ✓	
2	Main	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	100 ✓	
3	Main	TO RESPRAY REAR BUMPER	378.00	200.00 ✓	
4	Main	TO RESPRAY TAIL GATE	378.00	200.00 ✓	
5	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	80.00 ✓	
6	Main	TO RESPRAY REAR SPOILER	180.00	0.00	
7	Main	TO RESPRAY REAR PANEL	180.00	100.00 ✓	
8	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00	
9	Main	TO RESPRAY REAR MEMBER,RH	180.00	0.00	
10	Main	TO RESPRAY REAR MEMBER,LH	180.00	0.00	
11	Main	TO RESPRAY RH REAR WHEEL HOUSE	180.00	0.00	
12	Main	TO RESPRAY REAR LH WHEEL HOUSE	180.00	0.00	
13	Main	TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00	
14	Main	TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00	
15	Main	TO RESPRAY BATTERY PANEL	180.00	0.00	
16	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	0.00	
17	Main	TO RESPRAY TROUGH BACK DOOR LH	180.00	0.00	
18	Main	TO RESPRAY REAR FENDER LH	378.00	0.00	
Total:			4,410.00	880.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
19	Main	TO RESPRAY REAR FENDER RH	378.00	0.00	
Total:			4,410.00	880.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE & REFIT EXHAUST	120.00	0.00	
2	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	50.00	/ MC ✓
3	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00	SN NW
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20.00	/ MC ✓
5	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	40.00	/ MC ✓
6	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00	/ MC ✓
7	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120.00	/ MC ✓
8	Main	TO REMOVE AND REFIT WIRE HARDESS	250.00	0.00	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0.00	
10	Main	TO WASH AND VACUUM	60.00	0.00	
11	Main	TOWING CHARGE	56.00	0.00 40.00	/ MC ✓
12	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00	/ MC ✓
13	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00	
14	Main	TO REMOVE / REFIT SEAT	120.00	0.00	
15	Main	TO ALIGN CHASSIS	350.00	0.00	
16	Main	TO REMOVE & REFIT FUEL TANK	120.00	0.00	
Total:			2,301.00	200.00 330	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	21,516.24	3,044.41

36255.54
39746.44

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Labour Cost	2,028.00	1,000.00
Total Spray Painting	4,410.00	880.00
Other	2,301.00	290.00
Overall Total	30,255.24	5,214.41
Lump Sum Repair Option	☒	☒
Lump Sum Total	30,250.00	5,200.00
Surveyor Approved Amount		5,200.00
No of Repair Days*	12	7
Remarks		L/S REPAIR, PHOTO AFTER REPAIR.
Surveyor Name		Hwee Jie
Signature		
Survey Date	05/04/2019	

REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX/04/19/2011	Date of Collection	/ /
Vehicle No	SUC 4713 P	Date of Request	09 04 2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	

PHOTO 1mb

S/N	Part Number	Part Description	Quantity	Unit Price	
4715	4716	ARM SUB ASSY, REAR BUMPER	24.1pc	BT	\$187.80 ✓ (A)
4696	4697, 4699, 4704	UNDER COVER SUB ASSY, REAR FLOOR	1pc	DEF	\$385.88 ✓ (A)
4717	4719, 4720	TAILGATE DOOR LOCK	1pc	X SVC	
4725	4727, 4728, 4730	BOX DECK FLOOR REAR	1pc	CRA	\$487.78 ✓ (A)
4709	4710, 4711	BOARD ASSY, REAR RH	1pc	CRA	\$284.40 ✓ (B)
4712	4713, 4714	PROTECTOR, SPARE	1pc	CRA	\$107.78 ✓ (B)

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that: - Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

PJX

REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX/04/19/2011	Date of Collection	/ /
Vehicle No	SHE 4713P	Date of Request	09 04 2019
Vehicle Model	TOYOTA PRINS	Number of Days to Extend (If any)	

S/N	Part Number	Part Description	Quantity	Unit Price	
4707,	4708	BREAKDOWN SIGN	1pc	/ CRA	\$35 ✓ (A)
4721,	4722, 4723	TAILLAMP LH	1pc	/ CRA	\$493.56 ✓ (A)
	Labour to	REPAIR REAR FENDER LH		\$ 200	✓ (A)
	Labour to	SPRAY REAR FENDER LH		\$ 370	\$200 ✓ (A)
	Labour to	REPAIR SPARE TYRE PANEL		\$ 200	✓ (A)
	Labour to	SPRAY SPARE SPARE TYRE PANEL		\$ 200	\$100 ✓ (A)

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.



For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

pg 2/3

Section A - Accident Details

Registration Number	SHC4713P
Case Reference Number	TAX/04/19/2011
Registration Date	6/8/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	SHEIKH ZAINI BIN SHAHAR
Type of Accident	Head to Rear
Accident Date and Time	3/4/2019 5:45 PM
Accident Reported Date and Time	4/4/2019 12:52 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	3/4/2019 6:38 PM
Replacement Vehicle issued?	No
Job Card Number	24100897
Special Instruction to ARC, if any	TOWED \$40/TP
Prepared Date and Time	4/4/2019 2:12 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,428.00	\$1,400.00
Total Spray Cost	\$4,968.00	\$1,180.00
Total Spare Part Cost	\$18,798.35	\$4,728.77
Total Other Cost	\$2,301.00	\$330.00
TOTAL COST	\$28,495.35	\$7,638.77
Lump Sum Total	\$28,500.00	\$7,650.00 (L/S)
Number of Repair Days	12.0	7.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	05/04/2019 4:01 PM	05/04/2019 3:35 PM
Signature		
Remarks		L/S REPAIR, PHOTO AFTER REPAIR.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1910-0073	Invoice Number	
Quotation Date	05.10.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR FENDER LH	\$200.00	\$200.00 (Supp)
TO REPAIR REAR SPARE TYRE PANEL	\$200.00	\$200.00 (Supp)
TO REPAIR REAR PORTION	\$1,690.00	\$800.00
TO REPAIR FRONT PORTION	\$338.00	\$200.00
Total Labour	\$2,428.00	\$1,400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00 (Supp)
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$100.00 (Supp)
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$180.00	\$100.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$80.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY REAR MEMBER, RH	\$180.00	\$0.00
TO RESPRAY REAR MEMBER, LH	\$180.00	\$0.00
TO RESPRAY RH REAR WHEEL HOUSE	\$180.00	\$0.00
TO RESPRAY REAR LH WHEEL HOUSE	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	\$180.00	\$0.00
TO RESPRAY BATTERY PANEL	\$180.00	\$0.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
TO RESPRAY TROUGH BACK DOOR LH	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$4,968.00	\$1,180.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & REFIT EXHAUST	\$120.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$50.00

TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO TEST AND REFIT REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$40.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$30.00
TO REMOVE AND REFIT REAR WINDSCREEN	\$240.00	\$120.00
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$56.00	\$40.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO ALIGN CHASSIS	\$350.00	\$0.00
TO REMOVE & REFIT FUEL TANK	\$120.00	\$0.00
Total Other Costs	\$2,301.00	\$330.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace ✓
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace ✓
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace ✓
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check X
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace ✓
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	1.00	\$157.40	10.00	\$141.66	Replace	Replace ✓
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace ✓
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		76088-47020	BUMPER LIP COVER RR/LH	1.00	\$72.20	25.00	\$54.15	Replace	Replace ✓
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace ✓
		76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace ✓
		52592-47021	BUMPER SEAL, RR LH	1.00	\$88.90	25.00	\$66.68	Replace	Replace ✓
		52591-47021	BUMPER SEAL, RR RH	1.00	\$65.70	25.00	\$49.28	Replace	Replace ✓
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace ✓
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace ✓
		58308-47011	UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Check X
		58327-47020	EXHAUST HEAT SHIELD, REAR	0.00	\$107.40	0.00	\$0.00	Replace	Check X
		17430-37380	EXHAUST TAIL PIPE	0.00	\$656.20	0.00	\$0.00	Replace	Check X
		17565-22030	SUPPORT, EXHAUST REAR	0.00	\$33.60	0.00	\$0.00	Replace	Check X
		67005-47241	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace ✓
		75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace ✓
		75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace ✓
		75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$29.40	25.00	\$22.05	Replace	Replace ✓

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
Fax Number : 63655522
Estimator Telephone Number : 68662823
Accident Reporting Number : 68662872

Date Generated : 09/10/2019

User ID : PehSuan

	56117-50140	DAM, BACK DOOR GLASS ADHESIVE, NO.1	1.00	\$27.30	25.00	\$20.48	Replace	Replace	
	68294-47050	DAM, BACK DOOR GLASS ADHESIVE, NO.2	1.00	\$17.40	25.00	\$13.05	Replace	Replace	
	75575-47020	MOULDING, BACK WINDOW, LOWER NO.2	1.00	\$29.40	25.00	\$22.05	Replace	Replace	
	75574-47010	MOULDING, BACK WINDOW, OUTSIDE LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	
	75573-47090	MOULDING, BACK WINDOW, OUTSIDE RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	
		SEALANT W/SCREEN	3.00	\$37.00	25.00	\$83.25	Replace	Replace	
	68810-47010	TAILGATE DOOR HINGE LH/RH	0.00	\$58.30	0.00	\$0.00	Replace	Check	X
	69350-47030	TAILGATE DOOR LOCK	0.00	\$444.10	0.00	\$0.00	Replace	Check	X
	68960-0W532	TAILGATE DOOR STAY LH	0.00	\$241.50	0.00	\$0.00	Replace	Check	X
	68950-0W542	TAILGATE DOOR STAY RH	0.00	\$241.50	0.00	\$0.00	Replace	Check	X
	67881-47022	TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	0.00	\$0.00	Replace	Check	X
	69415-47020	TAILGATE LOCK, COVER	0.00	\$15.70	0.00	\$0.00	Replace	Check	X
	76801-47070-B0	TAILGATE OUTSIDE GARNISH	1.00	\$504.90	25.00	\$378.68	Replace	Replace	
	69431-47010	STRIKER, BACK DOOR	0.00	\$48.90	0.00	\$0.00	Replace	Check	X
	67938-47031C0	TAILGATE TRIM, LH	0.00	\$85.90	0.00	\$0.00	Replace	Check	X
	67751-47040C0	TAILGATE TRIM, LOWER	0.00	\$180.70	0.00	\$0.00	Replace	Check	X
	67937-47031C0	TAILGATE TRIM, RH	0.00	\$88.30	0.00	\$0.00	Replace	Check	X
	64790-47030C0	TAILGATE TRIM, UPPER	0.00	\$49.60	0.00	\$0.00	Replace	Check	X
	67750-47071C0	TAILGATE, BOARD ASSY	0.00	\$246.90	0.00	\$0.00	Replace	Check	X
	82184-47370	WIRE, BACK DOOR, NO.1	0.00	\$582.40	0.00	\$0.00	Replace	Not Given	X
	84840-28040	SWITCH ASSY, BACK DOOR OPENER	0.00	\$146.10	0.00	\$0.00	Replace	Check	X
	75310-47020	EMBLEM REAR	1.00	\$60.30	25.00	\$45.23	Replace	Replace	
	81271-53011	LICENSE PLATE LAMP	0.00	\$35.70	0.00	\$0.00	Replace	Check	X
		NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	X
		NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given	X
	75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	
	75442-47030	NAME PLATE (PRIUS)	1.00	\$60.80	25.00	\$45.60	Replace	Replace	
	75443-47030	NAME PLATE (TOYOTA)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	
	76085-47910	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Check	X
	81006-47011	3RD BRAKE LAMP	0.00	\$231.30	0.00	\$0.00	Replace	Check	X
		SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	
	58307-47060	END PANEL	1.00	\$602.10	25.00	\$451.58	Replace	Replace	
	64716-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Check	X
	64716-47031B0	END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	0.00	\$0.00	Replace	Check	X
	58336-12090	REINFORCEMENT, RR	0.00	\$34.60	0.00	\$0.00	Replace	Check	X
4006314		SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace	
	58311-47071	SPARE TYRE PANEL	0.00	\$667.70	0.00	\$0.00	Replace	Not Given	X
	57604-47030	MEMBER SUB-ASSY, RR LH	0.00	\$174.10	0.00	\$0.00	Replace	Check	X
	57603-47030	MEMBER SUB-ASSY, RR RH	0.00	\$174.10	0.00	\$0.00	Replace	Check	X
	58303-47301	FLOOR PANEL RR/LH	0.00	\$102.00	0.00	\$0.00	Replace	Check	X



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Woodlands Industrial Park E4, Singapore 757105
Fax Number: 63865562
Estimator Telephone Number: 69662023
Accident Reporting Number: 92662672

Date Generated : 09/16/2019

User ID : PohBuan

	58302-47030	FLOOR PANEL RR/RH	0.00	\$209.90	0.00	\$0.00	Replace	Check	X
	64993-47020	BOX, DECK FLOOR, RR	0.00	\$649.70	0.00	\$0.00	Replace	Not Given	X
	58416-47030B3	BOX, RR FLOOR, BOARD	0.00	\$679.60	0.00	\$0.00	Replace	Not Given	X
	58415-47030	BOARD, RR FLOOR	0.00	\$392.30	0.00	\$0.00	Replace	Not Given	Y
	58490-47140B0	BOARD ASSY, RR RH	0.00	\$379.20	0.00	\$0.00	Replace	Not Given	X
	58427-47040	SPACER, RR FLOOR	0.00	\$130.60	0.00	\$0.00	Replace	Not Given	X
	58418-47070B0	BOX, DECK FLOOR, COVER LH	0.00	\$230.10	0.00	\$0.00	Replace	Not Given	X
	64997-47020	BOX, DECK FLOOR, LH	0.00	\$196.80	0.00	\$0.00	Replace	Not Given	X
	64910-47020-B0	COVER ASSY, TONNEAU	0.00	\$602.10	0.00	\$0.00	Replace	Not Given	X
	64777-47090	CUSHION, SPARE WHEEL	0.00	\$230.80	0.00	\$0.00	Replace	Check	X
	64778-47050	PROTECTOR, SPARE	0.00	\$143.70	0.00	\$0.00	Replace	Check	X
	51931-47020	CARRIER, SPARE	0.00	\$19.70	0.00	\$0.00	Replace	Check	X
6503707		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
	42611-47140	WHEEL, DISC	0.00	\$1,490.20	0.00	\$0.00	Replace	Not Given	X
		BREAKDOWN SIGN	0.00	\$35.00	0.00	\$0.00	Replace	Check	X
	64740-47031B2	PANEL ASSY, DECK LH	0.00	\$307.00	0.00	\$0.00	Replace	Check	X
	64730-47031B2	PANEL ASSY, DECK RH	0.00	\$307.00	0.00	\$0.00	Replace	Check	X
		BATTERY	0.00	\$278.00	0.00	\$0.00	Replace	Check	X
	74461-47050	BATTERY CLAMP	0.00	\$16.10	0.00	\$0.00	Replace	Check	X
	74440-47030	BATTERY TRAY	0.00	\$42.80	0.00	\$0.00	Replace	Check	X
	82161-47B22	WIRE, FLOOR	0.00	\$1,675.00	0.00	\$0.00	Replace	Not Given	X
	82162-47B20	WIRE, FLOOR, NO.2	0.00	\$1,305.40	0.00	\$0.00	Replace	Not Given	X
	61607-47060	PANEL SUB-ASSY, QTR	0.00	\$588.40	0.00	\$0.00	Replace	Not Given	X
	61608-47061	PANEL SUB-ASSY, QTR WHEEL HOUSE	0.00	\$588.40	0.00	\$0.00	Replace	Not Given	X
	52563-47010	TAIL LAMP BRACKET, LH	0.00	\$30.70	0.00	\$0.00	Replace	Check	X
	81561-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Check	X
	61622-47030	TROUGH, BACK DOOR LH	0.00	\$110.90	0.00	\$0.00	Replace	Not Given	X
	61602-47091	FENDER RR/LH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given	X
		SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
		STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
	65638-47021	FENDER LINER RR/LH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given	X
	62720-47031	QUARTER GLASS RR/LH	0.00	\$168.10	0.00	\$0.00	Replace	Not Given	X
		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
	52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Check	X
	81551-47180	TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Check	X
	61621-47030	TROUGH, BACK DOOR	0.00	\$110.90	0.00	\$0.00	Replace	Not Given	X
	61604-47090	FENDER RR/RH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given	X
		SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
		STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
	65637-47021	FENDER LINER RR/RH	1.00	\$141.30	25.00	\$105.98	Replace	Replace	✓
	52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair	R

	52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given	X
	52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given	X
	57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X
	57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X
	52114-47140	BRACKET, FR BUMPER	1.00	\$110.40	25.00	\$82.80	Replace	Replace	X
		NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace	X
		NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace	X
	52127-47903	COVER, FR BUMPER HOLE RH	1.00	\$18.50	25.00	\$13.88	Replace	Replace	X
Total				\$27,242.55		\$3,929.26			

3929.26

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	1.00	\$250.40	25.00	\$187.80	Replace	Replace
		58308-47011	UNDER COVER SUBASSY, RR FLOOR	1.00	\$514.50	25.00	\$385.88	Replace	Replace
		64993-47020	BOX, DECK FLOOR, RR	1.00	\$649.70	25.00	\$487.28	Replace	Replace
		58490-47140B0	BOARD ASSY, RR RH	1.00	\$379.20	25.00	\$284.40	Replace	Replace
		64778-47050	PROTECTOR, SPARE	1.00	\$143.70	25.00	\$107.78	Replace	Replace
			BREAKDOWN SIGN	1.00	\$35.00	0.00	\$35.00	Replace	Replace
		81561-47170	TAIL LAMP LH	1.00	\$548.40	10.00	\$493.56	Replace	Replace
Total					2,520.90		1,981.70		

BT
DE
CRA
CRA
CRA
CRA
CRA
CRA

5910.96

5910.96
- 20%
4728.77
+ 1400.00
+ 1510.00
7638.77
L/S \$7650/-

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHC4713P
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1394029
Chassis No.:	JTDKN36U805747368
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	06 Aug 2014
First Registration Date:	06 Aug 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Aug 2022
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	05 Aug 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,088.00
COE Rebate Amount:	\$20,819.00
Total Rebate Amount:	\$26,885.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Apr 2019

OK

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	08 Apr 2019 15:23	Clim Dtl Modified	Claimant's Name: -> SMRT TAXIS PTE LTD. Claimant's ID: -> 198905369K.	[A] Lau Shu Pei
2	08 Apr 2019 15:23	Clim Veh Model Changed	(204897) TOYOTA PRIUS TAXI 1.8 (A).	[A] Lau Shu Pei
3	08 Apr 2019 15:23	Clim Created	Reg No: SHC4713P. Acct Date: 2019/04/03. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). TP Insurer: MS First Capital Insurance Ltd (HQ). Workshop: SMRT Automotive Services Pte Ltd (Woodlands)	[A] Lau Shu Pei
4	08 Apr 2019 15:23	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
5	08 Apr 2019 15:23	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/04/17	[A] Lau Shu Pei
6	08 Apr 2019 15:23	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] Lau Shu Pei
7	08 Apr 2019 15:23	Clim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	08 Apr 2019 15:23	Adj Adjuster Assigned	[None] -> ONG HWEE JIE	[A] Lau Shu Pei
9	08 Apr 2019 15:23	Label Added	(23):Express.	[A] Lau Shu Pei
10	09 Jan 2020 17:26	Adj Rpt Initiated		[A] NUR SHAQILAH BTE ABDOL WAHAB
11	09 Jan 2020 17:26	Clim Dtl Modified	JPJ Reg. Date: -> 2014/08/06.	[A] NUR SHAQILAH BTE ABDOL WAHAB
12	09 Jan 2020 17:26	Clim Details Notified		[A] NUR SHAQILAH BTE ABDOL WAHAB
13	16 Jan 2020 12:24	Adj Mandate Request	Cur.Req:9001.25:LIABILITY: 100% B:28 3VEH CC OI LAST	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2402042	09 Jan 2020 17:26:43	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SHC4713P	SKT2218R	11.77

2/12/2020

Merimen e-Claims

Print Received Message

This mail is associated with :

***SHC4713P (5800043995SG)**

[SKT2218R]

TP

SMRT TAXIS PTE LTD

Apr 3 2019 5:00PM

[AU KOK HUA]

SMRT Automotive Services Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 07/02/2020 14:21 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9001.25) - SHC4713P - Claim Handler: Foo, Chit Yan

Approved:9001.25.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Apr 2019 Edit Reg		05 Apr 2019 00:00 Edit Adj Rpt	\$7,650.00 Edit Estimates	\$7,650.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	AU KOK HUA, ID: S2192680I, Tel: +6597485439		
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHC4713P	Date of Loss:	03/04/2019 17:00 - :59 [55 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5800043995SG	Policy/Cover Note No.:	2100407252 (Comprehensive)
Vehicle Reg. No. (Insured):	SKT2218R	Policy No. (Claimant):	D-19093197MFSH
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 17/04/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (07/02/2020): Alert - Adj Mandate Approved (\$9001.25) - SHC4713P - Claim Handler: Foo, Chit Y...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHC4713P (5800043995SG)**
[SKT2218R]

TP

SMRT TAXIS PTE LTD

Apr 3 2019 5:00PM

[AU KOK HUA]

SMRT Automotive Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Letters/Correspondences

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/04/19 09:20	General View	 Load JPG ☒	☒
2	11/04/19 09:20	General View	 Load JPG ☒	☒
3	11/04/19 09:20	General View	 Load JPG ☒	☒
4	11/04/19 09:20	General View	 Load JPG ☒	☒
5	11/04/19 09:20	General View	 Load JPG ☒	☒
6	11/04/19 09:20	General View	 Load JPG ☒	☒
7	11/04/19 09:20	General View	 Load JPG ☒	☒
8	11/04/19 09:20	General View	 Load JPG ☒	☒
9	11/04/19 09:20	General View	 Load JPG ☒	☒
10	11/04/19 09:20	General View	 Load JPG ☒	☒
11	11/04/19 09:20	General View	 Load JPG ☒	☒
12	11/04/19 09:20	General View	 Load JPG ☒	☒
13	11/04/19 09:20	General View	 Load JPG ☒	☒
14	11/04/19 09:20	General View	 Load JPG ☒	☒
15	11/04/19 09:20	General View	 Load JPG ☒	☒
16	11/04/19 09:20	General View	 Load JPG ☒	☒
17	11/04/19 09:20	General View	 Load JPG ☒	☒
18	11/04/19 09:20	General View	 Load JPG ☒	☒
19	11/04/19 09:20	General View	 Load JPG ☒	☒
20	11/04/19 09:20	General View	 Load JPG ☒	☒
21	11/04/19 09:20	General View	 Load JPG ☒	☒
22	11/04/19 09:20	General View	 Load JPG ☒	☒
23	11/04/19 09:20	General View	 Load JPG ☒	☒
24	11/04/19 09:20	General View	 Load JPG ☒	☒
25	11/04/19 09:20	General View	 Load JPG ☒	☒
26	11/04/19 09:20	General View	 Load JPG ☒	☒
27	11/04/19 09:20	General View	 Load JPG ☒	☒
28	11/04/19 09:20	General View	 Load JPG ☒	☒
29	11/04/19 09:20	General View	 Load JPG ☒	☒
30	11/04/19 09:20	General View	 Load JPG ☒	☒
31	11/04/19 09:20	General View	 Load JPG ☒	☒
32	11/04/19 09:20	General View	 Load JPG ☒	☒

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	11/04/19 09:20	General View	 Load JPG	☒
34	11/04/19 09:20	General View	 Load JPG	☒
35	11/04/19 09:20	General View	 Load JPG	☒
36	11/04/19 09:20	General View	 Load JPG	☒
37	11/04/19 09:20	General View	 Load JPG	☒
38	11/04/19 09:20	General View	 Load JPG	☒
39	11/04/19 09:20	General View	 Load JPG	☒
40	11/04/19 09:20	General View	 Load JPG	☒
41	11/04/19 09:20	General View	 Load JPG	☒
42	11/04/19 09:20	General View	 Load JPG	☒
43	11/04/19 10:06	Dismantled Parts	 Load JPG	☒
44	11/04/19 10:06	Dismantled Parts	 Load JPG	☒
45	11/04/19 10:06	Dismantled Parts	 Load JPG	☒
46	11/04/19 10:06	Dismantled Parts	 Load JPG	☒
47	11/04/19 10:06	Dismantled Parts	 Load JPG	☒
48	11/04/19 10:06	Dismantled Parts	 Load JPG	☒
49	11/04/19 10:06	Dismantled Parts	 Load JPG	☒
50	11/04/19 10:06	Dismantled Parts	 Load JPG	☒
51	11/04/19 10:06	Dismantled Parts	 Load JPG	☒
52	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
53	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
54	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
55	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
56	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
57	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
58	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
59	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
60	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
61	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
62	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
63	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
64	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
65	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
66	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
67	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
68	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
69	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
70	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
71	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
72	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
73	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
74	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
75	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
76	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
77	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
78	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
79	11/04/19 10:07	Dismantled Parts	 Load JPG	☒
80	11/04/19 10:07	Dismantled Parts	Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	11/04/19 10:07	Dismantled Parts	Load JPG	☒
82	11/04/19 10:07	Dismantled Parts	Load JPG	☒
83	11/04/19 10:07	Dismantled Parts	Load JPG	☒
84	10/10/19 19:18	After Repair Photo	Load JPG	☒
85	10/10/19 19:18	After Repair Photo	Load JPG	☒
86	10/10/19 19:18	After Repair Photo	Load JPG	☒
87	10/10/19 19:18	After Repair Photo	Load JPG	☒
88	10/10/19 19:18	After Repair Photo	Load JPG	☒
89	10/10/19 19:18	After Repair Photo	Load JPG	☒
90	10/10/19 19:18	After Repair Photo	Load JPG	☒
91	10/10/19 19:18	After Repair Photo	Load JPG	☒
92	10/10/19 19:18	After Repair Photo	Load JPG	☒
93	10/10/19 19:18	After Repair Photo	Load JPG	☒
94	10/10/19 19:18	After Repair Photo	Load JPG	☒
95	10/10/19 19:18	After Repair Photo	Load JPG	☒
96	10/10/19 19:18	After Repair Photo	Load JPG	☒
97	10/10/19 19:18	After Repair Photo	Load JPG	☒
98	10/10/19 19:18	After Repair Photo	Load JPG	☒
99	10/10/19 19:18	After Repair Photo	Load JPG	☒
100	10/10/19 19:18	After Repair Photo	Load JPG	☒
101	10/10/19 19:18	After Repair Photo	Load JPG	☒
102	10/10/19 19:18	After Repair Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/04/19 17:55	TP ESTIMATE- MARKED	Load PDF	
2	08/04/19 17:55	TP GIA REPORT	Load PDF	
3	15/01/20 17:23	LETTER TO OI	Load PDF	
4	15/01/20 17:23	LOD	Load PDF	
5	15/01/20 17:23	LTA SEARCH	Load PDF	
6	15/01/20 17:23	RENTAL MILEAGE	Load PDF	
7	15/01/20 17:23	RENTAL RECEIPT	Load PDF	
8	19/02/20 10:16	Authorisation to Act	Load PDF	
9	19/02/20 10:16	Release Voucher	Load PDF	
10	19/02/20 10:16	WORKSHOP INVOICE	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/04/19 09:59	OI GIA REPORT	Load PDF	
2	07/02/20 14:20	Clear Report	Load XLSX	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKT2218R (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHC4713P (TP veh)		
Date of Accident:	03/04/2019		

Global Sum Settlement	:	☒ Yes	☐ No	
Repair Estimate	:	\$		39,746.44
Final Repair Cost	:	\$		9,000.00
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		12.5 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (GLOBAL SUM)	:	\$		9,000.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)				
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	:	9,000.00
2)		:	
3)		:	

NUR SHAQILAH BTE ABDOL WAHAB

19 Feb
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19006154/JES3S2
Date: 19/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100407252
Claimant Vehicle No : SHC4713P **Insured Vehicle No :** SKT2218R
 Date of Loss: 03/04/2019 Nature of Claim: TP Claim No: 5800043995SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC4713P** Engine No: 2ZR1394029
 Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Chassis No: JTDKN36U805747368
 Reg. Date: 06/08/2014 (Man. Year: 2014) Odometer: 0 km
 Colour: Maroon
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Chilles 6 mm Rear Left Side: Chilles 6 mm
 Front Right Side: Chilles 6 mm Rear Right Side: Chilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,162.44	5,910.98	24,251.46	80.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,584.00	2,910.00	6,674.00	69.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,746.44	8,820.98	30,925.46	77.81
Approved Total (Overridden) (S\$)		7,650.00		
Nett Amount (S\$)	39,746.44	7,650.00	32,096.44	80.75
+ Car Rental (12.5 x S\$107.54/day) (S\$)		1,344.25		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		9,001.25		
Global Sum Settlement (S\$)		9,000.00		

INSPECTION

Date of Assignment: 05/04/2019
 Date Inspected: 05/04/2019 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705
 Estimated Period of Repair: 7.0 days

2/19/2020

Adjuster Report

Adjuster: ONG HWEE JIE

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR (DISC 25%)	Dented	458.60 F	*343.95 F
2	1		*BUMPER CLIPS (DISC 25%) 10pcs	Necessary	15.10 F	*12.08 F
3	1		*BUMPER REINFORCEMENT REAR (DISC 25%)	Dented	205.70 F	*154.28 F
4	1		*ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	Bent	139.60 F	*104.70 F
5	1		*BUMPER LIP COVER RR/LH (DISC 25%)	Crushed	72.20 F	*54.15 F
6	1		*BUMPER LIP COVER RR/RH (DISC 25%)	Crushed	118.10 F	*88.58 F
7	1		*BUMPER LIP REAR (DISC 25%)	Crushed	228.90 F	*171.68 F
8	1		*BUMPER SEAL, RR LH (DISC 25%)	Cut	88.90 F	*66.68 F
9	1		*BUMPER SEAL, RR RH (DISC 25%)	Cut	65.70 F	*49.28 F
10	1		*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Broken	94.80 F	*71.10 F
11	1		*BUMPER SIDE RETAINER RR/RH (DISC 25%)	Broken	94.80 F	*71.10 F
12	1		*TAILGATE ASY (DISC 25%)	Dented	1,007.90 F	*755.93 F
13	1		*TAIL GATE DOOR GLASS MOULDING, LH (DISC 25%)	Necessary	29.40 F	*22.05 F
14	1		*TAIL GATE DOOR GLASS MOULDING, RH (DISC 25%)	Necessary	29.40 F	*22.05 F
15	1		*MOULDING BACK WINDOW, LOWER NO.1 (DISC 25%)	Necessary	29.40 F	*22.05 F
16	1		*DAM, BACK DOOR GLASS ADHESIVE, NO.1 (DISC 25%)	Necessary	27.30 F	*20.48 F
17	1		*DAM, BACK DOOR GLASS ADHESIVE, NO.2 (DISC 25%)	Necessary	17.40 F	*13.05 F
18	1		*MOULDING, BACK WINDOW, LOWER NO.2 (DISC 25%)	Necessary	29.40 F	*22.05 F
19	1		*MOULDING, BACK WINDOW OUTSIDE LH NO.2 (DISC 25%)	Necessary	29.40 F	*22.05 F
20	1		*MOULDING, BACK WINDOW, OUTSIDE RH NO.2 (DISC 25%)	Necessary	29.40 F	*22.05 F
21	3		*SEALANT W/SCREEN (DISC 25%)	Necessary	111.00 F	*83.25 F
22	1		*TAILGATE OUTSIDE GARNISH (DISC 25%)	Broken	504.90 F	*378.68 F
23	1		*EMBLEM REAR (DISC 25%)	Necessary	60.30 F	*45.23 F
24	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
25	1		*NAME PLATE (PRIUS) (DISC 25%)	Necessary	60.80 F	*45.60 F
26	1		*NAME PLATE (TOYOTA) (DISC 25%)	Necessary	51.90 F	*38.93 F
27	1		*END PANEL (DISC 25%)	Dented	602.10 F	*451.58 F
28	1		*FENDER LINER RR/RH (DISC 25%)	Cut	141.30 F	*105.98 F
29	1		*BRACKET, FR BUMPER (DISC 25%)	Broken	110.40 F	*82.80 F
30	1		*COVER, FR BUMPER HOLE RH (DISC 25%)	Crushed	18.50 F	*13.88 F
31	1		*ARM SUB-ASSY, FR BUMPER LH (DISC 25%)	Bent	250.40 F	*187.80 F
32	1		*UNDER COVER SUBASSY, FF FLOOR (DISC 25%)	Deformed	514.50 F	*385.88 F
33	1		*BOX, DECK FLOOR, RR (DISC 25%)	Cracked	649.70 F	*487.28 F
34	1		*BOARD ASSY, RR RH (DISC 25%)	Cracked	379.20 F	*284.40 F
35	1		*PROTECTOR, SPARE (DISC 25%)	Cracked	143.70 F	*107.78 F
36	1		*ANTENNA ELECTRICAL LOWER REAR (DISC 10%)	Broken	157.40 F	*141.68 F
37	1		*TAIL LAMP LH (DISC 10%)	Cracked	548.40 F	*493.56 F
38	1		*SENSOR REVERSE (SN)	Broken	180.00 F	*180.00 F
39	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
40	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
41	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
42	1		*SEALANT SIKAFLEX (SN)	Necessary	37.00 F	*37.00 F
43	1		*NUMBER PLATE (SN)	Cut	15.00 F	*15.00 F
44	1		*NUMBER PLATE FRAME (SN)	Cut	12.00 F	*12.00 F
45	1		*BREAKDOWN SIGN (SN)	Cracked	35.00 F	*35.00 F
46	1		*ARM SUB-ASSY, RR BUMPER LH	Not Necessary	139.60 F	*- F
47	1		*UNDER COVER SUBASSY, RR FLOOR	Not Necessary	514.50 F	*- F
48	1		*EXHAUST HEAT SHIELD, REAR	Not Necessary	107.40 F	*- F
49	1		*EXHAUST TAIL PIPE	Not Necessary	656.20 F	*- F
50	2		*SUPPORT, EXHAUST REAR	Not Necessary	67.20 F	*- F
51	2		*TAILGATE DOOR HINGE LH/RH	Not Necessary	116.60 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*TAILGATE DOOR LOCK	Not Necessary	444.10 F	*- F
53	1		*TAILGATE DOOR STAY LH	Not Necessary	241.50 F	*- F
54	1		*TAILGATE DOOR STAY RH	Not Necessary	241.50 F	*- F
55	1		*TAILGATE DOOR WEATHERSTRIP	Not Necessary	353.40 F	*- F
56	1		*TAILGATE LOCK, COVER	Not Necessary	15.70 F	*- F
57	1		*STRIKER, BACK DOOR	Not Necessary	48.90 F	*- F
58	1		*TAILGATE TRIM, LH	Not Necessary	85.90 F	*- F
59	1		*TAILGATE TRIM, LOWER	Not Necessary	180.70 F	*- F
60	1		*TAILGATE TRIM, RH	Not Necessary	88.30 F	*- F
61	1		*TAILGATE TRIM, UPPER	Not Necessary	49.60 F	*- F
62	1		*TAILGATE, BOARD ASSY	Not Necessary	246.90 F	*- F
63	1		*WIRE, BACK DOOR, NO.1	Not Necessary	582.40 F	*- F
64	1		*SWITCH ASSY, BACK DOOR OPENER	Not Necessary	146.10 F	*- F
65	1		*LICENSE PLATE LAMP	Not Necessary	35.70 F	*- F
66	1		*NUMBER PLATE	Not Necessary	15.00 F	*- F
67	1		*NUMBER PLATE FRAME	Not Necessary	12.00 F	*- F
68	1		*SPOILER REAR	Not Necessary	953.70 F	*- F
69	1		*3RD BRAKE LAMP	Not Necessary	231.30 F	*- F
70	1		*END PANEL COVER, DECK TRIM HOLE	Not Necessary	46.10 F	*- F
71	1		*END PANEL COVER, DECK TRIM, RR	Not Necessary	121.10 F	*- F
72	2		*REINFORCEMENT, RR	Not Necessary	69.20 F	*- F
73	1		*SPARE TYRE PANEL	Not Necessary	667.70 F	*- F
74	1		*MEMBER SUB-ASSY, RR LH	Not Necessary	174.10 F	*- F
75	1		*MEMBER SUB-ASSY, RR RH	Not Necessary	174.10 F	*- F
76	1		*FLOOR PANEL RR/LH	Not Necessary	102.00 F	*- F
77	1		*FLOOR PANEL RR/RH	Not Necessary	209.90 F	*- F
78	1		*BOX, DECK FLOOR, RR	Not Necessary	649.70 F	*- F
79	1		*BOX, RR FLOOR, BOARD	Not Necessary	679.60 F	*- F
80	1		*BOARD, RR FLOOR	Not Necessary	392.30 F	*- F
81	1		*BOARD ASSY, RR RH	Not Necessary	379.20 F	*- F
82	1		*SPACER, RR FLOOR	Not Necessary	130.60 F	*- F
83	1		*BOX, DECK FLOOR, COVER LH	Not Necessary	230.10 F	*- F
84	1		*BOX, DECK FLOOR, LH	Not Necessary	196.80 F	*- F
85	1		*COVER ASSY, TONNEAU	Not Necessary	602.10 F	*- F
86	1		*CUSHION, SPARE WHEEL	Not Necessary	230.80 F	*- F
87	1		*PROTECTOR, SPARE	Not Necessary	143.70 F	*- F
88	1		*CARRIER, SPARE	Not Necessary	19.70 F	*- F
89	1		*TYRE	Not Necessary	126.74 F	*- F
90	1		*WHEEL, DISC	Not Necessary	1,490.20 F	*- F
91	1		*BREAKDOWN SIGN	Not Necessary	35.00 F	*- F
92	1		*PANEL ASSY, DECK LH	Not Necessary	307.00 F	*- F
93	1		*PANEL ASSY, DECK RH	Not Necessary	307.00 F	*- F
94	1		*BATTERY	Not Necessary	278.00 F	*- F
95	1		*BATTERY CLAMP	Not Necessary	16.10 F	*- F
96	1		*BATTERY TRAY	Not Necessary	42.80 F	*- F
97	1		*WIRE, FLOOR	Not Necessary	1,675.00 F	*- F
98	1		*WIRE, FLOOR NO.2	Not Necessary	1,305.40 F	*- F
99	1		*PANEL SUB-ASSY, QTR	Not Necessary	588.40 F	*- F
100	1		*PANEL SUB-ASSY, QTR WHEEL HOUSE	Not Necessary	588.40 F	*- F
101	1		*TAIL LAMP BRACKET, LH	Not Necessary	30.70 F	*- F
102	1		*TAIL LAMP LH	Not Necessary	548.40 F	*- F
103	1		*TROUGH, BACK DOOR LH	Not Necessary	110.90 F	*- F
104	1		*FENDER RR/LH	Not Necessary	766.80 F	*- F
105	1		*SMRT LOGO	Not Necessary	7.80 F	*- F
106	1		*STICKER DECAL 6555 8888	Not Necessary	21.60 F	*- F
107	1		*FENDER LINER RR/LH	Not Necessary	141.30 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
108	1		*QUARTER GLASS RR/LH	Not Necessary	168.10 F	*- F
109	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
110	1		*TAIL LAMP BRACKET, RH	Not Necessary	30.70 F	*- F
111	1		*TAIL LAMP RH	Not Necessary	557.80 F	*- F
112	1		*TROUGH, BACK DOOR	Not Necessary	110.90 F	*- F
113	1		*FENDER RR/RH	Not Necessary	766.80 F	*- F
114	1		*SMRT LOGO	Not Necessary	7.80 F	*- F
115	1		*STICKER DECAL 6555 8888	Not Necessary	21.60 F	*- F
116	1		*BUMPER ENERGY ABSORBER FRT	Not Necessary	78.80 F	*- F
117	1		*BUMPER REINFORCEMENT FRT	Not Necessary	498.40 F	*- F
118	1		*ARM SUB-ASSY, FR BUMPER LH	Not Necessary	250.40 F	*- F
119	1		*ARM SUB-ASSY, FR BUMPER RH	Not Necessary	250.40 F	*- F
120	1		*SOLAR FILM (SN)	Not Necessary	125.00 F	*- F
121	1		*TAILGATE DOOR LOCK (NPA)	Serviceable	0.00 F	*- F
122	1		*BUMPER FRT	Repair	482.00 F	*- F
Total Parts (\$\$)					30,162.44	5,910.98

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	2,028.00	1,000.00
2	SPRAY PAINT.	New	4,410.00	880.00
3	TO REMOVE & REFIT EXHAUST.	New	120.00	0.00
4	TO TRANSFER REAR TAILGATE MECHANISM.	New	120.00	50.00
5	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	20.00
6	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	New	120.00	40.00
7	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.	New	120.00	30.00
8	TO REMOVE AND REFIX REAR WINDSCREEN.	New	240.00	120.00
9	TO REMOVE AND REFIT WIRE HARDESS.	New	250.00	0.00
10	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
11	TO WASH AND VACUUM.	New	60.00	0.00
12	TOWING CHARGE.	New	56.00	40.00
13	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	30.00
14	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	200.00	0.00
15	TO REMOVE / REFIT SEAT.	New	120.00	0.00
16	TO ALIGN CHASSIS.	New	350.00	0.00
17	TO REMOVE & REFIT FUEL TANK.	New	120.00	0.00
18	REPAIR REAR FENDER LH.	New	200.00	200.00
19	SPRAY REAR FENDER LH.	New	370.00	200.00
20	REPAIR SPARE TYRE PANEL.	New	200.00	200.00
21	SPRAY SPARE SPARE TYRE PANEL.	New	200.00	100.00
Gross Labour Cost (\$\$)			9,584.00	2,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >