

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III19006164/KPS3Q2
Date: 20/10/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SMH1197M	Insured Vehicle No :	SHA7833S
Date of Loss:	04/04/2019	Nature of Claim:	TP
		Claim No:	MCT19040108

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH1197M	Engine No:	2AZJ121326
Make & Model:	TOYOTA PREVIA, 2.4 7-seater (A)	Chassis No:	JTEGD54M70A046668
Reg. Date:	03/02/2015 (Man. Year: 2014)	Odometer:	34808 km
Colour:	Metallic Grey		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,964.96	4,984.75	8,980.21	64.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,780.00	2,420.00	1,360.00	35.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,744.96	7,404.75	10,340.21	58.27
Approved Total (Overridden) (S\$)		5,950.00		

Nett Amount (S\$)	17,744.96	5,950.00	11,794.96	66.47
+ Car Rental (7.0 x S\$130.00/day + 7.00% GST) (S\$)		973.70		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,931.15		
Global Sum Settlement (S\$)		6,860.00		

INSPECTION

Date of Assignment: 08/04/2019

Date Inspected: 08/04/2019

Estimated Period of Repair: 9.0 days

Inspected At: Autoworx House - Sin Ming (HQ)
176 SIN MING DRIVE #02-01
Singapore 575721

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2021)
Parts:	M1-MPV	TOYOTA PREVIA 2.4 7-seater (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH1197M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	1,940.38 FL	*1,470.80 FL
2	1		*REAR BOOT LOCK	Serviceable	387.92 FL	*- FL
3	1		*REAR BOOT LOCK CATCH	Repair	132.20 FL	*- FL
4	2		*REAR BOOT DAMPER	Serviceable	594.20 FL	*- FL
5	1		*REAR BOOT LID SIDE GUILD	Serviceable	344.18 FL	*- FL
6	1		*REAR BOOT INNER HANDLE	Serviceable	170.65 FL	*- FL
7	1		*REAR BOOT OUTER HANDLE SWITCH	Serviceable	701.40 FL	*- FL
8	1		*REAR BOOT INNER TRIM	Serviceable	590.65 FL	*- FL
9	1		*REAR BOOT WEATHERSTRIP (50%)	Dented / Distorted	222.15 FS	*148.10 FS
10	1		*REAR BOOT LOGO EMBLEM	Necessary	101.00 FL	*101.00 FL
11	1		*REAR BOOT PREVIA EMBLEM	Necessary	86.30 FL	*86.30 FL
12	1		*REAR BOOT GL EMBLEM	Necessary	77.70 FL	*77.70 FL
13	1		*REAR BOOT LID INNER TRIM BOARD COVER L/H	Serviceable	198.40 FL	*- FL
14	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	182.40 FL	*182.40 FL
15	1		*REAR BUMPER	Buckled	1,535.10 FL	*785.30 FL
16	2		*REAR BUMPER SIDE RETAINER	Serviceable	155.00 FL	*- FL
17	2		*REAR BUMPER CORNER RETAINER	Serviceable	144.00 FL	*- FL
18	1		*REAR BUMPER SIDE REFLECTOR	N/S Cut	129.20 FL	*64.60 FL
19	2		*REAR BUMPER CORNER DUST COVER	Serviceable	233.00 FL	*- FL
20	2		*REAR BUMPER TOW HOOK COVER	Serviceable	135.20 FL	*- FL
21	2		*REAR CABIN SIDE LOWER TRIM	Buckled	482.60 FL	*482.60 FL
22	1		*REAR CABIN LOWER TRIM COVER R/H	Serviceable	297.60 FL	*- FL
23	1		*REAR CABIN LOWER TRIM COVER L/H	Serviceable	297.60 FL	*- FL
24	2		*REAR TAIL LAMP ASSY	Serviceable	973.60 FL	*- FL
25	1		*REAR END PANEL	Bent	728.10 FL	*688.60 FL
26	1		*REAR END INNER PANEL	No such part	467.30 FL	*- FL
27	1		*REAR END PANEL TRIM	Distorted	356.10 FL	*356.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR END COMPARTMENT TOP BOARD	Serviceable	785.60 FL	*- FL
29	1		*REAR END COMPARTMENT PANEL	Bent	604.30 FL	*604.30 FL
30	1		*REAR END COMPARTMENT PANEL TRIM	Buckled	560.20 FL	*560.20 FL
31	1		*REAR KEY LOCK SWITCH SENSOR	Cracked	346.70 FL	*346.70 FL
32	1		*REAR COMPARTMENT FLOOR PANEL	Repair	922.60 FL	*- FL
33	1		*REAR COMPARTMENT FLOOR PANEL SUB-FRAME	Repair	656.90 FL	*- FL
34	1		*REAR EXHAUST SILENCER	Repair	884.50 FL	*- FL
35	1		*REAR EXHAUST SILENCER HEAT SHIELD	Repair	264.10 FL	*- FL
36	1		*REAR NUMBER PLATE	Serviceable	35.00 FS	*- FS
37	1		*REAR NUMBER PLATE CASING	Serviceable	35.00 FS	*- FS
38	1		*TUBE WINDSCREEN GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
39	3		*EXHAUST RUBBER MOUNT	Serviceable	270.00 FS	*- FS
40	1		*SET REVERSE SENSOR	Shorted	220.00 FS	*220.00 FS
41	2		*REAR BUMPER PARK SENSOR	Repeated	734.80 FL	*- FL
42	1		*REAR PART CLOSING MODE BUZZER	Dented	295.60 FL	*295.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,339.23	6,510.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,374.27	1,525.55
Total Parts (\$\$)	13,964.96	4,984.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE ,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	1,600.00	1,100.00
2	TO CHECK WIRING SYSTEM	New	60.00	20.00
3	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	200.00	60.00
4	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS	New	180.00	30.00
5	TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	880.00
6	TO INSTALL REVERSE SENSORS	New	80.00	50.00
7	TO REMOVE FUEL TANK TO ENABLE REPAIR	New	80.00	0.00
8	TO REMOVE REAR AND SIDE WINDSCREEN GLASSES TO ENABLE REPAIR	New	140.00	120.00
9	TO REMOVE CARPET ,TRIMMING AND SEATS TO ENABLE REPAIR	New	300.00	100.00
10	TO TRANSFER TAIL DOOR ACCESSORIES	New	60.00	60.00
11	TO CARRY OUT EXHAUST WORKS	New	80.00	0.00
Gross Labour Cost (\$\$)			3,780.00	2,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >