



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R


## Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III19003099/Gqd3e2-1

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 17-04-2019



Code : III2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHC 8234D	<b>Veh. Inspected</b>	SJL 2274G
<b>Policy No.</b>	MCOM0015	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MCT19020376	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	STANLEY LAI	<b>Assign Date</b>	05/04/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA AXIO	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2008
<b>Chassis No.</b>	NZE1416100576	<b>Colour</b>	BLUE
<b>Odometer</b>	314030	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/60 R15	BRIDGESTONE	5 mm
<b>L/H Front Tyre</b>	195/60 R15	BRIDGESTONE	5 mm
<b>R/H Rear Tyre</b>	195/60 R15	BRIDGESTONE	5 mm
<b>L/H Rear Tyre</b>	195/60 R15	BRIDGESTONE	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	13/02/2019	<b>Inspection Date</b>	19/02/2019
<b>Survey held at</b>	MTA AUTO-25 KAKI BUKIT RD 4#07-47		
<b>Repairer</b>	-		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**