



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2003849  
INV Date 13/05/2020  
Reference CC6/CTI19006240/Uka3q2  
Code CTI



#### PROFESSIONAL SERVICE FEE

Vehicle No. SLK 6916T  
Insured Veh. SDS 6762Y  
Claim No. SNM19D201593C02  
Policy No. DMPCSN1817471800  
Accident Date 09/04/2019  
Inspection Date 09/04/2019

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19006240/Uka3q2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 13-05-2020



Code : CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SDS 6762Y	<b>Veh. Inspected</b>	SLK 6916T
<b>Policy No.</b>	DMPCSN1817471800	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	SNM19D201593C02	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	09/04/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	NISSAN QASHQAI (A)	<b>c.c</b>	1197
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	SJNFEAJ11U1720846	<b>Colour</b>	BROWN
<b>Odometer</b>	24535	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	215/60 R17	GOODYEAR	6 mm
<b>L/H Front Tyre</b>	215/60 R17	GOODYEAR	6 mm
<b>R/H Rear Tyre</b>	215/60 R17	GOODYEAR	6 mm
<b>L/H Rear Tyre</b>	215/60 R17	GOODYEAR	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	09/04/2019	<b>Inspection Date</b>	09/04/2019
<b>Survey held at</b>	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>4 Working Days</b>
-------------------------------------	-----------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 6916T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR WINDSCREEN W/MOULding	NOT NECESSARY	1,855.30	-
2	REAR WINDSCREEN INNER SIDE GARNISH @\$165.00	NOT NECESSARY	330.00	-
1	TAILGATE	TO REPAIR SEE LABOUR	3,066.20	-
1	TAILGATE OUTER GARNISH	NOT NECESSARY	450.00	-
1	TAILGATE REAR LOGO	NOT NECESSARY	38.50	-
1	TAILGATE 'QASHQAI' EMBLEM	NECESSARY	78.50	78.50
2	TAILGATE REFLECTORS @\$650.00	NOT NECESSARY	1,300.00	-
1	TAILGATE REAR WIPER ARM	NOT NECESSARY	166.00	-
1	TAILGATE REAR WIPER MOTOR	NOT NECESSARY	966.00	-
1	TAILGATE INNER LOCK	NOT NECESSARY	292.00	-
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	595.30	-
1	SET TAILGATE INNER TRIM BOARD CLIPS	NOT NECESSARY	30.00	-
1	TAILGATE WEATHERSTRIP	TWISTED	166.20	166.20
1	TAILGATE REVERSE CAMERA	NOT NECESSARY	485.00	-
2	TAILGATE LICENCE PLATE LAMPS @\$53.00	NOT NECESSARY	106.00	-
1	REAR BUMPER	DENTED / DEFORMED	891.00	717.00
1	REAR BUMPER TOW COVER	NOT NECESSARY	22.00	-
2	REAR BUMPER REFLECTORS @\$68.00	NOT NECESSARY	136.00	-
2	REAR BUMPER SIDE RETAINERS @\$35.00	NOT NECESSARY	70.00	-
1	SET REAR BUMPER CLIPS	NECESSARY	35.00	35.00
1	REAR BUMPER SPONGE	TORN	185.00	126.40
1	REAR BUMPER REINFORCEMENT	BENT	721.00	619.20
2	REAR BUMPER REINFORCEMENT BRACKETS @\$150.00	SERVICEABLE	300.00	-
1	REAR END PANEL	DENTED	720.00	482.60
1	REAR SUPPORT PANEL TOP GARNISH	TWISTED	408.00	315.30
1	REAR FLOOR PANEL	NOT NECESSARY	1,288.00	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	622.00	-
2	REAR FLOOR PANEL TOOLS SPONGES @\$305.00	NOT NECESSARY	610.00	-
1	REAR END PANEL LOCK SENSOR	NOT NECESSARY	265.00	-

Report Ref No. CC6/CTI19006240/Uka3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR FLOOR PANEL TOP BOARD SPONGE	NOT NECESSARY	495.00	-
1	REAR EXHAUST	TO REPAIR SEE LABOUR	1,122.30	-
2	REAR EXHAUST MOUNTINGS @\$60.00	NOT NECESSARY	120.00	-
2	TAILLAMPS @\$580.00	CRACKED	1,160.00	647.40
2	REAR FENDERS @\$1150.00	NOT NECESSARY	2,300.00	-
2	REAR FENDER OUTER PROTECTORS @\$541.00	TORN	1,082.00	1,082.00
	LESS 10% DISCOUNT		-	-426.96
			22,477.30	3,842.64
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR LICENCE PLATE W/HOLDER (SN)	NOT NECESSARY	50.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	50.00	-
			480.00	250.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REPLACING REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX REAR EXHAUST .		150.00	80.00
	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY.		100.00	80.00
	TO SPRAY RUST PROOFING.		120.00	50.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE AND REAR EXHAUST .		1,500.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	950.00
			4,060.00	2,040.00
<b>GRAND TOTAL</b>			<b>27,017.30</b>	<b>6,132.64</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,900.00</b>

Report Ref No. CC6/CTI19006240/Uka3q2



Report Ref No. CC6/CTI19006240/Uka3q2

A handwritten signature in black ink, appearing to read 'Chua'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SLK 6916T

### INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLK 6916T

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLK 6916T

RE-INSPECTION

