



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2003324
INV Date 21/04/2020
Reference CC3/CTI19006241/K1ea3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SHA 1359J
Insured Veh. XD 3414P
Claim No. SNM19D201573C02/4
Policy No. DMCVSN1831231800
Accident Date 06/04/2019
Inspection Date 08/04/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI19006241/K1ea3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 21-04-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 3414P	Veh. Inspected	SHA 1359J	
Policy No.	DMCVSN1831231800	Coverage (\$)	0.00	
Claim No.	SNM19D201573C02/4	Excess (\$)	0.00	
Assign From		Assign Date	08/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KMHC851CVKU122209	Colour	BLUE	
Odometer	42270	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	8 mm	
L/H Front Tyre	195/65 R15	MICHELIN	8 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	8 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/04/2019	Inspection Date	08/04/2019	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1359J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOT LID	BENT	2,489.40	2,489.40
1	BOOT LID LOCK UPPER	SERVICEABLE	224.00	-
1	BOOT LID 'H' EMBLEM	NOT NECESSARY	28.00	-
1	EMBLEM -HYBRID	NECESSARY	24.30	24.30
1	EMBLEM -IONIQ	NECESSARY	31.30	31.30
1	EMBLEM -BLUE DRIVE (LH/RH) @\$26.60	NOT NECESSARY	53.20	-
1	BOOT LID GLASS ,UPPER	SERVICEABLE	543.30	-
1	BOOT LID GLASS ,LOWER	CRACKED	384.90	384.90
1	REAR SPOILER	TO REPAIR SEE LABOUR	665.40	-
1	BOOT LID LAMP (LH)	CRACKED	794.40	794.40
1	BOOTLID GARNISH	SERVICEABLE	36.10	-
1	BOOTLID LOWER GARNISH	SERVICEABLE	25.40	-
1	REAR BUMPER	DEFORMED	459.40	459.40
1	REAR BUMPER REINFORCEMENT	BENT	294.80	294.80
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$138.10	SERVICEABLE	276.20	-
1	REAR BUMPER CENTRE MOULDING ASSY	CRACKED	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	SERVICEABLE	47.50	-
10	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	TAIL LAMP (LH)	SERVICEABLE	870.40	-
1	REAR PANEL	TO REPAIR SEE LABOUR	532.00	-
1	REAR PANEL GARNISH	SERVICEABLE	155.00	-
2	REAR PANEL LOWER PANEL @\$39.40	TO REPAIR SEE LABOUR	78.80	-
1	ANTENNA ASSY -SMARTK (ADDITIONAL)	NECESSARY	40.50	40.50
1	UNIT ASSY -BSD LH (ADDITIONAL)	SHORTED	1,487.00	1,487.00
1	REAR FOG LAMP ASSY (ADDITIONAL)	CRACKED	201.50	201.50
	LESS 20% DISCOUNT		-2,043.21	-1,336.15
			8,172.84	5,344.60

Report Ref No. CC3/CTI19006241/K1ea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	BOOT LID COMFORT LOGO STICKER (SN)	NECESSARY	30.00	30.00
1	REAR NO.PLATE (SN)	CRACKED	25.00	25.00
2	GLASS SEALANT (SN)(ADDITIONAL)	NECESSARY	46.00	46.00
1	REAR BUMPER MAT (SN) (ADDITIONAL)	NECESSARY	50.00	50.00
1	REVERSE SENSOR (SN) (ADDITIONAL)	SHORTED	135.70	135.70
			286.70	286.70
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR SPOILER ,REAR PANEL AND REAR PANEL LOWER PANEL.		800.00	600.00
	SPRAY PAINTING CHARGE.		900.00	600.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.		50.00	20.00
	REMOVE/REFIX REVERSE SENSOR .		120.00	30.00
			1,920.00	1,270.00
GRAND TOTAL			10,379.54	6,901.30
RECOMMENDED COST OF REPAIRS				6,901.30

Report Ref No. CC3/CTI19006241/K1ea3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.