

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS1/MSG19006245/ETD3E2  
**Date:** 02/09/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 26565729MTR  
**Claimant Vehicle No :** SMC5050C **Insured Vehicle No :** SDD5242S  
Date of Loss: 02/04/2019 Nature of Claim: TP Claim No: 589795

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC5050C**  
Make & Model: TOYOTA C-HR, 1.8 HYBRID S/G (A) Engine No: 2ZR6999466  
Reg. Date: 11/08/2017 (Man. Year: 2017) Chassis No: ZYX102002453  
Colour: Black Odometer: 73148 km  
Engine Capacity: 1797 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18  
Front Left Side: Toyo 7 mm Rear Left Side: Toyo 7 mm  
Front Right Side: Toyo 7 mm Rear Right Side: Toyo 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,102.79	4,952.92	3,149.87	38.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,120.00	1,740.00	1,380.00	44.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,222.79</b>	<b>6,692.92</b>	<b>4,529.87</b>	<b>40.36</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,350.00</b>		
<b>(S\$)</b>	11,222.79	5,350.00	5,872.79	52.33
<b>+ GST 7.00/7.00% (S\$)</b>	785.60	374.50	411.10	52.33
<b>Nett Amount (S\$)</b>	<b>12,008.39</b>	<b>5,724.50</b>	<b>6,283.89</b>	<b>52.33</b>

### INSPECTION

Date of Assignment: 09/04/2019  
Date Inspected: 09/04/2019 Inspected At: Aesop Auto-care Pte Ltd (HQ)  
2, #01-299/301  
Singapore 569535  
Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 02 Sep 2019)

**Parts:** M1-SUV      TOYOTA C-HR 1.8 HYBRID S/G (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** LKK Auto Consultants Pte Ltd/SMC5050C/02/09/2019 08:43

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LED HEADLAMP ASSEMBLY - O/S	Len Deep Grazed	1,916.05 FL	*1,916.05 FL
2	1		*FRONT FENDER PANEL - O/S	Damage	889.60 FL	*655.00 FL
3	1		*FRONT FENDER ARCH GARNISH - O/S	Missing / Dislodged	156.11 FL	*156.11 FL
4	1		*FRONT FENDER ARCH GARNISH CLIP - O/S (11PCS)	Necessary	29.48 FL	*20.00 FL
5	1		*FRONT FENDER INNER SHIELD - O/S	Deformed / Cracked	257.98 FL	*257.98 FL
6	8		*FRONT FENDER INNER SHIELD CLIP - O/S	Necessary	21.44 FL	*21.44 FL
7	1		*FRONT DOOR ASSEMBLY - O/S	Repair	1,409.51 FL	*- FL
8	10		*FRONT BUMPER CLIP	Necessary	42.80 FL	*30.00 FL
9	1		*FRONT BUMPER SIDE RETAINER - O/S	Cracked / Broken	125.51 FL	*125.51 FL
10	1		*FRONT WHEEL HUB ASSEMBLY - O/S	Dented / Bent	745.90 FL	*374.45 FL
11	1		*FRONT STEERING KNUCKLE - O/S	Dented / Bent	637.51 FL	*591.60 FL
12	1		*FRONT SUSPENSION STRUT ABSORBER - O/S	No Damage	493.70 FL	*- FL
13	1		*FRONT SUSPENSION LOWER ARM - O/S	Bent / Twisted	694.11 FL	*489.00 FL
14	1		*FRONT SUSPENSION LOWER ARM BALL JOINT - O/S	No Damage	272.85 FL	*- FL
15	1		*FRONT FENDER HYBRID PLATE - O/S	Necessary	51.90 FS	*51.90 FS
16	1		*FRONT TOYO 225/50R18 TYRE - O/S	Serviceable	250.00 FS	*- FS
17	1		*FRONT 18 ALLOY WHEEL RIM - O/S	Deep Grazed	500.00 FS	*350.00 FS
18	1		*FRONT BUMPER FACE - O/S	Grazed / Torn	419.55 FL	*419.55 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>8,914.00</b>	<b>5,458.59</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	811.21	505.67
<b>Total Parts (S\$)</b>	<b>8,102.79</b>	<b>4,952.92</b>

LKK Auto Consultants Pte Ltd/SMC5050C/02/09/2019 08:43. Not valid without Reference section.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO PANEL BEAT RIGHT FRONT DOOR PANEL AND REPAIR BONNET INCLUDING REPLACEMENT OF THE RIGHT FRONT ACCIDENT DAMAGED PARTS	New	1,250.00	600.00
2	TO CHECK FRONT LIGHTINGS AND ELECTRICAL WIRING SYSTEMS INCLUDE FOCUSING BOTH HEADLIGHTS AND ADJUST IF NECESSARY	New	80.00	30.00
3	TO TRANSFER FRONT BUMPER PARKING AID SENSORS TO NEW BUMPER FACE INCLUDE TESTING FOR FUNCTIONS	New	120.00	20.00
4	TO REMOVE / INSTALL RIGHT FRONT WHEEL TO TRANSFER TYRE TO NEW ALLOY WHEEL INCLUDE BALANCING THE WHEEL	New	45.00	20.00
5	TO REMOVE / INSTALL FRONT SUSPENSION SYSTEM TO REPLACE RIGHT FRONT DAMAGED UNDERCARRIAGE PART	New	225.00	180.00
6	TO CARRY OUT COMPUTERISED 4 WHEELS ALIGNMENT AND ADJUST IF NECESSARY	New	120.00	60.00
7	TO PUTTY AND RE-SPRAY PAINTING ON THE BONNET, RIGHT FRONT FENDER, RIGHT FRONT DOOR AND FRONT BUMPER FACE	New	1,200.00	800.00
8	RUST-PROOFING ON THE RIGHT FRONT ACCIDENT AFFECTED PORTIONS	New	80.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>3,120.00</b>	<b>1,740.00</b>

LKK Auto Consultants Pte Ltd/SMC5050C/02/09/2019 08:43. Not valid without Reference section.

< END OF ESTIMATES >