



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2004372  
INV Date 17/06/2020  
Reference CC6/CTI19006249/Uba3s2  
Code CTI



#### PROFESSIONAL SERVICE FEE

Vehicle No. SJP 4441G  
Insured Veh. SKP 3057C  
Claim No. SNM19D201582C02(thp)  
Policy No. DMPCSN1657201802  
Accident Date 08/04/2019  
Inspection Date 09/04/2019

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19006249/Uba3s2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 17-06-2020



Code : CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SKP 3057C	<b>Veh. Inspected</b>	SJP 4441G
<b>Policy No.</b>	DMPCSN1657201802	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	SNM19D201582C02(thp)	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	09/04/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	NISSAN X-TRAIL (A)	<b>c.c</b>	1997
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
<b>Chassis No.</b>	JN1JANT32Z0002631	<b>Colour</b>	WHITE
<b>Odometer</b>	34686	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	225/60 R18	DUNLOP	6 mm
<b>L/H Front Tyre</b>	225/60 R18	DUNLOP	6 mm
<b>R/H Rear Tyre</b>	225/60 R18	DUNLOP	6 mm
<b>L/H Rear Tyre</b>	225/60 R18	DUNLOP	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	08/04/2019	<b>Inspection Date</b>	09/04/2019
<b>Survey held at</b>	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>10 Working Days</b>
-------------------------------------	------------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 4441G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR WINDSCREEN (N)	NOT NECESSARY	1,850.10	-
1	REAR WINDSCREEN MOULDING (N)	NECESSARY	155.60	65.70
1	TAILGATE (N)	CRACKED / WARPED	5,066.20	4,200.00
1	TAILGATE INNER LOCK (N)	SERVICEABLE	399.20	-
1	TAILGATE REAR LOGO (N)	NECESSARY	68.00	68.00
1	TAILGATE X-TRAIL EMBLEM (N)	NECESSARY	105.00	105.00
2	TAILGATE REFLECTORS @ \$850.00 (N)	NOT NECESSARY	1,700.00	-
1	TAILGATE WEATHERSTRIP (N)	TWISTED	299.50	299.50
1	TAILGATE LOCK SWITCH (N)	SHORTED	425.00	425.00
1	REAR BUMPER (N)	DISTORTED	775.00	623.80
2	REAR BUMPER SIDE RETAINERS @ \$58.00 (N)	BENT	116.00	116.00
2	REAR BUMPER REFLECTORS @ \$215.00 (N)	CRACKED	430.00	430.00
1	REAR BUMPER TOW COVER (N)	TORN	35.00	35.00
1	REAR BUMPER SPONGE (N)	TORN	215.00	215.00
1	REAR BUMPER REINFORCEMENT (N)	DISTORTED	755.00	533.80
2	REAR BUMPER BRACKETS @ \$285.00 (N)	BENT	570.00	570.00
1	SET REAR BUMPER CLIPS (N)	NECESSARY	39.00	39.00
1	REAR END PANEL (N)	DENTED / BENT	711.60	447.50
1	REAR END PANEL TOP GARNISH (N)	NOT NECESSARY	388.00	-
2	TAILLAMPS @ \$950.00 (N)	NOT NECESSARY	1,900.00	-
2	REAR FENDERS @ \$1215.00 (N)	TO REPAIR SEE LABOUR	2,430.00	-
2	REAR FENDER INNER TRIM BOARDS @ \$695.00 (N)	NOT NECESSARY	1,390.00	-
2	REAR FENDER OUTER PROTECTORS @ \$541.00 (N)	TORN	1,082.00	1,082.00
1	REAR FENDER QUARTER GLASS N/S (N)	NOT NECESSARY	699.00	-
1	REAR FLOOR PANEL (N)	TO REPAIR SEE LABOUR	1,120.50	-
1	REAR FLOOR PANEL TOP BOARD (N)	NOT NECESSARY	688.00	-
1	REAR FLOOR PANEL TOOLS SPONGE (N)	NOT NECESSARY	385.00	-
1	REAR EXHAUST (N)	DENTED / BENT	1,217.30	1,217.30
3	REAR EXHAUST MOUNTINGS @ \$60.00 (N)	NECESSARY	180.00	180.00

Report Ref No. CC6/CTI19006249/Uba3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST HEAT SHIELD (N)	NOT NECESSARY	255.00	-
1	REAR END PANEL LOCK SENSOR (N)	CRACKED	311.00	311.00
1	REAR DOOR N/S (N)	TO REPAIR SEE LABOUR	1,211.30	-
1	REAR BUMPER CENTRE LAMP (N)	NO SUCH PARTS	250.00	-
1	TAILLAMP HOUSING PANEL N/S (N)	TO REPAIR SEE LABOUR	315.00	-
1	REAR TAILGATE SPOILER (N)	NOT NECESSARY	820.00	-
1	BONNET (N)	BENT / BUCKLED	1,150.00	901.90
2	BONNET HINGES @ \$41.80 (N)	NOT NECESSARY	83.60	-
1	BONNET INSULATOR (N)	NOT NECESSARY	188.20	-
1	SET BONNET INSULATOR CLIPS (N)	NOT NECESSARY	39.00	-
1	BONNET RUBBER (N)	NECESSARY	68.00	68.00
1	BONNET LOCK (N)	TWISTED	93.00	93.00
2	HEADLAMPS @ \$2650.00 (N)	CRACKED	5,300.00	4,704.00
1	FRONT BUMPER (N)	DISTORTED	671.00	534.70
1	FRONT BUMPER TOW COVER (N)	TORN	35.00	35.00
1	FRONT BUMPER REINFORCEMENT (N)	BENT	755.00	453.10
1	FRONT BUMPER SPONGE (N)	TORN	291.60	291.60
2	FRONT BUMPER SIDE HOLDERS @ \$65.00 (N)	BENT	130.00	130.00
2	FRONT BUMPER BRACKET @ \$185.00 (N)	BENT	370.00	370.00
1	SET FRONT BUMPER CLIPS (N)	NECESSARY	39.00	39.00
1	FRONT BUMPER LOWER GRILLE (N)	NOT NECESSARY	199.50	-
1	FRONT BUMPER LOWER GRILLE CHROME MOULDING (N)	NOT NECESSARY	153.10	-
2	FRONT BUMPER FOG LAMPS @ \$380.00 (N)	N/S CRACKED	760.00	380.00
2	FRONT BUMPER FOG LAMP COVERS @ \$80.90 (N)	SERVICEABLE	161.80	-
1	FRONT GRILLE (N)	CRACKED	390.30	390.30
1	FRONT GRILLE LOGO (N)	NECESSARY	38.50	38.50
1	FRONT GRILLE OUTER CHROME MOULDING (N)	SCRATCHED	182.50	182.50
1	FRONT SUPPORT PANEL (N)	BENT / CRACKED	541.00	541.00
1	FRONT SUPPORT PANEL TOP GARNISH (N)	NOT NECESSARY	184.00	-
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS (N)	NOT NECESSARY	30.00	-

Report Ref No. CC6/CTI19006249/Uba3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT FENDERS @ \$583.40 (N)	TO REPAIR SEE LABOUR	1,166.80	-
2	FRONT FENDER OUTER PROTECTORS @ \$250.00 (N)	SERVICEABLE	500.00	-
2	HEADLAMP TOP PANELS @\$165.00 (N)	TO REPAIR SEE LABOUR	330.00	-
1	HORN UNIT (N)	NOT NECESSARY	89.60	-
2	AIR CON SIDE GARNISH @ \$65.00 (N)	DEFORMED / TORN	130.00	81.00
1	ALTRANSMISSION OIL COOLER (N)	NOT NECESSARY	340.00	-
1	AIRCON CONDENSER (N)	BENT / PUNCTURE	743.20	743.20
1	WIPER WASHER TANK (N)	NOT NECESSARY	201.90	-
1	RADIATOR (N)	BENT / PUNCTURE	1,455.00	687.40
1	RADIATOR FAN MOTOR (N)	NOT NECESSARY	1,008.60	-
1	AIRCON SUCTION HOSE (N)	NOT NECESSARY	545.20	-
1	AIRCON DISCHARGE HOSE (N)	NOT NECESSARY	499.50	-
1	AIR CLEANER BOX ASSY (N)	NOT NECESSARY	766.80	-
1	TAILGATE OUTER CHROME MOULDING (N)	NOT NECESSARY	288.50	-
1	FRONT SUPPORT TOP BRACKET (N)	NO SUCH PARTS	285.60	-
	LESS 10% DISCOUNT		-	-2,162.78
			48,562.10	19,465.02
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN SOLAR FILM (SN)	NOT NECESSARY	250.00	-
1	REAR LICENCE PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER REVERSE SENSOR 4 PCS (SN)	SHORTED	300.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR FENDER QUARTER GLASS SEALANT N/S (SN)	NOT NECESSARY	50.00	-
1	SET REAR REVERSE CAMERA (SN)	NOT NECESSARY	380.00	-
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	300.00	-
1	FRONT LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	BOT RADIATOR COOLANT (SN)	NECESSARY	50.00	50.00
1	SET REAR BUMPER SENSOR (SN)	NOT NECESSARY	300.00	-
1	REAR BUMPER TOP CHROME PLATE (SN)	BENT	500.00	300.00
			2,330.00	680.00

Report Ref No. CC6/CTI19006249/Uba3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REAR REVERSE SENSOR.		100.00	50.00
	TO DISMANTLE & REPLACING REAR WINDSCREEN.		150.00	120.00
	TO TRANSFER TAILGATE MECHANISM.		100.00	80.00
	TO DISMANTLE & REFIX REAR QUARTER GLASS N/S.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.		150.00	80.00
	TO DISMANTLE & REPLACING REAR EXHAUST.		150.00	100.00
	TO DISMANTLE & REFIX FUEL TANK.	NOT NECESSARY	100.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO REFILL GAS AIRCON GAS.		150.00	100.00
	TO SPRAY RUST PROOFING.		200.00	80.00
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTENING & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDERS, REAR FLOOR PANEL, REAR DOOR N/S, TAILLAMP HOUSING PANEL N/S, FRONT FENDERS AND HEADLAMP TOP PANELS.		2,800.00	1,400.00
	TO PUTTY & SPRAY PAINTING.		2,500.00	1,800.00
			7,110.00	3,840.00
<b>GRAND TOTAL</b>			<b>58,002.10</b>	<b>23,985.02</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>19,000.00</b>

Report Ref No. CC6/CTI19006249/Uba3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.