

INS. CASE OWNER:

CC 4, Pnd 1900

b153, U 0A37

LKK:
IDAC:

Surveyor:

bryan

DOI:

ASSIGNMENT

9/4/19

Date / Time:

9/4/2019

Registered in Merimen:

9/4/2019

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLK 2996m

Name of Insured:

Tan Chu Heng

Insured Tel No.:

HP:

Excess Sec II : \$5

D.O.A:

7/4/2019

Is driver the owner?

(YES) (NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SHC 10280



INSRS:

WSP:

Tel:

Liability:

RMKS:

Chuan



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SHC 10280 - 15/10/19 - 18/10/19 - 19/10/19 - 20/10/19 - 21/10/19

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

25-06-19

FHE PASS TO TYPIST TO PREPARE REPORT.

30-07-19

FWD REQUEST TO SUBMIT QIP REPORT.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Agt

Repair Cost: 45 \$335,000

(21 days) Reduction: 43 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with

Email ☐ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.: 90

If NO or B 28, Ass. Lia:

Repair Cost:

\$5

OI MAKE A RIGHT FROM OPP DIRECTION THO TP.

Loss of Rental (LOK):

\$5

(days)

Loss of Use (LOU):

\$5

(\$ x days)

Loss of Income (LOI):

\$5

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost

\$5

Total:

\$5

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirms with:

Email ☐ Call ☐

Payee 1:

\$5

Name 1:

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP/4P

3) Survey fee:

9250

COPY SENT
6/8/19

ASSIGNMENT

CJB 2025 July

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No _____

Claims No _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: 21 ~~14~~ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 1028 D Yr Regn: July 2017
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 271524 T/Radio: Insured / Std / NI / NA

Eng/No: 2ZRS056262

C/No: JTDKB3FU403561332

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Davanti

Front _____ Rear _____

P/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 27/04/2019 D.O.I. 18/04/2019 09/04/20

Survey held at Chunni AMC

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Front 4 H/O Rnt 4 O/S Rnt 4 O/S Body 4

The U/C / Chassis frame / Body Structure affected due to collision.

015 Rev

Date / Time	Action / Instruction
	<u>FWD SLK2996M</u>
<u>15/05/19</u>	<u>Judgment 2/5 38000/- with 21 days 7 rev</u>
	<u>(RED 28,301.61 43%)</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Report Format :

Lump Sum / L.B.I: (\$)

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

10 + RS, 50

Photos

Others

TOTAL

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 24 Apr 2019

Preliminary Advice

Insured Vehicle No	: SLK2996M	Accident Date	: 07/04/2019
TP Vehicle No	: SHC1028D	Assignment Date	: 09/04/2019
Make	: TOYOTA PRIUS HYBRID	Est. Duration of Repair	: 14 days
Date of Inspection	: 09/04/2019		
Inspection At	: Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesfront / N/S front / O/S front / O/S body / O/S rear... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	66,379.61
Revised Amount	:S\$	42,296.86
Check Items (Estimated)	:S\$	0.00
Total	:S\$	42,296.86

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.

REPAIR ESTIMATE

FWD

VEHICLE NO: SHC 1028D

DATE : 8.04.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
BONNET <i>inc</i>			\$ 950.50	✓
INSULATOR, HOOD NW			\$ 398.10	X
INSULATOR CLIPS NW			\$ 3.60	X
BONNET RUBBER NW			\$ 35.50	X
BONNET CABLE NW			\$ 53.20	X
BONNET HINGE (RH) <i>1st</i>			\$ 57.70	✓
BONNET HINGE (LH) <i>1st</i>			\$ 57.70	✓
BONNET LOCK <i>1st</i>			\$ 132.60	✓
RADIATOR GRILLE <i>broken mounting</i>			\$ 438.00	✓
RADIATOR GRILLE EMBLEM NW			\$ 88.00	✓
LAMP ASSY, FOG, RH <i>broken</i>			\$ 920.00	✓
FRONT BUMPER COVER <i>broken</i>			\$ 499.90	✓
FRONT BUMPER REINFORCEMENT <i>broken</i>			\$ 696.40	✓
FRONT BUMPER REINFORCEMENT ABSORBER <i>Dented</i>			\$ 115.70	✓
FRONT BUMPER SPONGE <i>form</i>			\$ 78.80	✓
FRONT BUMPER CENTRE GRILLE <i>broken mounting</i>			\$ 301.90	✓
FRONT BUMPER CLIPS NW			\$ 22.00	✓
FRONT BUMPER SIDE RETAINER NW		\$ 77.00	\$ 154.00	X
FRONT UNDER COVER NW			\$ 180.80	X
FRONT BUMPER TOP GARNISH <i>damaged</i>			\$ 225.40	✓
COVER, FRONT BUMPER HOLE, RH <i>cut</i>			\$ 28.38	✓
COVER, FRONT BUMPER HOLE, LH NW			\$ 28.38	X
REINFORCEMENT SUB-ASSY, FRONT BUMPER LOWER NW			\$ 241.40	X
SUPPORT FR BUMPER, RH <i>broken</i> NW			\$ 81.70	X
FRONT BUMPER CENTRE FRAME NW			\$ 236.90	X
BRACKET, FRONT BUMPER SIDE, RH <i>broken</i>			\$ 82.30	✓
ABSORBER, FRONT BUMPER, LOWER (SPONGE LOWER) NW			\$ 127.70	X
UNIT ASSY, HEADLAMP, RH (LED) <i>broken</i>			\$ 3,455.00	✓
UNIT ASSY, HEADLAMP, LH (LED) <i>broken</i>			\$ 3,455.00	✓
HEAD LAMP PANEL (RH) <i>Dented</i>			\$ 240.10	✓
TOP PANEL CENTRE <i>1st</i>			\$ 364.90	✓
TOP PANEL (RH) <i>Dented</i>			\$ 145.90	✓
BRACE PANEL <i>1st</i>			\$ 75.20	✓
BRACKET, HEADLAMP MOUNTING, RH <i>1st</i>			\$ 25.50	✓
RADIATOR ASSY <i>1st</i>			\$ 1,881.30	✓
RADIATOR FAN COWLING ASSY <i>2nd damaged</i>			\$ 661.30	✓
RADIATOR TOP HOSE, LH NW			\$ 43.03	X
RADIATOR TOP HOSE, RH NW			\$ 42.60	X
RADIATOR SPARE TANK <i>2nd broken</i>			\$ 125.80	✓
RADIATOR BOTTOM MOUNTING NW			\$ 27.50	X
STAY, RADIATOR SUPPORT, RH NW		15591.48	\$ 65.70	X
STAY, RADIATOR SUPPORT, LH NW			\$ 65.70	X
RADIATOR FAN BLADE (RH) <i>damaged</i>			\$ 233.10	X
RADIATOR FAN BLADE (LH) <i>damaged</i>			\$ 233.10	X
RADIATOR FAN MOTOR (RH) NW			\$ 543.70	X
RADIATOR FAN MOTOR (LH) NW			\$ 543.70	X

SHC 1028D

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
DEFLECTOR, RADIATOR SIDE, RH NH		\$	83.50 X
DEFLECTOR, RADIATOR SIDE, LH NH		\$	77.00 X
PIPE, RADIATOR NH		\$	126.50 Y
CLEANER ASSY, AIR NH		\$	970.30 X
AIR CLEANER TOP COVER NH		\$	446.50 X
AIR CLEANER BOTTOM COVER NH		\$	947.80 X
AIR CLEANER HOSE NH		\$	62.12 X
AIR DUCT damaged		\$	129.40 ✓
INLET ASSY, AIR CLEANER damaged		\$	132.00 ✓
AIR DUCT CENTRE damaged		\$	94.03 ✓
COMPRESSOR ASSY, W/MOTOR NH		\$	2,924.20 X
CONDENSER ASSY, W/RECEIVER 2 bt		\$	1,336.60 Z ✓
AIRCON DISCHARGE HOSE 2 bt		\$	386.90 Z ✓
AIRCON LIQUID HOSE & PIPE 2 bt		\$	580.45 Z ✓
AIRCON HOSE SUCTION 2 bt		\$	548.50 Z ✓
FENDER SUB-ASSY, FRONT LH Damaged		\$	945.30 ✓
FENDER SUB-ASSY, FRONT RH Damaged		\$	945.30 ✓
FRONT HOUSING ASSY, RH Damaged		\$	958.30 ✓
FRONT FENDER SHIELD, LH NH		\$	196.60 X
FRONT FENDER SHIELD, RH destroyed		\$	196.60 ✓
FRONT FENDER SHIELD CLIP h/c	S	3.80	\$ 7.60 ✓
FRONT FENDER HYBRID EMBLEM, LH h/c		\$	53.50 ✓
FRONT FENDER HYBRID EMBLEM, RH h/c		\$	53.50 ✓
PANEL SUB-ASSY, FRONT DOOR, RH Damaged		\$	1,264.00 ✓
FRONT PILLAR UPPER COVER, RH NH		\$	96.00 X
FRONT WINDSCREEN GLASS crack		\$	1,627.30 ✓
FRONT WINDSCREEN GLASS MOULDING h/c		\$	208.60 ✓
FRONT WHEEL RIM (LH/RH) 2 destroyed	S	1,555.10	\$ 3,110.20 Z ✓
FRONT WHEEL HUB CAP (LH/RH) cut	S	177.70	\$ 355.40 ✓
FRONT WHEEL HUB BEARING (LH/RH) 1/2 destroyed Dam	S	560.10	\$ 1,120.20 Z ✓
FRONT SHOCK ABSORBER (LH) 2 destroyed		\$	401.80 Z ✓
FRONT SHOCK ABSORBER (RH) not destroyed		\$	401.80 X ✓
ABSORBER TOP MOUNTING ,LH NH		\$	196.20 X
ABSORBER TOP MOUNTING ,RH NH		\$	196.20 X
FRONT SUSPENSION LOWER ARM (RH) not destroyed		\$	637.50 X ✓
FRONT SUSPENSION LOWER ARM (LH) 2 destroyed		\$	637.50 Z ✓
FRONT DRIVE SHAFT (LH) not Dam destroyed		\$	1,310.10 X ✓
FRONT DRIVE SHAFT (RH) not Dam destroyed		\$	1,310.10 X ✓
RACK & PINION ASSY ? Dam		\$	1,634.90 Z ✓
BAR, STABILIZER 2 destroyed		\$	360.00 Z ✓
LINK ASSY, FRONT STABILIZER, LH 2 destroyed		\$	199.00 Z ✓
LINK ASSY, FRONT STABILIZER, LH RH not destroyed		\$	199.00 X ✓
KNUCKLE, STEERING, RH not destroyed		\$	562.30 X ✓
KNUCKLE, STEERING, LH 2 destroyed		\$	562.30 Z ✓
JOINT ASSY, LOWER BALL, FRONT RH NH		\$	202.40 X
END SUB-ASSY, TIE ROD, RH not destroyed		\$	158.10 Z ✓
END SUB-ASSY, TIE ROD, LH 2 destroyed		\$	158.10 Z ✓
ENGINE UNDER COVER NH		\$	457.20 X ✓
ENGINE CROSS MEMBER 2 destroyed		\$	2,531.70 Z ✓

SHC 1028D

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
FRT ABS N/W		\$ 455.10	\$ 910.20	X
SENSOR, SPEED, FRONT RH N/W			\$ 455.10	X
WIRING FRONT 2 3 socket brake			\$ 6,685.90	2 ✓
WIRING ENGINE N/W			\$ 2,133.90	X
		47395.26		
SUB TOTAL			\$ 60,750.19	
LESS 20% 25%			\$ 12,150.04	
DISCOUNTED TOTAL			\$ 48,600.15	
FRONT NO. PLATE 1st			\$ 25.00	NETT ✓
FRONT NO PLATE TRIM COVER 1st 1st			\$ 30.00	NETT ✓
FRONT NO. PLATE GARNISH 1st 1st			\$ 99.00	NETT ✓
FRONT DOOR COMFORT LOGO 1st 1st			\$ 75.00	NETT ✓
FRONT TYRE (LH/RH) N/S cut o/s N/W		\$ 218.00	\$ 108.00 122.00	NETT ✓
50% depreciation		327.00	\$ 661.00	
REAR BUMPER 1st 1st			\$ 458.60	X
REAR FENDER, RH 1st 1st			\$ 836.70	X ✓
REAR FENDER SHEILD (RH) N/W			\$ 134.20	X
PANEL SUB-ASSY, FRONT DOOR, RH 1st 1st			\$ 1,264.00	✓
CENTRE ROCKER PANEL (GARNISH) 2 cut 1st 1st			\$ 576.00	2 ✓
REAR WHEEL HUB CAP, LH/RH o/s 1st N/S N/W		\$ 177.70	\$ 355.40	✓
REAR CROSS MEMBER 1st 1st			\$ 2,200.40	X ✓
REAR SHOCK ABSORBER, LH/RH o/s N/S N/W o/s 1st 1st		\$ 118.30	\$ 236.60	✓ 118.3
REAR SHOCK ABSORBER MOUNTING, LH/RH N/W		\$ 125.30	\$ 250.60	X
REAR LOWER ARM, LH/RH N/S N/W o/s 1st 1st		\$ 492.50	\$ 985.00	✓ 497.5
REAR UPPER ARM, LH/RH N/S N/W o/s 1st 1st		\$ 356.80	\$ 713.60	✓ 356.8
REAR KNUCKLE ARM, LH/RH N/S N/W o/s 1st 1st		\$ 810.60	\$ 1,621.20	✓
REAR STABILIZER BAR 2 1st			\$ 311.50 311.50	2 ✓
REAR STABILIZER LINK, LH/RH N/S N/W		\$ 151.50	\$ 303.00	X
REAR TRAILING ARM, LH/RH N/S N/W o/s 1st 1st		\$ 314.20	\$ 628.40	✓
REAR ASSIST ARM, LH/RH N/S N/W o/s 1st 1st		\$ 342.20	\$ 684.40	✓
SUB TOTAL			\$ 11,569.80	
LESS 20% 25%			\$ 2,313.96	
DISCOUNTED TOTAL			\$ 9,255.84	
		7805.90		
		5854.42		

SHC 1028D

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR DOOR COMFORT & APPS STICKER <i>h/c</i>		<i>80.00</i>	\$ 80.00	NETT ✓
			\$ 80.00	
LABOUR CHARGE				
Panel Beating			\$ 1,400.00	1000/-
Spray Painting Charge			\$ 1,300.00	1000/-
Wiring Charge			\$ 50.00	30/-
Tuff Kote			\$ 80.00	40/-
Towing Charge			\$ 50.00	h/w
Frt Chassis Alignment			\$ 200.00	150/-
Remove/Refix Reverse Sensor			\$ 80.00	h/w
Remove/Refix Undercarriage (FRT)			\$ 120.00	120/-
Remove/Refix Undercarriage (RR)			\$ 150.00	120/-
Four Wheel Alignment			\$ 80.00	60/-
Remove/Refix Aircon & Refill Gas			\$ 80.00 800.00	60/-
Remove/Refix Engine			\$ 200.00	150/-
Remove/Refix Dashboard		<i>3230.00</i>	\$ 200.00	2180/-
Remove/Refix Fuse Box			\$ 180.00	250/-
Remove/Refix Front Windscreen Glass			\$ 120.00	80/-
Remove/Refix Cushion & Upholstery Front			\$ 90.00	40/-
Diagnosis & Resetting To Erase Fault Code			\$ 200.00	150/-
TOTAL LABOUR			\$ 4,508.00	
ESTIMATE TOTAL			\$ 63,104.99	
<i>09/04/2019 @ 1600m</i> <i>via Antura</i> <i>21 days.</i> <i>Man</i> <i>2kk Auto</i>			<i>45037.86</i> <i>2808.20</i> <i>47846.06</i> <i>1/538000/-</i>	<i>66307.61</i>
Date: _____ Signature: _____ Acknowledged by Reparer: _____ * To resurvey before/after spray painting * To display damaged part(s) during resurvey * Parts prices are subject to confirmation * Third party survey is on a "Without Prejudice" basis * No illegal modifications is allowed * Supplementary items must be resurveyed and is subject to final approval from Insurance Company This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHC 1028D (SUPPLEMENTARY)

DATE : 11.04.2019

MAKE :


TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
WATER PUMP ASSY <i>broken</i>			\$ 925.30
WIPER GARNISH <i>broken</i>			\$ 668.32
WIPER GARNISH SIDE COVER, RH <i>destroyed</i>			\$ 26.50
HEAD LAMP PANEL (LH) <i>bt</i>			\$ 240.10
TOP PANEL (LH) <i>bt</i>			\$ 145.90
RADIATOR LOWER SUPPORT PANEL <i>bt</i>			\$ 397.40
WIPER SPARE TANK <i>defunct</i>			\$ 183.75
WIPER SPARE TANK MOTOR <i>Don</i>			\$ 242.70
WIPER SPARE TANK FLOAT (NECK) <i>defunct</i>			\$ 55.50
ENGINE MOUNTING <i>Don</i>		3744.27	\$ 386.60
ENGINE MTG (REAR) <i>Don</i>			\$ 172.90
GEARBOX MOUNTING <i>Don</i>		2808.20	\$ 299.30
ENGINE CROSSMEMBER SIDE STAY (LH/RH) <i>Nml</i>		\$ 129.50	\$ 259.00
SUB TOTAL <i>25%</i>			\$ 4,003.27
LESS 20% <i>25%?</i>			\$ 800.65
DISCOUNTED TOTAL			\$ 3,202.62

18/04/2019



LKE Auto



This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHC 1028 D

Technician:

Mileage: 271525

Time Printed 9.4.19 4:48 PM

TOYOTA PRIUS

Front : Left

Actual	BEFORE	Specified Range
0°16'		-1°20' 0°10'
6°29'		2°25' 3°55'
-1°04'		-0°06' 0°06'
14°29'		11°50' 13°20'
14°45'		10°30' 13°30'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-1°28'		-1°20' 0°10'
5°46'		2°25' 3°55'
1°18'		-0°06' 0°06'
14°16'		11°50' 13°20'
12°49'		10°30' 13°30'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
1°44'		-0°45' 0°45'
0°43'		-0°45' 0°45'
0°13'		-0°45' 0°45'
0°14'		-0°12' 0°12'

Rear : Left

Actual	BEFORE	Specified Range
-1°51'		-2°00' -1°00'
0°04'		0°02' 0°17'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°54'		-2°00' -1°00'
0°36'		0°02' 0°17'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°57'		-0°30' 0°30'
0°39'		0°03' 0°33'
-0°16'		

Niyitha (LKK Auto)

From: clara.li@fwd.com
Sent: Tuesday, 9 April 2019 11:07 AM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com; AsherSng@lkkauto.com
Subject: FW: Accident involving veh no: SHC 1028D & SLK 2996M on 07.04.19 Our Ref: PNPV2019-00000119/CL
Attachments: 09042019103701.pdf

11:56am @ 9/4/19
vehicle in
lynn

Hi LKK team,

Please assist with the TP survey.

Thank you.

Regards,
Clara

From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: Tuesday, 9 April, 2019 11:01 AM
To: Clara Li Zirong - SGUser
Cc: Motor Claims SG - SG Common
Subject: Re: Accident involving veh no: SHC 1028D & SLK 2996M on 07.04.19 Our Ref: PNPV2019-00000119/CL

Dear Sir,

We appoint LKK Auto Consultants P/L

Thank you

Regards,
Chunni Motor Work P/L

On Tue, Apr 9, 2019 at 10:58 AM <clara.li@fwd.com> wrote:

WITHOUT PREJUDICE

Dear Sir/ Madam,

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

**Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.*

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.*

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.


6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg





From: Chunni Motor [<mailto:chunnimotor@gmail.com>]
Sent: Tuesday, 9 April, 2019 10:46 AM
To: Motor Claims SG - SG Common
Subject: Accident involving veh no: SHC 1028D & SLK 2996M on 07.04.19

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly survey at AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any

attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	09 Apr 2019 15:28	Cim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD. Claimant's ID: -> 1993038 21R.	[A] HOW MEI KWAN
2	09 Apr 2019 15:28	Cim Veh Model Changed	(205436) TOYOTA PRIUS HYBRID 1.8 CVT (A).	[A] HOW MEI KWAN
3	09 Apr 2019 15:28	Cim Created	Reg No: SHC1028D, Acct Date: 2019/04/07. Claim Type: TP. Insurer: FWD Singapore Pte. Ltd. (HQ). TP Insurer: MS First Capital Insurance Ltd (HQ). Workshop: Chunni Motor Work Pte Ltd (HQ)	[A] HOW MEI KWAN
4	09 Apr 2019 15:28	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : VICOM Ltd.	[A] HOW MEI KWAN
5	09 Apr 2019 15:28	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/04/18	[A] HOW MEI KWAN
6	09 Apr 2019 15:28	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
7	09 Apr 2019 15:28	Label Added	(20005):Direct Settlement .	[A] HOW MEI KWAN
8	09 Apr 2019 15:28	Adj Adjuster Assigned	[None] -> BRYAN TAN	[A] HOW MEI KWAN
9	09 Apr 2019 15:31	Cim Registration Modified	Pol No:->PNPV2019-00000119.	[I] Belliana
10	09 Apr 2019 15:31	Cim Registration Modified	Excess: -> 3300.00.	[I] Belliana
11	09 Apr 2019 15:31	Cim Registration Modified	Acct Time:13:00:00->12:00:00.	[I] Belliana
12	24 Apr 2019 12:14	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/04/18	[A] HOW MEI KWAN
13	22 Jul 2019 13:54	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
14	22 Jul 2019 13:54	Cim Dtl Modified	JPJ Reg. Date: -> 2017/07/05.	[A] Elaine Kuan Hwa Meen
15	22 Jul 2019 13:54	Cim Details Notified		[A] Elaine Kuan Hwa Meen
16	25 Jul 2019 16:35	Adj Mandate Request	Cur.Req:45397.80:LIABILITY: 100% B:9a OI MAKE A RIGHT FROM OPP DIRECTION HIT TP QUANTUM: (a) COR w/GST: \$40,660.00 + (b) LOR : \$3,385.80 (27days x \$125.40) + (c) LOI : \$1,350.00 (27days x \$50) + (d) LTA: \$2.00 Total: a+b+c+d = \$45,397.80 P LEASE REV	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2125504	24/04/2019 12:14	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SHC1028D	SLK2996M	10.70

Print Received Message

This mail is associated with :

***SHC1028D (1201900009257)**
[SLK2996M]

TP

COMFORT TRANSPORTATION PTE LTD

Apr 7 2019 12:00PM

[Tan Chu Hiang]

Chunni Motor Work Pte Ltd

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 30/07/2019 10:47 AM.
To LKK_HQ
Subject Alert - Adj Mandate Revoked - SHC1028D - Claim Handler: Clara Li Zi Rong

Revoked:Hi Please submit WP report and we will be making offer to TP workshop directly, thanks.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	08 Apr 2019 Edit Reg		09 Apr 2019 00:00 Edit Adj Rpt	\$38,000.00 Edit Estimates	\$38,000.00 View Rpt	Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Tan Chu Hiang, ID: S1646971H								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHC1028D	Date of Loss:	07/04/2019 12:00 - :59 [21 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900009257	Policy/Cover Note No.:	PNPV2019-00000119 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLK2996M	Policy No. (Claimant):	D-18088936MFSH						
		Excess:	\$3,300.00						
Repairer:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 18/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
FWD_SG (30/07/2019): Alert - Adj Mandate Revoked - SHC1028D - Claim Handler: Clara Li Zi Rong									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC1028D (1201900009257)
[SLK2996M]
TP
COMFORT TRANSPORTATION PTE LTD
Apr 7 2019 12:00PM
[Tan Chu Hiang]
Chunni Motor Work Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/04/19 12:14	Adjuster Immediate Advice	 Load HTML	
Photos/Images			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/05/19 13:32	Front View Left	 Load JPG	☒
2	11/05/19 13:32	Front View Right	 Load JPG	☒
3	11/05/19 13:34	General View	 Load JPG	☒
4	11/05/19 13:34	General View	 Load JPG	☒
5	11/05/19 13:34	General View	 Load JPG	☒
6	11/05/19 13:34	General View	 Load JPG	☒
7	11/05/19 13:34	General View	 Load JPG	☒
8	11/05/19 13:34	General View	 Load JPG	☒
9	11/05/19 13:34	General View	 Load JPG	☒
10	11/05/19 13:34	General View	 Load JPG	☒
11	11/05/19 13:34	General View	 Load JPG	☒
12	11/05/19 13:34	General View	 Load JPG	☒
13	11/05/19 13:34	General View	 Load JPG	☒
14	11/05/19 13:34	General View	 Load JPG	☒
15	11/05/19 13:34	General View	 Load JPG	☒
16	11/05/19 13:34	General View	 Load JPG	☒
17	11/05/19 13:34	General View	 Load JPG	☒
18	11/05/19 13:34	General View	 Load JPG	☒
19	11/05/19 13:34	General View	 Load JPG	☒
20	11/05/19 13:34	General View	 Load JPG	☒
21	11/05/19 13:34	General View	 Load JPG	☒
22	11/05/19 13:34	General View	 Load JPG	☒
23	11/05/19 13:34	General View	 Load JPG	☒
24	11/05/19 13:34	General View	 Load JPG	☒
25	11/05/19 13:34	General View	 Load JPG	☒
26	11/05/19 13:34	General View	 Load JPG	☒
27	11/05/19 13:34	General View	 Load JPG	☒
28	11/05/19 13:34	General View	 Load JPG	☒
29	11/05/19 13:34	General View	 Load JPG	☒
30	11/05/19 13:34	General View	 Load JPG	☒
31	11/05/19 13:34	General View	 Load JPG	☒
32	11/05/19 13:34	General View	 Load JPG	☒
33	11/05/19 13:34	General View	 Load JPG	☒
34	11/05/19 13:34	General View	 Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	11/05/19 13:34	General View		☒
36	11/05/19 13:34	General View		☒
37	11/05/19 13:34	General View		☒
38	11/05/19 13:34	General View		☒
39	11/05/19 13:34	General View		☒
40	11/05/19 13:34	General View		☒
41	11/05/19 13:34	General View		☒
42	11/05/19 13:34	General View		☒
43	11/05/19 13:34	General View		☒
44	11/05/19 13:34	General View		☒
45	11/05/19 13:34	General View		☒
46	11/05/19 13:34	General View		☒
47	11/05/19 13:34	General View		☒
48	11/05/19 13:34	General View		☒
49	11/05/19 13:34	General View		☒
50	11/05/19 13:34	General View		☒
51	11/05/19 13:34	General View		☒
52	11/05/19 13:34	General View		☒
53	11/05/19 13:34	General View		☒
54	11/05/19 13:34	General View		☒
55	11/05/19 13:34	General View		☒
56	11/05/19 13:34	General View		☒
57	11/05/19 13:34	General View		☒
58	11/05/19 13:34	General View		☒
59	11/05/19 13:34	General View		☒
60	11/05/19 13:34	General View		☒
61	11/05/19 13:34	General View		☒
62	11/05/19 13:34	General View		☒
63	11/05/19 13:34	General View		☒
64	11/05/19 13:34	General View		☒
65	11/05/19 13:34	General View		☒
66	11/05/19 13:34	General View		☒
67	11/05/19 13:34	General View		☒
68	11/05/19 13:34	General View		☒
69	11/05/19 13:34	General View		☒
70	11/05/19 13:34	General View		☒
71	11/05/19 13:34	General View		☒
72	11/05/19 13:34	General View		☒
73	11/05/19 13:34	General View		☒
74	11/05/19 13:34	General View		☒
75	11/05/19 13:34	General View		☒
76	11/05/19 13:34	General View		☒
77	11/05/19 13:34	General View		☒
78	11/05/19 13:34	General View		☒
79	11/05/19 13:34	General View		☒
80	11/05/19 13:34	General View		☒
81	11/05/19 13:34	General View		☒
82	11/05/19 13:34	General View		☒
83	11/05/19 13:34	General View		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	11/05/19 13:34	General View	 Load JPG	☒
85	11/05/19 13:34	General View	 Load JPG	☒
86	11/05/19 13:34	General View	 Load JPG	☒
87	11/05/19 13:34	General View	 Load JPG	☒
88	11/05/19 13:34	General View	 Load JPG	☒
89	11/05/19 13:34	General View	 Load JPG	☒
90	11/05/19 13:34	General View	 Load JPG	☒
91	11/05/19 13:34	General View	 Load JPG	☒
92	11/05/19 13:34	General View	 Load JPG	☒
93	11/05/19 13:34	General View	 Load JPG	☒
94	11/05/19 13:34	General View	 Load JPG	☒
95	11/05/19 13:34	General View	 Load JPG	☒
96	11/05/19 13:34	General View	 Load JPG	☒
97	11/05/19 13:34	General View	 Load JPG	☒
98	11/05/19 13:34	General View	 Load JPG	☒
99	11/05/19 13:34	General View	 Load JPG	☒
100	11/05/19 13:34	General View	 Load JPG	☒
101	11/05/19 13:34	General View	 Load JPG	☒
102	11/05/19 13:34	General View	 Load JPG	☒
103	11/05/19 13:34	General View	 Load JPG	☒
104	11/05/19 13:34	General View	 Load JPG	☒
105	11/05/19 13:34	General View	 Load JPG	☒
106	11/05/19 13:34	General View	 Load JPG	☒
107	11/05/19 13:34	General View	 Load JPG	☒
108	11/05/19 13:35	General View	 Load JPG	☒
109	11/05/19 13:35	General View	 Load JPG	☒
110	11/05/19 13:35	General View	 Load JPG	☒
111	11/05/19 13:35	General View	 Load JPG	☒
112	11/05/19 13:35	General View	 Load JPG	☒
113	11/05/19 13:35	General View	 Load JPG	☒
114	11/05/19 13:35	General View	 Load JPG	☒
115	11/05/19 13:35	General View	 Load JPG	☒
116	11/05/19 13:35	General View	 Load JPG	☒
117	11/05/19 13:35	General View	 Load JPG	☒
118	11/05/19 13:35	General View	 Load JPG	☒
119	11/05/19 13:35	General View	 Load JPG	☒
120	11/05/19 13:35	General View	 Load JPG	☒
121	11/05/19 13:35	General View	 Load JPG	☒
122	11/05/19 13:35	General View	 Load JPG	☒
123	11/05/19 13:35	General View	 Load JPG	☒
124	11/05/19 13:35	General View	 Load JPG	☒
125	11/05/19 13:35	General View	 Load JPG	☒
126	11/05/19 13:35	General View	 Load JPG	☒
127	11/05/19 13:35	General View	 Load JPG	☒
128	11/05/19 13:35	General View	 Load JPG	☒
129	11/05/19 13:35	General View	 Load JPG	☒
130	11/05/19 13:35	General View	 Load JPG	☒
131	11/05/19 13:35	General View	 Load JPG	☒
132	11/05/19 13:35	General View	 Load JPG	☒
133	11/05/19 13:35	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
134	11/05/19 13:35	General View	 Load JPG	☒
135	11/05/19 13:35	General View	 Load JPG	☒
136	11/05/19 13:35	General View	 Load JPG	☒
137	11/05/19 13:35	General View	 Load JPG	☒
138	11/05/19 13:35	General View	 Load JPG	☒
139	11/05/19 13:35	General View	 Load JPG	☒
140	11/05/19 13:35	General View	 Load JPG	☒
141	11/05/19 13:35	General View	 Load JPG	☒
142	11/05/19 13:35	General View	 Load JPG	☒
143	11/05/19 13:35	General View	 Load JPG	☒
144	11/05/19 13:35	General View	 Load JPG	☒
145	11/05/19 13:35	General View	 Load JPG	☒
146	11/05/19 13:35	General View	 Load JPG	☒
147	11/05/19 13:35	General View	 Load JPG	☒
148	11/05/19 13:35	General View	 Load JPG	☒
149	11/05/19 13:35	General View	 Load JPG	☒
150	11/05/19 13:35	General View	 Load JPG	☒
151	11/05/19 13:35	General View	 Load JPG	☒
152	11/05/19 13:35	General View	 Load JPG	☒
153	11/05/19 13:35	General View	 Load JPG	☒
154	11/05/19 13:35	General View	 Load JPG	☒
155	11/05/19 13:35	General View	 Load JPG	☒
156	11/05/19 13:35	General View	 Load JPG	☒
157	11/05/19 13:35	General View	 Load JPG	☒
158	11/05/19 13:35	General View	 Load JPG	☒
159	11/05/19 13:35	General View	 Load JPG	☒
160	11/05/19 13:35	General View	 Load JPG	☒
161	11/05/19 13:35	General View	 Load JPG	☒
162	11/05/19 13:35	General View	 Load JPG	☒
163	11/05/19 13:35	General View	 Load JPG	☒
164	11/05/19 13:35	General View	 Load JPG	☒
165	11/05/19 13:35	General View	 Load JPG	☒
166	11/05/19 13:35	General View	 Load JPG	☒
167	11/05/19 13:35	General View	 Load JPG	☒
168	11/05/19 13:35	General View	 Load JPG	☒
169	11/05/19 13:35	General View	 Load JPG	☒
170	11/05/19 13:35	General View	 Load JPG	☒
171	11/05/19 13:35	General View	 Load JPG	☒
172	11/05/19 13:35	General View	 Load JPG	☒
173	11/05/19 13:35	General View	 Load JPG	☒
174	11/05/19 13:35	General View	 Load JPG	☒
175	11/05/19 13:35	General View	 Load JPG	☒
176	11/05/19 13:35	General View	 Load JPG	☒
177	11/05/19 13:35	General View	 Load JPG	☒
178	11/05/19 13:35	General View	 Load JPG	☒
179	11/05/19 13:35	General View	 Load JPG	☒
180	11/05/19 13:35	General View	 Load JPG	☒
181	11/05/19 13:35	General View	 Load JPG	☒
182	11/05/19 13:35	General View	 Load JPG	☒
183	11/05/19 13:35	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
184	11/05/19 13:35	General View	 Load JPG	☒
185	11/05/19 13:35	General View	 Load JPG	☒
186	11/05/19 13:35	General View	 Load JPG	☒
187	11/05/19 13:35	General View	 Load JPG	☒
188	11/05/19 13:35	General View	 Load JPG	☒
189	11/05/19 13:35	General View	 Load JPG	☒
190	11/05/19 13:35	General View	 Load JPG	☒
191	11/05/19 13:35	General View	 Load JPG	☒
192	11/05/19 13:35	General View	 Load JPG	☒
193	11/05/19 13:35	General View	 Load JPG	☒
194	11/05/19 13:35	General View	 Load JPG	☒
195	11/05/19 13:35	General View	 Load JPG	☒
196	11/05/19 13:35	General View	 Load JPG	☒
197	11/05/19 13:36	Odometer Reading	 Load JPG	☒
198	11/05/19 13:36	Chassis Number	 Load JPG	☒
199	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
200	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
201	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
202	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
203	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
204	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
205	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
206	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
207	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
208	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
209	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
210	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
211	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
212	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
213	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
214	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
215	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
216	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
217	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
218	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
219	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
220	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
221	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
222	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
223	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
224	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
225	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
226	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
227	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
228	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
229	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
230	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
231	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
232	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
233	11/05/19 13:51	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
234	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
235	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
236	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
237	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
238	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
239	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
240	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
241	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
242	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
243	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
244	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
245	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
246	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
247	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
248	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
249	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
250	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
251	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
252	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
253	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
254	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
255	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
256	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
257	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
258	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
259	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
260	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
261	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
262	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
263	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
264	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
265	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
266	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
267	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
268	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
269	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
270	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
271	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
272	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
273	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
274	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
275	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
276	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
277	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
278	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
279	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
280	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
281	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
282	11/05/19 13:51	Reinspection Photo	 Load JPG	☒
283	11/05/19 13:51	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
284	11/05/19 13:51	Reinspection Photo		☒
285	11/05/19 13:51	Reinspection Photo		☒
286	11/05/19 13:51	Reinspection Photo		☒
287	11/05/19 13:51	Reinspection Photo		☒
288	11/05/19 13:51	Reinspection Photo		☒
289	11/05/19 13:51	Reinspection Photo		☒
290	11/05/19 13:51	Reinspection Photo		☒
291	11/05/19 13:51	Reinspection Photo		☒
292	11/05/19 13:51	Reinspection Photo		☒
293	11/05/19 13:51	Reinspection Photo		☒
294	11/05/19 13:51	Reinspection Photo		☒
295	11/05/19 13:51	Reinspection Photo		☒
296	11/05/19 13:51	Reinspection Photo		☒
297	11/05/19 13:51	Reinspection Photo		☒
298	11/05/19 13:51	Reinspection Photo		☒
299	11/05/19 13:51	Reinspection Photo		☒
300	11/05/19 13:51	Reinspection Photo		☒
301	11/05/19 13:51	Reinspection Photo		☒
302	11/05/19 13:51	Reinspection Photo		☒
303	11/05/19 13:51	Reinspection Photo		☒
304	11/05/19 13:51	Reinspection Photo		☒
305	11/05/19 13:51	Reinspection Photo		☒
306	11/05/19 13:51	Reinspection Photo		☒
307	11/05/19 13:51	Reinspection Photo		☒
308	11/05/19 13:51	Reinspection Photo		☒
309	11/05/19 13:51	Reinspection Photo		☒
310	11/05/19 13:51	Reinspection Photo		☒
311	11/05/19 13:51	Reinspection Photo		☒
312	11/05/19 13:51	Reinspection Photo		☒
313	11/05/19 13:51	Reinspection Photo		☒
314	11/05/19 13:51	Reinspection Photo		☒
315	11/05/19 13:51	Reinspection Photo		☒
316	11/05/19 13:51	Reinspection Photo		☒
317	11/05/19 13:51	Reinspection Photo		☒
318	11/05/19 13:51	Reinspection Photo		☒
319	11/05/19 13:51	Reinspection Photo		☒
320	11/05/19 13:51	Reinspection Photo		☒
321	11/05/19 14:07	Reinspection Photo		☒
322	11/05/19 14:07	Reinspection Photo		☒
323	11/05/19 14:07	Reinspection Photo		☒
324	11/05/19 14:07	Reinspection Photo		☒
325	11/05/19 14:07	Reinspection Photo		☒
326	11/05/19 14:07	Reinspection Photo		☒
327	11/05/19 14:07	Reinspection Photo		☒
328	11/05/19 14:07	Reinspection Photo		☒
329	11/05/19 14:07	Reinspection Photo		☒
330	11/05/19 14:07	Reinspection Photo		☒
331	11/05/19 14:07	Reinspection Photo		☒
332	11/05/19 14:07	Reinspection Photo		☒
333	11/05/19 14:07	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
334	11/05/19 14:07	Reinspection Photo		☒
335	11/05/19 14:07	Reinspection Photo		☒
336	11/05/19 14:07	Reinspection Photo		☒
337	11/05/19 14:07	Reinspection Photo		☒
338	11/05/19 14:07	Reinspection Photo		☒
339	11/05/19 14:07	Reinspection Photo		☒
340	11/05/19 14:07	Reinspection Photo		☒
341	11/05/19 14:07	Reinspection Photo		☒
342	11/05/19 14:07	Reinspection Photo		☒
343	11/05/19 14:07	Reinspection Photo		☒
344	11/05/19 14:07	Reinspection Photo		☒
345	11/05/19 14:07	Reinspection Photo		☒
346	11/05/19 14:07	Reinspection Photo		☒
347	11/05/19 14:07	Reinspection Photo		☒
348	11/05/19 14:07	Reinspection Photo		☒
349	11/05/19 14:07	Reinspection Photo		☒
350	11/05/19 14:07	Reinspection Photo		☒
351	11/05/19 14:07	Reinspection Photo		☒
352	11/05/19 14:07	Reinspection Photo		☒
353	11/05/19 14:07	Reinspection Photo		☒
354	11/05/19 14:07	Reinspection Photo		☒
355	11/05/19 14:07	Reinspection Photo		☒
356	11/05/19 14:07	Reinspection Photo		☒
357	11/05/19 14:07	Reinspection Photo		☒
358	11/05/19 14:07	Reinspection Photo		☒
359	11/05/19 14:07	Reinspection Photo		☒
360	11/05/19 14:07	Reinspection Photo		☒
361	11/05/19 14:07	Reinspection Photo		☒
362	11/05/19 14:07	Reinspection Photo		☒
363	11/05/19 14:07	Reinspection Photo		☒
364	11/05/19 14:07	Reinspection Photo		☒
365	11/05/19 14:07	Reinspection Photo		☒
366	11/05/19 14:07	Reinspection Photo		☒
367	11/05/19 14:07	Reinspection Photo		☒
368	11/05/19 14:07	Reinspection Photo		☒
369	11/05/19 14:07	Reinspection Photo		☒
370	11/05/19 14:07	Reinspection Photo		☒
371	11/05/19 14:07	Reinspection Photo		☒
372	11/05/19 14:07	Reinspection Photo		☒
373	11/05/19 14:07	Reinspection Photo		☒
374	11/05/19 14:07	Reinspection Photo		☒
375	11/05/19 14:07	Reinspection Photo		☒
376	11/05/19 14:07	Reinspection Photo		☒
377	11/05/19 14:07	Reinspection Photo		☒
378	11/05/19 14:07	Reinspection Photo		☒
379	11/05/19 14:07	Reinspection Photo		☒
380	11/05/19 14:07	Reinspection Photo		☒
381	11/05/19 14:07	Reinspection Photo		☒
382	11/05/19 14:07	Reinspection Photo		☒
383	11/05/19 14:07	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
384	11/05/19 14:07	Reinspection Photo		☒
385	11/05/19 14:07	Reinspection Photo		☒
386	11/05/19 14:07	Reinspection Photo		☒
387	11/05/19 14:07	Reinspection Photo		☒
388	11/05/19 14:07	Reinspection Photo		☒
389	11/05/19 14:07	Reinspection Photo		☒
390	11/05/19 14:07	Reinspection Photo		☒
391	11/05/19 14:07	Reinspection Photo		☒
392	11/05/19 14:07	Reinspection Photo		☒
393	11/05/19 14:07	Reinspection Photo		☒
394	11/05/19 14:07	Reinspection Photo		☒
395	11/05/19 14:07	Reinspection Photo		☒
396	11/05/19 14:07	Reinspection Photo		☒
397	11/05/19 14:07	Reinspection Photo		☒
398	11/05/19 14:07	Reinspection Photo		☒
399	11/05/19 14:07	Reinspection Photo		☒
400	11/05/19 14:07	Reinspection Photo		☒
401	11/05/19 14:07	Reinspection Photo		☒
402	11/05/19 14:07	Reinspection Photo		☒
403	11/05/19 14:07	Reinspection Photo		☒
404	11/05/19 14:07	Reinspection Photo		☒
405	11/05/19 14:07	Reinspection Photo		☒
406	11/05/19 14:07	Reinspection Photo		☒
407	11/05/19 14:07	Reinspection Photo		☒
408	11/05/19 14:07	Reinspection Photo		☒
409	11/05/19 14:07	Reinspection Photo		☒
410	11/05/19 14:07	Reinspection Photo		☒
411	11/05/19 14:07	Reinspection Photo		☒
412	11/05/19 14:07	Reinspection Photo		☒
413	11/05/19 14:07	Reinspection Photo		☒
414	11/05/19 14:07	Reinspection Photo		☒
415	11/05/19 14:07	Reinspection Photo		☒
416	11/05/19 14:07	Reinspection Photo		☒
417	11/05/19 14:07	Reinspection Photo		☒
418	11/05/19 14:07	Reinspection Photo		☒
419	11/05/19 14:07	Reinspection Photo		☒
420	11/05/19 14:07	Reinspection Photo		☒
421	11/05/19 14:07	Reinspection Photo		☒
422	11/05/19 14:07	Reinspection Photo		☒
423	11/05/19 14:07	Reinspection Photo		☒
424	11/05/19 14:07	Reinspection Photo		☒
425	11/05/19 14:07	Reinspection Photo		☒
426	11/05/19 14:07	Reinspection Photo		☒
427	11/05/19 14:07	Reinspection Photo		☒
428	11/05/19 14:07	Reinspection Photo		☒
429	11/05/19 14:07	Reinspection Photo		☒
430	11/05/19 14:07	Reinspection Photo		☒
431	11/05/19 14:07	Reinspection Photo		☒
432	11/05/19 14:07	Reinspection Photo		☒
433	11/05/19 14:07	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
434	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
435	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
436	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
437	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
438	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
439	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
440	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
441	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
442	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
443	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
444	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
445	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
446	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
447	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
448	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
449	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
450	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
451	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
452	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
453	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
454	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
455	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
456	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
457	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
458	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
459	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
460	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
461	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
462	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
463	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
464	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
465	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
466	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
467	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
468	11/05/19 14:07	Reinspection Photo	 Load JPG	☒
469	11/05/19 14:13	Finishing Photo	 Load JPG	☒
470	11/05/19 14:13	Finishing Photo	 Load JPG	☒
471	11/05/19 14:13	Finishing Photo	 Load JPG	☒
472	11/05/19 14:13	Finishing Photo	 Load JPG	☒
473	11/05/19 14:13	Finishing Photo	 Load JPG	☒
474	11/05/19 14:13	Finishing Photo	 Load JPG	☒
475	11/05/19 14:13	Finishing Photo	 Load JPG	☒
476	11/05/19 14:13	Finishing Photo	 Load JPG	☒
477	11/05/19 14:13	Finishing Photo	 Load JPG	☒
478	11/05/19 14:13	Finishing Photo	 Load JPG	☒
479	11/05/19 14:13	Finishing Photo	 Load JPG	☒
480	11/05/19 14:13	Finishing Photo	 Load JPG	☒
481	11/05/19 14:13	Finishing Photo	 Load JPG	☒
482	11/05/19 14:13	Finishing Photo	 Load JPG	☒
483	11/05/19 14:13	Finishing Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
484	11/05/19 14:13	Finishing Photo		☒
485	11/05/19 14:13	Finishing Photo		☒
486	11/05/19 14:13	Finishing Photo		☒
487	11/05/19 14:13	Finishing Photo		☒
488	11/05/19 14:13	Finishing Photo		☒
489	11/05/19 14:13	Finishing Photo		☒
490	11/05/19 14:13	Finishing Photo		☒
491	11/05/19 14:13	Finishing Photo		☒
492	11/05/19 14:13	Finishing Photo		☒
493	11/05/19 14:13	Finishing Photo		☒
494	11/05/19 14:13	Finishing Photo		☒
495	11/05/19 14:13	Finishing Photo		☒
496	11/05/19 14:13	Finishing Photo		☒
497	11/05/19 14:13	Finishing Photo		☒
498	11/05/19 14:13	Finishing Photo		☒
499	11/05/19 14:13	Finishing Photo		☒
500	11/05/19 14:13	Finishing Photo		☒
501	11/05/19 14:13	Finishing Photo		☒
502	11/05/19 14:13	Finishing Photo		☒
503	11/05/19 14:13	Finishing Photo		☒
504	11/05/19 14:13	Finishing Photo		☒
505	11/05/19 14:13	Finishing Photo		☒
506	11/05/19 14:13	Finishing Photo		☒
507	11/05/19 14:13	Finishing Photo		☒
508	11/05/19 14:13	Finishing Photo		☒
509	11/05/19 14:13	Finishing Photo		☒
510	11/05/19 14:13	Finishing Photo		☒
511	11/05/19 14:13	Finishing Photo		☒
512	11/05/19 14:13	Finishing Photo		☒
513	11/05/19 14:13	Finishing Photo		☒
514	11/05/19 14:13	Finishing Photo		☒
515	11/05/19 14:13	Finishing Photo		☒
516	11/05/19 14:13	Finishing Photo		☒
517	11/05/19 14:13	Finishing Photo		☒
518	11/05/19 14:13	Finishing Photo		☒
519	11/05/19 14:13	Finishing Photo		☒
520	11/05/19 14:13	Finishing Photo		☒
521	11/05/19 14:13	Finishing Photo		☒
522	11/05/19 14:13	Finishing Photo		☒
523	11/05/19 14:13	Finishing Photo		☒
524	11/05/19 14:13	Finishing Photo		☒
525	11/05/19 14:13	Finishing Photo		☒
526	11/05/19 14:13	Finishing Photo		☒
527	11/05/19 14:13	Finishing Photo		☒
528	11/05/19 14:13	Finishing Photo		☒
529	11/05/19 14:13	Finishing Photo		☒
530	11/05/19 14:13	Finishing Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/04/19 15:29	TP ESTIMATE + TP GIA REPORT		☐

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
2	09/04/19 15:29	ACKNOWLEDGEMENT EMAIL TO FWD DD 09.04.2019		
3	09/04/19 15:31	email - FWD TO OI DD 09.04.2019	Load PDF	
4	24/04/19 13:14	TP ESTIMATE - MARKED	Load PDF	
5	24/04/19 13:14	WHEEL ALIGNMENT REPORT	Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	09/04/19 15:32	E-filed GIA report	Load PDF	
2	07/06/19 20:32	Letter of Demand from Third Party	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19006253/DEA3Q2

Date: 13/08/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00000119

Claimant Vehicle No: SHC1028D Insured Vehicle No: SLK2996M

Date of Loss: 07/04/2019 Nature of Claim: TP Claim No: 1201900009257

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC1028D**
 Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRS056262
 Reg. Date: 05/07/2017 (Man. Year: 2017) Chassis No: JTDKB3FU403561332
 Colour: Blue Odometer: 271524 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Davanti 5 mm Rear Left Side: Davanti 5 mm
 Front Right Side: Davanti 5 mm Rear Right Side: Davanti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	61,799.61	44,616.07	17,183.54	27.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,580.00	3,230.00	1,350.00	29.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	66,379.61	47,846.07	18,533.54	27.92
Approved Total (Overridden) (S\$)		38,000.00		
(S\$)	66,379.61	38,000.00	28,379.61	42.75
+ GST 7.00/7.00% (S\$)	4,646.57	2,660.00	1,986.57	42.75
Nett Amount (S\$)	71,026.18	40,660.00	30,366.18	42.75

INSPECTION

Date of Assignment: 09/04/2019

Date Inspected: 09/04/2019 Inspected At:

Chunni Motor Work Pte Ltd (HQ)
 Blk 10 Ang Mo Kio Industrial Park 2A, #03-19
 AMK Autopoint
 Singapore 568047

Estimated Period of Repair: 21.0 days

Adjuster: BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jul 2019)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1028D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	950.50 FL	*950.50 FL
2	1		*INSULATOR ,HOOD	Not Necessary	398.10 FL	*- FL
3	1		*INSULATOR CLIPS	Not Necessary	3.60 FL	*- FL
4	1		*BONNET RUBBER	Not Necessary	35.50 FL	*- FL
5	1		*BONNET CABLE	Not Necessary	53.20 FL	*- FL
6	1		*BONNET HINGE (RH)	Bent	57.70 FL	*57.70 FL
7	1		*BONNET HINGE (LH)	Bent	57.70 FL	*57.70 FL
8	1		*BONNET LOCK	Bent	132.60 FL	*132.60 FL
9	1		*RADIATOR GRILLE	Mtg Broken	438.00 FL	*438.00 FL
10	1		*RADIATOR GRILLE EMBLEM	Necessary	88.00 FL	*88.00 FL
11	1		*LAMP ASSY ,FOG ,RH	Broken	920.00 FL	*920.00 FL
12	1		*FRONT BUMPER COVER	Broken	499.90 FL	*499.90 FL
13	1		*FRONT BUMPER REINFORCEMENT	Broken	696.40 FL	*696.40 FL
14	1		*FRONT BUMPER REINFORCEMENT ABSORBER	Dented	115.70 FL	*115.70 FL
15	1		*FRONT BUMPER SPONGE	Torn	78.80 FL	*78.80 FL
16	1		*FRONT BUMPER CENTRE GRILLE	Mtg Broken	301.90 FL	*301.90 FL
17	1		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
18	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	154.00 FL	*- FL
19	1		*FRONT UNDER COVER	Not Necessary	180.80 FL	*- FL
20	1		*FRONT BUMPER TOP GARNISH	Deformed	225.40 FL	*225.40 FL
21	1		*COVER ,FRONT BUMPER HOLE, RH	Cut	28.38 FL	*28.38 FL
22	1		*COVER ,FRONT BUMPER HOLE, LH	Not Necessary	28.38 FL	*- FL
23	1		*REINFORCEMENT SUB -ASSY ,FRONT BUMPER LOWER	Not Necessary	241.40 FL	*- FL
24	1		*SUPPORT FR BUMPER ,RH	Not Necessary	81.70 FL	*- FL
25	1		*FRONT BUMPER CENTRE FRAME	Not Necessary	236.90 FL	*- FL
26	1		*BRACKET ,FRONT BUMPER SIDE ,RH	Broken	82.30 FL	*82.30 FL
27	1		*ABSORBER ,FRONT BUMPER LOWER (SPONGE LOWER)	Not Necessary	127.70 FL	*- FL
28	1		*UNIT ASSY ,HEADLAMP ,RH (LED)	Broken	3,455.00 FL	*3,455.00 FL
29	1		*UNIT ASSY ,HEADLAMP ,LH (LED)	Broken	3,455.00 FL	*3,455.00 FL
30	1		*HEAD LAMP PANEL (RH)	Dented	240.10 FL	*240.10 FL
31	1		*TOP PANEL CENTRE	Bent	364.90 FL	*364.90 FL
32	1		*TOP PANEL (RH)	Dented	145.90 FL	*145.90 FL
33	1		*BRACE PANEL	Bent	75.20 FL	*75.20 FL
34	1		*BRACKET ,HEADLAMP MOUNTING ,RH	Bent	25.50 FL	*25.50 FL
35	1		*RADIATOR ASSY	Bent	1,881.30 FL	*1,881.30 FL
36	1		*RADIATOR FAN COWLING ASSY	Deformed	661.30 FL	*661.30 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*RADIATOR TOP HOSE ,LH	Not Necessary	43.03 FL	*- FL
38	1		*RADIATOR TOP HOSE ,RH	Not Necessary	42.60 FL	*- FL
39	1		*RADIATOR SPARE TANK	Broken	125.80 FL	*125.80 FL
40	1		*RADIATOR BOTTOM MOUNTING	Not Necessary	27.50 FL	*- FL
41	1		*STAY ,RADIATOR SUPPORT ,RH	Not Necessary	65.70 FL	*- FL
42	1		*STAY ,RADIATOR SUPPORT ,LH	Not Necessary	65.70 FL	*- FL
43	1		*RADIATOR FAN BLADE (RH)	Deformed	233.10 FL	*233.10 FL
44	1		*RADIATOR FAN BLADE (LH)	Deformed	233.10 FL	*233.10 FL
45	1		*RADIATOR FAN MOTOR (RH)	Not Necessary	543.70 FL	*- FL
46	1		*RADIATOR FAN MOTOR (LH)	Not Necessary	543.70 FL	*- FL
47	1		*DEFLECTOR ,RADIATOR SIDE ,RH	Not Necessary	83.50 FL	*- FL
48	1		*DEFLECTOR ,RADIATOR SIDE ,LH	Not Necessary	77.00 FL	*- FL
49	1		*PIPE,RADIATOR	Not Necessary	126.50 FL	*- FL
50	1		*CLEANER ASSY ,AIR	Not Necessary	970.30 FL	*- FL
51	1		*AIR CLEANER TOP COVER	Not Necessary	446.50 FL	*- FL
52	1		*AIR CLEANER BOTTOM COVER	Not Necessary	947.80 FL	*- FL
53	1		*AIR CLEANER HOSE	Not Necessary	62.12 FL	*- FL
54	1		*AIR DUCT	Deformed	129.40 FL	*129.40 FL
55	1		*INLET ASSY ,AIR CLEANER	Deformed	132.00 FL	*132.00 FL
56	1		*AIR DUCT CENTRE	Deformed	94.03 FL	*94.03 FL
57	1		*COMPRESSOR ASSY ,W/MOTOR	Not Necessary	2,924.20 FL	*- FL
58	1		*COMPRESSOR ASSY ,W/RECEIVER	Bent	1,336.60 FL	*1,336.60 FL
59	1		*AIRCON DISCHARGE HOSE	Bent	386.90 FL	*386.90 FL
60	1		*AIRCON LIQUID HOSE & PIPE	Bent	580.45 FL	*580.45 FL
61	1		*AIRCON HOSE SUCTION	Bent	548.50 FL	*548.50 FL
62	1		*FENDER SUB-ASSY ,FRONT LH	Dented	945.30 FL	*945.30 FL
63	1		*FENDER SUB-ASSY ,FRONT RH	Dented	945.30 FL	*945.30 FL
64	1		*FRONT HOUSING ASSY ,RH	Dented	958.30 FL	*958.30 FL
65	1		*FRONT FENDER SHIELD ,LH	Not Necessary	196.60 FL	*- FL
66	1		*FRONT FENDER SHIELD ,RH	Dislodged	196.60 FL	*196.60 FL
67	2		*FRONT FENDER SHIELD CLIP	Necessary	7.60 FL	*7.60 FL
68	1		*FRONT FENDER HYBRID EMBLEM ,LH	Necessary	53.50 FL	*53.50 FL
69	1		*FRONT FENDER HYBRID EMBLEM ,RH	Necessary	53.50 FL	*53.50 FL
70	1		*PANEL SUB-ASSY,FRONT DOOR ,RH	Dented	1,264.00 FL	*1,264.00 FL
71	1		*FRONT PILLAR UPPER COVER ,RH	Not Necessary	96.00 FL	*- FL
72	1		*FRONT WINDSCREEN GLASS	Cracked	1,627.30 FL	*1,627.30 FL
73	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	208.60 FL	*208.60 FL
74	2		*FRONT WHEEL RIM (LH/RH)	Distorted	3,110.20 FL	*3,110.20 FL
75	2		*FRONT WHEEL HUB CAP (LH/RH)	Cut	355.40 FL	*355.40 FL
76	2		*FRONT WHEEL HUB BEARING (LH/RH)	Damaged	1,120.20 FL	*1,120.20 FL
77	1		*FRONT SHOCK ABSORBER (LH)	Distorted	401.80 FL	*401.80 FL
78	1		*FRONT SHOCK ABSORBER (RH)	Distorted	401.80 FL	*401.80 FL
79	1		*ABSORBER TOP MOUNTING ,LH	Not Necessary	196.20 FL	*- FL
80	1		*ABSORBER TOP MOUNTING ,RH	Not Necessary	196.20 FL	*- FL
81	1		*FRONT SUSPENSION LOWER ARM (RH)	Distorted	637.50 FL	*637.50 FL
82	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	637.50 FL	*637.50 FL
83	1		*FRONT DRIVE SHAFT (LH)	Distorted	1,310.10 FL	*1,310.10 FL
84	1		*FRONT DRIVE SHAFT (RH)	Distorted	1,310.10 FL	*1,310.10 FL
85	1		*RACK & PINION ASSY	Damaged	1,634.90 FL	*1,634.90 FL
86	1		*BAR ,STABILIZER	Distorted	360.00 FL	*360.00 FL
87	1		*LINK ASSY ,FRONT STABILIZER ,LH	Distorted	199.00 FL	*199.00 FL
88	1		*LINK ASSY ,FRONT STABILIZER ,RH	Distorted	199.00 FL	*199.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
89	1		*KNUCKLE ,STEERING ,RH	Distorted	562.30 FL	*562.30 FL
90	1		*KNUCKLE ,STEERING ,LH	Distorted	562.30 FL	*562.30 FL
91	1		*JOINT ASSY ,LOWER BALL ,FRONT RH	Not Necessary	202.40 FL	*- FL
92	1		*END SUB-ASSY ,TIE ROD ,RH	Distorted	158.10 FL	*158.10 FL
93	1		*END SUB-ASSY ,TIE ROD ,LH	Distorted	158.10 FL	*158.10 FL
94	1		*ENGINE UNDER COVER	Not Necessary	457.20 FL	*- FL
95	1		*ENGINE CROSS MEMBER	Distorted	2,531.70 FL	*2,531.70 FL
96	2		*FRT ABS	Not Necessary	910.20 FL	*- FL
97	1		*SENSOR ,SPEED ,FRONT RH	Not Necessary	455.10 FL	*- FL
98	1		*WIRING FRONT	Socket / Broken	6,685.90 FL	*6,685.90 FL
99	1		*WIRING ENGINE	Not Necessary	2,133.90 FL	*- FL
100	1		*FRONT NO.PLATE }	Bent	25.00 FS	*45.00 FS
101	1		*FRONT NO.PLATE TRIM COVER }	Bent	30.00 FS	*- FS
102	1		*FRONT NO PLATE GARNISH	Deformed	99.00 FS	*99.00 FS
103	1		*FRONT DOOR COMFORT LOGO	Necessary	75.00 FS	*75.00 FS
104	1		*FRONT TYRE (LH/RH)	N/S Cut / O/S Not Necessary	432.00 FS	*108.00 FS
105	1		*REAR BUMPER	Repair	458.60 FL	*- FL
106	1		*REAR FENDER,RH	Dented	836.70 FL	*836.70 FL
107	1		*REAR FENDER SHIELD (RH)	Not Necessary	134.20 FL	*- FL
108	1		*PANEL SUB-ASSY ,FRONT DOOR ,RH	Buckled	1,264.00 FL	*1,264.00 FL
109	1		*CENTRE ROCKER PANEL (GARNISH)	Cut / Mtg Broken	576.00 FL	*576.00 FL
110	1		*REAR WHEEL HUB CAP ,LH/RH	O/S Bent / N/S Not Necessary	355.40 FL	*177.70 FL
111	1		*REAR CROSS MEMBER	Distorted	2,200.40 FL	*2,200.40 FL
112	1		*REAR SHOCK ABSORBER ,LH/RH	N/S Not Necessary/O/SDistorted	236.60 FL	*118.30 FL
113	2		*REAR SHOCK ABSORBER MOUNTING ,LH/RH	Not Necessary	250.60 FL	*- FL
114	1		*REAR LOWER ARM ,LH/RH	N/S Not Necessary/O/SDistorted	995.00 FL	*497.50 FL
115	1		*REAR UPPER ARM ,LH/RH	N/S Not Necessary/O/SDistorted	713.60 FL	*356.80 FL
116	1		*REAR KNUCKLE ARM ,LH/RH	N/S Not Necessary/O/SDistorted	1,621.20 FL	*810.60 FL
117	1		*REAR STABILIZER BAR	Distorted	311.50 FL	*311.50 FL
118	2		*REAR STABILIZER LINK,LH/RH	Not Necessary	303.20 FL	*- FL
119	1		*REAR TRAILING ARM LH/RH	N/S Not Necessary/O/SDistorted	628.40 FL	*314.20 FL
120	1		*REAR ASSIST ARM ,LH/RH	N/S Not Necessary/O/SDistorted	684.40 FL	*342.20 FL
121	1		*REAR DOOR COMFORT & APPS STICKER	Necessary	80.00 FS	*80.00 FS
122	1		*WATER PUMP ASSY	Broken	925.30 FL	*925.30 FL
123	1		*WIPER GARNISH	Broken	668.32 FL	*668.32 FL
124	1		*WIPER GARNISH SIDE COVER ,RH	Dislodged	26.50 FL	*26.50 FL
125	1		*HEAD LAMP PANEL (LH)	Bent	240.10 FL	*240.10 FL
126	1		*TOP PANEL (LH)	Bent	145.90 FL	*145.90 FL
127	1		*RADIATOR LOWER SUPPORT PANEL	Bent	397.40 FL	*397.40 FL
128	1		*WIPER SPARE TANK	Deformed	183.75 FL	*183.75 FL
129	1		*WIPER SPARE TANK MOTOR	Damaged	242.70 FL	*242.70 FL
130	1		*WIPER SPARE TANK FLOAT (NECK)	Deformed	55.50 FL	*55.50 FL
131	1		*ENGINE MOUNTING	Damaged	386.60 FL	*386.60 FL
132	1		*ENGINE MTG (REAR)	Damaged	172.90 FL	*172.90 FL
133	1		*GEARBOX MOUNTING	Damaged	299.30 FL	*299.30 FL
134	2			Not Necessary	259.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
*ENGINE CROSSMEMBER SIDE STAY (LH/RH)						
F=Franchise part, S=SpcNett, L=ListItemDisc.						
					Sub Total (S\$)	77,064.26
					59,352.43	
					- List Item Discount on L Items 20.00/25.00% (S\$)	15,264.65
					14,736.36	
					Total Parts (S\$)	61,799.61
					44,616.07	

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	1,000.00
2	SPRAY PAINTING CHARGE	New	1,300.00	1,000.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	80.00	40.00
5	TOWNG CHARGE	New	50.00	0.00
6	FRT CHASSIS ALIGNMENT	New	200.00	150.00
7	REMOVE/REFIX REVERSE SENSOR	New	80.00	0.00
8	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	120.00	120.00
9	REMOVE/REFIX UNDERCARRIAGE (RR)	New	150.00	120.00
10	FOUR WHEEL ALIGNMENT	New	80.00	60.00
11	REMOVE/REFIX AIRCON & REFILL GAS	New	80.00	60.00
12	REMOVE/REFIX ENGINE	New	200.00	150.00
13	REMOVE/REFIX DASHBOARD	New	200.00	180.00
14	REMOVE/REFIX FUSE BOX	New	180.00	50.00
15	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	80.00
16	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT	New	90.00	40.00
17	DIAGNOSIS & RESETTING TO ERASE FAULT CODE	New	200.00	150.00
Gross Labour Cost (S\$)			4,580.00	3,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >