

INS. CASE OWNER:

CC3, LPL 1900 6763, Klean3m

LKK:
IDAC:

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SHE 4078 U



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 2,200

(5 - days) Reduction:

31 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 2,354.00

OID REVERSED AND HIN

TP.

Loss of Rental (LOR):

S\$ 338.01

(2 days) x 112.67

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ 150.00

(\$ 50 x 3 days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☒

[Tick only one]

GIA/LTA Search

S\$ 7.44

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+450

Total:

S\$ 2,849.50

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1:

S\$ 2,849.50

Name 1:

COMFORTDRUGS ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

Surveyor: Kolvin

REF: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / INS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vhc _____

(Policy Condition)

Remark: the veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: no % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Type: M. Car / M. Cycle / Bus / Van / Lorry / ☒ Prime Mover /

Truck / Trailer or

Make: _____

Colour: _____

Sp. Reading _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / ☒ Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Brim or

Tyre Size: _____

F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. _____

L/Bal. _____

D.O.A. _____

Rear

R/Bal. _____

L/Bal. _____

D.O.I. _____

Survey held at

Des. of Damages: Frl / Rear / O/S / N/S / U/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4.30 - 2.300 (RSD + 986.61 31%)

Longpac
4/.

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: _____

☐ : Site Insp (\$ _____)

☐ : Inter/Veh (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Fuel \$ _____

Tolls \$ _____

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Date: 12/04/2019

Your ref: TBA
Our ref: CC3/LPC19006263/K1ea3

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB 4078U


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 08/04/2019 at the premises of M/s ComfortDelGro Engineering Pte Ltd (Loyang) and have the following to report:-

Workshop Estimate Amount	: S\$	3,186.64
Revised Estimate Amount	: S\$	2,200.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	2,200.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
O/S Front portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Date/Time: 08.04.2019 12:04

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 3912673

JC NO.: 305285254

STOMER
MS
STOMER NO.
RESS
(R)
(P)
COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)

REGN NO.: SHB4078U	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 07.04.2019 11:40
YR OF MANU. 16.07.2015	TARGET DATE
CHASSIS CODE KMHLB41UMGU075402	COMPLETION DATE/TIME:

COUNT CARD NO.

Accident Date: 07.04.2019
NATURE: 3P 07.04.19/B-


S/NO

LABOR CODE

JOB DESCRIPTION

RIGHT FRONT
DESCRIPTION

LONPAC



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

e No.:

SHB4078U

FZ LONPAC

Vehicle No.:

SHB4078U

Signature/Date

Name of Service Advisor

Date

To be kept by Security Guard

of Service Advisor

returned to Service Reception upon collection

REPAIR ESTIMATE*

MAKE :

MODEL : HYUNDAI i40

DATE 8/4/2019 10:53

五

MAKE	MODEL	Parts Description/ Labour	Type	Unit Price	Amount
		Front Bumper Cover			\$ 544.50
		Front Bumper Bracket Top (RH) ?			\$ 22.40
		Front Bumper Bracket (RH) ✓			\$ 24.60
		Front RH Head lamp ✓			\$ 591.50
		Front RH Fender ✓			\$ 118.30
		SUB TOTAL			\$ 473.20
		LESS 20%			
		DISCOUNTED TOTAL			
		Front Fender Advertisement Logo (RH) ✓			\$ 100.00
					\$ 100.00
		Labour Charge			\$ 300.00
		Panel Beating-Repair Fender			\$ 400.00
		Spray Painting Charge			\$ 600.00
		Tuff Kote			\$ 50.00
		TOTAL LABOUR			\$ 1,050.00
		ESTIMATE TOTAL			\$ 1,623.20

Kalish 100M
 8/4/19 1400L
 3 hrs
 45
 After Repair 7th

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

REPAIR ESTIMATE*

MAKE :

MODEL : HYUNDAI i40

DATE 8/4/2019 10:53

五

MAKE	MODEL	HYUNDAI i40	Type	Unit Price	Amount
Qty	Parts Description/ Labour				
	Front Bumper Cover	— <i>Painted</i>			\$ 544.50
	Front Bumper Bracket Top (RH)	<i>X sm</i>			\$ 22.40
	Front Bumper Bracket (RH)	<i>2 cm</i>			\$ 24.60
	Front RH Head lamp	— <i>cm</i>			\$ 591.50
	Front RH Fender	— <i>Painted</i>			\$ 118.30
	SUB TOTAL			\$1388	
	LESS 20%			\$566.30	
	DISCOUNTED TOTAL				
	Front Fender Advertisement Logo (RH)	— <i>me</i>			\$ 100.00
					\$ 100.00
	Labour Charge				
	Panel Beating-Repair Fender				\$ 400.00
	Spray Painting Charge				\$ 600.00
	Tuff Kote				\$ 50.00
	TOTAL LABOUR				\$ 1,050.00
	ESTIMATE TOTAL				\$ 1,623.20
<i>Kalvin LUK</i> <i>8/4/19 1400h</i> <i>3 hrs</i> <i>45</i> <i>After Repair 2h</i>					
LKK Auto Consultants hereby notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305285254
Date : 11.04.2019

FINALIZATION FORM

To : LKK
Attn : KALVIN
Vehicle Reg No. : SHB4078U

Fax :

Date of Accident : 07.04.2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: LONPAC --- SMA 657X
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$0.00
(b) Labour Charges	\$0.00
Total for Part-By-Part Repair Cost	\$0.00
(c) Lumpsum Repair (if applicable)	\$2,200.00
Total for Lumpsum repair cost after Less: <u>20%</u>	<u>\$2,200.00</u>
Final Lumpsum Repair cost	\$2,200.00

3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : FAUZY BIN MOKHTAR
Tel : 62148319
Fax : 65468156

Signature : 
Name : Kalvin
Date : 12/4/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Mei Kwan (LKKAUTO)


From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 17 April, 2019 5:06 PM
To: Mei Kwan (LKKAUTO); MT_Claim_SG
Cc: Asher Sng (LKKAUTO); Admin A; CS A Team
Subject: RE: Direct Settlement - Accident Involving SMA657X (OI : 19/19/19/VP05/021648)
AND SHB4078U (TP : LKK REF - CC3/LPC19006263/K1ea3) on 07/04/20199 [External
General]
Attachments: SMA657X 070419.PDF

Lonpac External - General

Dear Mei Kwan

Please see attached for our Insured's GIA report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 16 April, 2019 11:31 AM
To: MT_Claim_SG
Cc: GERALD POH WEE BIN; ONG LI LI; Asher Sng (LKKAUTO); Admin A; CS A Team
Subject: Direct Settlement - Accident Involving SMA657X (OI : LPC - TBA) AND SHB4078U (TP : LKK REF - CC3/LPC19006263/K1ea3) on 07/04/20199

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHB 4078U at M/s ComfortDelGro Engineering Pte Ltd (Loyang) on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly assist to verify validity of our insured's policy and let us have a copy of insured's accident report for our necessary action.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC3/LPC19006263/K1ea3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 29-07-2019



Code : LPC2

Policy Particulars :- THIRD PARTY CLAIM

1.	Insured Veh.	SMA 657X	Veh. Inspected	SHB 4078U
	Policy No.	Z19VP05021749	Coverage (\$)	0.00
	Claim No.	19/19/19/VP05/021648	Excess (\$)	0.00
	Assign From		Assign Date	08/04/2019

Vehicle Particulars & Condition

2.	Make & Model	HYUNDAI I40	c.c	1685
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	KMHLB41UMGU075402	Colour	BLUE
	Odometer	498912	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre	205/60 R16	WEST LAKE	6 mm
	L/H Front Tyre	205/60 R16	WEST LAKE	6 mm
	R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
	L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm

Description of Damages

4.	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.
----	---

General Information

5.	Accident Date	07/04/2019	Inspection Date	08/04/2019
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

Remarks

5a.	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
-----	--

Estimate Days of Repair

5b.	ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-----	-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4078U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER COVER	DEFORMED	544.50	544.50
1	FRONT BUMPER BRACKET TOP (RH)	SERVICEABLE	22.40	-
1	FRONT BUMPER BRACKET (RH)	CRACKED	24.60	24.60
1	FRONT RH HEADLAMP	CRACKED	1,388.00	1,388.00
1	FRONT RH FENDER	BUCKLED	566.30	566.30
	LESS 20% DISCOUNT		-509.16	-504.68
			2,036.64	2,018.72
SPECIAL NETT ITEMS				
1	FRONT FENDER ADVERTISEMENT LOGO (RH) (SN)	NECESSARY	100.00	100.00
			100.00	100.00
LABOUR				
	PANEL BEATING -REPAIR FENDER .		400.00	300.00
	SPRAY PAINTING CHARGE.		600.00	400.00
	TUFF KOTE.		50.00	20.00
			1,050.00	720.00
			3,186.64	2,838.72
GRAND TOTAL				
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00

Report Ref No. CC3/LPC19006263/K1ea3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.