

ASS. REC. BY:

REF: CS/MSG/900664/kvd372

Special Instruction:

Surveyor: Kenneth
Minn

ASSIGNMENT (Office)

From (Person): Jasmine Lot Khung Kwei of MSIG

Date/Time: 9.4.19 10.18 a.m

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKK 8318T

Insured: SGR1894C

at Workshop m/s Chew Goon Motor

Tel: 6484/626

of BIK 10 Ang Mo Kio Industrial Park 2A #01-15/16 & 17

Policy No: A27464842MX

Claim No: 589779

Sum Insured:

Excess:

Make of Veh:

D.O.A. 5.4.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

Date/Time: 9.4.19 12.53p.m

Person Contacted:

Gau / Kelly /
Xiao Yan

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKK 8318T - X
	SGR 1894C - X
11/4/19	Send preli revised via merimen
10/5	Call Sup 8940d email

ASS. REC. BY:

REF: MSG/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Chen Gou

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04-5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKK 83187 Yr Regn: 05, 13Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw 528i c.c. 1997Colour: M. Gray A/C: Insured / Std / NI / NASp. Reading: 117754 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAXG 320900122130Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 245/45R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIRT / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 5/4/19 D.O.I. 9/4/19

Survey held at _____

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

/ File pass to

13/5/19 @ 546pm LS \$9400 confirmed with Kelly (Reel 8158.45, 46%)

RECEIVED 14 MAY 2019

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 14/5- typistDays Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

200

10

210

Report Format:

Lump Sum / I.B.I. (\$

merimen9400k

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 11 Apr 2019

Preliminary Advice

Insured Vehicle No	: SGR1894C	Accident Date	: 05/04/2019
TP Vehicle No	: SKK8318T	Assignment Date	: 09/04/2019
Make	: BMW 528i	Est. Duration of Repair	: 5.00
Date of Inspection	: 09/04/2019		
Inspection At	: CHEW GOON MOTOR (AMK) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-15/16 & 17, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,991.65
Revised Amount	:S\$	5,416.35
Check Items (Estimated)	:S\$	6,841.30
Total	:S\$	12,257.65

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Apr 2019		09 Apr 2019 10:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HAN AH SIEW, ID: S1089066G, Tel: +6597242286, Email: NOEMAIL		
Main Claimant:	LIU YUAN, ID: S8674503H		
Vehicle Reg. No.:	SKK8318T	Date of Loss:	05/04/2019 14:00 - :59 [70 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 589779	Policy/Cover Note No.:	A27416484QMX (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	SGR1894C	Policy No. (Claimant):	
		Excess:	
Repairer:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 10/04/2019]		
Driver/Custodian (Insured):	HAN AH SIEW (76 / Male), NRIC: S1089066G, Tel: +6597242286 Email: NOEMAIL		
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK. LIABILITY: 100% CONTACT: XIAO YAN 6484 1626. ON WP		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 4503H

Vehicle Details

Vehicle No.: SKK8318T
Vehicle to be Exported: No
Intended Deregistration Date: 06 Apr 2019
Vehicle Make: B.M.W.
Vehicle Model: 528I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Primary Colour: Brown
Manufacturing Year: 2013
Engine No.: A7290478N20B20A
Chassis No.: WBAXG32090D122130
Maximum Power Output: 180.0 kW (241 bhp)
Open Market Value: \$46,422.00
Original Registration Date: 23 May 2013
First Registration Date: 23 May 2013
Transfer Count: 1
Actual ARF Paid: \$51,991.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 22 May 2023
PARF Rebate Amount: \$36,393.00

Intended COE Rebate Details

COE Expiry Date: 22 May 2023
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$66,701.00
COE Rebate Amount: \$27,523.00
Total Rebate Amount: \$63,916.00

The information contained herein is correct as at 06 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/04/2019 17:48
Date Of Accident	05/04/2019 14:25
Exact Location Of Accident	SLIP ROAD FROM BRADDELL ROAD TO CTE SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK8318T
Insured/Policyholder	
Name Of Registered Owner	LIU YUAN
NRIC No	S8674503H
Email Address	ROBIN722@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-81803106
Alternative Phone No	OTHERS-81803106

Vehicle Particulars

Manufacturer	BMW
Model	528i
Exact Purpose for which vehicle was being used at time of accident	LEISURE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093649878-01
Cover Note Number	DRIVO CLASSIC

Driver

Name of Driver	LIU YUAN
NRIC No	S8674503H
Date Of Birth	22/07/1986
Occupation	INDOOR
Date Of Driving Pass	15/04/2009
Driving Experience	9 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81803106
Fax Number	
Contact Number	OTHERS-81803106
Email Address	ROBIN722@HOTMAIL.COM

Address	BLK 119 #02-1026 POTONG PASIR AVENUE 1
Postcode	350119
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was travelling along the slip road along lane 1. Suddenly, vehicle B dashed out from the side road. This resulted in the left front area of my vehicle A to hit into the right front fender and right front door area of vehicle B.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGR1894C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HAN AH SIEW
NRIC/Passport Number	S1089066G
Contact Number	UNKNOWN
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan Pg. 1

INCOME MOTOR SERVICE CENTRE

Report Date & Start Time: 05/04/2019 / 17:44

Report No: MT/

D.O.A: 05/04/2019
Time: 14:25 hrs

Vehicle No: SKK8318T Reporting Type: _____


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



05/04/19 / 17:44
Policyholder's Signature / Date & Time

05/04/19 / 17:44
Driver's Signature (If driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre

Witnessed by Reporting Centre Personnel

Sketch Plan Pg. 2

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was travelling along the slip road along lane 1. Suddenly, vehicle B dashed out from the side road. This resulted in the left front area of my vehicle A to hit into the right front fender and right front door area of vehicle B.

Declaration

I/We declare the foregoing particulars are true in every respect.


05/04/19 / 17:44
Policyholder's Signature / Date & Time

05/04/19 / 17:44
Driver's Signature (If driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre

Witnessed by Reporting Centre Personnel

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8674503H**

Name: **LIU YUAN**

Birth Date: **22 Jul 1986**

Issue Date: **15 Apr 2009**

001731427E




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8674503H

Name: **LIU YUAN**





刘 源

Race: **CHINESE**

Date of birth: **22-07-1986**

Country/Place of birth: **CHINA**

Sex: **M**







YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE: **15 Apr 2009**

is 3 Motor Cars $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of the driver; and other motor vehicles $\leq 2500\text{kg}$

Licence No: **S8674503H**



IP 428A

5441608

NRIC No. S8674503H

Date of Issue: **23-03-2015**

APT BLK 119 POTONG PASIR AVENUE 1 #02-1026

SINGAPORE 350119

NRIC No: **S8674503H** Date: **20/01/2016**




趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Authorized
1/4/19
61km 89400k
Resurvey After Paint

4-5 days

To: MSIG Insurance (S) Pte Ltd

Policy No: _____ THIRD PARTY

Date: _____ 05.04.2019

Accident Date : 05.04.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.	
Estimate Cost of Repair "BMW 528i" Reg. No. SKK8318T Claiming Against Your Insured Veh. No. SGR1894C				
1pc	Front Bumper 1350	4.50	Ben 1,470.00	
15pcs	Front Bumper Clips		Ben 67.50	
1pc	Front Bumper Bracket Upper LH		A 140.00	
1pc	Front Bumper Bracket Middle LH		H 120.00	
1pc	Front Bumper Sponge		CMT 60.00	
1pc	Front Bumper Reinforcement		R 820.00	
1pc	Front Bumper Beam		R 200.00	
1pc	Front Bumper Side Holder LH L Shape		Ben 13.00	
1pc	Front Bumper Inner Core		Ben 182.00	
1pc	Front Bumper Top Retainer		CMT 102.00	
1pc	Front Bumper Sensor LH 230-230		Scr 385.00	
1pc	Front Bumper Sensor Holder		Ben 60.00	
1pc	Front Bumper Sensor Wire		Ben 186.00	
1pc	Front bumper Headlamp Noozle		CMT 210.00	
1pc	Front bumper Headlamp Noozle Cover LH		MSCMT 55.00	
1pc	Front bumper Headlamp Noozle Bracket		Ben 7.50	
1pc	Front bumper Headlamp Noozle Hose		Ben 60.00	
1pc	Front bumper Air Duct		CMT 285.00	
1pc	Front Bumper Side Grille		Ad/Let 86.00	
1pc	Front Bumper Side Finisher		Ben 43.00	
1pc	Front Bumper Fog Lamp		Scr 305.00	
1pc	Front Bumper Corner Retainer		CMT 136.00	
1pc	Headlamp Lower Panel		R 220.00	
1pc	Headlamp Bulb HID 305		Shan 385.00	
1pc	Headlamp Ballast HID 815		Ben 955.00	
1pc	Headlamp Directional ECU 720		CMT 870.00	
1pc	Headlamp Signal LED Module		Ben 435.00	
1pc	Front Fender LH 842-30		R 980.00	
1pc	Front Fender Shield LH		CMT 286.00	
5pcs	Front Fender Shield Clips		Ben 22.50	
1pc	Front Wheel Rim LH 850		Ad/Let 1,000.00	
			10,146.50	
C/F			10,146.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before a temporary painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party assessment on "Without Prejudice" basis
- No illegal practices are allowed
- Supply of parts cannot be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer

Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before and after painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No legal proceedings are allowed
- Supplies and services must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer
Signature

C/F

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: MSIG Insurance (S) Pte Ltd

Policy No: THIRD PARTY

Date: 05.04.2019

Accident Date : 05.04.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair "BMW 528i" Reg. No. SKK8318T Claiming Against Your Insured Veh. No. SGR1894C		
		B/F	10,146.50
1pc	Front Shock Absorber LH <i>580</i>		<i>By</i> 705.00 <i>R</i>
1pc	Front Upper Arm		<i>in</i> 635.00 <i>X</i>
1pc	Front Knuckle Arm LH		<i>By</i> 760.00 <i>R</i>
1pc	Front Wheel Bearing LH <i>480</i>		<i>in</i> 560.00 <i>X</i>
1pc	Front Lower Arm <i>420</i>		<i>Di</i> 670.00 <i>R</i>
1pc	Front Track Arm LH		<i>in</i> 560.00 <i>X</i>
1pc	Front Stabilizer Bar Linkage		<i>in</i> 132.00 <i>X</i>
			14,168.50
	Less 10%		1416.85
			12,751.65
	To Conduct Front Electrical Check, Locking System, Focus Headlamp		<i>200</i> 40.00
	To Reseal Tuff Coating		<i>300</i> 60.00
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		<i>1800</i> 220.00 <i>?</i>
	To Conduct Computerize Wheel Alignment Test		<i>600</i> 80.00
	To Conduct High Speed Balancing		<i>200</i> 80.00
	To Reprogram Front Adaptive, Directional Headlamp		<i>1200</i> 180.00
	To Reprogram Front Sensor, PDC System		<i>600</i> 180.00
	Labour Charge - Panel Beating, Repairing Of Support Panel, Front Fender Inner Panel, Front LH Door & Parts Replacement.		<i>5000</i> 700.00
	Cnt, Weld Rear Fender and Parts Replacement		
	To Spray Painting Affected Areas		<i>6000</i> 700.00
		Total :	14,991.65
			<i>17,558.45</i>



WHEEL ALIGNMENT SYSTEM

Customer: CHEW GOON
 Description: BMW 5' F10/F11 INDIAN 18"
 Reference Diameter: 18"
 Working Notes:
 Date: 09/04/2019
 Operator:

Reg. N.: SKK 8318 T
 Repair order no.
 Mileage: km

Time: 14.56.52

FRONT AXLE

	Data		Databank - Tolerance	+ Tolerance	Previous Values		Final Values	
	LH	RH			LH	RH	LH	RH
Total toe	+00°10'		-00°04'	+00°04'	+00°01'		+00°01'	
Half-toe	+00°05'	+00°05'	-00°02'	+00°02'	-00°19'	+00°20'	-00°19'	+00°20'
Max Dif.	00°00'		-00°12'	+00°12'	-00°38'		-00°38'	
Camber	-00°16'	-00°16'	-00°25'	+00°25'	-02°08'	+00°02'	-02°07'	+00°02'
Max Dif.	00°00'		-00°30'	+00°30'	-02°10'		-02°10'	
Caster	+07°00'	+07°00'	-01°00'	+01°00'	+07°30'	+06°43'	+07°30'	+06°43'
Max Dif.	00°00'		-00°30'	+00°30'	+00°47'		+00°47'	
King-pin angle	+09°57'	+09°57'	-01°00'	+01°00'	+07°24'	+08°37'	+07°24'	+08°37'
Max Dif.								
Included angle					+05°17'	+08°40'	+05°17'	+08°40'
Steering angle diff. at 20°								
Max Int. Steering Angle	+42°14'		00°00'	00°00'				
Max Ext. Steering Angle	+33°00'		00°00'	00°00'				
Set Back	00°00'		-00°15'	+00°15'	+00°02'		+00°01'	
Tyre							LH	RH
Pressure measured								
Tread depth (mm)								

REAR AXLE

	Data		- Tolerance	+ Tolerance	Previous Values		Final Values	
	LH	RH			LH	RH	LH	RH
Total toe	+00°18'		-00°04'	+00°04'	+00°18'		+00°17'	
Half-toe	+00°09'	+00°09'	-00°02'	+00°02'	+00°19'	-00°01'	+00°18'	-00°01'
Max Dif.								
Camber	-01°50'	-01°50'	-00°05'	+00°05'	-01°32'	-01°37'	-01°32'	-01°37'
Max Dif.	00°00'		-00°30'	+00°30'	+00°05'		+00°05'	
Set Back					-00°04'		-00°03'	
Thrust angle	00°00'		-00°12'	+00°12'	+00°10'		+00°10'	
Track difference					-00°04'		-00°04'	
Tyre							LH	RH
Pressure measured								
Tread depth (mm)								

Veron Chen (LKKAUTO)

From: Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>
Sent: Monday, 13 May 2019 9:44 AM
To: Kenneth Kong (LKKAUTO)
Subject: RE: SKK 8318T

Noted.

Sent from Mail for Windows 10

From: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Sent: Monday, May 13, 2019 8:34:36 AM
To: Chew Goon Motor(ad3)
Subject: RE: SKK 8318T

5days.

From: Chew Goon Motor(ad3) [mailto:ad3@chewgoonmotor.com.sg]
Sent: Friday, 10 May, 2019 3:44 PM
To: Kenneth Kong (LKKAUTO)
Subject: RE: SKK 8318T

Dear Kenneth,

The recommend day is 4 days or 5 days?

Chew Goon Motor

Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15, 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

Sent from Mail for Windows 10

From: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Sent: Friday, May 10, 2019 9:10:02 AM
To: Chew Goon Motor(ad3)
Subject: RE: SKK 8318T

Attach finalised for SKK 8318T

趙 源 摩 哆 Chew Goon Motor

新加坡宏茂桥第 2A 工业园第五道大牌十号门牌十五,十六,十七(一楼)及门牌五(三楼)
Blk 10, Ang Mo Kio Industrial Park 2A, Ave. 5, #01-15, 16, 17 & #03-05, AMK Autopoint
Singapore 568047

Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

TEL: 6484 1626 (24Hrs) FAX: 6484 0465

◀ 修理各种汽车敲焊打吗咭喷漆等 ▶

MSIG Insurance (S) Pte Ltd

Accident Date : 05.04.2019

12.04.2019

Estimate Cost of Repair "BMW 528I" Reg. No. SKK8318T
Claiming Against Your Insured Veh. No. SGR1894C

Supplementary 2210.
1pc Front Headlamp LH (LED)
1pc Front Bumper Air Lower Duct
Less 10%

CM 2,790.00
R 62.00
2,852.00
285.20
2,566.80

Grand Total :

2,566.80

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19006264/KVD3N2

Date: 15/05/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A27416484QMX
Claimant Vehicle No :	SKK8318T	Insured Vehicle No :	SGR1894C
Date of Loss:	05/04/2019	Nature of Claim:	TP
		Claim No:	589779

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK8318T	Engine No:	A7290478N20B20A
Make & Model:	BMW 528i, 2.0 D/AB 2WD 4DR GAS/D NAV (A)	Chassis No:	WBAXG32090D122130
Reg. Date:	23/05/2013 (Man. Year: 2013)	Odometer:	117754 km
Colour:	Metallic Grey		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45R18	Rear Tyre Size:	245/45R18
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,318.45	10,208.07	5,110.38	33.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	1,590.00	650.00	29.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,558.45	11,798.07	5,760.38	32.81
Approved Total (Overridden) (S\$)		9,400.00		
(S\$)	17,558.45	9,400.00	8,158.45	46.46
+ GST 7.00/7.00% (S\$)	1,229.09	658.00	571.09	46.46
Nett Amount (S\$)	18,787.54	10,058.00	8,729.54	46.46

INSPECTION

Date of Assignment: 09/04/2019

Date Inspected: 09/04/2019 Inspected At:

Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A,
#01-15/16 & 17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2019)
Parts:	143	BMW 528I 2.0 D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK8318T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,470.00 FL	*1,350.00 FL
2	15		*FRONT BUMPER CLIPS	Necessary	67.50 FL	*67.50 FL
3	1		*FRONT BUMPER BRACKET UPPER LH	Repair	140.00 FL	*- FL
4	1		*FRONT BUMPER BRACKET MIDDLE LH	Repair	120.00 FL	*- FL
5	1		*FRONT BUMPER SPONGE	Cracked	60.00 FL	*60.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Repair	820.00 FL	*- FL
7	1		*FRONT BUMPER BEAM	Repair	200.00 FL	*- FL
8	1		*FRONT BUMPER SIDE HOLDER LH L SHAPE	Serviceable	13.00 FL	*- FL
9	1		*FRONT BUMPER INNER CORE	Serviceable	182.00 FL	*- FL
10	1		*FRONT BUMPER TOP RETAINER	Cracked	102.00 FL	*102.00 FL
11	1		*FRONT BUMPER SENSOR LH	Scratched	385.00 FL	*230.00 FL
12	1		*FRONT BUMPER SENSOR HOLDER	Necessary	60.00 FL	*60.00 FL
13	1		*FRONT BUMPER SENSOR WIRE	Serviceable	186.00 FL	*- FL
14	1		*FRONT BUMPER HEADLAMP NOOZLE	Cracked	210.00 FL	*210.00 FL
15	1		*FRONT BUMPER HEADLAMP NOOZLE COVER LH	Mtg Cracked	55.00 FL	*55.00 FL
16	1		*FRONT BUMPER HEADLAMP NOOZLE BRACKET	Serviceable	7.50 FL	*- FL
17	1		*FRONT BUMPER HEADLAMP NOOZLE HOSE	Serviceable	60.00 FL	*- FL
18	1		*FRONT BUMPER AIR DUCT	Cracked	285.00 FL	*285.00 FL
19	1		*FRONT BUMPER SIDE GRILLE	Dented/Cut	86.00 FL	*86.00 FL
20	1		*FRONT BUMPER SIDE FINISHER	Cut	43.00 FL	*43.00 FL
21	1		*FRONT BUMPER FOG LAMP	Scratched	305.00 FL	*305.00 FL
22	1		*FRONT BUMPER CORNER RETAINER	Cracked	136.00 FL	*136.00 FL
23	1		*HEADLAMP LOWER PANEL	Repair	220.00 FL	*- FL
24	1		*HEADLAMP BULB HID	Shorted	385.00 FL	*305.00 FL
25	1		*HEADLAMP BALLAST HID	Dented	955.00 FL	*815.00 FL
26	1		*HEADLAMP DIRECTIONAL ECU	Cracked	870.00 FL	*720.00 FL
27	1		*HEADLAMP SIGNAL LED MODULE	Serviceable	435.00 FL	*- FL
28	1		*FRONT FENDER LH	Bent	980.00 FL	*842.30 FL
29	1		*FRONT FENDER SHIELD LH	Cracked	286.00 FL	*286.00 FL
30	5		*FRONT FENDER SHIELD CLIPS	Necessary	22.50 FL	*22.50 FL
31	1		*FRONT WHEEL RIM LH	Dented/Scratched	1,000.00 FL	*850.00 FL
32	1		*FRONT HEADLAMP LH (LED)	Cracked	2,790.00 FL	*2,210.00 FL
33	1		*FRONT BUMPER AIR LOWER DUCT	Dented	62.00 FL	*62.00 FL
34	1		*FRONT SHOCK ABSORBER LH	Bent	705.00 FL	*580.00 FL
35	1		*FRONT UPPER ARM	Serviceable	635.00 FL	*- FL
36	1		*FRONT KNUCKLE ARM LH	Bent	760.00 FL	*760.00 FL
37	1		*FRONT WHEEL BEARING LH	Necessary	560.00 FL	*480.00 FL
38	1		*FRONT LOWER ARM	Distorted	670.00 FL	*420.00 FL
39	1		*FRONT TRACK ARM LH	Serviceable	560.00 FL	*- FL
40	1		*FRONT STABILIZER BAR LINKAGE	Serviceable	132.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) 17,020.50 11,342.30

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 10.00/10.00% (S\$)					1,702.05	1,134.23
Total Parts (S\$)					15,318.45	10,208.07
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT FRONT ELECTRICAL CHECK,LOCKING SYSTEM,FOCUS HEADLAMP	New	40.00	20.00
2	TO RESEAL TUFF COATING	New	60.00	30.00
3	TO DISMANTLE/REPLACE FRONT UNDER CARRIAGE TO FACILITATE REPAIR	New	220.00	180.00
4	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
5	TO CONDUCT HIGH SPEED BALANCING	New	80.00	20.00
6	TO REPROGRAM FRONT ADAPTIVE,DIRECTIONAL HEADLAMP	New	180.00	120.00
7	TO REPROGRAM FRONT SENSOR,PDC SYSTEM	New	180.00	60.00
8	LABOUR CHARGE-PANEL BEATING,REPAIRING OF SUPPORT PANEL,FRONT FENDER INNER PANEL,FRONT LH DOOR & PARTS REPLACEMENT.CUT,WELD REAR FENDER AND PARTS REPLACEMENT	New	700.00	500.00
9	TO SPRAY PAINTING AFFECTED AREAS	New	700.00	600.00
Gross Labour Cost (\$\$)			2,240.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >