

ADP-100-100

ADP-100-100

Estimated Cost

OD / TP / WS / TP / RES / OD / RES / EVA / INV / MY / CS

To Inspect Vehicle No

at Workshop n/o

of

Policy No

Sum insured

Make of Veh

(Client's Record)

CA / REV / REP / REV 24 HRS

Date/Time

08/FCI19006267/At d3 n2

ASSIGNMENT (Office)

of FCI

Date/Time: 9/4/19 @ 10:58am

Bill to:

Insured

Tel

Claim No

Excess:

D.O.A

H.O.D. Endorsement

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLG 9400R-x

3H/C0200D-CS3/FCI16006516/Fvbc2

DvA: 6/4/2016

Lump Sum \$3800/- (Red: 9973.49: 72%)

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SL69400R Yr Regn: 2016 1 Oct.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish C.C. 1798Colour: Maroon A/C: Insured / Std / NI / NASp. Reading: 91149 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JT06620W50J005733Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: 195/65R15195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 09/04/19Survey held at Torque 5.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap.

RECEIVED 11 JUN 2019

mv:

pv:

Nett:

Date/Time, File Pass to?

1) 10/6 Typist

3) _____

5) _____

Prel. Report: _____

Final Report: _____

Date/Time, File Return to?

2) _____

4) _____

6) _____

Part Prices Check:

IN

OUT

Survey Fee:

Date: 9/15/135

Basic & Add.

S + RS. SI

Photos

Others

TOTAL

1704 1355050+5039494

MOTOR SURVEY ASSIGNMENT

Date	08-04-2019	Our Ref No. D19002337MFSH
Accident Date	06-04-2019	Claim Type. Third Party
Insured Vehicle	SHC0200D	Third Party Vehicle. SLG9400R
Survey Location	NO. 8 KAKI BUKIT AVE 4 PREMIER @ KAKI BUKIT#01-50	
Contact Person.	TEO	
Contact No.	0/ 91478841	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TORQUE 5 PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 1590C

Vehicle Details

Vehicle No.: SLG9400R
Vehicle to be Exported: Yes
Intended Deregistration Date: 08 Apr 2019
Vehicle Make: TOYOTA
Vehicle Model: WISH 1.8 CVT
Primary Colour: Red
Manufacturing Year: 2016
Engine No.: 2ZR1848919
Chassis No.: JTDGG20W50J005733
Maximum Power Output: 105.0 kW (140 bhp)
Open Market Value: \$19,955.00
Original Registration Date: 19 Oct 2016
First Registration Date: 19 Oct 2016
Transfer Count: 0
Actual ARF Paid: \$19,955.00

Intended PARF Rebate Details
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 18 Oct 2026
PARF Rebate Amount: \$14,966.00

Intended COE Rebate Details
COE Expiry Date: 18 Oct 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$55,501.00
COE Rebate Amount: \$41,774.00
Total Rebate Amount: \$56,740.00

The information contained herein is correct as at 08 Apr 2019

OK



No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

Torque 5 Pte Ltd

TP 1st Cap.

Denise

JTDG7610W50J005333

ESTIMATION REPORT

Vehicle No : SLG9400R
Make & Model : TOYOTA WISH,

Estimation No. : E19040006
DOA : 06/04/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bumper <i>Dehid</i>	1.00	681.70	681.70 -
2	Rear bumper retainer long (LH) <i>3 new</i>	1.00	121.50	121.50 +
3	Rear bumper retainer long (RH)	1.00	121.50	121.50 +
4	Rear bumper retainer short (LH) <i>2 new</i>	1.00	89.20	89.20 -
5	Rear bumper retainer short (RH)	1.00	89.20	89.20 -
6	Rear bumper bracket (LH) <i>2 new</i>	1.00	179.00	179.00 +
7	Rear bumper bracket (RH) <i>2 new</i>	1.00	179.00	179.00 +
8	Rear bumper reflector (LH) <i>3 new</i>	1.00	199.20	199.20 +
9	Rear bumper reflector (RH)	1.00	199.20	199.20 +
10	Tailgate <i>Dehid</i>	1.00	1,239.70	1,239.70 -
11	Tailgate hinge (LH) <i>2 new</i>	1.00	98.70	98.70 +
12	Tailgate hinge (RH)	1.00	98.70	98.70 +
13	Tailgate damper (LH)	1.00	278.00	278.00 +
14	Tailgate damper (RH)	1.00	278.00	278.00 +
15	Tailgate rubber beading <i>new</i>	1.00	0.00	0.00 +
16	Tailgate emblem - Logo <i>3 new</i>	1.00	98.90	98.90 - 53
17	Tailgate emblem - Elegance	1.00	98.90	98.90 - 65
18	Tailgate emblem - Valve Matic	1.00	98.90	98.90 - 55
19	Tailgate lamp (LH) <i>2 new</i>	1.00	450.00	450.00 +
20	Tailgate lamp (RH)	1.00	450.00	450.00 +
21	License lamp chrome garnish <i>new</i>	1.00	229.00	229.00 +
22	License lamp (LH) <i>2 new</i>	1.00	180.00	180.00 +
23	License lamp (RH)	1.00	180.00	180.00 +
24	Tailgate lock <i>new</i>	1.00	252.20	252.20 +
25	Tailgate lock switch <i>new</i>	1.00	160.00	160.00 +
26	Tailgate lock sensor <i>new</i>	1.00	362.00	362.00 + 107.80
27	Tailgate lock catch <i>new</i>	1.00	0.00	0.00 +
28	Tailgate inner trim board <i>new</i>	1.00	780.00	780.00 +

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLG9400R
Make & Model : TOYOTA, WISH,

Estimation No. : E19040006
DOA : 06/04/2019

No	Description	Qty	U/P	Amt
29	Tailgate inner pull handle	1.00	0.00	0.00 +
30	Tailgate inner side garnish (LH)	1.00	0.00	0.00 +
31	Tailgate inner side garnish (RH)	1.00	0.00	0.00 +
32	Tailgate inner top garnish	1.00	290.00	290.00 +
33	Tailgate windscreen moulding top	1.00	130.00	130.00 -
34	Tailgate windscreen moulding lower	1.00	92.00	92.00 -
35	Tailgate windscreen outer side moulding (LH)	1.00	150.00	150.00 +
36	Tailgate windscreen outer side moulding (RH)	1.00	150.00	150.00 +
37	Tailgate wiper motor	1.00	690.00	690.00 +
38	Tailgate top spoiler	1.00	0.00	0.00 +
39	Third brake lamp	1.00	0.00	0.00 +
40	Tail lamp (LH)	1.00	599.20	599.20 +
41	Tail lamp (RH)	1.00	599.20	599.20 +
42	Tailgate lamp gasket (LH)	1.00	0.00	0.00 +
43	Tailgate lamp gasket (RH)	1.00	0.00	0.00 +
44	Tail lamp gasket (LH)	1.00	0.00	0.00 +
45	Tail lamp gasket (RH)	1.00	0.00	0.00 +
46	Tail lamp inner panel (LH)	1.00	442.00	442.00 +
47	End panel	1.00	869.70	869.70 +
48	End panel top garnish	1.00	340.00	340.00 +
49	Rear floor panel top board	1.00	432.00	432.00 +
50	Rear fender inner trim (RH)	1.00	1,333.96	1,333.96 +
51	Rear fender inner trim (LH)	1.00	462.93	462.93 +
				Amt S\$
				13,773.49
Discount (0.00%)				S\$ 0.00
Subtotal				S\$
				13,773.49

Section: Special Nett Items

52	Reverse camera	1.00	550.00	550.00 +
----	----------------	------	--------	----------

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLG9400R
Make & Model : TOYOTA, WISH,

Estimation No. : E19040006
DOA : 06/04/2019

No	Description	Qty	U/P	Amt
53	Reverse sensor set <i>Hand</i>	1.00	250.00	250.00 <i>200</i>
54	Rear bumper clip set <i>Ne</i>	1.00	45.00	45.00 <i>30</i>
55	Tailgate inner trim board clip set <i>Ne ne</i>	1.00	45.00	45.00 <i>+</i>
56	End panel top garnish clip set <i>Ne</i>	1.00	30.00	30.00 <i>5/10</i>
57	Rear fender inner trim clip set (LH) <i>Ne</i>	1.00	45.00	45.00 <i>+</i>
58	Rear windscreen tinted <i>Hand</i>	1.00	250.00	250.00 <i>+</i>
59	Rear windscreen sealant <i>Hand</i>	1.00	100.00	100.00 <i>+</i>
60	End panel sealant <i>Ne</i>	1.00	50.00	50.00 <i>2</i>
61	Rear number plate & casing <i>Ne</i>	1.00	45.00	45.00 <i>+</i>

Amt S\$ 1,410.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 1,410.00

Section: Labour Items

62	To R&R rear bumper reverse sensor	1.00	60.00	60.00 <i>40</i>
63	To check wiring and lighting system	1.00	60.00	60.00 <i>30</i>
64	To supply undercoating & putty on parts replacement	1.00	80.00	80.00 <i>+</i>
65	To perform anti-rust treatment on affected areas	1.00	80.00	80.00 <i>760</i>
66	To R&R rear windscreen	1.00	200.00	200.00 <i>120</i>
67	To R&R tailgate mechanism	1.00	200.00	200.00 <i>80</i>
68	To R&R rear seats, garnish & trims assy	1.00	250.00	250.00 <i>50</i>
69	To repair, replace & realign damage areas	1.00	1,600.00	1,600.00 <i>800</i>
70	To spray painting on affected areas	1.00	1,200.00	1,200.00 <i>700</i>
71	To check water seepage after repair	1.00	150.00	150.00 <i>+</i>
72	To car wash and polishing vehicle after repair	1.00	150.00	150.00 <i>+</i>

Amt S\$ 4,030.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 4,030.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King
w/s 09/04/19.
No of days : 05

Total: 4802.35
A/S: 3.81K

List Items Subtotal S\$ 13,773.49
Special Nett Items Subtotal S\$ 1,410.00
Labour Items Subtotal S\$ 4,030.00
Total S\$ 19,213.49



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19006267/Atd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-06-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 200D	Veh. Inspected	SLG 9400R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002337MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	09/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDGG20W50J005733	Colour	MAROON	
Odometer	91149	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/04/2019	Inspection Date	09/04/2019	
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 9400R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	681.70	681.70
1	REAR BUMPER RETAINER LONG (LH)	NOT NECESSARY	121.50	-
1	REAR BUMPER RETAINER LONG (RH)	NOT NECESSARY	121.50	-
1	REAR BUMPER RETAINER SHORT (LH)	NECESSARY	89.20	89.20
1	REAR BUMPER RETAINER SHORT (RH)	NECESSARY	89.20	89.20
1	REAR BUMPER BRACKET (LH)	NOT NECESSARY	179.00	-
1	REAR BUMPER BRACKET (RH)	NOT NECESSARY	179.00	-
1	REAR BUMPER REFLECTOR (LH)	NOT NECESSARY	199.20	-
1	REAR BUMPER REFLECTOR (RH)	NOT NECESSARY	199.20	-
1	TAILGATE	DENTED	1,239.70	1,239.70
1	TAILGATE HINGE (LH)	NOT NECESSARY	98.70	-
1	TAILGATE HINGE (RH)	NOT NECESSARY	98.70	-
1	TAILGATE DAMPER (LH)	NOT NECESSARY	278.00	-
1	TAILGATE DAMPER (RH)	NOT NECESSARY	278.00	-
1	TAILGATE RUBBER BEADING (NPA)	NOT NECESSARY	-	-
1	TAILGATE EMBLEM-LOGO	NECESSARY	98.90	55.00
1	TAILGATE EMBLEM-ELEGANCE	NECESSARY	98.90	65.00
1	TAILGATE EMBLEM-VALVE MATIC	NECESSARY	98.90	55.00
1	TAILGATE LAMP (LH)	NOT NECESSARY	450.00	-
1	TAILGATE LAMP (RH)	NOT NECESSARY	450.00	-
1	LICENSE LAMP CHROME GARNISH	NOT NECESSARY	229.00	-
1	LICENSE LAMP (LH)	NOT NECESSARY	180.00	-
1	LICENSE LAMP (RH)	NOT NECESSARY	180.00	-
1	TAILGATE LOCK	NOT NECESSARY	252.20	-
1	TAILGATE LOCK SWITCH	NOT NECESSARY	160.00	-
1	TAILGATE LOCK SENSOR	DAMAGED	362.00	107.90
1	TAILGATE LOCK CATCH (NPA)	NOT NECESSARY	-	-
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	780.00	-
1	TAILGATE INNER PULL HANDLE (NPA)	NOT NECESSARY	-	-
1	TAILGATE INNER SIDE GARNISH (LH)(NPA)	NOT NECESSARY	-	-
1	TAILGATE INNER SIDE GARNISH (RH)(NPA)	NOT NECESSARY	-	-

Report Ref No. CS/FCI19006267/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE INNER TOP GARNISH	NOT NECESSARY	290.00	-
1	TAILGATE WINDSCREEN MOULDING TOP	NECESSARY	130.00	130.00
1	TAILGATE WINDSCREEN MOULDING LOWER	NECESSARY	92.00	92.00
1	TAILGATE WINDSCREEN OUTER SIDE MOULDING (LH)	NOT NECESSARY	150.00	-
1	TAILGATE WINDSCREEN OUTER SIDE MOULDING (RH)	NOT NECESSARY	150.00	-
1	TAILGATE WIPER MOTOR	NOT NECESSARY	690.00	-
1	TAILGATE TOP SPOILER (NPA)	NOT NECESSARY	-	-
1	THIRD BRAKE LAMP (NPA)	NOT NECESSARY	-	-
1	TAIL LAMP (LH)	NOT NECESSARY	599.20	-
1	TAIL LAMP (RH)	NOT NECESSARY	599.20	-
1	TAILGATE LAMP GASKET (LH)(NPA)	NOT NECESSARY	-	-
1	TAILGATE LAMP GASKET (RH)(NPA)	NOT NECESSARY	-	-
1	TAIL LAMP GASKET (LH)(NPA)	NOT NECESSARY	-	-
1	TAIL LAMP GASKET (RH)(NPA)	NOT NECESSARY	-	-
1	TAIL LAMP INNER PANEL (LH)	NOT NECESSARY	442.00	-
1	END PANEL	DENTED	869.70	650.10
1	END PANEL TOP GARNISH	DEFORMED	340.00	255.00
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	432.00	-
1	REAR FENDER INNER TRIM (RH)	NOT NECESSARY	1,333.96	-
1	REAR FENDER INNER TRIM (LH)	NOT NECESSARY	462.93	-
	LESS 25% DISCOUNT		-	-877.45
			13,773.49	2,632.35
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE CAMERA (SN)	NOT NECESSARY	550.00	-
1	SET REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	30.00
1	SET TAILGATE INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	45.00	-
1	SET END PANEL TOP GARNISH CLIP (SN)	NECESSARY	30.00	10.00
1	REAR FENDER INNER TRIM CLIP SET (LH)(SN)	NOT NECESSARY	45.00	-
1	REAR WINDSCREEN TINTED (SN)	NOT NECESSARY	250.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	-
1	END PANEL SEALANT (SN)	NECESSARY	50.00	50.00

Report Ref No. CS/FCI19006267/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE & CASING (SN)	NOT NECESSARY	45.00	-
			1,410.00	290.00
	LABOUR			
	TO R&R REAR BUMPER REVERSE SENSOR.		60.00	40.00
	TO CHECK WIRING AND LIGHTING SYSTEM.		60.00	30.00
	TO SUPPLY UNDERCOATING & PUTTY ON PARTS REPLACEMENT.	NOT NECESSARY	80.00	-
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.		80.00	60.00
	TO R&R REAR WINDSCREEN.		200.00	120.00
	TO R&R TAILGATE MECHANISM.		200.00	80.00
	TO R&R REAR SEATS. GARNISH & TRIMS ASSY.		250.00	50.00
	TO REPAIR, REPLACE & REALIGN DAMAGE AREAS.		1,600.00	800.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		1,200.00	700.00
	TO CHECK WATER SEEPAGE AFTER REPAIR.	NOT NECESSARY	150.00	-
	TO CAR WASH AND POLISHING VEHICLE AFTER REPAIR.	NOT NECESSARY	150.00	-
			4,030.00	1,880.00
GRAND TOTAL			19,213.49	4,802.35
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,800.00

Report Ref No. CS/FCI19006267/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.