

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19006330/KEA3Q2

Date: 11/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800010442

Claimant
Vehicle No : SLV5069L **Insured Vehicle No :** SLW3255Z

Date of Loss: 29/03/2019 Nature of Claim: TP Claim No: 2841287702SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV5069L		
Make & Model:	TOYOTA C-HR, 1.2 (A)	Engine No:	2ZR8238217
Reg. Date:	29/12/2017 (Man. Year: 2017)	Chassis No:	ZYX102085469
Colour:	Metallic Blue	Odometer:	51296 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Bridgestone 3 mm	Rear Left Side:	Bridgestone 2 mm
Front Right Side:	Bridgestone 3 mm	Rear Right Side:	Bridgestone 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,866.59	9,373.66	4,492.93	32.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,550.00	2,250.00	2,300.00	50.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,416.59	11,623.66	6,792.93	36.88
+ GST 7.00/7.00% (S\$)	1,289.16	813.66	475.50	36.88
Nett Amount (S\$)	19,705.75	12,437.32	7,268.43	36.88
+ Car Rental (8.0 x S\$85.00/day) (S\$)		680.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		13,124.77		

INSPECTION

Date of Assignment: 09/04/2019

Date Inspected: 09/04/2019 Inspected At:

Esteem Performance Pte Ltd - Sin
Ming (HQ)
385 Sin Ming Drive
Singapore 575718

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Dented	45.00 FS	*45.00 FS
2	1		*FRONT NUMBER PLATE GARNISH	Cracked	89.70 FL	*89.70 FL
3	1		*FRONT GRILLE	Serviceable	422.92 FL	*- FL
4	1		*FRONT GRILLE EMBLEM	Cracked	1,641.20 FL	*1,641.20 FL
5	1		*FRONT BUMPER	Buckled	441.90 FL	*441.90 FL
6	10		*FRONT BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	487.30 FL	*487.30 FL
8	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	123.90 FL	*123.90 FL
9	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	123.90 FL	*- FL
10	1		*FRONT BUMPER BRACKET LH	Repair	201.50 FL	*- FL
11	1		*FRONT BUMPER BRACKET RH	Repair	201.50 FL	*- FL
12	1		*FRONT BUMPER SPONGE	Cracked	89.50 FL	*89.50 FL
13	2		*FRONT BUMPER SENSOR	Serviceable	379.60 FS	*- FS
14	1		*FRONT BUMPER LOWER GRILLE	Cracked	494.20 FL	*494.20 FL
15	2		*REVERSE SENSOR	Serviceable	379.60 FS	*- FS
16	1		*REAR BUMPER	Buckled	398.30 FL	*398.30 FL
17	10		*REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
18	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	97.80 FL	*- FL
19	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	97.80 FL	*- FL
20	1		*REAR BUMPER BRACKET LH	Repair	122.67 FL	*- FL
21	1		*REAR BUMPER BRACKET RH	Repair	122.67 FL	*- FL
22	1		*REAR BUMPER REINFORCEMENT	Bent	398.90 FL	*398.90 FL
23	1		*REAR BUMPER REFLECTOR LH	Serviceable	62.30 FL	*- FL
24	1		*REAR BUMPER REFLECTOR RH	Serviceable	62.30 FL	*- FL
25	1		*REAR BUMPER REFLECTOR GARNISH LH	Serviceable	108.70 FL	*- FL
26	1		*REAR BUMPER REFLECTOR GARNISH RH	Serviceable	108.70 FL	*- FL
27	1		*REAR BUMPER LOWER GARNISH CENTRE	Buckled	397.60 FL	*397.60 FL
28	1		*REAR BUMPER TOW COVER	Dented	21.69 FL	*21.69 FL
29	1		*TAIL DOOR	Bent	1,022.50 FL	*1,022.50 FL
30	1		*TAIL DOOR LOCK	Dented	478.40 FL	*478.40 FL
31	1		*TAIL DOOR EMBLEM	Necessary	61.70 FL	*61.70 FL
32	1		*WORDING CH-R	Necessary	51.36 FL	*51.36 FL
33	1		*WORDING HYBRID	Necessary	49.87 FL	*49.87 FL
34	1		*TAIL DOOR GARNISH	Serviceable	882.70 FL	*- FL
35	1		*TAILDOOR REFLECTOR LH	Serviceable	486.70 FL	*- FL
36	1		*TAILDOOR REFLECTOR RH	Serviceable	489.70 FL	*- FL
37	1		*TAIL END PANEL	Repair	701.25 FL	*- FL
38	1		*TAIL END PANEL GARNISH	Serviceable	295.50 FL	*- FL
39	8		*TAIL END PANEL GARNISH CLIP	Not Necessary	28.00 FL	*- FL
40	1		*BOOT WEATHERSTRIP	Serviceable	361.70 FL	*- FL
41	1		*BONNET	Bent	1,089.90 FL	*1,089.90 FL
42	1		*FRONT BUMPER UPPER BEAM	Buckled	168.30 FL	*168.30 FL
43	1		*HEADLAMP LH (LED)	Mtg Cracked	4,655.00 FL	*4,655.00 FL
44	10		*HEADLAMP LH CLIP	Necessary	35.00 FL	*35.00 FL
45	1		*FRONTBUMPER UPPER RETAINER	Distorted	77.49 FL	*77.49 FL
46	1		*FRONT BUMPER SPONGE LOWER	Cracked	84.50 FL	*84.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,220.72	12,483.21
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,354.13	3,109.55
Total Parts (\$\$)	13,866.59	9,373.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (REAR BUMPER ,TAILDOOR ,END PANEL,SPARE TYRE WELL PANEL)	New	1,600.00	600.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (REAR BUMPER ,TAILDOOR ,END PANEL,SPARE TYRE WELL PANEL)	New	1,400.00	1,000.00
3	TO CHECK WIRING	New	50.00	40.00
4	TO REMOVE & REFIT FRONT BUMPER SENSOR	New	120.00	50.00
5	TO REMOVE & REFIT REAR BUMPER SENSOR	New	120.00	50.00
6	TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPET TRIM TO ASSIST WORK LOAD	New	150.00	0.00
7	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
8	TO TUFF COAT	New	150.00	30.00
9	TO TRANSFER BOOT MECHANISM TO NEW BOOT	New	120.00	60.00
10	TO CONDUCT WATER SEEPAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	0.00
11	TO RENEW DAMAGE PARTS & KNOCK OUT ACCIDENT REPAIR AREA (BONNET)	New	300.00	100.00
12	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (BONNET)	New	300.00	200.00
Gross Labour Cost (\$\$)			4,550.00	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >