

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19006349/ADA3Q2

**Date:** 30/07/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	999994322
<b>Claimant</b>		
<b>Vehicle No :</b> GW3468K	<b>Insured Vehicle No :</b>	SMC7264P
Date of Loss: 09/04/2019	Nature of Claim: TP	Claim No: 2823423929SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GW3468K		
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Engine No:	HIDDEN
Reg. Date:	01/06/2003 (Man. Year: 2003)	Chassis No:	JTFUF34Y503001166
Colour:	White	Odometer:	491683 km
Engine Capacity:	2986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185 R15C	Rear Tyre Size:	155 R12C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,955.43	2,877.40	6,078.03	67.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,700.00	2,520.00	3,180.00	55.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,655.43</b>	<b>5,397.40</b>	<b>9,258.03</b>	<b>63.17</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,655.43</b>	<b>4,300.00</b>	<b>10,355.43</b>	<b>70.66</b>
<b>+ Car Rental (7.0 x S\$120.00/day + 7.00% GST) (S\$)</b>		898.80		
<b>Nett Liability (S\$)</b>		<b>5,198.80</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,150.00</b>		

### INSPECTION

Date of Assignment:	10/04/2019	
Date Inspected:	10/04/2019 Inspected At:	Ace Autolution Pte Ltd 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre Singapore 417807
Estimated Period of Repair:	6.0 days	

**Adjuster:** ADRIAN LING

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,837.50 FL	*1,248.00 FL
2	1		*REAR TAILGATE SIDE L BRACKET	Bent	166.00 FL	*166.00 FL
3	1		*REAR TAILGATE LAMP	Not Necessary	393.75 FL	*- FL
4	1		*REAR END PANEL (LOWER MEMBER)	Dented	1,341.90 FL	*495.00 FL
5	2		*REAR TAILLAMP LH & RH	Cracked	712.20 FL	*500.20 FL
6	2		*REAR LOWER MEMBER BRACKET	Not Necessary	390.81 FL	*- FL
7	1		*REAR CHASSIS FRAME (DECK SUPPORT)	Repair	1,659.00 FL	*- FL
8	1		*REAR FLOOR DECKING	Repair	2,079.00 FL	*- FL
9	1		*REAR CHASSIS FRAME U BOLTS	Not Necessary	367.50 FL	*- FL
10	1		*REAR EXHAUST PIPE	Bent	504.00 FL	*504.00 FL
11	1		*REAR EXHAUST PIPE BRACKET	Not Necessary	126.00 FL	*- FL
12	1		*REAR TOW HOCK	Not Necessary	78.75 FL	*- FL
13	2		*REAR TAILGATE STEP BRACKET	Damaged	168.00 FL	*168.00 FL
14	1		*REAR TAILGATE INNER ALUMINIUM COVER PLATE	Not Necessary	787.50 FL	*- FL
15	2		*REAR TAILGATE HINGE	Bent	170.00 FL	*170.00 FL
16	2		*REAR TAILGATE STOPPER LH&RH	Cut	70.00 FL	*70.00 FL
17	2		*REAR TAILLAMP PANEL LH & RH	Bent	302.00 FL	*302.00 FL
18	1		*SET REVERSE SENSOR	Not Necessary	300.00 FS	*- FS
19	1		*STICKER 13 PAX	Necessary	70.00 FS	*15.00 FS
20	1		*STICKER 70KM/H	Necessary	70.00 FS	*15.00 FS
21	1		*TAILGATE TOYOTA STICKER	Necessary	100.00 FS	*100.00 FS
22	1		*CAR PLATE	Bent	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,743.91</b>	<b>3,783.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>2,788.48</b>	<b>905.80</b>
<b>Total Parts (\$\$)</b>	<b>8,955.43</b>	<b>2,877.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO CONNENCE REPAIRS ,REPLACE PARTS	New	2,200.00	800.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED	New	1,600.00	800.00
3	TO CARRY OUT CHASSIS ALIGNMENT	New	350.00	350.00
4	TO REMOVE,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS	New	250.00	30.00
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	270.00	80.00
6	TO REMOVE AND REFIX REAR TAILLAMP	New	80.00	0.00
7	TO REMOVE AND REPLACE EXHAUST PIPE	New	150.00	80.00
8	TO REMOVE REAR DECK TO FACILITATE REPAIRS	New	800.00	380.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,700.00</b>	<b>2,520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >