

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 2191D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR SPARE TYRE BRACKET	SERVICEABLE	197.00	-
2	REAR SIGNAL LAMP @\$102.00 (N/S CRACKED)	O/S CRACKED / N/S OLD DAMAGED	204.00	102.00
1	REAR NUMBER PLATE LAMP	CRACKED	22.00	22.00
1	REAR NUMBER PLATE BRACKET	BENT	150.00	150.00
	LESS 15% DISCOUNT		-85.95	-41.10
			487.05	232.90
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	BENT	15.00	15.00
1	REAR BUMPER (SN)	BENT	300.00	300.00
2	REAR BUMPER BRACKET @\$100.00 (SN)	BENT	200.00	200.00
2	REAR CHASIS WOODEN BEAM @\$750.00 (SN) (CRACKED)	OLD DAMAGED	1,500.00	-
1	REAR WOODEN STEP (HORIZONTAL) (SN)	CRACKED	285.00	285.00
1	REAR SPARE TYRE (SN)	SERVICEABLE	280.00	-
			2,580.00	800.00
<u>LABOUR</u>				
	TO CHECK WIRING.	NOT NECESSARY	30.00	30.00
	TO LIFT UP REAR DECK.		400.00	-
	TO KNOCK, WELD, REMOVE & REFIT ABOVE PARTS.		800.00	350.00
	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS.		250.00	200.00
			1,480.00	580.00
GRAND TOTAL			4,547.05	1,612.90
RECOMMENDED COST OF REPAIRS				1,612.90

Report Ref No. CS/FCI19006371/R1td3e2

MARKET VALUE: \$21,000.00(EST)-LTA REIMBURSEMENT VALUE: \$7,709.00=NETT VALUE: \$13,291.00**MOHAMMED RASUL BIN MOHD YUNUS**

Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.