

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: FWD	DATE	: 08/04/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	: Asher		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: GY1121M		
MODEL	: TOYOTA HIACE MANUAL		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 5-Apr-19
		TIME	: 16:45HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE Bented	1	\$ 1,689.50	\$ 1,689.50
2	TAILGATE LOGO 3mm	1	\$ 68.00	\$ 68.00
3	TAILGATE HIACE STICKER	1	\$ 68.00	\$ 68.00
4	TAILGATE WEATHERSTRIP Lt	1	\$ 380.00	\$ 380.00
5	TAILGATE INNER LOCK Rgt.	1	\$ 270.00	\$ 270.00
6	TAILGATE LOWER LOCK new	1	\$ 116.30	\$ 116.30
7	TAILGATE WINDSCREEN MOULDING m	1	\$ 190.00	\$ 190.00
8	REAR BUMPER Disbld	1	\$ 526.00	\$ 526.00
9	REAR BUMPER STEP PANEL Best	1	\$ 388.20	\$ 388.20
10	REAR BUMPER SIDE RETAINER m	2	\$ 78.60	\$ 157.20
11	TAIL LAMP Cracked	2	\$ 355.30	\$ 710.60
12	TAILLAMP LOWER GARNISH cracked	2	\$ 122.20	\$ 244.40
13	TAILLAMP LOWER GARNISH RETAINER new	2	\$ 45.00	\$ 90.00
14	REAR END PANEL (INNER) Bented	1	\$ 630.00	\$ 630.00
15	REAR END PANEL (OUTER) Disbld	1	\$ 590.30	\$ 590.30
16	REAR EXHAUST PIPE 3m	1	\$ 980.00	\$ 980.00
17	REAR EXHAUST MOUNTING m	2	\$ 75.60	\$ 151.20

TOTAL PRICE \$ 7,249.70

5912.20
4434.15

LESS 25% \$ 1,812.43

SUB TOTAL PRICE \$ 5,437.28

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>the net</i>	1	\$ 50.00	\$ 50.00 <i>x</i>
2	TAILGATE WINDSCREEN SEALANT <i>net</i>	1	\$ 60.00	\$ 60.00 <i>-</i>
3	REAR BUMPER CLIP (SET) <i>net</i>	1	\$ 65.00	\$ 65.00 <i>30</i>
4	STICKER 70KM/H <i>net</i>	1	\$ 30.00	\$ 30.00 <i>10</i>
5	TAIL LAMP CLIP (SET) <i>net net</i>	2	\$ 45.00	\$ 90.00 <i>x</i>
6	REAR END PANEL (INNER) SEALANT <i>net net</i>	1	\$ 60.00	\$ 60.00 <i>x</i>
7	REAR END PANEL (OUTER) SEALANT <i>net</i>	1	\$ 60.00	\$ 60.00 <i>-</i>
8	REVERSE SENSOR <i>Revised</i>	1	\$ 220.00	\$ 220.00 <i>200</i>

360

TOTAL \$ 635.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING AND REPLACE PARTS	\$ 1,400.00	800 <i>1300</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	800 <i>1300</i>	
3	TUFF COAT	\$ 150.00	<i>60</i>	
4	WIRNING, BULB CHECKING	\$ 80.00	<i>30</i>	
5	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 160.00	<i>120</i>	
6	TRANSFER TAILGATE MECHAISM	\$ 120.00	<i>80</i>	
7	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	<i>50</i>	
8	TO REMOVE AND REFIX EXHAUST PIPE	\$ 250.00	<i>x</i>	

2940

TOTAL

\$3,640.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,072.28
TOTAL LABOUR COST : \$ 3,640.00
TOTAL REPAIR COST : \$ 9,712.28

*Adrian L
4/3 08/04/19
06 hrs*

total: 7734.15

*h/s: S.SK
(Nett Value)*

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: FWD	DATE	: 08/04/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: GY1121M		
MODEL	: TOYOTA HIACE MANUAL		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 5-Apr-19
		TIME	: 16:45HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	AIRVENT RH <i>crash d</i>	1	\$ 80.00	\$ 80.00
2	REAR FENDER RH <i>spare</i>	1	\$ 1,888.20	\$ 1,888.20

TOTAL PRICE \$ 1,968.20

LESS 25% \$ 492.05

SUB TOTAL PRICE \$ 1,476.15

Adrian Lj
10/04/19.