



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 413K

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--------------------|--|--------------------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | COVER TAIL LH (RED) (CUT) | NOT CONSISTENT WITH THE IMPACT | 90.00 | - |
| 1 | CRASH BAR | NOT NECESSARY | 195.00 | - |
| 1 | FOOTREST REAR ASSY LH | NOT NECESSARY | 15.00 | - |
| 1 | HANDLE SEAT (CUT) | NOT CONSISTENT WITH THE IMPACT | 98.00 | - |
| 1 | HANDLE ASSY | CRACKED | 147.00 | 147.00 |
| 1 | METER IU (12V) NEW MODEL | NOT NECESSARY | 200.00 | - |
| 1 | MUDGUARD FRONT (RED) | CRACKED | 98.00 | 98.00 |
| 1 | PROTECTOR MUFFLER (REAR) | NOT NECESSARY | 32.00 | - |
| 1 | PROTECTOR MUFFLER 3 | NOT NECESSARY | 145.00 | - |
| | LESS 10% DISCOUNT | | - | -24.50 |
| | | | 1,020.00 | 220.50 |
| | <u>LABOUR</u> | | | |
| | LABOUR - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED. | | 105.00 | 60.00 |
| | TRANSPORT CHARGES. | | 35.00 | 35.00 |
| | | | 140.00 | 95.00 |
| GRAND TOTAL | | | 1,160.00 | 315.50 |

| | | | | |
|------------------------------------|--|--|--|---------------|
| RECOMMENDED COST OF REPAIRS | | | | 315.50 |
|------------------------------------|--|--|--|---------------|

Report Ref No. CC6/EQ19006398/Ups3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.