Shirley Hiew (LKK Auto)

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Tuesday, 25 February 2020 2:24 pm

To: SUR

Cc: Lim, Kok-Chong; Fong, Andy-SY

Subject: RE: Fw: Re: Alert - Adj Mandate Maintained - SLT8155L - Claim Handler: Gan,

Hunchung

Hi Shirley,

Where is the damage? No damage photos to take out.



36/60: General View



37/60: General View



37/60: General View

Thanks & Regards

Victor Koh AIG

Claims Technical Controller Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120 Tel +65 6419 1785 | Fax +65 68357416 <u>Victor-ck.koh@aig.com</u> | www.aig.com

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]

Sent: Tuesday, February 25, 2020 11:20 AM

To: Koh, Victor-CK

Cc: Lim, Kok-Chong; Fong, Andy-SY; sur@lkkauto.com

Subject: [EXTERNAL] Fw: Re: Alert - Adj Mandate Maintained - SLT8155L - Claim Handler: Gan, Hunchung

This message is from an external sender; be cautious with links and attachments.

This mail is associated with:
*SLT8155L (2160517999SG)
OD
Apr 9 2019 9:10AM
[LEE ZHEN JIAN]
Premium Automobiles Pte Ltd

RE-SEND

Dear Victor,

We refer to your below email above matter.

According to our surveyor, to remove the LH door chrome moulding, the door inner trim board has to be removed to facilitate the replacement of the door chrome moulding.

The condenser Photo please refer to the no. 36, 37, 39.

Hope that the above clarifies matter and kindly let us have your mandate approval.

Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->

From: LKK_HQ

To: victor-ck.koh@aig.com

CC: Kok-Chong.Lim@aig.com; Andy-SY.Fong@aig.com; sur@lkkauto.com

Sent On: 25/02/2020 11:15 AM

Subject: Re: Alert - Adj Mandate Maintained - SLT8155L - Claim Handler: Gan, Hunchung

Dear Victor,

We refer to your below email above matter.

According to our surveyor, to remove the LH door chrome moulding, the door inner trim board has to be removed to facilitate the replacement of the door chrome moulding. Hope that the above clarifies matter and kindly let us have your mandate approval.

Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->

From: AIG_SG To: LKK_HQ

Sent On: 21/01/2020 11:05 AM

Subject: Alert - Adj Mandate Maintained - SLT8155L - Claim Handler: Gan, Hunchung

Maintained:Labour 2 only remove 1 side why at \$600.00? Condenser, Bowden cable damage photos?

This is an auto-generated email. Do not reply to this email.

Sent by: Hiew May Fung (LKK Auto Consultants Pte Ltd)