

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG19006443/ASD3E2

Date: 01/12/2020

REFERENCE

Insured/Claimant:	LEE ZHEN JIAN	Policy No:	1700052840-01	
Date of Loss:	09/04/2019	Nature of Claim:	OD	Claim No: 2160517999SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT8155L			
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)		Engine No:	CVN041502
Reg. Date:	25/09/2017 (Man. Year: 2017)		Chassis No:	WAUZZZF48HA182383
Colour:	Silver		Odometer:	25923 km
Engine Capacity:	1395 cc			
Market Value/New Car Price:	S\$112,000.00			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,350.60	17,974.32	17,376.28	49.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,552.00	6,802.00	5,750.00	45.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	47,902.60	24,776.32	23,126.28	48.28
- Excess (\$\$)	300.00	300.00	0.00	0.00
(\$\$)	47,602.60	24,476.32	23,126.28	48.58
+ GST 7.00/7.00% (\$\$)	3,332.18	1,713.34	1,618.84	48.58
Nett Amount (\$\$)	50,934.78	26,189.66	24,745.12	48.58

INSPECTION

Date of Assignment:	11/04/2019	
Date Inspected:	10/04/2019	Inspected At:
		Premium Automobiles Pte Ltd (UBI)
		55 Ubi Road 1
		Singapore 408699
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Distorted	1,703.00 FS	*1,362.40 FS
2	1		*FIXING PARTS FOR FRONT BUMPER	Not Necessary	240.00 FS	*- FS
3	2		*SECURING STRIP FOR FRONT BUMPER	Not Necessary	57.00 FS	*- FS
4	1		*FRONT CENTER GRILLE	Not Necessary	163.00 FS	*- FS
5	1		*CLOSING ELEMENT	Not Necessary	171.00 FS	*- FS
6	1		*AIR GUIDE GRILLE FOR FRONT BUMPER - LH	Not Necessary	67.00 FS	*- FS
7	1		*AIR GUIDE GRILLE FOR FRONT BUMPER - RH	Not Necessary	67.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	941.00 FS	*752.40 FS
9	1		*AIR GUIDE GRILLE - LH	Not Necessary	112.00 FS	*- FS
10	1		*AIR GUIDE GRILLE - RH	Not Necessary	112.00 FS	*- FS
11	1		*FOAM FILLER PIECE	Cracked	101.00 FS	*90.40 FS
12	1		*BUMPER CARRIER	Not Necessary	674.00 FS	*- FS
13	1		*GUIDE SECTION - LH	Not Necessary	29.00 FS	*- FS
14	1		*GUIDE SECTION - RH	Not Necessary	31.00 FS	*- FS
15	1		*BUMPER COVER	Cracked	104.00 FS	*82.80 FS
16	1		*CAUTION SIGN	Necessary	12.00 FS	*9.76 FS
17	1		*STICKER FOR AIR CONDITIONER	Necessary	6.00 FS	*5.12 FS
18	1		*BRACKET FOR LOCK CARRIER	Cracked	112.00 FS	*89.20 FS
19	1		*SUPPORT - LH	Damaged	23.00 FS	*20.32 FS
20	1		*SUPPORT - RH	Damaged	23.00 FS	*20.32 FS
21	1		*FRONT FENDER - LH	Repair	643.00 FS	*- FS
22	1		*FRONT FENDER - RH	Buckled	643.00 FS	*514.40 FS
23	2		*ATTACHMENT PARTS FOR FENDER	Not Necessary	365.00 FS	*- FS
24	1		*CLOSING ELEMENT - LH	Not Necessary	29.00 FS	*- FS
25	1		*CLOSING ELEMENT - RH	Damaged	36.00 FS	*36.00 FS
26	1		*BRACKET FOR FENDER - LH	Not Necessary	29.00 FS	*- FS
27	1		*BRACKET FOR FENDER - RH	Not Necessary	29.00 FS	*- FS
28	1		*BRACKET FOR DEFORMATION ELEMENT - RH	Necessary	42.00 FS	*35.60 FS
29	1		*BRACE - FRONT LH	Not Necessary	100.00 FS	*- FS
30	1		*BRACE - FRONT RH	Not Necessary	100.00 FS	*- FS
31	1		*WHEEL HOUSING LINER - LH	Not Necessary	208.00 FS	*- FS
32	1		*WHEEL HOUSING LINER - RH	Not Necessary	202.00 FS	*- FS
33	2		*ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Not Necessary	152.00 FS	*- FS
34	1		*WHEEL SPOILER - LH	Not Necessary	61.00 FS	*- FS
35	1		*WHEEL SPOILER - LH	Not Necessary	66.00 FS	*- FS
36	1		*STONE CHIP GUARD	Necessary	46.00 FS	*36.64 FS
37	1		*BONNET	Dented	2,001.00 FS	*1,600.80 FS
38	1		*ATTACHMENT PARTS FOR BONNET	Not Necessary	103.00 FS	*- FS
39	1		*LID HINGE - LH	Not Necessary	257.00 FS	*- FS
40	1		*LID HINGE - RH	Not Necessary	257.00 FS	*- FS
41	1		*IMPACT PROTECTION - CENTER	Necessary	23.00 FS	*19.76 FS
42	1		*IMPACT PROTECTION - LH	Not Necessary	23.00 FS	*- FS
43	1		*IMPACT PROTECTION - RH	Necessary	23.00 FS	*19.76 FS
44	1		*COVER - LH	Not Necessary	28.00 FS	*- FS
45	1		*COVER - RH	Damaged	28.00 FS	*22.24 FS
46	1		*COVER FOR IMPACT PROTECTION - LH	Not Necessary	19.00 FS	*- FS
47	1		*COVER FOR IMPACT PROTECTION - RH	Damaged	19.00 FS	*16.16 FS
48	2		*GAS FILLED STRUT	Not Necessary	196.00 FS	*- FS
49	1		*STRIKER - LH	Not Necessary	43.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*STRIKER - RH	Not Necessary	43.00 FS	*- FS
51	2		*LID LOCK	Not Necessary	360.00 FS	*- FS
52	1		*BOWDEN CABLE - CENTER	Damaged	49.00 FS	*41.68 FS
53	1		*COVER	Damaged	9.60 FS	*9.60 FS
54	1		*BOWDEN CABLE	Not Necessary	49.00 FS	*- FS
55	1		*RELEASE LEVER	Not Necessary	12.00 FS	*- FS
56	1		*LID LOCK CABLE	Not Necessary	67.00 FS	*- FS
57	1		*SOUND ABS FOR ENGINE BONNET	Not Necessary	311.00 FS	*- FS
58	1		*FAN FARE HIGH TONE - LH	Not Necessary	35.00 FS	*- FS
59	1		*FAN FARE LOW TONE - RH	Not Necessary	248.00 FS	*- FS
60	1		*SPRING SHACKLE - LH	Not Necessary	26.00 FS	*- FS
61	1		*SPRING SHACKLE - RH	Not Necessary	26.00 FS	*- FS
62	1		*LED HEADLIGHT - LH	Cracked	7,861.00 FS	*6,288.80 FS
63	1		*LED HEADLIGHT - RH	Cracked	7,861.00 FS	*6,288.80 FS
64	1		*LIFT CYLINDER - LH	Not Necessary	180.00 FS	*- FS
65	1		*LIFT CYLINDER - RH	Not Necessary	180.00 FS	*- FS
66	1		*LOCK CARRIER WITH MOUNTING FOR RADIATOR	Not Necessary	878.00 FS	*- FS
67	1		*A/C CONDENSER WITH DRYER	Not Necessary	568.00 FS	*- FS
68	1		*COOLER FOR COOLANT	Not Necessary	576.00 FS	*- FS
69	2		*RUBBER BUSH - LOWER	Not Necessary	16.00 FS	*- FS
70	2		*RUBBER BUSH	Not Necessary	22.00 FS	*- FS
71	1		*ADDITIONAL COOLER FOR COOLANT	Not Necessary	444.00 FS	*- FS
72	4		*PREMIX COOLANT	Necessary	81.00 FS	*67.20 FS
73	1		*AIR GUIDE - LH	Deformed	22.00 FS	*19.84 FS
74	1		*AIR GUIDE - RH	Deformed	22.00 FS	*19.84 FS
75	1		*AIR GUIDE - LH	Deformed	10.00 FS	*8.32 FS
76	1		*AIR GUIDE - RH	Deformed	10.00 FS	*8.32 FS
77	1		*AIR GUIDE - UPPER	Not Necessary	13.00 FS	*- FS
78	1		*AIR GUIDE - LOWER	Not Necessary	17.00 FS	*- FS
79	1		*FAN RING	Not Necessary	222.00 FS	*- FS
80	1		*RADIATOR FAN WITH CONTROL UNIT	Not Necessary	2,107.00 FS	*- FS
81	1		*INTAKE AIRDUCT	Not Necessary	17.00 FS	*- FS
82	1		*AIR GUIDE	Not Necessary	48.00 FS	*- FS
83	1		*SEAL	Not Necessary	12.00 FS	*- FS
84	1		*AIR FILTER	Not Necessary	352.00 FS	*- FS
85	1		*INTAKE HOSE	Not Necessary	85.00 FS	*- FS
86	1		*WINDOW SLOT SEAL WITH TRIM STRIP - LH	Cut	259.00 FS	*207.20 FS
87	1		*WINDOW SLOT SEAL WITH TRIM STRIP - RH	Cut	259.00 FS	*207.20 FS
88	1		*TRIM STRIP FOR WINDOW GUIDE - LH	Not Necessary	217.00 FS	*- FS
89	1		*TRIM STRIP FOR WINDOW GUIDE - RH	Not Necessary	217.00 FS	*- FS
90	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*40.00 FS
91	1		*SUNDRIES	Necessary	1,000.00 FS	*33.44 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **35,350.60** **17,974.32**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH FRONT WING MIRROR ASSY	New	600.00	300.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,200.00	1,200.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BOTH HEADLIGHTS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	2,000.00
5	TO RESPRAY FRONT BUMPER, BONNET HINGES, BOTH FRONT FENDER, BONNET AND BOTH FRONT DOORS	New	4,600.00	2,750.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			12,552.00	6,802.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >