Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19005551/BPA3Q2

Date: 17/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: M489426/03

Claimant SGX6848Y Insured Vehicle No: 5350SSHA7678

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGX6848Y

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4685223

Reg. Date: 03/09/2007 (Man. Year: 2007) Chassis No: MR053ZEC107152992

Colour: Silver Odometer: 129825 km

Engine Capacity: 1598 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
3,700.30	1,954.74	1,745.56	47.17
0.00	0.00	0.00	
2,905.00	1,060.00	1,845.00	63.51
0.00	0.00	0.00	
0.00	0.00	0.00	
6,605.30	3,014.74	3,590.56	54.36
	2,400.00		
6,605.30	2,400.00	4,205.30	63.67
60.00/day) (S\$)	420.00		
+ Doc/Search Fee (S\$)			
tt Liability (S\$)	2,827.45		
settlement (S\$)	2,800.00		
t	3,700.30 0.00 2,905.00 0.00 0.00 6,605.30 6,605.30 6,605.30 6,605.30 6,605.30 6,605.30	3,700.30 1,954.74 0.00 0.00 2,905.00 1,060.00 0.00 0.00 0.00 0.00 6,605.30 3,014.74 2,400.00 6,605.30 2,400.00 6,605.30 420.00 earch Fee (S\$) 7.45 tt Liability (S\$) 2,827.45	3,700.30 1,954.74 1,745.56 0.00 0.00 0.00 2,905.00 1,060.00 1,845.00 0.00 0.00 0.00 0.00 0.00 0.00 6,605.30 3,014.74 3,590.56 2,400.00 6,605.30 2,400.00 4,205.30 60.00/day) (\$\$) 420.00 earch Fee (\$\$) 7.45 tt Liability (\$\$) 2,827.45

INSPECTION

Date of Assignment: 28/03/2019

Date Inspected: 28/03/2019 Inspected At: Supreme Auto Service Pte Ltd (HQ)

176 Sin Ming Drive #02-01, Sin Ming

Autocare

Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster Report Page 2 of 4

Adjuster: Lim Teow Guan Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference
Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Dec 2019)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGX6848Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Candition

Donoiror'o

Amount

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No Oty Bort No

				•	Amount
1		*FRONT BUMPER	Dented	567.40 FL	*447.25 FL
1		*FRONT BUMPER SIDE RETAINER	Necessary	56.80 FL	*23.90 FL
1		*FRONT BUMPER FOG LAMP	Missing	246.70 FL	*246.70 FL
1		*FRONT BUMPER REINFORCEMENT	No Damage	341.20 FL	*- FL
1		*FRONT FENDER RH	Dented	477.70 FL	*477.70 FL
1		*FRONT FENDER DUST COVER	Dented	192.60 FL	*192.60 FL
8		*FRONT FENDER DUST COVER CLIP	Necessary	20.80 FL	*20.80 FL
1		*FRONT HEAD LAMP ASSY	Cut	765.70 FL	*445.20 FL
1		*FRONT WIPER WASHER TANK	Dented	267.40 FL	*210.40 FL
1		*FRONT SHOCK ABSORBER	No Damage	567.70 FL	*- FL
1		*FRONT LOWER ARM RH	Dented	576.40 FL	*275.10 FL
1		*ALLOY RIM (LOCAL REPAIR)	Cut	480.00 FS	*200.00 FS
1		*TYRE-MICHELIN 195/65R15	No Damage	160.00 FS	*- FS
nchise	part. S=SpcN	ett. L=ListItemDisc.			
			Sub Total (S\$)	4,720.40	2,539.65
		- List Item Discount on L Items 25	5.00/25.00% (S\$) _	1,020.10	584.91
			Total Parts (S\$)	3,700.30	1,954.74
	1 8 1 1 1 1 1	1 8 1 1 1 1 1 1	1 *FRONT BUMPER SIDE RETAINER 1 *FRONT BUMPER FOG LAMP 1 *FRONT BUMPER REINFORCEMENT 1 *FRONT FENDER RH 1 *FRONT FENDER DUST COVER 8 *FRONT FENDER DUST COVER CLIP 1 *FRONT HEAD LAMP ASSY 1 *FRONT WIPER WASHER TANK 1 *FRONT SHOCK ABSORBER 1 *FRONT LOWER ARM RH 1 *ALLOY RIM (LOCAL REPAIR) 1 *TYRE-MICHELIN 195/65R15 nchise part. S=SpcNett. L=ListItemDisc.	1 *FRONT BUMPER SIDE RETAINER Necessary 1 *FRONT BUMPER FOG LAMP Missing 1 *FRONT BUMPER REINFORCEMENT No Damage 1 *FRONT FENDER RH Dented 1 *FRONT FENDER DUST COVER Dented 8 *FRONT FENDER DUST COVER CLIP Necessary 1 *FRONT HEAD LAMP ASSY Cut 1 *FRONT WIPER WASHER TANK Dented 1 *FRONT SHOCK ABSORBER No Damage 1 *FRONT LOWER ARM RH Dented 1 *ALLOY RIM (LOCAL REPAIR) Cut 1 *TYRE-MICHELIN 195/65R15 No Damage nchise part. S=SpcNett. L=ListItemDisc.	1 *FRONT BUMPER SIDE RETAINER Necessary 56.80 FL 1 *FRONT BUMPER FOG LAMP Missing 246.70 FL 1 *FRONT BUMPER REINFORCEMENT No Damage 341.20 FL 1 *FRONT FENDER RH Dented 477.70 FL 1 *FRONT FENDER DUST COVER Dented 192.60 FL 8 *FRONT FENDER DUST COVER CLIP Necessary 20.80 FL 1 *FRONT HEAD LAMP ASSY Cut 765.70 FL 1 *FRONT WIPER WASHER TANK Dented 267.40 FL 1 *FRONT SHOCK ABSORBER No Damage 567.70 FL 1 *FRONT LOWER ARM RH Dented 576.40 FL 1 *ALLOY RIM (LOCAL REPAIR) Cut 480.00 FS 1 *TYRE-MICHELIN 195/65R15 No Damage 160.00 FS nchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) 4,720.40 - List Item Discount on L Items 25.00/25.00% (S\$) 1,020.10

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE ,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	1,000.00	500.00
TO CHECK WIRING SYSTEM	New	40.00	20.00
TO APPLY RUST PROOFING ON AFFECTED AREAS	New	120.00	0.00
TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS	New	120.00	0.00
TO REMOVE AND INSTALL FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR	New	220.00	80.00
TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT	New	85.00	60.00
TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	400.00
TO REPLACE ALLOY RIMS AND PERFORM WHEEL BALANCING	New	60.00	0.00
TOWING CHARGES	New	60.00	0.00
Gross Labou	2,905.00	1,060.00	
Report was unsubmitted durir	ng this print-out.		
	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE ,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS TO CHECK WIRING SYSTEM TO APPLY RUST PROOFING ON AFFECTED AREAS TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS TO REMOVE AND INSTALL FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS TO REPLACE ALLOY RIMS AND PERFORM WHEEL BALANCING TOWING CHARGES Gross Labour	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS TO CHECK WIRING SYSTEM New TO APPLY RUST PROOFING ON AFFECTED AREAS TO APPLY WATERPROOF SEALANT ON AFFECTED New AREAS TO REMOVE AND INSTALL FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT New AREAS TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED New AREAS TO REPLACE ALLOY RIMS AND PERFORM WHEEL New BALANCING	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE ,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS TO CHECK WIRING SYSTEM New 40.00 TO APPLY RUST PROOFING ON AFFECTED AREAS TO REMOVE AND INSTALL FRONT UNDERCARRIAGE TO REMOVE AND INSTALL FRONT UNDERCARRIAGE TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED New 1,200.00 AREAS TO REPLACE ALLOY RIMS AND PERFORM WHEEL New 60.00 Gross Labour Cost (S\$) Cross Labour Cost (S\$)

< END OF ESTIMATES >