



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 3156B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT LID EMBLE LOGO (CONSISTENT)	NOT NECESSARY	60.00	-
3	REAR BOOT LID EMBLE LOGO CLIPS @\$3.50 (CONSISTENT)	NOT NECESSARY	10.50	-
1	REAR BOOT LID CNC LOGO (CONSISTENT)	NOT NECESSARY	55.00	-
1	REAR BOOT LID LAMP -RH (CONSISTENT)	NOT NECESSARY	525.00	-
1	REAR BUMPER (CONSISTENT)	TORN	1,746.00	1,458.00
1	SET REAR REVERSE SENSOR (CONSISTENT)	NOT NECESSARY	500.00	-
1	REAR BUMPER SIDE BRACKET (CONSISTENT)	NECESSARY	118.00	118.00
1	REAR BUMPER SIDE MOULDING -RH (CONSISTENT)	CUT	138.00	138.00
1	REAR FENDER -RH (CONSISTENT)	DENTED	1,770.00	1,770.00
1	REAR FENDER INNER PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	855.00	-
1	REAR TAIL LAMP -RH (CONSISTENT)	NOT NECESSARY	825.00	-
1	REAR R/H WHEEL BEARING HUP (CONSISTENT)	DAMAGED	366.00	366.00
1	REAR R/H LOWER ARM (CONSISTENT)	BENT	472.00	472.00
1	REAR SHOCK ABSORBER -RH (CONSISTENT)	NOT NECESSARY	588.00	-
1	REAR R/H WHEEL BEARING (CONSISTENT)	NECESSARY	385.00	385.00
1	REAR R/H CONTROL ARM (CONSISTENT)	NOT NECESSARY	747.00	-
1	REAR R/H DOOR (CONSISTENT)	DENTED	2,150.00	1,682.00
1	REAR R/H DOOR TOP MOULDING (CONSISTENT)	NOT NECESSARY	225.00	-
1	REAR R/H DOOR TOP MOULDING RUBBER (CONSISTENT)	NOT NECESSARY	155.00	-
1	REAR R/H DOOR TOP INNER RUBBER (CONSISTENT)	NOT NECESSARY	128.00	-
1	REAR EXHAUST (CONSISTENT)	NOT NECESSARY	1,523.00	-
1	REAR EXHAUST CHROME PIPE (CONSISTENT)	NOT NECESSARY	277.00	-
1	DOOR MIRROR GLASS (CONSISTENT)	NOT NECESSARY	608.00	-
1	DOOR MIRROR COVER (CONSISTENT)	DAMAGED	255.00	255.00
1	DOOR MIRROR HOUSING (CONSISTENT)	DAMAGED	882.00	882.00
	LESS 10% DISCOUNT		-	-752.60
			15,363.50	6,773.40

Report Ref No. CC4/ASM19006510/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TYRE -RH (CONSISTENT) (SN)	PUNCTURE	800.00	250.00
1	REAR RIM -RH (CONSISTENT) (SN)	CUT	900.00	600.00
			1,700.00	850.00
	<u>LABOUR</u>			
	TO REMOVE & REFIX REAR UNDERCARRIAGE.		450.00	220.00
	TO RESET COMPUTER.	NOT NECESSARY	200.00	-
	TO REMOVE REAR REVERSE SENSOR .		120.00	60.00
	TO CHECK WIRING SYSTEM.		60.00	30.00
	TOWING CHARGES.		100.00	100.00
	TUFF KOTE.		120.00	60.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FENDER INNER PANEL .		1,000.00	800.00
	SPRAY PAINTING.		1,000.00	800.00
			3,050.00	2,070.00
	GRAND TOTAL		20,113.50	9,693.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,700.00

Report Ref No. CC4/ASM19006510/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.