



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 7460E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (WCP) (CONSISTENT)	BUCKLED	270.00	270.00
1	L/R BUMPER BRACKET (WCP) (CONSISTENT)	SERVICEABLE	35.00	-
1	R/R BUMPER BRACKET (WCP) (CONSISTENT)	SERVICEABLE	35.00	-
1	RR BUMPER CLAMP KIT (WCP) (CONSISTENT)	NECESSARY	15.00	15.00
1	REAR NO PLATE TRIM (WCP) (CONSISTENT)	SERVICEABLE	130.00	-
1	REAR PANEL (WCP) (CONSISTENT)	BENT	195.00	195.00
1	BOOTLID/TAILGATE (WCP) (CONSISTENT)	BENT	530.00	530.00
1	BOOT/TAILGATE SEAL (WCP) (CONSISTENT)	DISTORTED / DENTED	105.00	105.00
1	LOCKING PLATE (WCP) (CONSISTENT)	* CHECK	20.00	-
1	BOOT/TAILGATE LOCK (WCP) (CONSISTENT)	DENTED	145.00	145.00
1	MANUFACTURE BADGE (WCP) (CONSISTENT)	NECESSARY	38.00	38.00
1	UPP R-SCREEN SEAL (WCP) (CONSISTENT)	NECESSARY	20.00	20.00
1	LWR REAR SCREEN SEAL (WCP) (CONSISTENT)	NECESSARY	20.00	20.00
1	L/R WINDOW SEAL (WCP) (CONSISTENT)	NECESSARY	20.00	20.00
1	R/R WINDOW SEAL (WCP) (CONSISTENT)	NECESSARY	20.00	20.00
1	END PANEL TRIM (WCP) (CONSISTENT)	* CHECK	130.00	-
1	L/R BUMPER SUPPORT (WCP) (CONSISTENT)	* CHECK	33.00	-
1	R/R BUMPER SUPPORT (WCP) (CONSISTENT)	* CHECK	33.00	-
1	VALVEMATIC EMBLEM (WCP) (CONSISTENT)	NECESSARY	35.00	35.00
	COST PLUS 15%		274.35	211.95
			2,103.35	1,624.95
SPECIAL NETT ITEMS				
1	AUDATEX FEE (SN) (CONSISTENT)	NECESSARY	42.00	42.00
1	REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	220.00	200.00
1	REVERSE CAMERA (SN) (CONSISTENT)	SERVICEABLE	380.00	-
1	REAR NUMBER PLATE (SN) (CONSISTENT)	SERVICEABLE	40.00	-
1	REAR WS SEALANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR WS DAMPING SEAL (SN) (CONSISTENT)	NECESSARY	20.00	20.00
			742.00	302.00

Report Ref No. CC4/ASM19006513/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR 158.0 WU X 45.00 SGD/H. LABOUR COST 130.0 WU X 45.00 SGD/H. MATERIAL COST.		711.00 585.00 231.05 1,527.05	711.00 585.00 231.05 1,527.05
	GRAND TOTAL		4,372.40	3,454.00
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$248.40 NETT)			3,454.00

Report Ref No. CC4/ASM19006513/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.