



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 2942U

| Qty | Description of Parts                                                                                                                                               | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>                                                                                                                                 |                      |                           |                   |
| 1   | REAR BUMPER (CONSISTENT)                                                                                                                                           | DEFORMED             | 530.00                    | 200.00            |
| 1   | REAR BUMPER RETAINER LH (CONSISTENT)                                                                                                                               | NECESSARY            | 60.00                     | 28.00             |
| 1   | REAR BUMPER RETAINER RH (CONSISTENT)                                                                                                                               | NECESSARY            | 60.00                     | 28.00             |
| 1   | REAR BUMPER CORNER RETAINER RH (CONSISTENT)                                                                                                                        | NECESSARY            | 60.00                     | 28.00             |
| 1   | REAR BUMPER CORNER RETAINER LH (CONSISTENT)                                                                                                                        | NECESSARY            | 60.00                     | 28.00             |
| 6   | REAR BUMPER CLIP (CONSISTENT)                                                                                                                                      | NECESSARY            | 44.00                     | 9.00              |
| 1   | REAR BUMPER STAY RH (CONSISTENT) (NPA)                                                                                                                             | NOT NECESSARY        | -                         | -                 |
| 1   | REAR BUMPER STAY LH (CONSISTENT) (NPA)                                                                                                                             | NOT NECESSARY        | -                         | -                 |
| 1   | REAR END PANEL (CONSISTENT)                                                                                                                                        | TO REPAIR SEE LABOUR | 660.00                    | -                 |
| 1   | REAR END PANEL TOP GARNISH (CONSISTENT) }                                                                                                                          | CUT                  | 269.00                    | 110.00            |
| 4   | REAR END PANEL TOP GARNISH CLIP (CONSISTENT) }                                                                                                                     |                      | -                         | -                 |
| 1   | TAILGATE WEATHERSTRIP (CONSISTENT)                                                                                                                                 | TWISTED              | 355.00                    | 105.00            |
| 1   | TAILGATE ESTIME EMBLEM (CONSISTENT)                                                                                                                                | NECESSARY            | 48.00                     | 25.00             |
| 1   | REAR LOGO (CONSISTENT)                                                                                                                                             | NECESSARY            | 48.00                     | 28.00             |
|     |                                                                                                                                                                    |                      | 2,194.00                  | 589.00            |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                                                                                                                                   |                      |                           |                   |
| 4   | REVERSE SENSOR (CONSISTENT) (SN)                                                                                                                                   | DAMAGED              | 200.00                    | 200.00            |
|     |                                                                                                                                                                    |                      | 200.00                    | 200.00            |
|     | <b><u>LABOUR</u></b>                                                                                                                                               |                      |                           |                   |
|     | TO CUT,WELD ON REAR END PANEL ,REPAIR AFFECTED AREAS,REPLACE DAMAGE PARTS AND REALIGN AFFECTED ARES TO REPAIR TAILGATE.INCLUSIVE OF THE REPAIR OF REAR END PANEL . |                      | 1,000.00                  | 200.00            |
|     | TO PUTTY ,RESPRAY ON REAR TAILGATE ,BUMPER FENDERS,END PANEL,FLOOR PANEL AND AFFECTED AREAS.                                                                       |                      | 1,000.00                  | 500.00            |
|     | TO TUFF KOTE ON REAR AFFECTED AREAS.                                                                                                                               | NOT NECESSARY        | 150.00                    | -                 |
|     | TO CHECK LIGHTING AND WIRING ,REPLACE REVERSE SENSOR.                                                                                                              |                      | 80.00                     | 40.00             |
|     | TO REMOVE INTERIOR UPHOLSTERY TO ASSIST REPAIR AND REFIT TO REMOVE REAR BACK SEAT TO ASSIST REPAIR AND CHECK FOR DAMAGE (JAMMED).                                  |                      | 180.00                    | 60.00             |
|     |                                                                                                                                                                    |                      | 2,410.00                  | 800.00            |
|     | <b>GRAND TOTAL</b>                                                                                                                                                 |                      | <b>4,804.00</b>           | <b>1,589.00</b>   |



|                             |  |  |                 |
|-----------------------------|--|--|-----------------|
| RECOMMENDED COST OF REPAIRS |  |  | <b>1,589.00</b> |
|-----------------------------|--|--|-----------------|

Report Ref No. CC6/AXA14021304/Gza3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.