

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Apr 2019 Edit Reg		12 Apr 2019 00:00 Edit Adj Rpt	S\$13,800.00 Edit Estimates	S\$13,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: CHIN JERH YUEN DEBBIE , ID: S1551257A									
Main Claimant: UNAG LOGISTICS PTE LTD , Co. Reg. No.: 201601737W									
Vehicle Reg. No.:	SKA7901T	Date of Loss:	07/04/2019 00:00 - :59 [96 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9144335274SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SKS6915R	Policy No. (Claimant):	5092970589-01						
		Excess:							
Repairer: Precise Auto Services (HQ) NO.1 KAKI BUKIT AVE 6 #02-34/36, 417883 Kaki Bukit - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 24/04/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (14/07/2020): Alert - Adj Mandate Approved (S\$18074.00) - SKA7901T - Claim Handler: MdNoor, No... - AIG_SG_EXPRESS (24/06/2020): Alert - Adj Mandate Maintained - SKA7901T - Claim Handler: MdNoor, Norsiah - AIG_SG_EXPRESS (29/05/2020): Alert - Adj Mandate Approved (S\$17474.00) - SKA7901T - Claim Handler: MdNoor, No... - AIG_SG_EXPRESS (08/01/2020): Alert - Adj Mandate Approved (S\$17474.00) - SKA7901T - Claim Handler: MdNoor, No... - AIG_SG (23/04/2019): Re: Request for OI GIA report - AIG_SG (22/04/2019): Re: Request for OI GIA report - AIG_SG (15/04/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKA7901T (9144335274SG)**
[SKS6915R]

TP

UNAG LOGISTICS PTE LTD

Apr 7 2019 12:00AM

[CHIN JERH YUEN DEBBIE]

Precise Auto Services

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#)

Letters/Correspondences

1 per page ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit	☐

Photos/Images

3 per page ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/10/19 16:20	General View	 Load JPG ☒	☒
2	11/10/19 16:20	General View	 Load JPG ☒	☒
3	11/10/19 16:20	General View	 Load JPG ☒	☒
4	11/10/19 16:20	General View	 Load JPG ☒	☒
5	11/10/19 16:20	General View	 Load JPG ☒	☒
6	11/10/19 16:20	General View	 Load JPG ☒	☒
7	11/10/19 16:20	General View	 Load JPG ☒	☒
8	11/10/19 16:20	General View	 Load JPG ☒	☒
9	11/10/19 16:20	General View	 Load JPG ☒	☒
10	11/10/19 16:20	General View	 Load JPG ☒	☒
11	11/10/19 16:20	General View	 Load JPG ☒	☒
12	11/10/19 16:20	General View	 Load JPG ☒	☒
13	11/10/19 16:20	General View	 Load JPG ☒	☒
14	11/10/19 16:20	General View	 Load JPG ☒	☒
15	11/10/19 16:20	General View	 Load JPG ☒	☒
16	11/10/19 16:20	General View	 Load JPG ☒	☒
17	11/10/19 16:20	General View	 Load JPG ☒	☒
18	11/10/19 16:20	General View	 Load JPG ☒	☒
19	11/10/19 16:20	General View	 Load JPG ☒	☒
20	11/10/19 16:20	General View	 Load JPG ☒	☒
21	11/10/19 16:20	General View	 Load JPG ☒	☒
22	11/10/19 16:20	General View	 Load JPG ☒	☒
23	11/10/19 16:20	General View	 Load JPG ☒	☒
24	11/10/19 16:20	General View	 Load JPG ☒	☒
25	11/10/19 16:20	General View	 Load JPG ☒	☒
26	11/10/19 16:20	General View	 Load JPG ☒	☒
27	11/10/19 16:20	General View	 Load JPG ☒	☒
28	11/10/19 16:20	General View	 Load JPG ☒	☒
29	11/10/19 16:20	General View	 Load JPG ☒	☒
30	11/10/19 16:20	General View	 Load JPG ☒	☒
31	11/10/19 16:20	General View	 Load JPG ☒	☒
32	11/10/19 16:20	General View	 Load JPG ☒	☒
33	11/10/19 16:20	General View	 Load JPG ☒	☒
34	11/10/19 16:20	General View	 Load JPG ☒	☒
35	11/10/19 16:20	General View	 Load JPG ☒	☒
36	11/10/19 16:20	General View	 Load JPG ☒	☒
37	11/10/19 16:20	General View	 Load JPG ☒	☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	11/10/19 16:20	General View		Load JPG	☒
39	11/10/19 16:20	General View		Load JPG	☒
40	11/10/19 16:20	General View		Load JPG	☒
41	11/10/19 16:20	General View		Load JPG	☒
42	11/10/19 16:20	General View		Load JPG	☒
43	11/10/19 16:20	General View		Load JPG	☒
44	11/10/19 16:20	General View		Load JPG	☒
45	11/10/19 16:20	General View		Load JPG	☒
46	11/10/19 16:20	General View		Load JPG	☒
47	11/10/19 16:20	General View		Load JPG	☒
48	11/10/19 16:20	General View		Load JPG	☒
49	11/10/19 16:20	General View		Load JPG	☒
50	11/10/19 16:20	General View		Load JPG	☒
51	11/10/19 16:20	General View		Load JPG	☒
52	11/10/19 16:20	General View		Load JPG	☒
53	11/10/19 16:20	General View		Load JPG	☒
54	11/10/19 16:20	General View		Load JPG	☒
55	11/10/19 16:20	General View		Load JPG	☒
56	11/10/19 16:21	Reinspection Photo		Load JPG	☒
57	11/10/19 16:21	Reinspection Photo		Load JPG	☒
58	11/10/19 16:21	Reinspection Photo		Load JPG	☒
59	11/10/19 16:21	Reinspection Photo		Load JPG	☒
60	11/10/19 16:21	Reinspection Photo		Load JPG	☒
61	11/10/19 16:21	Reinspection Photo		Load JPG	☒
62	11/10/19 16:21	Reinspection Photo		Load JPG	☒
63	11/10/19 16:21	Reinspection Photo		Load JPG	☒
64	11/10/19 16:21	Reinspection Photo		Load JPG	☒
65	11/10/19 16:21	Reinspection Photo		Load JPG	☒
66	11/10/19 16:21	Reinspection Photo		Load JPG	☒
67	11/10/19 16:21	Reinspection Photo		Load JPG	☒
68	11/10/19 16:21	Reinspection Photo		Load JPG	☒
69	11/10/19 16:21	Reinspection Photo		Load JPG	☒
70	11/10/19 16:21	Reinspection Photo		Load JPG	☒
71	11/10/19 16:21	Reinspection Photo		Load JPG	☒
72	11/10/19 16:21	Reinspection Photo		Load JPG	☒
73	11/10/19 16:21	Reinspection Photo		Load JPG	☒
74	11/10/19 16:21	Reinspection Photo		Load JPG	☒
75	11/10/19 16:21	Reinspection Photo		Load JPG	☒
76	11/10/19 16:21	Reinspection Photo		Load JPG	☒
77	11/10/19 16:21	Reinspection Photo		Load JPG	☒
78	11/10/19 16:21	Reinspection Photo		Load JPG	☒
79	11/10/19 16:21	Reinspection Photo		Load JPG	☒
80	11/10/19 16:21	Reinspection Photo		Load JPG	☒
81	11/10/19 16:21	Reinspection Photo		Load JPG	☒
82	11/10/19 16:21	Reinspection Photo		Load JPG	☒
83	11/10/19 16:21	Reinspection Photo		Load JPG	☒
84	11/10/19 16:21	Reinspection Photo		Load JPG	☒
85	11/10/19 16:21	Reinspection Photo		Load JPG	☒
86	11/10/19 16:21	Reinspection Photo		Load JPG	☒
87	11/10/19 16:21	Reinspection Photo		Load JPG	☒
88	11/10/19 16:21	Reinspection Photo		Load JPG	☒
89	11/10/19 16:21	Reinspection Photo		Load JPG	☒
90	11/10/19 16:21	Reinspection Photo		Load JPG	☒

Letters/Correspondences			1 per page	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
91	11/10/19 16:21	Reinspection Photo	Load JPG	✓
92	11/10/19 16:21	Reinspection Photo	Load JPG	✓
93	11/10/19 16:21	Reinspection Photo	Load JPG	✓
94	11/10/19 16:21	Reinspection Photo	Load JPG	✓
95	11/10/19 16:21	Reinspection Photo	Load JPG	✓
96	11/10/19 16:21	Reinspection Photo	Load JPG	✓
97	11/10/19 16:21	Reinspection Photo	Load JPG	✓
98	11/10/19 16:21	Reinspection Photo	Load JPG	✓
99	11/10/19 16:21	Reinspection Photo	Load JPG	✓
100	11/10/19 16:21	Reinspection Photo	Load JPG	✓
101	11/10/19 16:21	Reinspection Photo	Load JPG	✓
102	11/10/19 16:21	Reinspection Photo	Load JPG	✓
103	11/10/19 16:21	Reinspection Photo	Load JPG	✓
104	11/10/19 16:21	Reinspection Photo	Load JPG	✓
105	11/10/19 16:21	Reinspection Photo	Load JPG	✓
106	11/10/19 16:21	Reinspection Photo	Load JPG	✓
107	11/10/19 16:21	Reinspection Photo	Load JPG	✓
108	11/10/19 16:21	Reinspection Photo	Load JPG	✓
109	11/10/19 16:21	Reinspection Photo	Load JPG	✓
110	11/10/19 16:21	Reinspection Photo	Load JPG	✓
111	11/10/19 16:21	Reinspection Photo	Load JPG	✓
112	11/10/19 16:21	Reinspection Photo	Load JPG	✓
Documentation			1 per page	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/04/19 15:39	EMAIL FROM AIG DD 12042019	Load PDF	
2	12/04/19 15:39	WKSP NOTICE	Load PDF	
3	15/04/19 17:51	TP GIA REPORT	Load PDF	
4	23/07/19 14:07	EMAIL TO OI	Load PDF	
5	23/07/19 14:07	LETTER TO OI	Load PDF	
6	15/10/19 11:01	TP ESTIMATE - FINALIZED	Load PDF	
7	19/12/19 17:54	LOD	Load PDF	
8	19/12/19 17:54	LTA SEARCH	Load PDF	
9	28/05/20 12:03	LOU BREAKDOWN	Load PDF	
10	06/07/20 15:52	Towing Invoice	Load PDF	
11	23/07/20 09:22	Authorisation to Act	Load PDF	
12	23/07/20 09:22	Release Voucher	Load PDF	
13	23/07/20 09:22	WORKSHOP INVOICE	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	15/04/19 10:18	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKS6915R (Insd veh)	Model:	TOYOTA COROLLA ALTIS 1.6
	SKA7901T (TP veh)		(A)
Date of Accident:	07/04/2019		

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$				54,303.10
Final Repair Cost	:	\$				14,766.00
Loss of Use	:	\$				3,300.00
Rental (if any)	:	\$				0.00
LTA / GIA Search Fee	:	\$				8.00
Others:	:	\$				0.00
	:	\$				
Final Settlement Sum	:	\$				18,074.00

Is Third Party Workshop GIA Registered?				[]	YES	[X]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:				Agreed Liability _____ 100 _____ (%)				
B) For GIA Registered Workshop:				BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%)				Assessed Liability (*): _____ 100 _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.								
Remarks _____								

Payment Instruction: Payee's Breakdown			
1)	Precise Auto Services	: \$	18,074.00
2)		: \$	
3)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

23 Jul
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19006552/ABA3S2**Date:** 23/07/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKA7901T**Insured Vehicle No :** SKS6915R

Date of Loss: 07/04/2019

Nature of Claim: TP

Claim No: 9144335274SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKA7901T**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 1ZR078614

Reg. Date: 01/04/2011 (Man. Year: 2011)

Chassis No: MR053REE104114142

Colour: Blue

Odometer: 0 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,560.56	28,863.91	11,696.65	28.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,190.00	7,390.00	2,800.00	27.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	50,750.56	36,253.91	14,496.65	28.56
Approved Total (Overridden) (S\$)		13,800.00		
(S\$)	50,750.56	13,800.00	36,950.56	72.81
+ GST 7.00/7.00% (S\$)	3,552.54	966.00	2,586.54	72.81
Nett Amount (S\$)	54,303.10	14,766.00	39,537.10	72.81
+ Loss of Use (55.0 x S\$60.00/day) (S\$)		3,300.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		18,074.00		

INSPECTION

Date of Assignment: 12/04/2019

Date Inspected: 12/04/2019

Inspected At:

Precise Auto Services (HQ)

NO.1 KAKI BUKIT AVE 6 #02-34/36

Singapore 417883

Estimated Period of Repair: 35.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Distorted	316.20 FL	*316.20 FL
2	1		*FRONT BUMPER AIR GUIDE	Distorted	89.10 FL	*89.10 FL
3	1		*FRONT BUMPER REINFORCEMENT	Distorted	327.10 FL	*327.10 FL
4	1		*FRONT BUMPER BADGE	Necessary	149.20 FL	*75.00 FL
5	1		*FRONT BUMPER REINFORCEMENT BRACKET	O/s Bent	87.80 FL	*43.90 FL
6	2		*FRONT BUMPER SIDE RETAINER	Necessary	87.80 FL	*87.80 FL
7	2		*FRONT BUMPER BRACKET	Not Necessary	87.80 FL	*- FL
8	10		*FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
9	2		*FOG LAMP ASSY	Not Necessary	311.00 FL	*- FL
10	2		*FOG LAMP COVER	Not Necessary	87.80 FL	*- FL
11	4		*FOG LAMP CLIPS	Not Necessary	51.60 FL	*- FL
12	2		*HEAD LAMP ASSY	Cracked	569.20 FL	*569.20 FL
13	2		*HEAD LAMP CLIPS	Necessary	25.80 FL	*25.80 FL
14	1		*BONNET	Distorted	700.90 FL	*700.90 FL
15	2		*BONNET HINGE	Bent	87.80 FL	*87.80 FL
16	2		*BONNET RUBBER SPONGE	Not Necessary	107.80 FL	*- FL
17	1		*BONNET LOCK	Jammed	53.90 FL	*53.90 FL
18	1		*BONNET LOCK CABLE	Not Necessary	61.10 FL	*- FL
19	1		*BONNET LOCK BRACE PANEL	Bent	80.70 FL	*80.70 FL
20	1		*BONNET INNER RUBBER BEADING	Not Necessary	43.90 FL	*- FL
21	8		*BONNET INNER RUBBER BEADING CLIPS	Not Necessary	28.00 FL	*- FL
22	1		*BONNET INSULATOR	Crumpled	61.10 FL	*61.10 FL
23	8		*BONNET INSULATOR CLIPS	Necessary	28.00 FL	*28.00 FL
24	2		*BONNET STAND CLIPS	Not Necessary	87.80 FL	*- FL
25	1		*FRONT FENDER - RH	Buckled	213.40 FL	*213.40 FL
26	1		*FRONT FENDER SPLASH SHIELD	Not Necessary	53.90 FL	*- FL
27	8		*FRONT FENDER SPLASH SHIELD CLIPS	Not Necessary	28.00 FL	*- FL
28	1		*FRONT GRILLE	Cracked	262.50 FL	*262.50 FL
29	2		*FRONT GRILLE TOP CLIPS WITH STOPPER	Not Necessary	87.80 FL	*- FL
30	3		*FRONT GRILLE CLIPS	Necessary	10.50 FL	*10.50 FL
31	1		*AIR COND CONDENSOR	Distorted	1,224.05 FL	*1,224.05 FL
32	2		*AIR COND CONDENSOR TOP MOUNTING	Damaged	107.80 FL	*107.80 FL
33	2		*AIR COND CONDENSOR BOTTOM MOULDING	Damaged	122.20 FL	*122.20 FL
34	1		*AIR COND DISCHARGE HOSE	Bent	281.20 FL	*281.20 FL
35	1		*AIR COND SUCTION HOSE	Bent	261.10 FL	*261.10 FL
36	1		*AIR COND LIQUID PIPE	Bent	31.20 FL	*31.20 FL
37	1		*AIR COND CONDENSOR SIDE AIR GRILLE GARNISH	Distorted	242.20 FL	*242.20 FL
38	1		*RADIATOR ASSY	Distorted	805.50 FL	*805.50 FL
39	2		*RADIATOR TOP MOUNTING	Damaged	107.80 FL	*107.80 FL
40	2		*RADIATOR BOTTOM MOUNTING	Damaged	122.20 FL	*122.20 FL
41	1		*RADIATOR TOP HOSE	Distorted	61.10 FL	*61.10 FL
42	1		*RADIATOR BOTTOM HOSE	Distorted	53.90 FL	*53.90 FL
43	1		*RADIATOR FAN COWLING	Distorted	137.60 FL	*137.60 FL
44	1		*RADIATOR FAN BLADE	Damaged	58.60 FL	*58.60 FL
45	1		*RADIATOR FAN MOTOR	Damaged	210.20 FL	*210.20 FL
46	1		*FAN BELT	Not Necessary	181.10 FL	*- FL
47	1		*AIR COND COMPRESSOR	Not Necessary	1,770.55 FL	*- FL
48	1		*BATTERY BRACKET	Not Necessary	63.90 FL	*- FL
49	1		*BATTERY TRAY	Not Necessary	61.10 FL	*- FL
50	1		*AIR CLEANER INLET DUCT	Deformed	98.70 FL	*98.70 FL
51	2		*AIR CLEANER INLET DUCT CLIPS	Necessary	25.80 FL	*25.80 FL
52	1		*AIR CLEANER BOX ASSY	Not Necessary	362.60 FL	*- FL
53	1		*WIPER WASHER TANK	Distorted	83.10 FL	*83.10 FL
54	1		*WIPER WASHER TANK MOTOR	Not Necessary	121.20 FL	*- FL
55	1		*WIPER WASHER TANK MOTOR BUSH	Not Necessary	43.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*ENGINE UNDER COVER - O/S	Not Necessary	53.90 FL	*- FL
57	1		*ENGINE UNDER COVER - O/S	Not Necessary	53.90 FL	*- FL
58	16		*ENGINE UNDER COVER CLIPS	Not Necessary	56.00 FL	*- FL
59	1		*ENGINE MOUNTING - TOP O/S	Not Necessary	171.20 FL	*- FL
60	1		*ENGINE UNDER MOUNTING (FRONT)	Not Necessary	181.10 FL	*- FL
61	1		*ENGINE UNDER MOUNTING (REAR)	Not Necessary	171.10 FL	*- FL
62	1		*GEAR BOX MOUNTING	Not Necessary	161.20 FL	*- FL
63	1		*WIPER GRILLE GARNISH O/S	Not Necessary	63.90 FL	*- FL
64	3		*WIPER GRILLE GARNISH CLIPS	Not Necessary	10.50 FL	*- FL
65	1		*FRONT WINDSCREEN GLASS	Cracked	1,237.05 FL	*1,237.05 FL
66	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	83.90 FL	*83.90 FL
67	1		*FRONT WINDSCREEN GLASS CLIPS	Necessary	180.60 FL	*30.00 FL
		14pcs				
68	2		*HORN ASSY	Not Necessary	262.40 FL	*- FL
69	1		*REAR BUMPER FASCIA	Distorted	424.05 FL	*424.05 FL
70	2		*REAR BUMPER SIDE RETAINER	Necessary	173.80 FL	*173.80 FL
71	2		*REAR BUMPER SIDE ATTACHMENT	Necessary	162.20 FL	*162.20 FL
72	2		*REAR BUMPER SIDE BRACKET	Not Necessary	242.20 FL	*- FL
73	1		*REAR BUMPER STAY	O/s Distorted	323.50 FL	*161.75 FL
74	1		*REAR BUMPER SPONGE	Cracked	102.80 FL	*102.80 FL
75	10		*REAR BUMPER CLIPS	Necessary	129.00 FL	*129.00 FL
76	2		*REAR BUMPER REFLECTOR	Missing	167.80 FL	*167.80 FL
77	2		*REAR BUMPER DUST COVER	Torn	127.80 FL	*127.80 FL
78	1		*REAR BUMPER DUST COVER CLIPS	Necessary	51.90 FL	*51.90 FL
		4pcs				
79	1		*BOOT LID	Distorted	554.80 FL	*554.80 FL
80	2		*BOOT LID HINGE	Bent	127.80 FL	*127.80 FL
81	1		*BOOT LID LOCK	Jammed	92.82 FL	*92.82 FL
82	1		*BOOT LID LOCK STRIKER	Bent	63.90 FL	*63.90 FL
83	1		*BOOT LID LOCK CABLE	Jammed	81.10 FL	*81.10 FL
84	2		*BOOT LID HINGE SPRING	Bent	118.20 FL	*118.20 FL
85	2		*BOOT LID STOPPER	Necessary	87.80 FL	*87.80 FL
86	1		*BOOT LID WEATHER STRIPE	Cut	121.10 FL	*121.10 FL
87	1		*BOOT LID CHROME	Cracked	203.20 FL	*203.20 FL
88	4		*BOOT LID CHROME CLIPS	Necessary	51.60 FL	*51.60 FL
89	2		*BOOT LID REFLECTOR	Cracked	322.20 FL	*322.20 FL
90	2		*BOOT LID REFLECTOR SEALANT	Necessary	100.00 FL	*100.00 FL
91	4		*BOOT LID REFLECTOR CLIPS	Necessary	51.60 FL	*51.60 FL
92	1		*BOOT LID BADGE	Necessary	41.00 FL	*41.00 FL
93	1		*BOOT LID EMBLEM ALTIS	Necessary	31.00 FL	*31.00 FL
94	1		*BOOT LID EMBLEM 1.6	Necessary	31.00 FL	*31.00 FL
95	1		*BOOT LID EMBLEM COROLLA	Necessary	31.00 FL	*31.00 FL
96	1		*BOOT LID INSULATOR	Crumpled	151.10 FL	*151.10 FL
97	8		*BOOT LID INSULATOR CLIPS	Necessary	103.20 FL	*30.00 FL
98	1		*TAIL LAMP ASSY	O/s Smashed	640.20 FL	*320.10 FL
99	1		*TAIL LAMP SEALANT	O/s Necessary	100.00 FL	*50.00 FL
100	4		*TAIL LAMP CLIPS	Necessary	51.60 FL	*10.00 FL
101	2		*REAR NUMBER PLATE LAMP	Not Necessary	167.80 FL	*- FL
102	1		*REAR END PANEL	Distorted	495.85 FL	*495.85 FL
103	1		*REAR END PANEL TOP TRIM	Distorted	177.80 FL	*177.80 FL
104	4		*REAR END PANEL TOP TRIM CLIPS	Necessary	51.60 FL	*10.00 FL
105	1		*REAR FENDER - O/S & N/S	O/s Distorted	1,531.70 FL	*765.85 FL
106	1		*REAR FENDER AIR VENT - N/S	Not Necessary	80.70 FL	*- FL
107	2		*REAR FENDER SPLASH SHIELD	Distorted	107.40 FL	*107.40 FL
108	6		*REAR FENDER SPLASH SHIELD CLIPS	Necessary	77.40 FL	*77.40 FL
109	1		*REAR FENDER INNER TRIM BOARD	O/s Crumpled	617.20 FL	*308.60 FL
110	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	206.40 FL	*30.00 FL
		16pcs				
111	1		*REAR WHEEL HOUSING PANEL (INNER) - RH	Distorted	585.20 FL	*585.20 FL
112	1		*REAR WHEEL HOUSING PANEL (OUTER) - RH	Distorted	361.70 FL	*361.70 FL
113	1		*REAR FLOOR PANEL	Distorted	691.20 FL	*691.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
114	1		*REAR FLOOR PANEL BOARD	Torn	329.20 FL	*329.20 FL
115	1		*REAR FLOOR PANEL INSULATOR CLOTH	Necessary	361.10 FL	*361.10 FL
116	1		*REAR SUB CHASSIS FRAME MEMBER	O/s Distorted	762.40 FL	*381.20 FL
117	1		*FUEL LID COVER	Not Necessary	121.10 FL	*- FL
118	1		*FUEL LID CABLE	Not Necessary	131.20 FL	*- FL
119	1		*FUEL LIP SPRING	Not Necessary	63.90 FL	*- FL
120	2		*FUEL LIP RIVETS	Not Necessary	25.80 FL	*- FL
121	1		*FUEL LIP BRACKET	Not Necessary	24.10 FL	*- FL
122	1		*FUEL TANK INLET PIPE	Not Necessary	302.75 FL	*- FL
123	1		*FUEL TANK INLET PIPE RUBBER	Not Necessary	67.90 FL	*- FL
124	1		*FUEL TANK INLET PIPE HOSE	Not Necessary	231.20 FL	*- FL
125	1		*REAR WINDSCREEN GLASS	Shattered	974.40 FL	*974.40 FL
126	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	121.10 FL	*121.10 FL
127	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FL	*50.00 FL
128	1		*REAR WINDSCREEN GLASS CLIPS 14pcs	Necessary	180.60 FL	*30.00 FL
129	1		*REAR RH DOOR ASSY	Distorted	866.35 FL	*866.35 FL
130	1		*REAR RH DOOR WEATHER STRIPE	Cut	181.10 FL	*181.10 FL
131	1		*REAR RH DOOR INNER LOCK	Jammed	283.20 FL	*283.20 FL
132	1		*REAR RH DOOR PROTECTOR WITH CHROME	Distorted	161.70 FL	*161.70 FL
133	1		*REAR RH DOOR INNER TRIM BOARD	Cracked	383.20 FL	*383.20 FL
134	12		*REAR RH DOOR INNER TRIM BOARD CLIPS	Necessary	154.80 FL	*30.00 FL
135	1		*EXHAUST SILENCER	Bent	771.90 FL	*771.90 FL
136	3		*EXHAUST SILENCER HOOK	Torn	191.70 FL	*191.70 FL
137	1		*EXHAUST CENTRE PIPE	Bent	1,218.80 FL	*1,218.80 FL
138	1		*REAR AXLE BEAM	Bent	1,487.20 FL	*1,487.20 FL
139	1		*REAR ABSORBER MOUNTING	Torn	172.10 FL	*172.10 FL
140	2		*REAR ABSORBER	Bent	310.40 FL	*310.40 FL
141	1		*REAR COIL SPRING	Not Necessary	155.00 FL	*- FL
142	1		*REAR SPEAKER BOARD PANEL	Distorted	369.80 FL	*369.80 FL
143	1		*REAR SPEAKER BOARD	Torn	350.00 FL	*350.00 FL
144	1		*REAR SPEAKER BOARD SIDE PANEL - RH	Distorted	189.40 FL	*189.40 FL
145	1		*REAR WHEEL BEARING HUP	Damaged	561.60 FL	*561.60 FL
146	2		*TAIL LAMP LOWER PANEL	Distorted	161.40 FL	*161.40 FL
147	1		*SPORT RIM ASSY - RH	Cut	680.00 FL	*680.00 FL
148	8		*TAIL LAMP LOWER PANEL RIVETS	Necessary	103.20 FL	*20.00 FL
149	1		*TYRE ASSY	Cut	280.00 FL	*200.00 FL
150	1		*TAIL LAMP BASE PANEL	O/s Distorted	580.20 FL	*290.10 FL
151	4		*REAR BUMPER CENTRE MOUNTING	Not Necessary	175.60 FL	*- FL
152	1		*SPARE TYRE WINDNUT	Damaged	61.10 FL	*61.10 FL
153	1		*FRONT WINDSCREEN GLASS CLIPS 14pcs	Necessary	180.60 FL	*30.00 FL
154	2		*HORN ASSY	Not Necessary	262.40 FL	*- FL
155	1		*DASHBOARD FASCIA	Torn	781.85 FL	*781.85 FL
156	2		*FRONT SEAT BELT	Activated	1,178.40 FL	*1,178.40 FL
157	1		*STEERING AIR BAG	Activated	1,698.20 FL	*1,698.20 FL
158	1		*PASSENGER AIR BAG	Activated	2,790.20 FL	*2,790.20 FL
159	1		*AIR BAG ECU	Activated	1,698.20 FL	*1,698.20 FL
160	2		*AIR BAG CHASSIS CRASH SENSOR	Activated	766.40 FL	*766.40 FL
161	1		*FRONT DRIVER SEAT ASSY	Bent	985.40 FL	*985.40 FL
162	1		*REAR BACK REST CUHSION	Not Necessary	916.10 FL	*- FL
163	1		*ROOF LINING	Not Necessary	1,817.70 FL	*- FL
164	1		*ROOF PANEL	Repair	1,882.40 FL	*- FL
165	1		*REVERSE SENSOR WITH CONTROL UNIT	Damaged	380.00 FS	*200.00 FS
166	1		*REAR NUMBER PLATE	Cracked	45.00 FS	*30.00 FS
167	1		*REAR NUMBER PLATE CASING	Cracked	29.00 FS	*29.00 FS
168	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
169	1		*REAR WINDSCREEN GLASS SOLAR FILM	Necessary	180.00 FS	*180.00 FS
170	1		*BATTERY ASSY	Not Necessary	280.00 FS	*- FS
171	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
172	1		*FRONT WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
173	1		*FRONT NUMBER PLATE	Cracked	35.00 FS	*35.00 FS
174	1		*FRONT NUMBER PLATE CASING	Cracked	25.00 FS	*25.00 FS
175	1		*FRONT WINDSCREEN GLASS SOLAR FILM	Necessary	180.00 FS	*180.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (\$)	53,639.42	38,202.22
				- List Item Discount on L Items 25.00/25.00% (\$)	13,078.86	9,338.31
				Total Parts (\$)	40,560.56	28,863.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING.	New	200.00	150.00
2	TO CHECK & RECONNECT SNAP WIRING.	New	280.00	60.00
3	TO TUFF COAT AFFECTED AREAS.	New	280.00	200.00
4	TO REMOVE & REFIX DASHBOARD.	New	280.00	220.00
5	TO REMOVE & REFIX AIR COND CONDENSOR, PIPING, VACUUM & TOP UP AIR COND GAS.	New	180.00	60.00
6	TO REMOVE & REFIX RADIATOR, HOSES & TOP UP COOLANT.	New	120.00	60.00
7	TO REMOVE & REFIX ENGINE COMPONENTS.	New	480.00	0.00
8	TO ADJUST COMPUTER 4 WHEEL ALIGNMENT.	New	120.00	80.00
9	TO ADJUST CHASSIS ALIGNMENT ON CAR O LINER.	New	350.00	300.00
10	TO REMOVE & REFIX REAR UNDERCARRIAGE COMPONENTS.	New	450.00	350.00
11	TO RESPRAY AFFECTED AREAS.	New	2,800.00	2,200.00
12	TO RENEW DAMAGED PARTS, STRAIGHTEN / REPAIR FRONT & REAR CHASSIS FRAME MEMBER & ALIGNED ALL PARTS.	New	2,800.00	2,600.00
13	TO REMOVE & REFIX FRONT & REAR WINDSCREEN GLASS.	New	360.00	240.00
14	TO REMOVE & REFIX DASHBOARD & AIR BAG SYSTEM.	New	380.00	280.00
15	TO RESET AIR BAG MODULE SYSTEM.	New	280.00	100.00
16	TO REMOVE & REFIX INTERIOR UPHOLSTERY.	New	250.00	200.00
17	TO REMOVE & REFIX EXHAUST PIPE.	New	280.00	160.00
18	TO REMOVE & REFIX FUEL TANK.	New	180.00	80.00
19	TO REMOVE & REFIX REVERSE SENSOR.	New	120.00	50.00
Gross Labour Cost (\$\$)			10,190.00	7,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >