

 Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

General Details

Involving 1 2008 TOYOTA HARRIER 2.4 (SLT7205H)

Date of Loss 7 April 2019

Time of Loss 8.30

Loss Description SLT7205H (INSD) C/W FBF7966L (TP)

Comment

Workshop Details

Total Rebate Amount

Nett Loss Amount \$33,515.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion
*



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Vehicle & Driver Details

Vehicle Registration#	SLT7205H	Purchase Date	dd/mm/yyyy
Registration State	SINGAPORE	Registration Date *	16/09/2008
Mileage	157419	Age of Vehicle	10

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2008	2008
Make	TOYOTA	TOYOTA
Model	HARRIER 2.4	HARRIER 2.4GL A

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	TAY SU YONG DEREK	
Date of Birth	28 January 1979	dd/mm/yyyy
Age	40	

Type	POLICY	ASSESSMENT INFORMATION
CATEGORY	INFORMATION	
Type of Paint		
Chassis No	ACU300092056	ACU300092056
Engine No	2AZB343962	2AZB343962
Engine Capacity		2362
Sum Insured	0	0
Market Value	0	65000

Claim Portal

CATEGORY	END INFORMATION
Education Qualification	Other
Driving Experience	18
Driver License #	
License Type	
License Issue Date	dd/mm/yyyy
License Expiration Date	dd/mm/yyyy
Address	01-23, 25 Punggol Field Walk, 828751, Singapore
Address type	Residential

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Married	
Identification #	S7902857F	

 Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Detailed Assessment

Inspection Date *	11/04/2019
Total Loss	Yes No
Towing Charges	0
Voluntary Excess	0
Compulsory Excess	700
Young/Inexperienced/Un named Driver Excess	0
Other Excess	

Condition of Vehicle at time of survey

General condition	Good ▾
Steering (Serviceable)	Yes No
Footbrake (Serviceable)	Yes No
Handbrake (Serviceable)	Yes No
Engine Modification	Yes No
Pre-accident condition	Good ▾

Tyre Condition

Age of Tyres		Spare wheel	
--------------	-------------	-------------	-------------

Front Tyre Size

245/45ZR20

Rear Tyre Size

245/45ZR20

Front left side

PIRELLI9mm

Rear left side

PIRELLI9mm

Front right side

PIRELLI9mm

Rear right side

PIRELLI9mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add Approve Deny Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		FRT NO PLATE BRKT (WCP) (10%)	Cracked	0	55	No					55	Reviewing	
		0	1		L/F BUMPER COVER	Serviceable	0	0	No					0	Deny	
		0	1		R/F BUMPER COVER	Serviceable	0	0	No					0	Deny	
		0	1		FRONT BUMPER (WCP) (10%)	Buckled	0	280.5	No					280.5	Reviewing	
		0	1		L/INN BUMPER BRACKET	Serviceable	0	0	No					0	Deny	
		0	1		R/INN BUMPER BRACKET	Serviceable	0	0	No					0	Deny	
		0	1		FRT BUMPER REINF	Repair	0	0	No					0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		FRT IMPACT ABSORBER	Serviceable	0	0	No					0	Deny	
		0	1		GRILLE (WCP) (10%)	Cracked	0	203.5	No					203.5	Reviewing	
		0	1		RAD GRILLE BADGE (WCP) (10%)	Necessary	0	41.8	No					41.8	Reviewing	
		0	1		BONNET (WCP) (10%)	Bent	0	638	No					638	Reviewing	
		0	1		L/F HINGE	Repair	0	0	No					0	Deny	
		0	1		R/F HINGE	Repair	0	0	No					0	Deny	
		0	1		BONNET INSULATION	Serviceable	0	0	No					0	Deny	
		0	1		BONNET LOCK (WCP) (10%)	Damaged	0	55	No					55	Reviewing	
		0	1		SAFETY LATCH (NPA)	Serviceable	0	0	No					0	Deny	
		0	1		LEFT HEADLAMP ASSY (WCP) (10%)	Cracked	0	638	No					638	Reviewing	
		0	1		RIGHT HEADLAMP ASSY (WCP) (10%)	Cracked	0	638	No					638	Reviewing	
		0	1		LOCK CARRIER STRUT (WCP) (10%)	Bent	0	55	No					55	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		INNER FRT PANEL CPL	Repair	0	0	No					0	Deny	
		0	1		UPPER AIR GUIDE	Serviceable	0	0	No					0	Deny	
		0	1		CONDENSER (WCP) (10%)	Damaged	0	539	No					539	Reviewing	
		0	1		RADIATOR	Serviceable	0	0	No					0	Deny	
		0	1		RADIATOR SHROUD	Serviceable	0	0	No					0	Deny	
		0	1		L/FAN MOTOR	Serviceable	0	0	No					0	Deny	
		0	1		R/FAN MOTOR	Serviceable	0	0	No					0	Deny	
		0	1		L/BLOWER FAN	Serviceable	0	0	No					0	Deny	
		0	1		R/BLOWER FAN	Serviceable	0	0	No					0	Deny	
		0	1		LOW TONE HORN	Serviceable	0	0	No					0	Deny	
		0	1		HIGH TONE HORN (WCP) (10%)	Dented	0	49.5	No					49.5	Reviewing	
		0	1		INSULATOR CLIPS (10) (WCP) (10%)	Necessary	0	11	No					11	Reviewing	
		0	1		BUMP CLIPS (15) (WCP) (10%)	Necessary	0	16.5	No					16.5	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		BUMP LWR SPOILER	Serviceable	0	0	No					0	Deny	
		0	1		GARNISH CLIPS (8)	Serviceable	0	0	No					0	Deny	
		0	1		RAD SIDE AIR GUIDEX2	Serviceable	0	0	No					0	Deny	
		0	1		BONNET SEAL (WCP) (10%)	Cut	0	38.5	No					38.5	Reviewing	
		0	1		BONNET CABLE (WCP) (10%)	Damaged	0	38.5	No					38.5	Reviewing	
		0	2		HEADLAMP CLIPS (WCP) (10%)	Necessary	0	6.6	No					13.2	Reviewing	

Labour

Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
		0		129.0 WU X 45.00 SGD/H	0	256.5	0	0	Reviewing		
		0		LABOUR COST 98.0 WU X 45.00 SGD/H	0	441	0	0	Reviewing		
		0		MATERIAL COST	0	241.53	0	0	Reviewing		
		0		TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS	0	50	0	0	Reviewing		

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add Approve Deny Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
☐		0	DAYS OF REPAIR : 4 DAYS	Reviewing		0		
☐		0	NUMBER PLATE	Reviewing		35	BENT	
☐		0	RADIATOR COOLANT	Deny		0	NOT NECESSARY	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount \$0.00

Adjusted Claim Amount \$3,635.03

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

\$0.00

\$3,311.00

Labour

\$0.00

\$989.03

Miscellaneous

\$0.00

\$35.00

Excess

-\$700.00

[Submit for Review](#)