



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 2785Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	RH/F HEADLAMP (SN) (CONSISTENT)	CRACKED	2,578.52	2,578.52
1	RH/F HEADLAMP CONTROL UNIT (SN) (CONSISTENT)	NOT WORKING	922.93	922.93
1	FRT END SUPPORT MEMBER (SN) (CONSISTENT)	SERVICEABLE	643.80	-
1	RH/F FENDER (SN) (CONSISTENT)	BENT	659.41	659.41
1	RH/F INTERMEDIATE LAYER (SN) (CONSISTENT)	SERVICEABLE	9.35	-
1	RH/F BUMPER BRACKET (SN) (CONSISTENT)	NECESSARY	12.11	12.11
1	RH/F WHEEL ARCH (SN) (CONSISTENT)	DEFORMED	188.53	188.53
1	FRT BUMPER (SN) (CONSISTENT)	DEFORMED	1,387.61	1,387.61
1	RH/F BOTTOM GRILLE (SN) (CONSISTENT)	SERVICEABLE	47.59	-
1	FRT UNDER CARRIAGE COVER (SN) (CONSISTENT)	SERVICEABLE	286.38	-
1	FRT IMPACT ABSORBER (SN) (CONSISTENT)	SERVICEABLE	131.95	-
1	RH/F PARKING SENSOR (SN) (CONSISTENT)	SERVICEABLE	177.22	-
1	RH/F PARKING SENSOR SEAL (SN) (CONSISTENT)	SERVICEABLE	6.42	-
1	RH/F BOTTOM GRILLE GARNISH (SN) (CONSISTENT)	SERVICEABLE	75.02	-
1	RH/F DISC WHEEL (SN) (CONSISTENT)	SCRATCHED	509.20	509.20
1	FRONT RIGHT RIM (SN) (CONSISTENT)	SCRATCHED	60.00	60.00
1	FRT CROSS MEMBER (SN) (CONSISTENT)	SERVICEABLE	319.85	-
1	PLUG (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	4.96	4.96
			8,020.85	6,323.27
<b><u>LABOUR</u></b>				
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.			380.00	380.00
CHECK HEADLAMP WITH FOCUS ADJUSTMENT.			120.00	120.00
INSPECT & CONDUCT WHEEL ALIGNMENT.			540.00	540.00
REMOVE & REPLACE FRONT BUMPER, FRONT RIGHT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.			3,360.00	2,400.00
RESPRAY FRONT BUMPER, FRONT BONNET, FRONT RIGHT FENDER & FRONT RIGHT DOOR.			2,800.00	2,400.00
ACCIDENT TOWING FROM 32 DEFU LANE TO PLSC USING STRAIGHT TOWING.			120.00	120.00
			7,320.00	5,960.00

Report Ref No. CC4/ASM19006566/R1ps3s2



GRAND TOTAL		15,340.85	12,283.27
RECOMMENDED COST OF REPAIRS			12,283.27

Report Ref No. CC4/ASM19006566/R1ps3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.