

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM19006574/Kga3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	30/08/2021	
	ATTN:STACEY NG			Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLE 7189A	Veh. Inspected	l	SKT 4590B	
	Policy No.	GA238836	Coverage (\$)		0.00	
	Claim No.	S9M01JWG	Excess (\$)		0.00	
	Assign From		Assign Date		11/04/2019	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA JAZZ (A)	c.c		1318	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	JHMGK3850FX200838	Colour		METALLIC SILVER	
	Odometer	132947 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	175/65 R15	DUNLOP		8 mm	
	L/H Front Tyre	175/65 R15	DUNLOP		8 mm	
	R/H Rear Tyre	175/65 R15	DUNLOP		6 mm	
	L/H Rear Tyre	175/65 R15	DUNLOP		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	10/04/2019	Inspection Dat	е	11/04/2019	
	Survey held at	urvey held at K KIM HIN AUTOMOTIVE PTE LTD				
		BLK 34 SIN MING DRIVE, #01-114, SINGAPORE 575708				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	STIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					