

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG19006593/UBA3Q2**Date:** 13/11/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100441184
Claimant Vehicle No :	SJU7372B	Insured Vehicle No :	SKX1938G
Date of Loss:	19/02/2019	Nature of Claim:	TP
		Claim No:	0286380953SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU7372B	Engine No:	R18A14016775
Make & Model:	HONDA CIVIC, 1.8 L 5AT (A)	Chassis No:	JHMF16309S203257
Reg. Date:	24/12/2009 (Man. Year: 2009)	Odometer:	134733 km
Colour:	Grey		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,735.84	1,290.56	445.28	25.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	1,000.00	600.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,335.84	2,290.56	1,045.28	31.33
Approved Total (Overridden) (\$\$)		1,600.00		
(\$\$)	3,335.84	1,600.00	1,735.84	52.04
+ GST 7.00/7.00% (\$\$)	233.51	112.00	121.51	52.04
Nett Amount (\$\$)	3,569.35	1,712.00	1,857.35	52.04
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	15/04/2019	
Date Inspected:	15/04/2019	Inspected At:
Estimated Period of Repair:	4.0 days	

Hock Wah Motor Workshop Pte Ltd (Tampines)
Blk 9006, Tampines Street 93
#01-204
Singapore 528840

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER	Dented / Deformed	638.00 FL	*638.00 FL
2	2		*RR BUMPER SIDE RETAINER LH RH	Not Necessary	35.20 FL	*- FL
3	12		*RR BUMPER CLIPS	Necessary	44.40 FL	*44.40 FL
4	1		*RR BOOTLID	Badly Dented	610.70 FL	*610.70 FL
5	1		*RR BOOTLID LOGO CIVIC	Necessary	24.30 FL	*24.30 FL
6	1		*RR BOOTLID LOGO 1.8 I-VTEC	Necessary	21.70 FL	*21.70 FL
7	1		*RR BOOTLID EMBLEM	Necessary	24.10 FL	*24.10 FL
8	1		*RR BOOTLID INNER RUBBER	Not Necessary	95.80 FL	*- FL
9	1		*RR END PANEL	Repair	300.60 FL	*- FL
10	1		*SET RR REVERSE SENSOR LH RH	Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,094.80	1,563.20
- List Item Discount on L Items 20.00/20.00% (\$)	358.96	272.64
Total Parts (\$)	1,735.84	1,290.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	New	800.00	400.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	600.00
Gross Labour Cost (\$\$)			1,600.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >