

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9970K****AAD1904-091***Not Notarized**11 Sep @ 2700h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHB 9970K**

VF1ABL15AUC273468

RENAULT

LATITUDE

9.4.2019

**AIG**

30/9/2013

**PART****LIST**

|   |                                 |    |                        |     |
|---|---------------------------------|----|------------------------|-----|
| 1 | BUMPER COVER FRT                | \$ | <i>Bu</i> 1,259.42     | ✓   |
| 1 | BUMPER SPOILER FRT              | \$ | <i>SL</i> 181.75       | X   |
| 1 | BUMPER ABSORBER FRT             | \$ | <i>SL</i> 394.68       | X   |
| 1 | BUMPER RETAINER FRT RH          | \$ | <i>Dis</i> 150.77      | ✓   |
| 1 | BUMPER SUPPORT FRT              | \$ | <i>SL</i> 123.88       | X   |
| 1 | BUMPER UNDERTRAY FRT            | \$ | <i>SL</i> 472.83       | X   |
| 1 | BUMPER GRILLE LOWER FRT         | \$ | <i>SL</i> 266.80       | X   |
| 1 | BUMPER FOG LAMP GRILLE RH       | \$ | <i>Dis</i> 207.21      | ✓   |
| 1 | BUMPER BEAM FRT                 | \$ | <i>R</i> 914.08        | X   |
| 1 | HEADLAMP RH                     | \$ | <i>my car</i> 1,184.43 | ✓   |
| 1 | HEADLAMP PANEL FRT RH           | \$ | <i>R</i> 152.15        | } X |
| 1 | FENDER PANEL FRT RH             | \$ | <i>R</i> 783.83        |     |
| 1 | WHEELARCH FRT RH                | \$ | <i>SL</i> 278.84       |     |
| 1 | FENDER BRACKET LOWER RH         | \$ | <i>SL</i> 15.79        |     |
| 1 | FENDER INSULATOR RH             | \$ | <i>SL</i> 130.84       |     |
| 1 | WIPER RESERVOIR                 | \$ | <i>SL</i> 348.25       |     |
| 1 | WIPER RESERVOIR NECK            | \$ | <i>SL</i> 136.11       |     |
| 1 | WIPER RESERVOIR MOTOR           | \$ | <i>SL</i> 270.06       |     |
| 1 | RADIATOR GRILLE                 | \$ | <i>SL</i> 1,707.78     |     |
| 1 | RADIATOR GRILLE BADGE 'RENAULT' | \$ | <i>SL</i> 225.36       |     |
| 1 | RADIATOR GRILLE FRAME           | \$ | <i>SL</i> 1,353.75     |     |
| 1 | FRAME FULL SUPPORT PANEL        | \$ | <i>SL</i> 615.90       |     |
| 1 | FRAME FULL SUPPORT BRACKET      | \$ | <i>R</i> 89.79         |     |

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>11,264.31</b> |
| <b>10%</b>   | <b>\$</b> | <b>1,126.43</b>  |
| <b>TOTAL</b> | <b>\$</b> | <b>10,137.88</b> |

**Trans-cab Auto Services Pte Ltd**

AAD1904-091

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9970K

**Special Nett**

|                    |                            |           |                   |
|--------------------|----------------------------|-----------|-------------------|
| 1SET               | BUMPER CLIP FRT            | \$        | <i>nn</i> 66.00 ✓ |
| 1                  | BUMPER BRACKET CLIP FRT RH | \$        | <i>nn</i> 12.00 X |
| 1                  | BUMPER SUPPORT CLIP FRT RH | \$        | <i>nn</i> 10.50 X |
| 1SET               | BUMPER GRILLE LOWER CLIP   | \$        | <i>nn</i> 69.00 X |
|                    |                            | <b>\$</b> | <b>157.50</b>     |
| <b>TOTAL PARTS</b> |                            | <b>\$</b> | <b>10,295.38</b>  |

**LABOUR**

|                                                                                                                           |    |                  |             |
|---------------------------------------------------------------------------------------------------------------------------|----|------------------|-------------|
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | 3,000.00         | <i>3001</i> |
| Putty and spray painting of the affected portion.                                                                         | \$ | 3,000.00         | <i>4401</i> |
| To rust-proofing of the affected areas.                                                                                   | \$ | <i>nn</i> 170.00 | X           |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | <i>nn</i> 380.00 | X           |
| To check steering geometry and computer wheel alignment                                                                   | \$ | <i>nn</i> 220.00 | X           |
| To transfer of tire, rim and on wheel balancing.                                                                          | \$ | <i>nn</i> 170.00 | X           |
| To Check Electrical Lighting Concerned.                                                                                   | \$ | 170.00           | <i>201</i>  |
| To transfer of front fender fittings, attachment and perform water seepage test.                                          | \$ | <i>nn</i> 380.00 | X           |
| To vacuum, replace, refix and recharge air condenser                                                                      | \$ | <i>nn</i> 380.00 | X           |
| To replace, refix and top up coolant for radiator                                                                         | \$ | <i>nn</i> 170.00 | X           |

**Trans-cab Auto Services Pte Ltd****AAD1904-091**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9970K**To vacuum, replace, refix and recharge Air  
Intercooler\$ *nn* 170.00 X**TOTAL** \$ 8,210.00**Over All Total** \$ 18,505.38**LUMP SUM (REPAIR DAY)**~~10 DAYS~~*2 days*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary (extra) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: