Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19006671/K1GA3Q2

D4EAC100881

Date: 22/09/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2019-00000816

Claimant Vehicle No:

SHD4302L Insured Vehicle No: FBA5324D

Date of Loss: TP 13/04/2019 Nature of Claim: Claim No: 1201900009726

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHD4302L Reg No:

HYUNDAI SONATA NF, 2.0 CRDI AT ABS 2WD Make & Model:

Engine No: 4DR TURBO (A)

KMHET41VMCA826529 Reg. Date: 28/06/2012 (Man. Year: 2012) Chassis No:

Colour: Blue Odometer: 144614 km

Engine Capacity: 1991 cc Market Value/New Car N/A

Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm Front Right Side: Rear Right Side: West Lake 6 mm West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,001.08	2,301.16	699.92	23.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,020.00	880.00	46.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,901.08	3,321.16	1,579.92	32.24
Approved Total (Overridden) (S\$)		2,650.00		
(S\$)	4,901.08	2,650.00	2,251.08	45.93
+ GST 7.00/7.00% (S\$)	343.08	185.50	157.58	45.93
Nett Amount (S\$)	5,244.16	2,835.50	2,408.66	45.93
+ Loss of Use (4.0 x S\$	50.00/day) (S\$)	200.00		_
+ Car Rental (4.0 x S\$10	04.47/day) (S\$)	417.88		
	(S\$)	3,453.38		
Liable Amoun	t (50.00%) (S\$)	1,726.69		
+ Doc/S	earch Fee (S\$)	7.49		
Ne	tt Liability (S\$)	1,734.18		
Global Sum S	settlement (S\$)	1,700.00		

INSPECTION

Date of Assignment: 15/04/2019 Adjuster Report Page 2 of 4

ComfortDelGro Engineering Pte Ltd Date Inspected: 15/04/2019 Inspected At:

(Loyang) 59 Loyang Drive Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Aug 2020)		
Parts:	143	HYUNDAI SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for SHD4302L)			
Validity:	y: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER COVER	Cracked	538.80 FL	*538.80 FL	
2	1		*FRONT BUMPER BRACKET TOP (LH)	Serviceable	22.40 FL	*- FL	
3	1		*HEADLAMP (LH)	Serviceable	797.90 FL	*-FL	
4	1		*FRONT FENDER (LH)	Buckled	593.00 FL	*593.00 FL	
5	1		*FRONT FENDER SHIELD (LH)	Torn	86.00 FL	*86.00 FL	
6	1		*FRONT FENDER SIGNAL LAMP (LH)	Serviceable	45.40 FL	*- FL	
7	1		*FRONT FENDER RETAINER	Serviceable	9.20 FL	*- FL	
8	1		*FRONT DOOR (LH)	Buckled	1,345.00 FL	*1,345.00 FL	
9	1		*FRONT DOOR PROTECTOR (LH)	Cracked	74.90 FL	*74.90 FL	
10	1		*FRONT WHEEL HUB CAP (LH)	Grazed	145.00 FL	*145.00 FL	
11	1		*FRONT DOOR COMFORT LOGO (LH)	Necessary	75.00 FS	*75.00 FS	
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	3,732.60	2,857.70	
	- List Item Discount on L Items 20.00/20.00% (S\$)					556.54	
Total Parts (S\$) 3,001.08 2,301						2,301.16	
Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING CHARGE	New	900.00	600.00
3	WIRING CHARGE	New	30.00	0.00
4	TUFF KOTE	New	50.00	20.00
5	FRT WHEEL ALIGNMENT	New	120.00	0.00
		Gross Labour Cost (S\$)	1,900.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >