








ATOL









PHOTO



18212/17





SAFARI

PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Ms Alice Low

Assign Date:	05/10/2017	Survey Date:	05/10/2017	Our Ref:	AVS2017-12734/AT
Accident Date:	30/09/2017	TP Policy No:	TBA	Your Ref:	MT/0963605-002
Place of Survey:	Eng Soon Painting Services 399B Woodlands Rd, Yew Tee Ind Est Singapore 678035			Claim Type:	Third Party

Description of Vehicle:

Veh. No:	FBE6658M	Make/Model:	Yamaha
Colour:	Yellow	Engine No:	TBA
Line Capacity:	TBA	Chassis No:	TBA
Odometer:	71554	Reg. Date:	TBA

Condition of Vehicle:

General:	Good	Modification:	No	Steering:	NA
Handbrake:	NA	Footbrake:	NA	Paint work:	Good
Tyre Make:	Vifa				
Front Tyre Size:	70/90-17	Front Side:	4mm		
Rear Tyre Size:	80/90-17	Rear Side:	4mm		

Description of Damage:

The vehicle sustained damage on the left portion.

The rear box, exhaust pipe, front fairing, handle bar, clutch lever, brake lever and front mudguard were among the items affected.

Remarks:

Based on visual survey of the vehicle without any repair estimate provided, we viewed that the repair cost should not be more than S\$3,500.00 and could take approximately four (4) working days to complete.

All the stated damage are subject to consistency of the mentioned accident.



Adjuster: Lee Wee Ho
Motor Appraiser

COMPLETED

2017

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Date : 29 December 2017

To : **NTUC Income Insurance Co-operative Limited**
73 Bras Basah Road #05-01
NTUC Trade Union House
Singapore 189556

Attn : Ms Alice Low

AJAX Inspection Services Pte Ltd
120 Lower Delta Road
#08-08, Cendex Centre
Singapore 169208
Tel: +65 6255 0808
Fax: +65 6849 9155
info@ajaxinspection.com

Invoice No – AV12631
Company Reg No -201318067R
GST Reg No - 201318067R

TAX INVOICE

YOUR REF / CLAIM NUMBER : MT/0963605-002
OUR REF : AVS2017-12734/AT
TP VEHICLE NO : FBE6658M
CLAIM TYPE : PRE-REPAIR SURVEY
DATE OF SURVEY : 05 October 2017

No.	Description	Amount (\$\$)
1	Professional fee	50.00

Subtotal	50.00
GST 7.00%	3.50
Total	53.50

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows:

Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd

Account No: 450-309-276-4

Email remittance advice to: accounts@ajaxadjusters.com

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Ms Alice Low

Assign Date:	05/10/2017	Survey Date:	05/10/2017	Our Ref:	AVS2017-12734/WH
Accident Date:	30/09/2017	TP Policy No:	TBA	Your Ref:	MT/0963605-002
Place of Survey:	Eng Soon Painting Services 3998 Woodlands Rd, Yew Tee Ind Est Singapore 678035	Claim Type:	Third Party		

Description of Vehicle:

Veh. No:	FBE6658M	Make/Model:	Yamaha T135
Colour:	Yellow	Engine No:	5YP302747
Engine Capacity:	135cc	Chassis No:	5YP302747
Odometer:	71554	Reg. Date:	2010

Condition of Vehicle:

General:	Good	Modification:	No	Steering:	NA
Handbrake:	NA	Footbrake:	NA	Paint work:	Good
Tyre Make:	Vifa				
Front Tyre Size:	70/90-17	Front Side:	4mm		
Rear Tyre Size:	80/90-17	Rear Side:	4mm		

Description of Damage:

The vehicle sustained damage on the left portion.


The rear box, exhaust pipe, front fairing, handle bar, clutch lever, brake lever and front mudguard were among the items affected.

Remarks:

Our recommended amount for the cost of contract lumpsum repair is S\$1,800.00 with approximately four (4) working days to complete. However, no finalisation was agreed with the repairer.

All the stated damage are subject to consistency of the mentioned accident.

COMPLETED 05/10/2017

Adjuster:  Lee Wee Ho
Motor Appraiser

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle:			FBE6658M	Our Ref: AVS2017-12734/WH	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
List Items					
1	1	Headlamp top cover	Grazed	130.00	130.00
2	1	Headlamp assy with casing	Cracked	255.00	255.00
3	1	Front mudguard	Grazed	108.00	108.00
4	2	Rim	Not necessary	500.00	--
5	1	Front fork cover	Not necessary	94.00	--
6	2	Front fork tube	Not necessary	222.00	--
7	2	Front fork oil seal	Not necessary	104.00	--
8	1	Handle bar	Not necessary	208.00	--
9	1	Handle bar grip	Cut	88.00	88.00
10	2	Handle bar balance	Not necessary	168.00	--
11	1	Meter assy with casing	Not necessary	450.00	--
12	1	Horn switch	Not necessary	70.00	--
13	1	Starter switch	Not necessary	92.00	--
14	1	Side mirror assy	Not necessary	90.00	--
15	1	Crankshaft cover	Not necessary	255.00	--
16	1	Main stand	Not necessary	128.00	--
17	1	Front wheel shaft	Not necessary	68.00	--
18	2	Front side cover with signal lamp	Grazed	340.00	340.00
19	1	Brake pedal	Grazed	65.00	65.00
20	1	Front fork bracket	Not necessary	115.00	--
21	1	Steering cone	Not necessary	145.90	--
22	1	Steering cone bearing	Not necessary	85.00	--
23	1	Exhaust pipe assy	Not necessary	925.00	--

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
 Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No. 201318067R

AJAX

Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle:			FBE6658M	Our Ref: AVS2017-12734/WII	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
24	1	Kick starter	Not necessary	86.00	--
25	1	Seat assy	Not necessary	141.00	--
26	1	Main frame cover	Cracked	158.80	158.80
27	1	Rear swing arm assy	Not necessary	328.00	--
28	1	Body frame assy	Repair	--	--
29	1	Rear mudguard	Not necessary	88.00	--
30	2	Rear side fairing cover	Grazed	138.00	138.00
31	1	Shift gear pedal	Not necessary	68.00	--
32	1	Throttle handle	Not necessary	62.00	--
33	1	Brake lever	Grazed	52.00	52.00
34	1	Clutch lever	Not necessary	52.00	--
Sub Total:				5,879.70	1,334.80
				5,879.70	1,334.80

Special Nett Items

1	2	Number plate	Not necessary	70.00	--
2	2	Fork oil	Not necessary	60.00	--
3	2	Brake oil	Not necessary	60.00	--
4	1	Sticker	Necessary	128.00	128.00
5	1	Meter cable	Not necessary	65.00	--
6	1	Throttle cable	Not necessary	65.00	--
7	1	Wiring harness	Not necessary	250.00	--
8	1	Horn assy	Not necessary	65.00	--
9	2	Tyre	Not necessary	360.00	--

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808. Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067K

AJAX

Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle:		FBE6658M		Our Ref: AVS2017-12734/WH	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
10	1	Gasket	Not necessary	30.00	--
11	1	Front box	Not necessary	88.00	--
12	1	Rear box with bracket	Grazed	220.00	180.00
13	1	Tail brake lamp	Not necessary	120.00	--
Sub Total:				1,581.00	308.00
Total Parts Price:				7,460.70	1,642.80

Labour Cost			
1	Labour charges to repair and panel beat body frame structure cutting/ welding and replacing the above mentioned parts.	1,400.00	500.00
2	Transport.	100.00	100.00
3	To replace wiring harness system incl checking.	220.00	20.00
4	To tuff coat affected areas.	150.00	--
Sub Total:		1,870.00	620.00
Grand Total:		9,330.70	2,262.80

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd



120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Our Ref: AVS2017-12734/AT
Your Ref: MT/0963605-002

Pre-repair survey - 05/10/2017



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd


120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Our Ref: AVS2017-12734/AT
Your Ref: MT/0963605-002

Pre-repair survey



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd



120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Our Ref: AVS2017-12734/AT
Your Ref: MT/0963605-002

Pre-repair survey



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Our Ref: AVS2017-12734/AT

Your Ref: MT/0963605-002

Pre-repair survey



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R


AJAX

Inspection Services Pte Ltd

Our Ref: AVS2017-12734/AT
Your Ref: MT/0963605-002

Pre-repair survey

Re-survey items - 19/10/2017



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd


120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Our Ref: AVS2017-12734/AT
Your Ref: MT/0963605-002

Re-survey items



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R


AJAX

Inspection Services Pte Ltd

Our Ref: AVS2017-12734/AT

Your Ref: MT/0963605-002

Post repair survey - 27/12/2017



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R