

INS. CASE OWNER:

CC 3, C11 1900 6693, Jf03s2

LKK:
IDAC:

Surveyor:

OAS

DOI:

ASSIGNMENT

17/4/19

Date / Time:

12/4/19

Registered in Merimen:

Pre-assign / CCU / FTE

SLM 1245 T



Insured Vehicle No.:

Name of Insured:

CHOW BOON HWEI

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

11/4/19

Is driver the owner?

(YES) NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L) YES NO

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES NO ; TP GIA REPORT: YES NO

Insured Liability:

%

Final ? Yes / No

SAB 53342



INSRS:

WSP:

Tel:

Liability:

RMKS:

Smpt, m



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time	STAGE	DATE / PIC
24/6/2019	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI: 24/6/2019	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by: OAS
FINALIZATION	Date/Time:	Confirm with:	Confirm by: OAS
Repair Cost:	SS\$6,317.30	(9 days) Reduction:	77 %
FINAL SETTLEMENT	Date/Time: 17.03.20	Confirm with: LEE GEM	Email ☒ Call ☐
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	77
Repair Cost:	SS\$6,317.30		
Loss of Rental (LOR):	SS\$1,232.62	(9.5 days) x 113.96	
Loss of Use (LOU):	SS -	(\$ x days)	
Loss of Income (LOI):	SS\$415.00	(\$50 x 9.5 days)	
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☒	(Tick only one)	
GIA/LTA Search	SS\$7.00		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost	SS -		
Total:	SS\$7,881.92	Global Sum SS:	
FINAL PAYMENT	Date/Time: 17.03.20	Confirm with: LEE GEM	Email ☒ Call ☐
Payee 1:	SS\$7,881.92	Name 1:	SMRT TAXIS PTE LTD
Payee 2: (Strike if N.A.)	SS -	Name 2:	
Payee 3: (Strike if N.A.)	SS -	Name 3:	

COPY SENT
24/3/2019

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

400

REF: C71

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No. SHB 5334 Z Yr Regn: 30 Nov 2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Prius c.c. 1798Colour: maroon A/C: Insured / Std / NI / NASp. Reading: 238234 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU003575471Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 11/4/19 D.O.I. 12/4/19

Survey held at

SprintDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PR: +6.317.30 (RED): +20.160.19 77%

Date/Time: File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + PS. \$ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. : \$

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$



Case Details

Case Reference Number :
TAX/04/19/2039

Type of Repair : Accident Repair

Vehicle Registration Number :
SHB5334Z

Company : SMRT Taxis Pte Ltd

Estimation ID : EST-6446-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 10/04/2019 11:20 PM

Vehicle Age(In Months) : 17

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace ▾	/ 00
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace ▾	/ NPC
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace ▾	/ NPC
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace ▾	/ NPC
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace ▾	/ NPC
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace ▾	/ NPC
One Time Key In	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check ▾	X NAI
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check ▾	X NAI
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check ▾	X NAI
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace ▾	/ OR

Total Spare Part Cost 16,986.33

Surveyor Total 2,994.08

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 16,986.33

Final Sur Total 2,994.08

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	/ APC
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	1	83.63	Replace	/ BR
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	1	84.53	Replace	/ BR
One Time Key In	Main			STOPPER, RR BUMPER, RH & LH	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace	/ APC
One Time Key In	Main			SEAL, RR BUMPER, LH	1	85.20	85.20	25.00	63.90	Replace	1	63.90	Replace	/ APC
One Time Key In	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	25.00	63.90	Replace	1	63.90	Replace	/ APC
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	/ CVT
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10	Replace	/ CVT
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace	/ APC
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Check	X N/A
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Check	X N/A
One Time Key In	Main			REAR BUMPER GROMMET SCREW	2	2.20	4.40	25.00	3.30	Replace	2	3.30	Replace	/ APC
One Time Key In	Main			WIRE, LUGGAGE ROOM	1	143.50	143.50	10.00	129.15	Replace	0	0	Not Give	X N/A
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Check	X N/A
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Check	X N/A
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Check	X N/A

Total Spare Part Cost 16,986.33

Surveyor Total 2,994.08

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 16,986.33

Final Sur Total 2,994.08

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PIPE ASSY, EXHAUST, TAIL	1	1,173.90	1,173.90	25.00	880.43	Replace	0	0	Not Give	X N/A
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	1	0	Repair	X R
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	668.40	891.20	25.00	668.40	Replace	1	668.40	Replace	BR /
One Time Key In	Main			TAIL GATE BACK DOOR HINGE ASSY, RH & LH	2	59.10	118.20	25.00	88.65	Replace	0	0	Not Give	X N/A
One Time Key In	Main			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	452.10	10.00	406.89	Replace	0	0	Not Give	X N/A
One Time Key In	Main			TAIL GATE LOCK COVER, BACK DOOR	1	25.30	25.30	25.00	18.98	Replace	0	0	Not Give	X N/A
One Time Key In	Main			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	24.90	25.00	18.67	Replace	0	0	Not Give	X N/A
One Time Key In	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	27.90	55.80	25.00	41.85	Replace	0	0	Not Give	X N/A
One Time Key In	Main			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	29.70	25.00	22.27	Replace	0	0	Not Give	X N/A
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH	1	29.90	29.90	25.00	22.42	Replace	0	0	Not Give	X N/A
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH	1	29.90	29.90	25.00	22.42	Replace	0	0	Not Give	X N/A
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	1	19.70	19.70	25.00	14.77	Replace	0	0	Not Give	X N/A
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	0	0	Not Give	X N/A
One Time Key In	Main			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	360.70	25.00	270.52	Replace	1	270.52	Replace	/ CRU
One Time Key In	Main			TAILGATE BOARD, COVER	1	24.10	24.10	25.00	18.08	Replace	0	0	Check	X N/A
One Time Key In	Main			TAILGATE BOARD, HANDLE PULL	1	19.50	19.50	25.00	14.63	Replace	0	0	Check	X N/A

Total Spare Part Cost 16,986.33

Surveyor Total 2,994.08

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 16,986.33

Final Sur Total 2,994.08

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAILGATE BOARD ASSY	1	251.50	251.50	25.00	188.63	Replace	0	0	Check	X NAI
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give	X NAI
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	0	0	Not Give	X NAI
One Time Key In	Main			LAMP ASSY, LICENSE PLATE	2	63.70	127.40	10.00	114.66	Replace	0	0	Not Give	X NAI
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0	Check	X NAI
One Time Key In	Main			SPOILER SUB-ASSY, REAR	1	1,322.10	1,322.10	25.00	991.57	Replace	0	0	Not Give	X NAI
One Time Key In	Main			LAMP SET, STOP CENTER	1	186.50	186.50	10.00	167.85	Replace	0	0	Not Give	X NAI
One Time Key In	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	/ NPC
One Time Key In	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	/ NPC
One Time Key In	Main			EMBLEM SUB-ASSY REAR	1	46.30	46.30	25.00	34.72	Replace	1	34.72	Replace	/ NPC
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	/ NPC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	/ NPC
One Time Key In	Main			END PANEL SUBASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	1	472.35	Replace	/ DO
One Time Key In	Main			END PANEL, COVER, DECK TRIM SERVICE HOLE	1	47.00	47.00	25.00	35.25	Replace	0	0	Check	X NAI
One Time Key In	Main			END PANEL, COVER, DECK TRIM, REAR	1	122.80	122.80	25.00	92.10	Replace	0	0	Check	X NAI

Total Spare Part Cost 16,986.33

Surveyor Total 2,994.08

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 16,986.33

Final Sur Total 2,994.08

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			REINFORCEMENT ASSY, REAR FLOOR END PANEL, RH & LH	2	56.70	113.40	25.00	85.05	Replace	0	0	Check	X N/A
One Time Key In	Main		4006314	SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	/ APC
One Time Key In	Main			SPARE TYRE PANEL, PAN, REAR FLOOR	1	564.80	564.80	25.00	423.60	Replace	0	0	Check	X N/A
One Time Key In	Main			EXTENSION, REAR FLOOR SIDE PANEL, LH	1	76.20	76.20	25.00	57.15	Replace	0	0	Check	X N/A
One Time Key In	Main			EXTENSION, REAR FLOOR SIDE PANEL, RH	1	76.20	76.20	25.00	57.15	Replace	0	0	Check	X N/A
One Time Key In	Main			BOARD, REAR FLOOR, NO.1	1	502.20	502.20	25.00	376.65	Replace	0	0	Check	X N/A
One Time Key In	Main			BOX, DECK FLOOR, REAR	1	102.20	102.20	25.00	76.65	Replace	0	0	Check	X N/A
One Time Key In	Main			BOX, DECK FLOOR, LH	1	303.40	303.40	25.00	227.55	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BOX, DECK FLOOR, RH	1	304.00	304.00	25.00	228.00	Replace	0	0	Not Give	X N/A
One Time Key In	Main			PANEL ASSY, DECK TRIM SIDE, LH	1	344.70	344.70	25.00	258.52	Replace	0	0	Not Give	X N/A
One Time Key In	Main			PANEL ASSY, DECK TRIM SIDE, RH	1	344.70	344.70	25.00	258.52	Replace	0	0	Not Give	X N/A
One Time Key In	Main			WIRE, FLOOR	1	3,860.00	3,860.00	10.00	3,474.00	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BRACKET, SPARE WHEEL CLAMP	1	21.30	21.30	25.00	15.98	Replace	0	0	Not Give	X N/A
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	438.10	10.00	394.29	Replace	0	0	Check	X N/A
One Time Key In	Main			TROUGH, BACK DOOR, LH	1	99.80	99.80	25.00	74.85	Replace	0	0	Check	X N/A
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	824.80	25.00	618.60	Replace	0	0	Not Give	X N/A

Total Spare Part Cost 16,986.33

Surveyor Total 2,994.08

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 16,986.33

Final Sur Total 2,994.08

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			DUCT ASSY, QUARTER VENT, RH & LH	1	65.00	65.00	25.00	48.75	Replace	0	0	Not Give	X NAI
One Time Key In	Main			LINER, REAR FENDER, LH	1	135.80	135.80	25.00	101.85	Replace	0	0	Not Give	X NAI
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	438.10	438.10	10.00	394.29	Replace	0	0	Check	X NAI
One Time Key In	Main			TROUGH, BACK DOOR, RH	1	99.80	99.80	25.00	74.85	Replace	0	0	Check	X NAI
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	0	0	Not Give	X NAI
One Time Key In	Main			DUCT ASSY, QUARTER VENT, RH & LH	1	65.00	65.00	25.00	48.75	Replace	0	0	Not Give	X NAI
One Time Key In	Main			LINER, REAR FENDER, RH	1	135.80	135.80	25.00	101.85	Replace	0	0	Not Give	X NAI

Total Spare Part Cost 16,986.33

Surveyor Total 2,994.08

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 16,986.33

Final Sur Total 2,994.08

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,352.00	600	
Total:			1,352.00	600.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	0	
3	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
4	Main	TO RESPRAY TAIL GATE	378.00	200	
5	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	
Total:			3,312.00	600.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
- Remarks: elementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
6	Main	TO RESPRAY REAR SPOILER	180.00	0	
7	Main	TO RESPRAY REAR PANEL	180.00	100	
8	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	
9	Main	TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0	
10	Main	TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0	
11	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	0	
12	Main	TO RESPRAY TROUGH BACK DOOR LH	180.00	0	
13	Main	TO RESPRAY REAR FENDER LH	378.00	0	
14	Main	TO RESPRAY REAR FENDER RH	378.00	0	
Total:			3,312.00	600.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	NPC
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	30	NPC
3	Main	TO REMOVE / REFIT SEAT	120.00	0	
4	Main	TO REMOVE & REFIT EXHAUST	120.00	0	
5	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	
6	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	NPC
7	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	120.00	0	
8	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
9	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0	
10	Main	TO REMOVE AND REFIT WIRE HARDESS	250.00	0	
11	Main	TO REPLACE SUNDRY PARTS	100.00	0	
12	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,650.00	70.00	

27447.40
30968.60

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	16,986.33	2,994.08
Total Labour Cost	1,352.00	600.00
Total Spray Painting	3,312.00	600.00
Other	1,650.00	70.00
Overall Total	23,300.33	4,264.08
Lump Sum Repair Option		
Lump Sum Total	0.00	4,264.08
Surveyor Approved Amount		4,264.08
No of Repair Days*	10	5
Remarks		P/P REPAIR, PHOTO BEFORE PAINT.
Surveyor Name		Hwee jie
Signature		
Survey Date	12/04/2019	

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLYMENT PARTS

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TAX/04/19/2039	Date of Collection	12 1041 19
Vehicle No	84B 53342	Date of Request	12 041 19
Vehicle Model	TOYOTA prius 4	Number of Days to Extend (If any)	4 \$ day

S/N	Part Number	Part Description	Quantity	Unit Price	
1	9397, 98, 99	Filler, RR Bumper, LH	1	\$ 119.90	REF
2	9404, 05	Filler, RR Bumper RH	1	\$ 119.90	DER
3	9440, 9401	Rear Bumper Reinforcement	1	\$ 318.80	BT
4	9331, 9382, 9383 9334, 85, 86, 87	Tail Gate Panel Sub Assy.	1	\$ 929.60	BUC
5		Sealant w/screen	1	\$ 37.00	nec
6	To Respray Filler RR Bumper LH			\$ 180.00	\$50
7	To Respray Filler RR Bumper RH			\$ 180.00	\$50
8	To Respray Rear Fender LH			\$ 578.00	\$200

<<<Please submit photographs for damaged parts>>>

15/4/19

I, (Name) heeng Chue Keng

(Position)

Do solemnly and sincerely declare that Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

REQUEST FOR SUPPLYMENT PARTS

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TAX/04/19/2039	Date of Collection	12 1 04 19
Vehicle No	SHB 53342	Date of Request	12 1 04 19
Vehicle Model	Toyota Prius 4	Number of Days to Extend (If any)	

S/N	Part Number	Part Description	Quantity	Unit Price	
9		TO Respray Rear Fender Kit		\$378.00	\$200
10		TO Transfer Rear Tailgate Mechanism		\$120.00	\$50
11		TO INSPECT RR lighting mechanisms & water		\$120.00	\$30
		Test RR lighting for leakage.			
12		TO Remove and Refit Rear Windscreen		\$240.00	\$120
13		TO Request Labour for Repair Tailamp panel -		\$400.00	\$200
9338, 9389		CH & RH and Request five (5) more			
9392, 9393		working days			

<<<Please submit photographs for damaged parts>>>

I, (Name)

Leung Chee Kwai

(Position)

Do solemnly and sincerely declare that: Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration

[To be signed in front of an authorised witness]



I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

Poh Kin

Section A - Accident Details	
Registration Number	SHB5334Z
Case Reference Number	TAX/04/19/2039
Registration Date	30/11/2017
Company Type	SMRT Taxi's Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TEO BENG KENG
Type of Accident	Head to Rear
Accident Date and Time	11/4/2019 7:20 AM
Accident Reported Date and Time	11/4/2019 9:38 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101004
Special Instruction to ARC, if any	TP/CHINA TAIPING - LKK
Prepared Date and Time	11/4/2019 2:40 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Right Side

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,690.00	\$800.00
Total Spray Cost	\$4,428.00	\$1,100.00
Total Spare Part Cost	\$18,139.49	\$4,147.30
Total Other Cost	\$2,040.00	\$270.00
TOTAL COST	\$26,297.49	\$6,317.30 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	10.0	9.0
Prepared / Adjusted By	Zhi Yang Phua	Hwee Jie (LKK) / China Taiping
ARC / Surveyor Sign Off Date	25/04/2019 11:06 AM	25/04/2019 11:15 AM
Signature		
Remarks	SUP = 4 DAYS	P/P REPAIR, PHOTO BEFORE PAINT.

P/P \$6317.3/- 9 days.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1905-0070	Invoice Number	
Quotation Date	04.05.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$338.00	\$200.00
TO REPAIR REAR PORTION	\$1,352.00	\$600.00
Total Labour	\$1,690.00	\$800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$50.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$50.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	\$180.00	\$0.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
TO RESPRAY TROUGH BACK DOOR LH	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$4,428.00	\$1,100.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$50.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$30.00	\$30.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$120.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$30.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO REMOVE & REFIT EXHAUST	\$120.00	\$0.00

TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$2,040.00	\$270.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace
		52462470 30	PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52462470 20	PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52462470 10	PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52191470 30	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.00	25.00	\$16.50	Replace	Replace
		52566479 00	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Check
		52565479 00	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Check
		52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52576470 40	RETAINER, RR BUMPER, LH	1.00	\$111.50	25.00	\$83.63	Replace	Replace
		52575470 40	RETAINER, RR BUMPER, RH	1.00	\$112.70	25.00	\$84.53	Replace	Replace
		52599680 30	STOPPER, RR BUMPER, RH & LH	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		52592470 40	SEAL, RR BUMPER, LH	1.00	\$65.20	25.00	\$63.90	Replace	Replace
		52591470 50	SEAL, RR BUMPER, RH	1.00	\$65.20	25.00	\$63.90	Replace	Replace
		52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace
		52169470 20	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace
		52461470 10	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace
		81581470 10	LENS & BODY ASSY, RR BUMPER, RH	0.00	\$486.80	0.00	\$0.00	Replace	Check
		81591470 10	LENS & BODY ASSY, RR BUMPER, LH	0.00	\$486.80	0.00	\$0.00	Replace	Check
		90189060 29	REAR BUMPER GROMMET SCREW	2.00	\$2.20	25.00	\$3.30	Replace	Replace
		82183470 20	WIRE, LUGGAGE ROOM	0.00	\$143.50	0.00	\$0.00	Replace	Not Given
		58399470 30	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Check
		58398470 50	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Check
		66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Check
		17430377 30	PIPE ASSY, EXHAUST, TAIL	0.00	\$1,173.90	0.00	\$0.00	Replace	Not Given
		67005474 40	TAIL GATE PANEL SUB-ASSY, BACK DOOR	1.00	\$929.60	100.00	\$0.00	Replace	Repair
		76801471 10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$891.20	25.00	\$668.40	Replace	Replace



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 66662823
Accident Reporting Number : 66662672

Date Generated : 16/05/2019

User ID : PohSuan

	68810470 61	TAIL GATE BACK DOOR HINGE ASSY, RH & LH	0.00	\$59.10	0.00	\$0.00	Replace	Not Given	X
	69350470 50	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$452.10	0.00	\$0.00	Replace	Not Given	X
	69321470 10	TAIL GATE LOCK COVER, BACK DOOR	0.00	\$25.30	0.00	\$0.00	Replace	Not Given	X
	69430520 50	TAIL GATE STRIKER ASSY, BACK DOOR	0.00	\$24.90	0.00	\$0.00	Replace	Not Given	X
	56117501 40	TAIL GATE DAM, BACK DOOR GLASS UPPER	0.00	\$27.90	0.00	\$0.00	Replace	Not Given	X
	75571470 10	TAIL GATE MOULDING GLASS, BACK DOOR	0.00	\$29.70	0.00	\$0.00	Replace	Not Given	X
	75574470 40	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$29.90	0.00	\$0.00	Replace	Not Given	X
	75573471 10	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$29.90	0.00	\$0.00	Replace	Not Given	X
	75575470 51	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$19.70	0.00	\$0.00	Replace	Not Given	X
		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
	67881470 50	TAIL GATE WEATHERSTRIP, BACK	1.00	\$360.70	25.00	\$270.53	Replace	Replace	✓
	64721470 50C0	TAILGATE BOARD, COVER	0.00	\$24.10	0.00	\$0.00	Replace	Check	X
	74811470 20C0	TAILGATE BOARD, HANDLE PULL	0.00	\$19.50	0.00	\$0.00	Replace	Check	X
	67750470 80C0	TAILGATE BOARD ASSY	0.00	\$251.50	0.00	\$0.00	Replace	Check	X
		NUMBER PLATE	0.00	\$35.00	0.00	\$0.00	Replace	Not Given	X
		NUMBER PLATE FRAME	0.00	\$25.00	0.00	\$0.00	Replace	Not Given	X
	81270331 10	LAMP ASSY, LICENSE PLATE	0.00	\$63.70	0.00	\$0.00	Replace	Not Given	X
	89997301 00	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Check	X
	76085479 16	SPOILER SUB-ASSY, REAR	0.00	\$1,322.10	0.00	\$0.00	Replace	Not Given	X
	81006470 30	LAMP SET, STOP CENTER	0.00	\$186.50	0.00	\$0.00	Replace	Not Given	X
	75441470 90	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	✓
	75442471 30	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	✓
	75403480 10	EMBLEM SUB-ASSY REAR	1.00	\$46.30	25.00	\$34.73	Replace	Replace	✓
		SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓
	58307470 90	END PANEL SUBASSY, BODY LOWER BACK	1.00	\$629.80	25.00	\$472.35	Replace	Replace	✓
	64718470 80C0	END PANEL, COVER, DECK TRIM SERVICE	0.00	\$47.00	0.00	\$0.00	Replace	Check	X
	64716471 30C0	END PANEL, COVER, DECK TRIM, REAR	0.00	\$122.80	0.00	\$0.00	Replace	Check	X
	58350470 10	REINFORCEMENT ASSY, REAR FLOOR END PANEL	0.00	\$56.70	0.00	\$0.00	Replace	Check	✓
4006314		SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace	✓
	58311471 30	SPARE TYRE PANEL, PAN, REAR FLOOR	0.00	\$564.80	0.00	\$0.00	Replace	Check	X
	58316470 10	EXTENSION, REAR FLOOR SIDE PANEL, LH	0.00	\$76.20	0.00	\$0.00	Replace	Check	X
	58315470 20	EXTENSION, REAR FLOOR SIDE PANEL, RH	0.00	\$76.20	0.00	\$0.00	Replace	Check	X
	58415471 10C2	BOARD, REAR FLOOR, NO.1	0.00	\$502.20	0.00	\$0.00	Replace	Check	X
	64993471 10	BOX, DECK FLOOR, REAR	0.00	\$102.20	0.00	\$0.00	Replace	Check	X
	64997470 60	BOX, DECK FLOOR, LH	0.00	\$303.40	0.00	\$0.00	Replace	Not Given	X
	64995470 50	BOX, DECK FLOOR, RH	0.00	\$304.00	0.00	\$0.00	Replace	Not Given	X
	64740471 90C2	PANEL ASSY, DECK TRIM SIDE, LH	0.00	\$344.70	0.00	\$0.00	Replace	Not Given	X
	64730472 40C2	PANEL ASSY, DECK TRIM SIDE, RH	0.00	\$344.70	0.00	\$0.00	Replace	Not Given	X
	8216147 N40	WIRE, FLOOR	0.00	\$3,860.00	0.00	\$0.00	Replace	Not Given	X
	58351120 60	BRACKET, SPARE WHEEL CLAMP	0.00	\$21.30	0.00	\$0.00	Replace	Not Given	X

	81561471 51	LENS & BODY, REAR COMBINATION LAMP, LH	0.00	\$438.10	0.00	\$0.00	Replace	Check	X
	61622470 60	TROUGH, BACK DOOR, LH	0.00	\$99.80	0.00	\$0.00	Replace	Check	X
	61602471 60	PANEL SUB-ASSY, FENDER REAR LH	0.00	\$824.80	0.00	\$0.00	Replace	Not Given	X
	62940470 10	DUCT ASSY, QUARTER VENT, RH & LH	0.00	\$65.00	0.00	\$0.00	Replace	Not Given	X
	65638470 60	LINER, REAR FENDER, LH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	X
	81551472 81	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$438.10	0.00	\$0.00	Replace	Check	X
	61621470 50	TROUGH, BACK DOOR, RH	0.00	\$99.80	0.00	\$0.00	Replace	Check	X
	61601471 50	PANEL SUB-ASSY, FENDER REAR RH	0.00	\$824.80	0.00	\$0.00	Replace	Not Given	X
	62940470 10	DUCT ASSY, QUARTER VENT, RH & LH	0.00	\$65.00	0.00	\$0.00	Replace	Not Given	X
	65637470 60	LINER, REAR FENDER, RH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	X
Total				\$20,745.20		\$2,994.14			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52566479 00	FILLER, RR BUMPER, LH	1.00	\$119.90	25.00	\$89.93	Replace	Replace
		52565479 00	FILLER, RR BUMPER, RH	1.00	\$119.90	25.00	\$89.93	Replace	Replace
		52023470 30	REAR BUMPER REINFORCEMENT	1.00	\$318.80	25.00	\$239.10	Replace	Replace
		67005474 40	TAIL GATE PANEL SUB- ASSY, BACK DOOR	1.00	\$929.60	25.00	\$697.20	Replace	Replace
			SEALANT W/SCREEN	1.00	\$37.00	0.00	\$37.00	Replace	Replace
Total					1,525.20		1,153.16		

4147.30
+ 800.00
+ 1370.00

6317.30

REQUEST FOR SUPPLYMENT PARTS

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TAX/24/14/2039	Date of Collection	12 1041 19
Vehicle No	84G 53342	Date of Request	12 041 19
Vehicle Model	Toyota prius 4	Number of Days to Extend (If any)	4 \$ day


S/N	Part Number	Part Description	Quantity	Unit Price	
1	9397, 98, 99	Filler, RR Bumper LH	1	\$ 119.90	REF
2	9404, 05	Filler, RR Bumper RH	1	\$ 119.90	DER
3	9440, 9401	Rear Bumper Reinforcement	1	\$ 318.80	BT
4	9331, 9382, 9383 9384, 85, 86, 87	Tail Gate Panel Sub Assy.	1	\$ 929.60	BUC
5		Sealant w/screen	1	\$ 37.00	DEC
6	To Respray Filler RR Bumper LH			\$ 180.00	\$50
7	To Respray Filler RR Bumper RH			\$ 180.00	\$50
8	To Respray Rear Fender LH			\$ 578.00	\$200

<<<Please submit photographs for damaged parts>>>

I, (Name) Henry Choe Kwey

(Position)

Do solemnly and sincerely declare that Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....


Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC/ Reservation / Number
Photo Submitted	YES / NO	Date of submission

REQUEST FOR SUPPLYMENT PARTS

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	<i>TAKE/04/19/2019</i>	Date of Collection	<i>12 1 04 19</i>
Vehicle No	<i>SH13 53342</i>	Date of Request	<i>12 1 04 19</i>
Vehicle Model	<i>Toyota Prius 4</i>	Number of Days to Extend (If any)	

S/N	Part Number	Part Description	Quantity	Unit Price	
9		TO Respray Rear Fender Kit		\$378.00	\$200
10		TO Transfer Rear Tailgate Mechanism		\$120.00	\$50
11		TO INSPECT RR lighting mechanism & water		\$120.00	\$30
		Test RR lighting per leakage.			
12		TO Remove and Refit Rear Windscreen		\$240.00	\$120
13		TO Request Labour for Repair Tailamp panel -		\$400.00	\$200
9388, 9389 9392, 9393		CH & RH and Request since (5) more working days			

<<<Please submit photographs for damaged parts>>>

I, (Name) *Heung Cheung Kwai*
(Position) _____

Do solemnly and sincerely declare that: Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
[Signature]

Signature of person making this declaration
[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5369K

Vehicle Details

Vehicle No.:	SHB5334Z
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS109054
Chassis No.:	JTDKB3FU003575471
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	30 Nov 2017
First Registration Date:	30 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2025
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	29 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$27,810.00
Total Rebate Amount:	\$31,560.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Apr 2019

OK



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI19006693/Jpa3

Date: 16/04/2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB 5334Z

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/04/2019 at the premises of M/s SMRT Automotive Services Pte Ltd (Woodlands) and have the following to report:-

Workshop Estimate Amount	: S\$	26,721.53
Revised Estimate Amount	: S\$	6,689.28
"Check" Items Amount	: S\$	4,182.50
Total (Including Check Items)	: S\$	10,871.78

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

ONG HWEE JIE
Licensed Appraiser



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/CTI19006693/Jfa3

26 JUNE 2019

CHOW BOON HWEE
12 LORONG SARINA
#04-08
SINGAPORE 416736

Dear Sir/Madam,

ACCIDENT INVOLVING SLM 1245T AND SHB 5334Z ALONG/AT PIE GOING TOWARDS AMK (OPP SP GROUP) ON 11/04/2019

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Yours faithfully,

Poh Kin, Chong
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: pohkin@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI19006693/Jea3s2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 31-03-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLM 1245T	Veh. Inspected	SHB 5334Z	
Policy No.	DMPCSN3025981902	Coverage (\$)	0.00	
Claim No.	SNM19D201622	Excess (\$)	0.00	
Assign From		Assign Date	12/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU003575471	Colour	MAROON	
Odometer	238234	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/04/2019	Inspection Date	12/04/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5334Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER, RR BUMPER ASSY (DISC 25%)	DENTED	423.90	317.93
10	CLIPS PIECE, FRT & RR BUMPER @ \$1.50 (DISC 25%)	NECESSARY	15.00	11.25
2	PAD, RR BUMPER, RH & LH, 1 @ \$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD, RR BUMPER, RH & LH, 2 @ \$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD, RR BUMPER, RH & LH, 3 @ \$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	SEAL, RR BUMPER ARM, RH & LH @ \$11.00 (DISC 25%)	NECESSARY	22.00	16.50
1	RETAINER, RR BUMPER, LH (DISC 25%)	BROKEN	111.50	83.63
1	RETAINER, RR BUMPER, RH (DISC 25%)	BROKEN	112.70	84.53
2	STOPPER, RR BUMPER, RH & LH @ \$4.30 (DISC 25%)	NECESSARY	8.60	6.45
1	SEAL, RR BUMPER, LH (DISC 25%)	NECESSARY	85.20	63.90
1	SEAL, RR BUMPER, RH (DISC 25%)	NECESSARY	85.20	63.90
1	GUARD, RR BUMPER, LOWER (DISC 25%)	CUT	558.30	418.73
1	COVER, GUARD RR BUMPER LOWER (DISC 25%)	CUT	14.80	11.10
3	PAD, RR BUMPER, CTR @ \$2.20 (DISC 25%)	NECESSARY	6.60	4.95
2	REAR BUMPER GROMMET SCREW @ \$2.20 (DISC 25%)	NECESSARY	4.40	3.30
1	TAIL GATE BACK DOOR OUTSIDE SUB-ASSY (DISC 25%)	BROKEN	891.20	668.40
1	TAIL GATE WEATHERSTRIP, BACK DOOR (DISC 25%)	CRUSHED	360.70	270.53
1	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT (DISC 25%)	NECESSARY	52.30	39.23
1	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.23
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.73
1	END PANEL SUBASSY, BODY LOWER BACK (DISC 25%)	DENTED	629.80	472.35
1	SENSOR REVERSE (SN)	BROKEN	180.00	180.00
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888	NECESSARY	21.60	21.60
1	SEALANT SIKAFLEX	NECESSARY	37.00	37.00
1	FILLER, RR BUMPER, LH	NOT NECESSARY	119.90	-
1	FILLER, RR BUMPER, RH	NOT NECESSARY	119.90	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-

Report Ref No. CC3/CTI19006693/Jea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LENS & BODY ASSY, RR BUMPER, RH	NOT NECESSARY	486.80	-
1	LENS & BODY ASSY, RR BUMPER, LH	NOT NECESSARY	486.80	-
1	WIRE, LUGGAGE ROOM	NOT NECESSARY	143.50	-
1	COVER, REAR FLOOR UNDER, LH	NOT NECESSARY	234.30	-
1	COVER, REAR FLOOR UNDER, RH	NOT NECESSARY	169.50	-
1	COVER, REAR FLOOR UNDER CENTER	NOT NECESSARY	222.60	-
1	PIPE ASSY, EXHAUST, TAIL	NOT NECESSARY	1,173.90	-
2	TAIL GATE BACK DOOR HINGE ASSY, RH & LH @ \$59.10	NOT NECESSARY	118.20	-
1	TAIL GATE LOCK ASSY, BACK DOOR	NOT NECESSARY	452.10	-
1	TAIL GATE LOCK COVER, BACK DOOR	NOT NECESSARY	25.30	-
1	TAIL GATE STRIKER ASSY, BACK DOOR	NOT NECESSARY	24.90	-
2	TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE @ \$27.90	NOT NECESSARY	55.80	-
1	TAIL GATE MOULDING GLASS, BACK DOOR	NOT NECESSARY	29.70	-
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH	NOT NECESSARY	29.90	-
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH	NOT NECESSARY	29.90	-
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR	NOT NECESSARY	19.70	-
3	SEALANT W/SCREEN @ \$37.00	NOT NECESSARY	111.00	-
1	TAILGATE BOARD, COVER	NOT NECESSARY	24.10	-
1	TAILGATE BOARD, HANDLE PULL	NOT NECESSARY	19.50	-
1	TAILGATE BOARD ASSY	NOT NECESSARY	251.50	-
1	NUMBER PLATE	NOT NECESSARY	35.00	-
1	NUMBER PLATE FRAME	NOT NECESSARY	25.00	-
2	LAMP ASSY, LICENSE PLATE @ \$63.70	NOT NECESSARY	127.40	-
1	ANTENNA ELECTRICAL KEY	NOT NECESSARY	60.30	-
1	SPOILER SUB-ASSY, REAR	NOT NECESSARY	1,322.10	-
1	LAMP SET, STOP CENTER	NOT NECESSARY	186.50	-
1	END PANEL, COVER, DECK TRIM SERVICE HOLE	NOT NECESSARY	47.00	-
1	END PANEL, COVER, DECK TRIM, REAR	NOT NECESSARY	122.80	-
2	REINFORCEMENT ASSY, REAR FLOOR END PANEL, RH & LH @ \$56.70	NOT NECESSARY	113.40	-
1	SPARE TYRE PANEL, PAN REAR FLOOR	NOT NECESSARY	564.80	-
1	EXTENSION REAR FLOOR SIDE PANEL, LH	NOT NECESSARY	76.20	-
1	EXTENSION REAR FLOOR SIDE PANEL, RH	NOT NECESSARY	76.20	-

Report Ref No. CC3/CTI19006693/Jea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOARD, REAR FLOOR, NO.1	NOT NECESSARY	502.20	-
1	BOX, DECK FLOOR, REAR	NOT NECESSARY	102.20	-
1	BOX, DECK FLOOR, LH	NOT NECESSARY	303.40	-
1	BOX, DECK FLOOR, RH	NOT NECESSARY	304.00	-
1	PANEL ASSY, DECK TRIM SIDE, LH	NOT NECESSARY	344.70	-
1	PANEL ASSY, DECK TRIM SIDE, RH	NOT NECESSARY	344.70	-
1	WIRE, FLOOR	NOT NECESSARY	3,860.00	-
1	BRACKET, SPARE WHEEL CLAMP	NOT NECESSARY	21.30	-
1	LENS & BODY REAR COMBINATION LAMP, LH	NOT NECESSARY	438.10	-
1	TROUGH, BACK DOOR, LH	NOT NECESSARY	99.80	-
1	PANEL SUB-ASSY, FENDER REAR LH	NOT NECESSARY	824.80	-
1	DUCT ASSY, QUARTER VENT, RH & LH	NOT NECESSARY	65.00	-
1	LINER, REAR FENDER, LH	NOT NECESSARY	135.80	-
1	LENS & BODY REAR COMBINATION LAMP, RH	NOT NECESSARY	438.10	-
1	TROUGH BACK DOOR, RH	NOT NECESSARY	99.80	-
1	PANEL SUB-ASSY, FENDER REAR RH	NOT NECESSARY	824.80	-
1	DUCT ASSY, QUARTER VENT, RH & LH	NOT NECESSARY	65.00	-
1	LINER, REAR FENDER, RH	NOT NECESSARY	135.80	-
1	TAIL GATE PANEL SUB-ASSY, BACK DOOR	TO REPAIR SEE LABOUR	929.60	-
1	FILLER, RR BUMPER, LH (DISC 25%) (ADDITIONAL)	DEFORMED	119.90	89.93
1	FILLER, RR BUMPER, RH (DISC 25%) (ADDITIONAL)	DEFORMED	119.90	89.93
1	REAR BUMPER REINFORCEMENT (DISC 25%) (ADDITIONAL)	BENT	318.80	239.10
1	TAIL GATE PANEL SUB-ASSY, BACK DOOR (DISC 25%) (ADDITIONAL)	BUCKLED	929.60	697.20
1	SEALANT W/SCREEN (SN) (ADDITIONAL)	NECESSARY	37.00	37.00
			22,658.60	4,147.30
LABOUR				
PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF TAIL GATE PANEL SUB-ASSY, BACK DOOR.			1,352.00	600.00
SPRAY PAINT.			3,312.00	600.00
TO CHECK WIRING AND SYSTEM FUNCTION.			80.00	20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA.			200.00	30.00

Report Ref No. CC3/CTI19006693/Jea3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE / REFIT SEAT.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT EXHAUST.	NOT NECESSARY	120.00	-
	TO TRANSFER REAR TAILGATE MECHANISM.	NOT NECESSARY	120.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX REAR WINDSCREEN.	NOT NECESSARY	240.00	-
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	250.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO RESPRAY FILLER RR BUMPER LH. (ADDITIONAL)		180.00	50.00
	TO RESPRAY FILLER RR BUMPER RH. (ADDITIONAL)		180.00	50.00
	TO RESPRAY REAR FENDER LH. (ADDITIONAL)		378.00	200.00
	TO RESPRAY REAR FENDER RH. (ADDITIONAL)		378.00	200.00
	TO TRANSFER REAR TAILGATE MECHANISM. (ADDITIONAL)		120.00	50.00
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LEAKING FOR LEAKAGE. (ADDITIONAL)		120.00	30.00
	TO REMOVE AND REFIX REAR WINDSCREEN. (ADDITIONAL)		240.00	120.00
	TO REQUEST LABOUR FOR REPAIR TAILLAMP PANEL, LH & RH AND REQUEST FIVE (5) MORE WOARKING DAYS. (ADDITIONAL)		400.00	200.00
			8,310.00	2,170.00
GRAND TOTAL			30,968.60	6,317.30
RECOMMENDED COST OF REPAIRS				6,317.30

Report Ref No. CC3/CT19006693/Jea3s2

ONG HWEE JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.