



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 5808K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (CONSISTENT)	MTG CRACKED	915.40	915.40
5	REAR BUMPER CLIP @\$5.00 (CONSISTENT)	NECESSARY	25.00	25.00
1	REAR LH DOOR (CONSISTENT)	DENTED / WARPED	1,364.50	1,364.50
1	SET REAR LH DOOR FRAME STICKER (CONSISTENT)	NECESSARY	77.70	77.70
1	REAR LH DOOR INNER RUBBER (CONSISTENT)	SERVICEABLE	165.50	-
	LESS 20% DISCOUNT		-509.62	-476.52
			2,038.48	1,906.08
	<u>LABOUR</u>			
	REMOVE & REFIX REAR BUMPER ,REAR LH DOOR & ATTACHMENTS ,KNOCKING & REPAIR REAR LH FENDER & REALIGN THE SAME.		700.00	550.00
	PUTTY & RESPRAY REAR BUMPER ,REAR LH FENDER ,REAR LH DOOR & ALL AFFECTED AREAS.		800.00	660.00
	REMOVE & REFIX REAR LH DOOR WINDOW GLASSES AND RESET CENTRAL LOCKING.		60.00	60.00
	RUSTPROOFING.		30.00	30.00
			1,590.00	1,300.00
	GRAND TOTAL		3,628.48	3,206.08
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,550.00

Report Ref No. CC4/ASM19006700/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.