

ASS. REC. BY:

REF: CS/SMO19006732/ AV d3

N2
Special Instruction:

Survey: Adrian

minim-h

ASSIGNMENT (Office)

From (Person): Hwang shiang yi

of

SMO

Date/Time: 15.4.19 18.54p.m

Estimated Cost:

Bill to:

OD (TP) WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBF 4178 P

Insured:

SKT 2916T

at Workshop m/s Yap Lee

Tel:

68441555

of 1 Kaki Bukit Ave 6 #01-26

Policy No: D18MTPV01012222

Claim No: CMTD1901878

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13.4.2019

17.4.2019 (mar)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 16.4.19 9.23a.m

Person Contacted:

Shirley

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	GBF 4178 P - X	
	SKT 2916T - X	
17/4/19	Informed Shiang yi pending workshop est via mr. man	
13/5/19	Adrian confirmed LS \$ 5200 (Red 990423, 62/9)	

Sumpo

ASSIGNMENT

From: Date: 17.4.2019

Estimated Cost:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBF 4178P

at Workshop m/s YAP Lee Motor

of BIK 1 Kaki Bukit Ave 6 #01-26

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

mwp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: GBF4178P Yr Regn: 2016 Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

G.C 2982

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

61850

T/Radio: Insured / Std / NI / NA

Eng/No:

JTFHT02P800206999

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195R15C

R:

195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

17/04/19

Survey held at

Yap Lee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Sumpo

14/5/19

Send preli. revised via merimen

RECEIVED 14 MAY 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

14/5- typst

Report Format :

merimen

Lump Sum / I.B.I: (\$

6200/2

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

450

10

460

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	Sompo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Hwang Shiang Yi	Date:	14 May 2019

Preliminary Advice

Insured Vehicle No	: SKT2916J	Accident Date	: 13/04/2019
TP Vehicle No	: GBF4178P	Assignment Date	: 15/04/2019
Make	: TOYOTA HIACE	Est. Duration of Repair	: 7
Date of Inspection	: 17/4/2019		
Inspection At	: YAP LEE MOTOR		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,104.23
Revised Amount	:S\$	6,200.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,200.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :The above survey was conducted on a 'Without Prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Apr 2019		15 Apr 2019 18:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN ZAIXIANG ADRIAN, ID: S8228229G		
Main Claimant:	COOL SYSTEM TECHNOLOGY		
Vehicle Reg. No.:	GBF4178P	Date of Loss:	13/04/2019 10:00 - :59
Claim Type:	TP / CMTD1901878	Policy/Cover Note No.:	D18MTPV01012222 (Comprehensive)
Vehicle Reg. No. (Insured):	SKT2916T	Policy No. (Claimant):	
		Excess:	
Repairer:	Yap Lee Motor (HQ) 1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/04/2019]		
Adj Asg. Remarks:	Please assign to Mr Marcus Chua to conduct the survey.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***GBF4178P (CMTD1901878)**
[SKT2916T]

TP
COOL SYSTEM TECHNOLOGY
Apr 13 2019 10:00AM
[TAN ZAIXIANG ADRIAN]
Yap Lee Motor

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 17/04/2019 15:50 PM.
To shiangyi.hwang@sompo.com.sg
Subject TP SURVEY GBF 4178P

Dear Shiang Yi,

Please be informed that we have inspected the vehicle GBF 4178P on 17/4/2019.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

MSME19048233 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 13/04/2019 14:11
 SUBMITTED BY: Wen Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 13/04/2019 14:11
 Date Of Accident 13/04/2019 10:45
 Exact Location Of Accident KPE.
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBF4178P
Insured/Policyholder
 Name Of Registered Owner COOL SYSTEM TECHNOLOGY
 Co Reg No 53293367B
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-97333303

Vehicle Particulars

Manufacturer TOYOTA
 Model HIACE
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 2100486400
 Cover Note Number

Driver

Name of Driver KOO SIEW MENG
 NRIC No S1681293E
 Date Of Birth 03/02/1964
 Occupation INDOOR
 Date Of Driving Pass 04/06/1981
 Driving Experience 37 YEARS AND 10 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-97333303
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address BLK 524 HOUGANG AVE 6 #02-141
 Postcode 530524
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 3
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1 NAME: : NELSON
 GENDER: : MALE
 Passenger 2 NAME: : TIO YEW KOK
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

IN FRONT VEHICLE STOP, I STOP IN TIME. SUDDENLY VEHICLE B HIT ONTO MY VEHICLE REAR. TOTAL 3 VEHICLES WAS INVOLVED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKT2916J
 Vehicle Make/Model/Colour
 Details Of Properties VEH B
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

YP6299K

Vehicle Make/Model/Colour

Details Of Properties

VEH C

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's
Date & Time:

Driver's Signature:
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN

△
A
△
B
△
C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

INFROM VEHICLE STOP, I STOP IN TIME. SUDDENLY VEHICLE B
HIT ONTO MY VEHICLE REAR. TOTAL 3 VEHICLES WERE INVOLVED.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

YAP LEE MOTOR

Reg. No. 52910085A

1 Kaki Bukit Ave 6 #01-26 Autobay@Kaki Bukit Singapore 417883
Tel : 6844 1555 Fax. 6844 1311 Email : yap_lee_motor@singnet.com.sg

Date : 23-Apr-19

Sompo Insurance Singapore Pte Ltd
50 Raffles Place,
#05-01/06 Singapore Land Tower
Singapore 048623

Your Reference : SKT 2916J

Veron

JTFHT02P800206999

Owner Name : Cool System Technology
Accident Date : 13-Apr-19

ESTIMATE COST OF REPAIRS FOR Toyota Hiace - GBF 4178P

Quantity	Descriptions	Amount
<u>List Items</u>		
1	Tail Gate <i>Distorted</i>	\$ 1,868.70 ✓
2	Tail Gate Hinge <i>3 new</i>	\$ 102.80 \$ 205.60 X
2	Tail Gate Absorber <i>new</i>	\$ 281.30 \$ 562.60 X
1	Tail Gate Weatherstripe <i>lit</i>	\$ 291.40 ✓
2	Tail Gate Rubber Stopper <i>new</i>	\$ 18.20 \$ 36.40 X
4	Tail Gate Side Stopper "Male & Female" <i>new</i>	\$ 70.60 \$ 282.40 X
1	Tail Gate Lock <i>Damaged</i>	\$ 401.30 <i>359</i>
1	Tail Gate Striker <i>new</i>	\$ 51.30 X
1	Tail Gate Badge	\$ 58.30 ✓
1	Tail Gate Sticker 'Hiace' <i>new</i>	\$ 58.30 ✓
1	Tail Gate Sticker 'Toyota'	\$ 51.30 ✓
1	Tail Gate Outer Handle Garnish <i>cracked</i>	\$ 274.45 ✓
4	Tail Gate Outer Handle Garnish Clips <i>new</i>	\$ 12.90 \$ 51.60 <i>10</i>
1	Tail Gate Inner Trim Board <i>torn</i>	\$ 561.60 <i>196.50</i>
8	Tail Gate Inner Trim Board Clips <i>new</i>	\$ 12.90 \$ 103.20 <i>30</i>
2	Tail Lamp Assy <i>cracked</i>	\$ 281.50 \$ 563.00 ✓
2	Tail Lamp Sealant <i>new</i>	\$ 50.00 \$ 100.00 X
4	Tail Lamp Clips <i>new</i>	\$ 12.90 \$ 51.60 X
2	Rear Corner Panel <i>cracked</i>	\$ 101.30 \$ 202.60 ✓
2	Rear Corner Panel Clips <i>new</i>	\$ 12.90 \$ 25.80 ✓
1	Rear Bumper <i>Distorted</i>	\$ 401.80 ✓
2	Rear Bumper Side Retainer <i>new</i>	\$ 122.10 \$ 244.20 <i>138.40</i>
2	Rear Bumper Side Attachment <i>new</i>	\$ 98.30 \$ 196.60 X
4	Rear Bumper Lower Bracket <i>Bent</i>	\$ 141.45 \$ 565.80 <i>120</i>
8	Rear Bumper Clips <i>new</i>	\$ 12.90 \$ 103.20 <i>30</i>
1	Rear End Panel (Outer) <i>Dented</i>	\$ 561.40 ✓
1	Rear End Panel (Inner) <i>Dented</i>	\$ 1,156.40 <i>568</i>

2	Rear End Side Panel	Repair	\$ 186.75	\$	373.50	X
1	Rear End Panel Top Metal Plate	Bent		\$	289.15	✓
6	Rear End Panel Top Metal Plate Clips	new	\$ 12.90	\$	77.40	10
1	Spare Tyre Bracket	Bent		\$	171.60	✓
1	Spare Tyre Bracket Adjusting Screw	3 new		\$	61.70	X
1	Spare Tyre Bracket Adjusting Hook	3 new		\$	63.90	X
1	Exhaust Tail Pipe	Repair		\$	1,218.85	X
1	Exhaust Pipe Hook	new		\$	61.75	X
14	Rear Windscreen Clips	new	\$ 12.90	\$	180.60	30
2	Rear Number Plate Lamp	new	\$ 91.50	\$	183.00	X
6309.70			List Total S\$		\$ 11,712.30	
less 25% 4732.27			Less 25%		\$ 2,928.08	
					\$ 8,784.23	

1	Special Nett			\$	15.00	✓
1	70 km/h Sticker	new		\$	60.00	40
1	Rear Windscreen Glass Sealant	3 new	545	\$	50.00	40
1	Rear Windscreen Glass Inner Seal			\$	45.00	X
1	Rear Number Plate	Not new		\$	360.00	200
1	Reverse Sensor	Damaged		\$	350.00	X, 250
1	Rear Floor Panel Wooden Board	Crushed		\$		
			Special Nett Total S\$		\$ 900.00	

Labour Charges

Towing	\$	120.00	X
To check & reconnect snap wiring	\$	100.00	30
To full coat affected areas	\$	280.00	60
To adjust chasis alignment on car o liner	\$	380.00	X
To remove & refix rear windscreen glass	\$	180.00	120
To remove & refix interior upholstery	\$	180.00	60
To remove & refix reverse sensor	\$	120.00	50
To transfer tail gate mechanism into new tail gate	\$	280.00	80
To respray affected areas	\$	2,000.00	1000
To renew damaged parts, straighten & repair rear chassis member, rear floor panel, rear body mudguard & aligned all parts.	\$	2,500.00	1000
To remove & refix exhaust tail pipe & straighten exhaust center pipe.	\$	280.00	80
		\$	6,420.00

Grand-total \$ 16,104.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 7757.27

2/2. 62k

07 Days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19006732/AVD3N2

Date: 17/05/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01012222
Claimant Vehicle No :	GBF4178P	Insured Vehicle No :	SKT2916J
Date of Loss:	13/04/2019	Nature of Claim:	TP
		Claim No:	CMTD1901878

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF4178P	Engine No:	1KD2653954
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 4DR (A)	Chassis No:	JTFHT02P800206999
Reg. Date:	18/10/2016 (Man. Year: 2016)	Odometer:	61850 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,684.22	5,277.27	4,406.95	45.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,420.00	2,480.00	3,940.00	61.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,104.22	7,757.27	8,346.95	51.83
Approved Total (Overridden) (\$\$)		6,200.00		
Nett Amount (\$\$)	16,104.22	6,200.00	9,904.22	61.50

INSPECTION

Date of Assignment:	15/04/2019	
Date Inspected:	17/04/2019	Inspected At:
		Yap Lee Motor (HQ) 1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 May 2019)	
Parts:	N/A	TOYOTA HIACE 3.0 D TURBO 4DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF4178P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Distorted	1,868.70 FL	*1,868.70 FL
2	2		*TAIL GATE HINGE	Not Necessary	205.60 FL	*- FL
3	2		*TAIL GATE ABSORBER	Not Necessary	562.60 FL	*- FL
4	1		*TAIL GATE WEATHERSTRIPE	Cut	291.40 FL	*291.40 FL
5	2		*TAIL GATE RUBBER STOPPER	Not Necessary	36.40 FL	*- FL
6	4		*TAIL GATE SIDE STOPPER MALE & FEMALE	Not Necessary	282.40 FL	*- FL
7	1		*TAIL GATE LOCK	Damaged	401.30 FL	*359.00 FL
8	1		*TAIL GATE STRIKER	Not Necessary	51.30 FL	*- FL
9	1		*TAIL GATE BADGE	Necessary	58.30 FL	*58.30 FL
10	1		*TAIL GATE STICKER HIACE	Necessary	58.30 FL	*58.30 FL
11	1		*TAIL GATE STICKER TOYOTA	Necessary	51.30 FL	*51.30 FL
12	1		*TAIL GATE OUTER HANDLE GARNISH	Cracked	274.45 FL	*274.45 FL
13	4		*TAIL GATE OUTER HANDLE GARNISH CLIPS	Necessary	51.60 FL	*10.00 FL
14	1		*TAIL GATE INNER TRIM BOARD	Torn	561.60 FL	*196.50 FL
15	8		*TAIL GATE INNER TRIM BOARD CLIPS	Necessary	103.20 FL	*30.00 FL
16	2		*TAIL LAMP ASSY	Cracked	563.00 FL	*563.00 FL
17	2		*TAIL LAMP SEALANT	Not Necessary	100.00 FL	*- FL
18	4		*TAIL LAMP CLIPS	Not Necessary	51.60 FL	*- FL
19	2		*REAR CORNER PANEL	Cracked	202.60 FL	*202.60 FL
20	2		*REAR CORNER PANEL CLIPS	Necessary	25.80 FL	*25.80 FL
21	1		*REAR BUMPER	Distorted	401.80 FL	*401.80 FL
22	2		*REAR BUMPER SIDE RETAINER	Necessary	244.20 FL	*138.40 FL
23	2		*REAR BUMPER SIDE ATTACHMENT	Not Necessary	196.60 FL	*- FL
24	4		*REAR BUMPER LOWER BRACKET	Bent	565.80 FL	*120.00 FL
25	8		*REAR BUMPER CLIPS	Necessary	103.20 FL	*30.00 FL
26	1		*REAR END PANEL (OUTER)	Dented	561.40 FL	*561.40 FL
27	1		*REAR END PANEL (INNER)	Dented	1,156.40 FL	*568.00 FL
28	2		*REAR END SIDE PANEL	Repair	373.50 FL	*- FL
29	1		*REAR END PANEL TOP METAL PLATE	Bent	289.15 FL	*289.15 FL
30	1		*REAR END PANEL TOP METAL PLATE CLIPS	Necessary	77.40 FL	*10.00 FL
			(6 Pcs)			
31	1		*SPARE TYRE BRACKET	Bent	171.60 FL	*171.60 FL
32	1		*SPARE TYRE BRACKET ADJUSTING SCREW	Not Necessary	61.70 FL	*- FL
33	1		*SPARE TYRE BRACKET ADJUSTING HOOK	Not Necessary	63.90 FL	*- FL
34	1		*EXHAUST TAIL PIPE	Repair	1,218.85 FL	*- FL
35	1		*REAR WINDSCREEN CLIPS	Necessary	180.60 FL	*30.00 FL
			(14 Pcs)			
36	2		*REAR NUMBER PLATE LAMP	Not Necessary	183.00 FL	*- FL
37	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
38	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
39	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*40.00 FS
40	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
41	1		*REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
42	1		*REAR FLOOR PANEL WOODEN BOARD	Cracked	350.00 FS	*250.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*EXHAUST PIPE HOOK	Not Necessary	61.75 FL	*- FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	12,612.30	6,854.70
				- List Item Discount on L Items 25.00/25.00% (S\$)	2,928.08	1,577.43
				Total Parts (S\$)	9,684.22	5,277.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	120.00	0.00
2	TO CHECK & RECONNECT SNAP WIRING	New	100.00	30.00
3	TO FULL COAT AFFECTED AREAS	New	280.00	60.00
4	TO ADJUST CHASSIS ALIGNMENT ON CAR O LINER	New	380.00	0.00
5	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO REMOVE & REFIX INTERIOR UPHOLSTERY	New	180.00	60.00
7	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
8	TO TRANSFER TAIL GATE MECHANISM INTO NEW TAIL GATE	New	280.00	80.00
9	TO RESPRAY AFFECTED AREAS	New	2,000.00	1,000.00
10	TO RENEW DAMAGED PARTS,STRAIGHTEN & REPAIR REAR CHASSIS MEMBER,REAR FLOOR PANEL,REAR BODY MUDGUARD & ALIGNED ALL PARTS	New	2,500.00	1,000.00
11	TO REMOVE & REFIX EXHAUST TAIL PIPE & STRAIGHTEN EXHAUST CENTER PIPE	New	280.00	80.00
Gross Labour Cost (S\$)			6,420.00	2,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >