

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19006750/GGA3Q2

**Date:** 11/09/2020

### REFERENCE

|                              |                                       |                             |                 |
|------------------------------|---------------------------------------|-----------------------------|-----------------|
| Handling Insurer:            | India International Insurance Pte Ltd | Policy No:                  | D19MCV0001070   |
| <b>Claimant Vehicle No :</b> | SLW3631X                              | <b>Insured Vehicle No :</b> | GT1715B         |
| Date of Loss:                | 06/04/2019                            | Nature of Claim:            | TP              |
|                              |                                       | Claim No:                   | MCV2019D0000348 |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                       |             |                   |
|-----------------------------|---------------------------------------|-------------|-------------------|
| Reg No:                     | SLW3631X                              |             |                   |
| Make & Model:               | MAZDA 3, 1.5 HATCHBACK DELUXE EU6 (A) | Engine No:  | P520495618        |
| Reg. Date:                  | 08/02/2018 (Man. Year: 2017)          | Chassis No: | JM6BN24A8J0205343 |
| Colour:                     | Red                                   | Odometer:   | 20630 km          |
| Engine Capacity:            | 1496 cc                               |             |                   |
| Market Value/New Car Price: | N/A                                   |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>     |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |            |                  |            |
|-------------------|------------|------------------|------------|
| Front Tyre Size:  | 205/60 R16 | Rear Tyre Size:  | 205/60 R16 |
| Front Left Side:  | Toyo 6 mm  | Rear Left Side:  | Toyo 6 mm  |
| Front Right Side: | Toyo 6 mm  | Rear Right Side: | Toyo 6 mm  |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>              | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                              | 2,023.75          | 1,320.68          | 703.07            | 34.74         |
| Miscellaneous Items                | 0.00              | 0.00              | 0.00              |               |
| Labour                             | 4,045.00          | 2,780.00          | 1,265.00          | 31.27         |
| Paintwork Labour                   | 0.00              | 0.00              | 0.00              |               |
| Towing                             | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>           | <b>6,068.75</b>   | <b>4,100.68</b>   | <b>1,968.07</b>   | <b>32.43</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b>      | <b>424.81</b>     | <b>287.05</b>     | <b>137.76</b>     | <b>32.43</b>  |
| <b>Nett Amount (S\$)</b>           | <b>6,493.56</b>   | <b>4,387.73</b>   | <b>2,105.83</b>   | <b>32.43</b>  |
| <b>Global Sum Settlement (S\$)</b> |                   | <b>0.00</b>       |                   |               |

### INSPECTION

|                             |            |               |                                                                 |
|-----------------------------|------------|---------------|-----------------------------------------------------------------|
| Date of Assignment:         | 16/04/2019 |               |                                                                 |
| Date Inspected:             | 17/04/2019 | Inspected At: | Trans Eurokars Pte Ltd (Ubi)<br>5 Ubi Close<br>Singapore 408605 |
| Estimated Period of Repair: | 4.0 days   |               |                                                                 |

**Adjuster:** XING GUO QIANG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                        |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 10 Sep 2020)                          |
| <b>Parts:</b>        | 144                                                                                                                                                                          | MAZDA 3 1.5 HATCHBACK DELUXE EU6 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                      |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLW3631X)                                                                                                                                    |                                                                        |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                        |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                        |

### Recommended Parts

| No. | Qty | Part No. | Particulars                   | Condition     | Repairer's | Amount     |
|-----|-----|----------|-------------------------------|---------------|------------|------------|
| 1   | 1   |          | *REAR BUMPER                  | Deformed      | 997.50 FL  | *997.50 FL |
| 2   | 1   |          | *BRACKET CENTER               | *Check        | 5.40 FL    | *- FL      |
| 3   | 1   |          | *PROTECTOR CENTER REAR BUMPER | Necessary     | 58.80 FL   | *58.80 FL  |
| 4   | 1   |          | *TOWING CVER LH               | Deformed      | 15.80 FL   | *15.80 FL  |
| 5   | 1   |          | *REAR REINFORCEMENT           | *Check        | 564.20 FL  | *- FL      |
| 6   | 2   |          | *RETAINER ,CENTER ,SENSOR     | Necessary     | 31.00 FL   | *31.00 FL  |
| 7   | 2   |          | *SENSOR CENTER ,ULTRASONIC    | Necessary     | 2.00 FL    | *2.00 FL   |
| 8   | 2   |          | *TAPE PROTECTOR ,SENSOR       | Necessary     | 17.20 FL   | *17.20 FL  |
| 9   | 4   |          | *GROMMET ,REAR BUMPER         | Necessary     | 10.80 FL   | *10.80 FL  |
| 10  | 2   |          | *GROMMET ,REAR BUMPER         | Necessary     | 6.00 FL    | *6.00 FL   |
| 11  | 10  |          | *RIVET ,REAR BUMPER           | Necessary     | 45.00 FL   | *45.00 FL  |
| 12  | 2   |          | *RIVET ,REAR BUMPER           | Necessary     | 16.00 FL   | *16.00 FL  |
| 13  | 1   |          | *ORNAMENT ,MAZDA              | Necessary     | 56.10 FL   | *56.10 FL  |
| 14  | 1   |          | *MASCOT ,REAR                 | Necessary     | 78.20 FL   | *78.20 FL  |
| 15  | 1   |          | *ORNAMENT,SKYACTIVE           | Necessary     | 66.80 FL   | *66.80 FL  |
| 16  | 2   |          | *FASTENER ,TAILGATE           | Not Necessary | 5.80 FL    | *- FL      |
| 17  | 4   |          | *CLIP, FINISHER               | Not Necessary | 18.80 FL   | *- FL      |
| 18  | 4   |          | *CLIP, FINISHER               | Not Necessary | 40.40 FL   | *- FL      |
| 19  | 4   |          | *CLIP, FINISHER               | Not Necessary | 10.80 FL   | *- FL      |
| 20  | 1   |          | *GROMMET ,FINISHER            | Not Necessary | 2.90 FL    | *- FL      |
| 21  | 1   |          | *GASKET LHS ,TAILGATE LAMP    | Necessary     | 22.00 FL   | *22.00 FL  |
| 22  | 1   |          | *GASKET RHS ,TAILGATE LAMP    | Necessary     | 22.00 FL   | *22.00 FL  |
| 23  | 1   |          | *GASKET LHS ,TAILLAMP         | Not Necessary | 22.00 FL   | *- FL      |
| 24  | 1   |          | *GASKET RHS ,TAILLAMP         | Not Necessary | 22.00 FL   | *- FL      |
| 25  | 1   |          | *SUNDRIES                     | Necessary     | 100.00 FS  | *20.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>2,237.50</b> | <b>1,465.20</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 213.75          | 144.52          |
| <b>Total Parts (\$\$)</b>                                  | <b>2,023.75</b> | <b>1,320.68</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                              | Lab.Type | Repairer's      | Amount          |
|---------------------------------|------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                                                                          |          |                 |                 |
| 1                               | TO REPLACE REAR BUMPER AND REAR REINFORCEMENT ,REPAIR ALL AREAS AFFECTED BY THE ACCIDENT | New      | 990.00          | 660.00          |
| 2                               | TO RESPRAY REAR BUMPER ,REAR REINFORCEMENT AND TAILGATE                                  | New      | 1,575.00        | 1,260.00        |
| 3                               | TO TRANSFER REVERSE SENSORS                                                              | New      | 330.00          | 330.00          |
| 4                               | TO CARRY OUT BODY CAVITY PRESERVATION                                                    | New      | 250.00          | 0.00            |
| 5                               | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING                                        | New      | 250.00          | 150.00          |
| 6                               | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS                                           | New      | 350.00          | 180.00          |
| 7                               | TO SUPPLY BRILA PREMIUM COATING                                                          | New      | 300.00          | 200.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                          |          | <b>4,045.00</b> | <b>2,780.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >