

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120**Our File No:** CC3/AIG19006751/AVD3E2**Date:** 07/08/2019REFERENCE

Insured/Claimant:	DASWANI POOJA ISHWAR	Policy No:	1900017227		
Date of Loss:	13/04/2019	Nature of Claim:	OD	Claim No:	8926146818SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMJ794K</b>	Engine No:	CVK071519
Make & Model:	AUDI A4, 2.0 TFSI Limited Edition (A)	Chassis No:	WAUZZZF4XKN000733
Reg. Date:	21/02/2019 (Man. Year: 2018)	Odometer:	1589 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$170,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	16,306.40	9,474.96	6,831.44	41.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,652.00	3,302.00	1,350.00	29.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,958.40</b>	<b>12,776.96</b>	<b>8,181.44</b>	<b>39.04</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	20,358.40	12,176.96	8,181.44	40.19
<b>+ GST 7.00/7.00% (S\$)</b>	1,425.09	852.39	572.70	40.19
<b>Nett Amount (S\$)</b>	<b>21,783.49</b>	<b>13,029.35</b>	<b>8,754.14</b>	<b>40.19</b>

INSPECTION

Date of Assignment:	16/04/2019		
Date Inspected:	16/04/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER COVER	Distorted	1,755.00 FS	*1,404.00 FS	
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	531.00 FS	*- FS	
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	57.00 FS	*- FS	
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	171.00 FS	*- FS	
5	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	67.00 FS	*- FS	
6	1		*FRONT BUMPER SENSOR	Not Necessary	208.00 FS	*- FS	
7	1		*FRONT BUMPER SENSOR SEAL	Not Necessary	14.00 FS	*- FS	
8	1		*FOAM FILLER PIECE	Not Necessary	101.00 FS	*- FS	
9	1		*BUMPER CARRIER	Not Necessary	674.00 FS	*- FS	
10	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	31.00 FS	*27.12 FS	
11	1		*FRONT FENDER - RH	Distorted	643.00 FS	*514.40 FS	
12	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	183.00 FS	*- FS	
13	1		*FRONT FENDER CLOSING ELEMENT	Necessary	36.00 FS	*36.00 FS	
14	1		*FRONT FENDER BRACKET	Bent	29.00 FS	*25.20 FS	
15	1		*FRONT FENDER DEFORMATION ELEMENT	Necessary	42.00 FS	*35.60 FS	
16	1		*FRONT FENDER RIVET	Not Necessary	17.00 FS	*- FS	
17	1		*FRONT FENDER BRACKET - LH FRONT AND REAR	Not Necessary	30.00 FS	*- FS	
18	1		*FRONT FENDER BRACE	Bent	100.00 FS	*79.44 FS	
19	1		*FRONT WHEEL HOUSING LINER - RH	Torn	202.00 FS	*161.60 FS	
20	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	211.00 FS	*- FS	
21	1		*FRONT WHEEL SPOILER - RH	Cracked	66.00 FS	*52.32 FS	
22	1		*FRONT WHEEL SPOILER TRIM - RH	Not Necessary	29.00 FS	*- FS	
23	1		*FRONT FENDER STONE CHIP GUARD - RH	Necessary	46.00 FS	*36.64 FS	
24	1		*FRONT FENDER COVER TRIM - RH	Necessary	28.00 FS	*22.24 FS	
25	1		*FRONT FENDER TOP COVER - RH	Necessary	19.00 FS	*16.16 FS	
26	1		*LED HEADLIGHT - RH	Cut	7,861.00 FS	*6,288.80 FS	
27	1		*LED HEADLIGHT POWER MODULE	Not Necessary	641.00 FS	*- FS	
28	1		*LED HEADLIGHT CONTROL UNIT	Not Necessary	634.00 FS	*- FS	
29	1		*LED HEADLIGHT VENTILATION HOSE	Not Necessary	29.00 FS	*- FS	
30	1		*LED HEADLIGHT LIFT CYLINDER - RH	Not Necessary	180.00 FS	*- FS	
31	1		*FRONT TYRE RIM - RH	Cut	738.40 FS	*738.40 FS	
32	1		*FRONT AIR GUIDE - RHS	Not Necessary	333.00 FS	*- FS	
33	1		*SUNDRIES	Necessary	600.00 FS	*37.04 FS	
					<b>Total Parts (\$\$)</b>	<b>16,306.40</b>	<b>9,474.96</b>

F=Franchise part. S=SpcNett.

LKK Auto Consultants Pte Ltd/SMJ794K/07/08/2019 08:32

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,600.00	1,100.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>4,652.00</b>	<b>3,302.00</b>

LKK Auto Consultants Pte Ltd/SMJ794K/07/08/2019 08:32

< END OF ESTIMATES >