

HENG LAI HUAT MOTOR WORKSHOP
(JM0676600-M)
No. 3, Jalan Austin Heights 1/15,
Taman Mount Austin,
81100 Johor Bahru, Johor.

Not Authorised
21 Sep 87
Recovery After Paint

Date : 02/10/2016

QUOTATION -THIRD PARTY CLAIM

AXA INSURANCE SINGAPORE PTE LTD

Attn: Motor Claim Department . Officer In Charge

Accident on : 18/09/2016

Claim : Third Party Claim
Veh. No : JPT 5831
Model : PROTON EXORA
Insured Ins: AM GENERAL

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : SJR 9536 Z		
1	TAILGATE <i>Re</i>	\$ 2,585.60	✓
1	TAILGATE LOCK <i>Re</i>	\$ 784.50	✓
1	TAILGATE TRIM BOARD <i>Re</i>	\$ 1,708.56	X
1	TAILGATE CENTRE LOGO <i>Re</i>	\$ 180.00	✓
1	TAILGATE EXORA EMBLEM <i>Re</i>	\$ 144.50	✓
1	TAILGATE EFE EMBLEM <i>Re</i>	\$ 144.50	✓
1	TAILLAMP LH <i>Re</i>	\$ 1,343.20	X
1	TAILLAMP PANEL LH	REPAIR	
1	TAILLAMP APRON PANEL LH <i>Re</i>	\$ 424.60	X
1	REAR FENDER LH	REPAIR	
1	REAR FENDER INNER SIDE TRIM <i>Re</i>	\$ 980.65	X
1	REAR BUMPER <i>Re</i>	\$ 2,213.50	✓
1	REAR BUMPER BEAM	\$ 980.00	?
2	REAR BUMPER BRACKETS	\$ 280.00	?
2	REAR BUMPER SIDE RETAINERS <i>Re</i>	\$ 240.00	✓
1	REAR BUMPER TOW COVER <i>Re</i>	\$ 142.00	X
2	REAR BUMPER REFLECTORS <i>elsewhere n/s ?</i>	\$ 680.00	n/s ?
1	END PANEL <i>Re</i>	\$ 1,888.45	✓
1	END PANEL TOP GARNISH <i>Re</i>	\$ 685.00	✓
1	END PANEL TOP LATCH	\$ 120.00	X
1	FLOOR PANEL	\$ 1,988.45	?
1	FLOOR PANEL TOP BOARD	\$ 1,480.60	?
1	SPARE TYRE BRACKET	\$ 1,114.60	?
1	REAR EXHAUST ASSY	\$ 1,955.60	?
1	REAR EXHAUST MOUNTING	\$ 140.00	?
	TOTAL RINGIT :	RM 22,204.31	
	AMT AFTER LESS 10%	RM 19,983.88	
	S/NETT PARTS		
3TUBE	TAILGATE SELANT <i>Re</i>	\$ 180.00	40 in
1SET	REAR No.PLATE WITH HOLDER <i>Re</i>	\$ 55.00	X
1SET	REVERSE SENSOR <i>CR</i>	\$ 200.00	✓
1SET	REVERSE CAMERA <i>Re</i>	\$ 600.00	X
1	REAR BUMPER LOWER SKIRTING <i>NSP</i>	\$ 1,400.00	X
1	SPARE TYRE	\$ 980.00	?
	TOTAL S/N IN RINGIT	RM 3,415.00	
	TOTAL PARTS IN RINGIT :	RM 23,398.00	

HENG LAI HUAT MOTOR WORKSHOP
(JMD676600-M)
No. 3, Jalan Austin Heights 1/15,
Taman Mount Austin,
81100 Johor Bahru, Johor.

QTY	LABOUR	AMOUNT	SURVEYOR
	Balance b/f	RM 23,398.00	
	Labour charges to replace, repair, cutting, welding , align ajust on rear accident damage	\$ 2,000.00	<i>8000</i>
	To do spray painting on accident damage area	\$ 1,800.00	<i>10000</i>
	To check rear wiring system, replace sensors, camera	\$ 500.00	<i>1200</i>
	Transfer tailgate parts to another tailgate	\$ 200.00	<i>600</i>
	To do anti rust tuff coating	\$ 200.00	<i>600</i>
	To do sealant , seal gap on welding, accient area	\$ 400.00	<i>500</i>
	Remove refix replace garnish, side trim, car seat upholstery etc	\$ 500.00	<i>1000</i>
	Labour to remove refix w/screen	\$ 250.00	<i>1200</i>
	To do chassis body alignment	\$ 350.00	<i>7</i>
	Total Labour :	RM 6,200.00	
	Total	RM 29,598.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: