

REF: CS/FCI/9006777/Dsd3 | 02

Special Instruction

Date/Time

CWS

Bryen

ASSIGNMENT (OIGCC)

Person (Person)

Joanne Yong

of

Fei

Date/Time

2:04pm@15/4/19

Estimated Cost

15116

OD / IT / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.

SHA8643S

Insured

SH 9847Y

at Workshop no.

chunni Motor

Tel

65425119

of

AMK Autopoint #01-05/06

Policy No.

Claim No.

D19002511 MPSTH

Sum Insured

Excess

Make of Veh.

(if Ben's Record)

D.O.A

11/4/2019

CA / REV / REP. / REV 24 HRS

Lup

H.O.D. Endorsement

Date/Time

2:33pm@15/4/19

Person Contacted

Lynn

Vehicle

IN / OIT

Date/Time

Action/Instruction (✓) Estimate

SHA8643S-CS/FCI/4016528/Rgbd1

DOA: 26/8/14

SH 9847Y-CS/FCI/7017082/T/gbl2

DOA: 30/8/17

23/04/19

@ 11:29 p.m. revised PA to Joanne Yong via email

REF:

ASSIGNMENT

COR July 2024
2016 July

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 12.10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHA 86438

Yr Regn:

2016 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai I40

c.c.

1685

Colour:

Yellow

A/C:

Insured / Std / NI / NA

Sp. Reading:

380699

T/Radio:

Insured / Std / NI / NA

Eng/No:

D4FDGU660673

C/No:

KMHLB41UMGU092282

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

P/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

11/04/2019

D.O.I.

15/04/2019

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/8 Front y 0/8 Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First Capital SH 9847Y

13/15/19

Jammed 2/5 13,000/- with 12 days 2 reg
(9,568.68 Red - 42%)

RECEIVED 13 MAY 2019

Date/Time, File Pass to?

13/05/19

1)

Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

12

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$) 13,000/- HS

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

12x15: 180

170+180

50

50+50

216

716



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002511MFSH

Date: 23 April 2019

Our Ref: CS/FCI19006777/Dsd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHA 8643S

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/04/2019 at the premises of M/s Chunni Motor Work Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 22,568.68
Revised Estimate Amount (lump sum)	: S\$ 19,792.36
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s front portion & o/s body.



Comments/ Present Status:

Damages Consistent.
Repair days: 10 Days

Yours faithfully,
Bryan Ang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	12-04-2019	Our Ref No. D19002511MFSH
Accident Date	11-04-2019	Claim Type. Third Party
Insured Vehicle	SH9847Y	Third Party Vehicle. SHA8643S
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06.	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 0	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 23 April 2019 5:29 PM
To: 'Joanne Yong Lai fong'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D19002511MFSH/1
Attachments: SHA 8643S - Preli Advise.pdf

Dear Joanne,

Enclosed preliminary revised of vehicle SHA 8643S.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 16 April 2019 10:44 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002511MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 15 April 2019 2:04 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002511MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

To Survey by LK

VEHICLE NO : SHA 8643S

DATE : 12.04.2019

FCH

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>distorted / broken mounting</i>			\$ 1,052.20 ✓
	Front Bumper Bracket (RH) <i>NH</i>			\$ 24.60 X
	Headlamp Support Top Cover <i>NH</i>			\$ 222.60 X
	Headlamp Support Panel Assy <i>broken</i>			\$ 907.40 ✓ <i>broken</i>
	Headlamp (RH) <i>Scratched / mainly broken</i>			\$ 1,388.00 ✓ <i>broken</i>
	Front Fender (RH) <i>Dented</i>			\$ 663.00 ✓
	Front Fender Apron Panel (RH) <i>2 Dented</i>			\$ 637.00 2 ✓
	Front Fender Shield (RH) <i>deformed</i>			\$ 174.90 ✓
	Front Door (RH) <i>from 1st</i>			\$ 2,256.40 X ✓
	Front Door Mirror Assy (RH) <i>crack</i>			\$ 670.00 ✓
	Rear Door (RH) <i>from 1st</i>			\$ 2,201.10 X ✓
	Door Centre Pillar Outer (RH) <i>from Dented</i>			\$ 2,527.80 X ✓
	Wiper Container <i>2 mainly broken</i>			\$ 61.90 2 ✓
	Wiper Container Motor <i>from Dented</i>			\$ 75.00 X ✓
	Front Wheel Rim (RH) <i>2 distorted</i>			\$ 325.30 2 ✓
	Front Wheel Hub Cap (RH) <i>1st</i>			\$ 107.10 ✓
	Front Wheel Bearing <i>2 Dented</i>			\$ 540.50 2 ✓
	Front Shock Absorber (Assy) (RH) <i>2 distorted</i>			\$ 342.20 2 ✓
	Front Shock Absorber Mounting (RH) <i>NH</i>			\$ 108.80 X
	Front Drive Shaft (RH) <i>2 distorted</i>			\$ 1,030.80 2 ✓
	Rack & Pinion Assy <i>2 Dented</i>			\$ 1,191.30 2 ✓
	STG Tie End <i>2 distorted</i>			\$ 62.60 2 ✓
	Stabilizer Bar <i>2 distorted</i>			\$ 252.30 2 ✓
	Stabilizer Bar Bush (RH) <i>NH</i>			\$ 16.40 X
	Stabilizer Bar Link <i>2 distorted</i>			\$ 61.10 2 ✓
	Stabilizer Bracket <i>NH</i>			\$ 24.00 X
	Front Suspension Lower Arm (RH) <i>2 distorted</i>			\$ 529.30 2 ✓
	Knuckle Arm (RH) <i>2 distorted</i>			\$ 552.00 2 ✓
	Engine Under Cover <i>NH</i>			\$ 334.60 X
	Engine Crossmember <i>NH</i>			\$ 2,094.40 X
			17609.20	
			14087.36	
	SUB TOTAL			\$ 20,434.60
	LESS 20%			\$ 4,086.92
	DISCOUNTED TOTAL			\$ 16,347.68
	Front Fender Advertisement Logo (RH) <i>NH</i>			\$ 100.00 Nett X
	Front Door Comfort Logo (RH) <i>NH</i>			\$ 75.00 Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>NH</i>			\$ 80.00 Nett ✓
	Front Tyre (RH) <i>3vc</i>		155.00	\$ 216.00 Nett X
				\$ 471.00

SHA 8643S

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,000.00 800/-
	Spray Painting Charge			\$ 1,600.00 800/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 NW
	Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
	FRT Wheel Alignment			\$ 120.00 60/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 NW
	Transfer of Door		\$ 200.00	\$ 400.00 2120/-
	Re-set Frt ABS System			\$ 200.00
	Re-set Frt & Rear Power Window System		\$ 200.00	\$ 400.00 } 150/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
			2150.00	
	TOTAL LABOUR			\$ 5,750.00
	ESTIMATE TOTAL			\$ 22,568.68
	15/04/2019 @ 1430h		16392.36	
	HA Andrew		2/5 13000/-	
	2 pm 8 ¹⁰ 12			
	2 ¹ 12			
	you			
	LKK Auto			
	8			
	LKK Auto Consultants hence notify the Repairer of the following:			
	• To resurvey before/after spray painting			
	• To display damaged part(s) during resurvey			
	• Parts prices are subject to confirmation			
	• Third party survey is on a "Without Prejudice" basis			
	• No illegal modification(s) is allowed			
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
	Acknowledged by Repairer			
	Signature:			
	Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 8643 S

Technician:

Mileage: 380699

Time Printed 15.4.19 3:40 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°26'		-3°00' 3°00'
4°25'		-0°19' 5°41'
0°07'		-1°30' 1°30'
17°15'		
16°49'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-1°13'		-3°00' 3°00'
4°04'		-0°19' 5°41'
2°05'		-1°30' 1°30'
15°03'		
13°50'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
0°47'		-3°00' 3°00'
0°21'		-3°00' 3°00'
2°12'		-3°00' 3°00'
2°12'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°43'		-3°30' 2°30'
0°09'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°59'		-3°30' 2°30'
0°28'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
0°16'		-3°00' 3°00'
0°37'		-3°00' 3°00'
-0°09'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19006777/Dsd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 15-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9847Y	Veh. Inspected	SHA 8643S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002511MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	15/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU092282	Colour	YELLOW	
Odometer	380699	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/04/2019	Inspection Date	15/04/2019	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 8643S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER COVER	DISTORTED / MOUNTING BROKEN	1,052.20	1,052.20
1	FRONT BUMPER BRACKET (RH)	NOT NECESSARY	24.60	-
1	HEADLAMP SUPPORT TOP COVER	NOT NECESSARY	222.60	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	907.40	907.40
1	HEADLAMP (RH)	SCRATCHED / MOUNTING BROKEN	1,388.00	1,388.00
1	FRONT FENDER (RH)	DENTED	663.00	663.00
1	FRONT FENDER APRON PANEL (RH)	DENTED	637.00	637.00
1	FRONT FENDER SHIELD (RH)	DEFORMED	174.90	174.90
1	FRONT DOOR (RH)	BENT	2,256.40	2,256.40
1	FRONT DOOR MIRROR ASSY (RH)	CRACKED	670.00	670.00
1	REAR DOOR (RH)	BENT	2,201.10	2,201.10
1	DOOR CENTRE PILLAR OUTER (RH)	DENTED	2,527.80	2,527.80
1	WIPER CONTAINER	MOUNTING BROKEN	61.90	61.90
1	WIPER CONTAINER MOTOR	DAMAGED	75.00	75.00
1	FRONT WHEEL RIM (RH)	DISTORTED	325.30	325.30
1	FRONT WHEEL HUB CAP (RH)	BENT	107.10	107.10
1	FRONT WHEEL BEARING	DAMAGED	540.50	540.50
1	FRONT SHOCK ABSORBER (ASSY)(RH)	DISTORTED	342.20	342.20
1	FRONT SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	108.80	-
1	FRONT DRIVE SHAFT (RH)	DISTORTED	1,030.80	1,030.80
1	RACK & PINION ASSY	DAMAGED	1,191.30	1,191.30
1	STG TIE END	DISTORTED	62.60	62.60
1	STABILIZER BAR	DISTORTED	252.30	252.30
1	STABILIZER BAR BUSH (RH)	NOT NECESSARY	16.40	-
1	STABILIZER BAR LINK	DISTORTED	61.10	61.10
1	STABILIZER BRACKET	NOT NECESSARY	24.00	-
1	FRONT SUSPENSION LOWER ARM (RH)	DISTORTED	529.30	529.30

Report Ref No. CS/FCI19006777/Dsd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	KNUCKLE ARM (RH)	DISTORTED	552.00	552.00
1	ENGINE UNDER COVER	NOT NECESSARY	334.60	-
1	ENGINE CROSSMEMBER	NOT NECESSARY	2,094.40	-
	LESS 20% DISCOUNT		-4,086.92	-3,521.84
			16,347.68	14,087.36
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT FENDER ADVERTISEMENT LOGO (RH)(SN)	NOT NECESSARY	100.00	-
1	FRONT DOOR COMFORT LOGO (RH)(SN)	NECESSARY	75.00	75.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (RH) (SN)	NECESSARY	80.00	80.00
1	FRONT TYRE (RH)(SN)	SERVICEABLE	216.00	-
			471.00	155.00
	<u>LABOUR</u>			
	PANEL BEATING.		2,000.00	800.00
	SPRAY PAINTING CHARGE.		1,600.00	800.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX UNDERCARRIAGE (FRT).		200.00	150.00
	FRT WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
	TRANSFER OF DOOR.		400.00	120.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. }		480.00	150.00
	RE-SET FRT ABS SYSTEM. }		200.00	-
	RE-SET FRT & REAR POWER WINDOW SYSTEM. }		400.00	-
	-		-	-
	-		-	-
	-		-	-
			5,750.00	2,150.00
	GRAND TOTAL		22,568.68	16,392.36
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,000.00

Report Ref No. CS/FCI19006777/Dsd3n2



Report Ref No. CS/FCI19006777/Dsd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.