

ASSIGNMENT BY

REP CS/FCI 1900 6803 / Kqd3n2

Special Instruction

SA/VEY/OT Kenneth

ASSIGNMENT (Office)

aus

Eileen Lee

of FCI

Date/Time 9:40am @ 16/4/19

Estimated Cost: Bill to:

OD (T) / WS / TP / RS / OD / RS / KYA / INV / MY / CS

To Inspect Vehicle No

SLG 5182X

Insured:

SHD 3558Y

at Workshop no/

Eskeen Performance

Tel:

8799 0066

of

385 Sunning Drive

Policy No

Claim No:

D19002540MFSH

Sum Insured

Excess:

Make of Veh (Client's Record)

D.O.A

14/4/2019

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement

Date/Time

12:10pm @ 16/4/19

Person Contacted:

Carmen

Vehicle

(T) / (OFF)

Date/Time	Action/Instruction (✓) Estimate
	SLG 5182X - X
17/4/19 @ 2:30pm	SHD 3558Y - NS/INC16006141/H/vbc2 revised to Eileen Lee by email. D.O.A: 1/4/2016
	Kenneth confirmed final fig \$4485.83, 6 days. (Red \$5414.57, 55%)

ASS. REC. BY:

REF: 1021

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Estem

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 867k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6-8 days Res.: Yes or No

Lum Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLG 5182 X Yr Regn: 10, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius c.c. 1798

Colour: M. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 192552 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3F4X03535303

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front		Rear	
R/Bal.	<u>7</u> mm	R/Bal.	<u>7</u> mm
L/Bal.	<u>7</u> mm	L/Bal.	<u>7</u> mm
D.O.A.	<u>14/4/19</u>	D.O.I.	<u>16/4/19</u>

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Acc N/S & R

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

RECEIVED 21 MAY 2019

Date/Time, File Pass to?

11/15/19

Date/Time, File Return to?

: Prel. Report

: Final Report

Days Of Repair: 6

Resurvey No. of Trlp: 2

Survey Fee:

Transportation:

S + RS. St

Fuel/As

Others

TOTAL

170
90
90+90
28
348

Add Fee: : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Report Format: TP

Lump Sum / I.B.I: (\$ 4485-83)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002540MFSH

Date: 17 April 2019

Our Ref: CS/FCI19006803/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLG 5182X.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/04/2019 at the premises of M/s ESTEEM PERFORMANCE, and have the following to report:-

Workshop Estimate Amount	: S\$ 9,900.40 .
Revised Estimate Amount	: S\$ 4,785.83 .
"Check" Items Amount	: S\$ 2,464.48 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear n/s & front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	15-04-2019	Our Ref No. D19002540MFSH
Accident Date	14-04-2019	Claim Type. Third Party
Insured Vehicle	SHD3558Y	Third Party Vehicle. SLG5182X
Survey Location	385, SIN MING DRIVE (INSIDE VICOM)	
Contact Person.	SERENCE CHEE	
Contact No.	0/ 87990066	Fax No. 62593326
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 17 April 2019 2:30 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002540MFSH/1
Attachments: CSFCI19006803Kqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SLG 5182X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 16 April 2019 12:10 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002540MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 16 April 2019 9:40 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002540MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

MS. First Capital



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

*Not Authorized
Resurvey B4 paint*

Repair Estimates

SLG 5182 X

Parts	(a) Cost / List Price Items	\$	<u>8,460.53</u>
	Plus/Less 25%	\$	<u>2,115.13</u>
	Total of Cost / List	\$	<u><u>6,345.40</u></u>
	(b) Nett Price Items		_____
	Less		_____
	Total of Nett Item		_____
	(c) Special Nett Items	\$	<u>245.00</u>
Total Parts Cost		\$	<u><u>6,590.40</u></u>
Labour		\$	<u><u>3,310.00</u></u>
Total		\$	<u><u>9,900.40</u></u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This party agrees on a "without prejudice" basis
- Not to be held responsible for any damage
- To report any damage to the relevant authority

Accepted by Repairer: _____
Signature: _____
Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 18/4/11P at 11:20

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 06 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Sc Date: 18/4/11P



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLG 5182 X
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FUX03535303

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	S.N	✓
2	Front number plate garnish	1	\$129.00		✓
3	Front bumper	1	\$450.80		? XR
4	Front bumper clip	10	\$40.00		? XHN
5	Front bumper reinforcement - upper	1	\$711.50		? XR
6	Front bumper reinforcement - lower	1	\$245.30		? XR
7	Front bumper side retainer RH	1	\$107.20		? XSVL
8	Front bumper side retainer LH	1	\$107.20		? XSVL
9	Front bumper upper grille	1	\$321.90		✓ DR
10	Front bumper lower grille	1	\$148.60		? XSVL
11	Front bumper emblem	1	\$87.10		✓
12	Front bumper sponge - upper	1	\$89.81		? XSVL
13	Front bumper sponge - lower	1	\$135.70		? XSVL
14	Reverse sensor	1	\$200.00	S.N	? XSVL
15	Rear bumper	1	\$497.50		✓
16	Rear bumper clip	10	\$40.00		✓
17	Rear bumper side retainer LH	1	\$112.70		✓
18	Rear bumper side retainer RH	1	\$112.70		X
19	Rear bumper reinforcement	1	\$398.90		✓
20	Rear bumper lower garnish centre	1	\$582.60		✓
21	Rear bumper lower garnish LH	1	\$149.70		✓
22	Rear bumper lower garnish RH	1	\$149.70		X
23	Rear bumper under cover	1	\$355.20		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLG 5182 X
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FUX03535303

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Rear bumper under cover LH	CMJ 1	\$187.60		✓
25	Rear bumper under cover RH	SM 1	\$187.60		X
26	Rear bumper under cover clip	MM 4	\$14.00		✓
27	Tail door emblem	MM 1	\$61.70		✓
28	Wording "PRIUS"	MM 1	\$51.90		✓
29	Wording "HYBRID"	MM 1	\$55.47		✓
30	Tail door plate garnish	MM/CM 1	\$782.50		✓
31	Tail end panel	1	\$596.60		? XR
32	Tail end panel garnish	1	\$151.60		? X9UC
33	Tail end panel garnish clip	10	\$35.00		? XNN
34	Boot weatherstrip	SM 1	\$353.10		X
35	Tail lamp LH - UPPER	SM 1	\$498.75		X
36	Tail lamp LH - LOWER	SM 1	\$511.60		X
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLG 5182 X Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, FRONT BUMPER)	\$1,400.00	600-900
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, FRONT BUMPER)	\$1,200.00	800
3	To check wiring	\$50.00	40
4	To remove & refit reverse sensor	\$120.00	50
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	60
6	To tuff coat.	1h \$150.00	?x
7	To transfer boot mechanism to new boot	2h \$120.00	X
8	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

1st First Capital

Kg



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempf.com.sg

Repair Estimates

SLG 5182 X

Finalised

Parts (a) Cost / List Price Items	\$ 3827.77	8,460.53
Plus/Less 25%	\$ 956.94	2,115.13
Total of Cost / List	\$ 2870.83	6,345.40
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$ 4K	245.00
Total Parts Cost	\$ 2915.83	6,590.40
Labour	\$ 1570	3,310.00
Total	\$ 4485.83	9,900.40

Not Authorised
Resurvey B4 paint

Pls take photo, after
take out rear bump
Frt Bump

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : CKK

Survey conducted on : 18/4/11P at 11:20

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 06 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Sc Date: 18/4/11P



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Prepare Parts

Vehicle No. : SLG 5182 X
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FUX03535303

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. : _____
Cost / List

i/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	R 1	\$45.00	✓ S.N	✓
2	Front number plate garnish	CM 1	\$129.00	✓	✓
3	Front bumper	R 1	\$450.80		X
4	Front bumper clip	N 10	\$40.00		X
5	Front bumper reinforcement - upper	R 1	\$711.50		X
6	Front bumper reinforcement - lower	R 1	\$245.30		X
7	Front bumper side retainer RH	L 1	\$107.20		X
8	Front bumper side retainer LH	R 1	\$107.20		X
9	Front bumper upper grille	R 1	\$321.90	✓	✓
10	Front bumper lower grille	L 1	\$148.60		X
11	Front bumper emblem	N 1	\$87.10	✓	✓
12	Front bumper sponge - upper	L 1	\$89.81		X
13	Front bumper sponge - lower	L 1	\$135.70		X
14	Reverse sensor	L 1	\$200.00	S.N	X
15	Rear bumper	CM 1	\$497.50	✓	✓
16	Rear bumper clip	N 10	\$40.00	✓	✓
17	Rear bumper side retainer LH	CM 1	\$112.70	✓	✓
18	Rear bumper side retainer RH	L 1	\$112.70		X
19	Rear bumper reinforcement	R 1	\$398.90	✓	✓
20	Rear bumper lower garnish centre	CM 1	\$582.60	✓	✓
21	Rear bumper lower garnish LH	M3CM 1	\$149.70	✓	✓
22	Rear bumper lower garnish RH	L 1	\$149.70		X
23	Rear bumper under cover	L 1	\$355.20	✓	✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

31k 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
 Company Reg No. 200005485N / GST No. 20-0005485-N

2074.60

SN: 48



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLG 5182 X Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, FRONT BUMPER)	\$1,400.00	600 - 200
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, FRONT BUMPER)	\$1,200.00	800
3	To check wiring	\$50.00	40
4	To remove & refit reverse sensor	\$120.00	50
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	60
6	To tuff coat.	nn \$150.00	X
7	To transfer boot mechanism to new boot	nn \$120.00	X
8	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

1570



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19006803/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-06-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3558Y	Veh. Inspected	SLG 5182X
Policy No.		Coverage (\$)	0.00
Claim No.	D19002540MFSH	Excess (\$)	0.00
Assign From	EILEEN LEE	Assign Date	16/04/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDKB3FUX03535303	Colour	METALLIC SILVER
Odometer	192552	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/04/2019	Inspection Date	16/04/2019
Survey held at	385 SIN MING DRIVE		
Repairer	ESTEEM PERFORMANCE PTE LTD		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 5182X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT NUMBER PLATE GARNISH	CRACKED	129.00	129.00
1	FRONT BUMPER	TO REPAIR SEE LABOUR	450.80	-
10	FRONT BUMPER CLIP	NOT NECESSARY	40.00	-
1	FRONT BUMPER REINFORCEMENT - UPPER	TO REPAIR SEE LABOUR	711.50	-
1	FRONT BUMPER REINFORCEMENT - LOWER	TO REPAIR SEE LABOUR	245.30	-
1	FRONT BUMPER SIDE RETAINER RH	SERVICEABLE	107.20	-
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	107.20	-
1	FRONT BUMPER UPPER GRILLE	DENTED	321.90	321.90
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	148.60	-
1	FRONT BUMPER EMBLEM	NECESSARY	87.10	87.10
1	FRONT BUMPER SPONGE - UPPER	SERVICEABLE	89.81	-
1	FRONT BUMPER SPONGE - LOWER	SERVICEABLE	135.70	-
1	REAR BUMPER	CRACKED	497.50	497.50
10	REAR BUMPER CLIP	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH	CRACKED	112.70	112.70
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	112.70	-
1	REAR BUMPER REINFORCEMENT	BENT	398.90	398.90
1	REAR BUMPER LOWER GARNISH CENTRE	CRACKED	582.60	582.60
1	REAR BUMPER LOWER GARNISH LH	MTG CRACKED	149.70	149.70
1	REAR BUMPER LOWER GARNISH RH	SERVICEABLE	149.70	-
1	REAR BUMPER UNDER COVER	TORN	355.20	355.20
1	REAR BUMPER UNDER COVER LH	CRACKED	187.60	187.60
1	REAR BUMPER UNDER COVER RH	SERVICEABLE	187.60	-
4	REAR BUMPER UNDER COVER CLIP	NECESSARY	14.00	14.00
1	TAIL DOOR EMBLEM	NECESSARY	61.70	61.70
1	WORDING "PRIUS"	NECESSARY	51.90	51.90
1	WORDING "HYBRID"	NECESSARY	55.47	55.47
1	TAIL DOOR PLATE GARNISH	DENTED / CRACKED	782.50	782.50

Report Ref No. CS/FCI19006803/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAIL END PANEL	TO REPAIR SEE LABOUR	596.60	-
1	TAIL END PANEL GARNISH	SERVICEABLE	151.60	-
10	TAIL END PANEL GARNISH CLIP	NOT NECESSARY	35.00	-
1	BOOT WEATHERSTRIP	SERVICEABLE	353.10	-
1	TAIL LAMP LH - UPPER	SERVICEABLE	498.75	-
1	TAIL LAMP LH - LOWER	SERVICEABLE	511.60	-
	LESS 25% DISCOUNT		-2,115.13	-956.94
			6,345.40	2,870.83
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	BENT	45.00	45.00
1	REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
			245.00	45.00
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, FRONT BUMPER) INCLUSIVE OF THE REPAIR OF FRONT BUMPER, FRONT BUMPER REINFORCEMENT - UPPER, FRONT BUMPER REINFORCEMENT - LOWER AND TAIL END PANEL.		1,400.00	600.00
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, FRONT BUMPER)		1,200.00	800.00
	TO CHECK WIRING.		50.00	40.00
	TO REMOVE & REFIT REVERSE SENSOR.		120.00	50.00
	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD.		150.00	60.00
	TO TUFF COAT.	NOT NECESSARY	150.00	-
	TO TRANSFER BOOT MECHANISM TO NEW BOOT.	NOT NECESSARY	120.00	-
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		120.00	20.00
			3,310.00	1,570.00
	GRAND TOTAL		9,900.40	4,485.83
RECOMMENDED COST OF REPAIRS				4,485.83

Report Ref No. CS/FCI19006803/Kqd3n2



Report Ref No. CS/FCI19006803/Kqd3n2

A handwritten signature in black ink, consisting of the letters 'KSC' in a cursive, stylized font.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.