

03/01/2017

ASS. REC. BY:

REF: CS3/LPC 19004870/R1903-1<sup>n2</sup>

visit instruction.

SURVIVOR

RASHI

ASSIGNMENT (Office)

From (Person): Gerald Poh

of

LPC

Date/Time: 16/4/2019

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLC 7764A

Insured: SLR 4620Y

at Workshop info: Fix Auto Pte LTD

Tel: 67104077

of 5 Soon Lee Street #01-61

Policy No:

Claim No: 18/19/19/VP05/021525

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 17/3/19

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement

Date/Time: 18-3-2019

Person Contacted: Irene Lee

Vehicle: IN/OUT

Date/Time	Action/Instruction ( X ) (Stimale)
	SLC 7764A X SLR4620Y X

22/3/19	Submit PPS.
---------	-------------

08/5/19	Submit US \$2400, 5 days (Red. \$3100, 56%)
---------	--



7/5/2019

RECEIVED 08 MAY 2019

6463B

## 450

Voter No. SLC 7764A      In Regn. 2016 / Aug

Type: ☐ B.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Model: HOBAS VEZEL 1-5X No. 1496

Colour **BLACK** AC Insured / Std / NT / NA

Sp. Reading 039096 TRadio: Insured / Std / NI / NA

EngNo.

CINo: RUT111560

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Warder / Jammed / Leaked / Burst or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / A/Rm / STD A/Rm or

Tyre Size: F:

R: 10

DS / JUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FROM

Rear

R/Bol.	$\Sigma$	mm	R/Bol.	$\Sigma$	mm
--------	----------	----	--------	----------	----

L/Bal.	5	mm	L/Bal.	5	mm
--------	---	----	--------	---	----


D.O.A. 13/03/19 D.O.A. 18/03/19

Survey held at FIX AUTO

Dos. of Driftages: Frt / Rear / O/S / H/S / U/C / Rooftop or

O/S Ratan

The U/C / Chassis frame / Body Structure affected due to collision.



# LONPAC INSURANCE BHD

(S98FC5635C)

Our Ref : 18/19/19/VP05/021525

Your Ref :

12 April 2019

M/s LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1  
#01-25 Paya Ubi Industrial Pk  
Singapore 408933

Dear Sirs/Madam

## PAPER SURVEY OF SLC7764A

We refer to the above matter.

We enclose the following documents :-

- a) Survey report & photos of SLC7764A
- b) GIA report SLC7764A
- c) GIA report and photos of SLR4620Y

Kindly study the documents and let us have your report as soon as possible.

Yours faithfully

**GERALD POH**  
**SENIOR EXECUTIVE**  
**(CLAIMS)**  
Email : [mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)

# FIX AUTO PTE LTD

5 Soon Lee Street #01-61 (Pioneer Point) Singapore 627607

Tel No.: +65 6710 4077 | Mobile No.:+65 9222 2220

Date: 22<sup>nd</sup> March 2019

Invoice No.: FIX/SLC7764A/13032019

Messrs: Chu Geoffrey Bryan Ang

Vehicle No.: SLC7764A

	Amount
FINAL REPAIR COST	\$5,500.00
(LUMP SUM)	

**Total: \$ 5,500.00**

**DOLLARS SGD FIVE THOUSAND FIVE HUNDRED ONLY**

# SLC L APPRAISER PTE LTD

24 Penshurst Place, Singapore 556440  
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783  
Reg No: 201000228E

## VEHICLE INSPECTION REPORT

To: Chua Geoffrey Bryan Ang  
C/o: Fix Auto Pte Ltd  
5 Soon Lee Street #01-61 (Pioneer Point)  
Singapore 627607

Date : 22 March 2019  
Our ref : FIX/03/1902/TP

Accident Date : 13 March 2019  
Inspection Date : 18 March 2019  
Repairer Name : Fix Auto Pte Ltd  
5 Soon Lee Street #01-61 (Pioneer Point)  
Singapore 627607

Type of Survey : Third Party

### PARTICULARS OF VEHICLE

Registration No : SLC 7764 A  
Make / Model : Honda Vezel  
Chassis No : RU11111560  
Engine No : L15B4031565

Year / Capacity : 2016 / 1496 cc  
Colour : Black  
Mileage : 39096

### CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	Dunlop	215/60 R16	5 mm	Sport
Front Offside	Dunlop	215/60 R16	5 mm	Sport
Rear Nearside	Dunlop	215/60 R16	5 mm	Sport
Rear Offside	Dunlop	215/60 R16	5 mm	Sport

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the n/s rear portion.  
(Details refer to the photographs attached)

Enclosed number of photographs: 66 copies

### REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis  
and we have not given authorization and instruction to the repairer to proceed with the repair

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 5,500.00** on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

# SLC L APPRAISER PTE LTD

Vehicle Registration No: SLC 7764 A

Our Ref No: FIX/03/1902/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

## SPARE PARTS - LIST ITEMS

1	Rear bumper	Intact	\$ 950.60	XAN
1	Rear bumper - side	Damage	\$ 225.30	\$ 225.30
1	Rear bumper side retainer	Necessary	\$ 50.90	\$ 50.90 Xsuc
1	Rear o/s door	Damage	\$ 1,085.50	\$ 1,085.50 repair
1	Rear o/s door inner lock	Intact	\$ 285.00	XAN
1	Rear o/s door weatherstrip	Necessary	\$ 130.80	\$ 130.80 Xsuc
1	Rear o/s fender	Damage	\$ 1,500.70	\$ 1,500.70 964
1	Rear o/s fender inner shield	Damage	\$ 149.80	\$ 149.80 Xsuc
1	Rear o/s fender inner shield clip (1 set)	Necessary	\$ 50.00	\$ 50.00 Xsuc
1	Rear o/s fender wheel arch garnish	Damage	\$ 300.70	\$ 300.70 150
1	Rear o/s fender quarter glass moulding	Necessary	\$ 115.00	\$ 115.00 XAN
1	Rear o/s wheel rim	Damage	\$ 750.50	\$ 750.50 300 s/n
1	Rear o/s wheel hup with bearing	Damage	\$ 332.50	\$ 332.50 285
1	Rear o/s shock absorber	* Damage	\$ 421.00	\$ 421.00 Xsuc
1	Rear o/s axle beam	Intact	\$ 1,513.30	XAN
			<b>\$ 7,861.60</b>	<b>\$ 5,112.70</b> 1624.30
Less 20%			\$ 1,572.32	\$ 1,022.54 20%
<b>Total Cost - List Items</b>			<b>\$ 6,289.28</b>	<b>\$ 4,090.16</b> 1299.40

## SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	Necessary	\$ 45.00	\$ 45.00 30
1	Rear o/s fender quarter glass sealant	Necessary	\$ 80.00	\$ 50.00 XAN
<b>Total Cost - Special Nett items</b>			<b>\$ 125.00</b>	<b>\$ 95.00</b> 30

**Total cost of parts**

**\$ 6,414.28 \$ 4,185.16**

# **SLC L APPRAISER PTE LTD**

Vehicle Registration No: SLC 7764 A

Our Ref No: FIX/03/1902/TP

S/No	Description	Repairer's Estimate	Revised Amount
	<b>Total cost of parts c/f</b>	<b>\$ 6,414.28</b>	<b>\$ 4,185.16</b>

## LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ <del>50.00</del> 30
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ <del>120.00</del> 60
3	To remove and refit rear undercarriage.	\$ 250.00	\$ 200.00 80
4	To conduct wheel alignment.	\$ 150.00	\$ <del>120.00</del> 60
5	To remove and refit quarter glass to assist repair.	\$ 120.00	\$ 80.00 X 11
6	To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door.	\$ 150.00	\$ 120.00 X 11
7	To apply undercoating on repaired and replaced panel.	\$ 120.00	\$ <del>90.00</del> 80
8	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,400.00	\$ <del>1,000.00</del> 600
9	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,200.00	\$ <del>880.00</del> 500

**GRAND TOTAL**

**\$ 10,034.28 \$ 6,845.16**

1299.40  
 30.00  
 1370.00  
 300.00  
 2999.40  
 206  
 2399.52  
 411 - 2,400  
 5 days

Vehicle Registration No: SLC 7764 A

Our Ref No: FIX/03/1902/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 5,500.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

**Disclaimer**

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

**C L APPRAISER PTE LTD**



Cheong K. H  
Automotive Appraiser





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC19004870/R1qd3n2-1

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 09-05-2019



Code : LPC2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLR 4620Y	Veh. Inspected	SLC 7764A
Policy No.	Z18VP05020700	Coverage (\$)	0.00
Claim No.	18/19/19/VP05/021525	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	16/04/2019

## 2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL 1.5X	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11111560	Colour	BLACK
Odometer	39096	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	5 mm
L/H Front Tyre	215/60 R16	DUNLOP	5 mm
R/H Rear Tyre	215/60 R16	DUNLOP	5 mm
L/H Rear Tyre	215/60 R16	DUNLOP	5 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	13/03/2019	Inspection Date	18/03/2019
Survey held at	FIX IT AUTO PTE LTD NO. 5 SOON LEE STREET #01-61 PIONEER POINT SINGAPORE 627607		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 7764A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	REAR BUMPER	NOT NECESSARY	950.60	-
1	REAR BUMPER-SIDE	DAMAGED	225.30	225.30
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	50.90	-
1	REAR O/S DOOR	TO REPAIR SEE LABOUR	1,085.50	-
1	REAR O/S DOOR INNER LOCK	NOT NECESSARY	285.00	-
1	REAR O/S DOOR WEATHERSTRIP	SERVICEABLE	130.80	-
1	REAR O/S FENDER	DAMAGED	1,500.70	964.00
1	REAR O/S FENDER INNER SHIELD	SERVICEABLE	149.80	-
1	SET REAR O/S FENDER INNER SHIELD CLIP	SERVICEABLE	50.00	-
1	REAR O/S FENDER WHEEL ARCH GARNISH	DAMAGED	300.70	150.00
1	REAR O/S FENDER QUARTER GLASS MOULDING	NOT NECESSARY	115.00	-
1	REAR O/S WHEEL HUP WITH BEARING	DAMAGED	332.50	285.00
1	REAR O/S SHOCK ABSORBER	SERVICEABLE	421.00	-
1	REAR O/S AXLE BEAM	NOT NECESSARY	1,513.30	-
	LESS 20% DISCOUNT		-1,422.22	-324.86
			5,688.88	1,299.44
1	REAR O/S WHEEL RIM (SN)	DAMAGED	750.50	300.00
	LESS 20% DISCOUNT		-150.10	-
			600.40	300.00
	<b>SPECIAL NETT ITEMS</b>			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	30.00
1	REAR O/S FENDER QUARTER GLASS SEALANT (SN)	NOT NECESSARY	80.00	-
			125.00	30.00
	<b>LABOUR</b>			
	TO REMOVE,REFIT,REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.		80.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES,INNER TRIM TO ASSIST REPAIR.		150.00	60.00
	TO REMOVE AND REFIT REAR UNDERCARRIAGE.		250.00	80.00

Report Ref No. CS3/LPC19004870/R1qd3n2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT WHEEL ALIGNMENT.		150.00	60.00
	TO REMOVE AND REFIT QUARTER GLASS TO ASSIST REPAIR.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT DOORS COMPLETE FITTINGS AND REPLACE DAMAGED PARTS,TRANSFER ALL FITTINGS TO NEW DOOR.	NOT NECESSARY	150.00	-
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		120.00	40.00
	TO PROVIDE LABOUR CHARGES,WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS,REPAIR INCLUDING CUT AND WELD;RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR O/S DOOR.		1,400.00	600.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS,REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,200.00	500.00
			3,620.00	1,370.00
GRAND TOTAL			10,034.28	2,999.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS3/LPC19004870/R1qd3n2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.