

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang**  
**Mo Kio Ind. Park 2A**  
**568047**

**Claim Reference:**

**Assessment number: MC1900303**

**Version: 1810**

**Date calculated: 16/07/2019 1:26 PM**

**Full Report**

**Registration: SLC5278A**

**Printed: 16/07/2019 1:26 PM**

---

**Summary Information**

**Claim**

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Kee Mui Hong	Currency:	SGD
Claim Reference:		Date of Incident:	12/04/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

---

**Vehicle Details**

**Vehicle**

Manufacturer:	TOYOTA
Model:	WISH(ZGE21L/ZGE2)
Sub Model:	BASE MODEL
Model Sheet Number:	70 W2 01
Registration:	SLC5278A
VIN number:	
Odometer:	

**Model Specs**

FROM 12/2016	TWO COAT METALLIC	PREPARE OFF VEHICLE
--------------	-------------------	---------------------

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang**  
**Mo Kio Ind. Park 2A**  
**568047**

**Claim Reference:**  
**Assessment number: MC1900303**  
**Version: 1810**  
**Date calculated: 16/07/2019 1:26 PM**

**Full Report**  
**Registration: SLC5278A**  
**Printed: 16/07/2019 1:26 PM**


## Vehicle Condition

### Vehicle Status

Pre-Accident Damage:  
 Date of Inspection:

### Damage Areas

**All** ☐  
**Underbody** ☐



## Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
810151A	ADJUST HEADLAMP		3.0	13.50
520011)	R + R FRONT BUMPER		3.0	13.50
NO NUMBER	R + R FRONT BUMPER CARRIER		2.0	9.00
810051)	R + R LEFT HEADLAMP		7.0	31.50
810051)	R + R RIGHT HEADLAMP		7.0	31.50
531041)	R + R L/F WHEELARCH TRIM		1.0	4.50
0281	FRONT BUMPER REPAIR		20.0*	90.00
0741	L/F WING REPAIR		25.0*	112.50
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>	
<b>Panel / Mechanical Labour</b>		<b>6.80</b>	<b>68.0</b>	<b>306.00</b>
<b>Total of Labour</b>				<b>306.00</b>

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang**  
**Mo Kio Ind. Park 2A**  
**568047**

**Claim Reference:**  
**Assessment number: MC1900303**  
**Version: 1810**  
**Date calculated: 16/07/2019 1:26 PM**

**Full Report**  
**Registration: SLC5278A**  
**Printed: 16/07/2019 1:26 PM**

**Paint**

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	FRONT BUMPER REPAIR PAINT PLASTIC		16.0	
	L/F WING REPAIR PAINTING <50%		11.0	

**Paint Material Per Part**

Code	Description	Price SGD
0281	FRONT BUMPER REPAIR PAINT PLASTIC	51.84
0741	L/F WING REPAIR PAINTING <50%	13.57

**Labour Cost - Paint**

	Factor	45.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			27.0	
	Preparation Main Work Metal		2.50	25.0	112.50
	Preparation Comp. Work Plastic		0.80	8.0	36.00
<b>Total</b>		<b>10 WU/h</b>	<b>6.00</b>	<b>60.0</b>	<b>270.00</b>

**Material Cost - Paint**

	Price SGD
Repair Painting	13.57
Repair Painting Plastic	51.84
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
<b>Total</b>	<b>106.71</b>

**Extras**

Code	Description	Price SGD
1002	CHECK WIRING	10.00*
	<b>Total Extras</b>	<b>10.00</b>

**AH LIM Motor Company**  
**#01-09, AMK Autopoint, 10 Ang**  
**Mo Kio Ind. Park 2A**  
**568047**

**Claim Reference:**

**Assessment number: MC1900303**

**Version: 1810**

**Date calculated: 16/07/2019 1:26 PM**

**Full Report**

**Registration: SLC5278A**

**Printed: 16/07/2019 1:26 PM**

**Final Calculation**

	SGD	SGD
<b>Labour Time Base 10 WU/h</b>		
Total 68.0 WU X 45.00 SGD/h	306.00	
<b>Total of Labour</b>		<b>306.00</b>
<b>Total Of Extras</b>		<b>10.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 60.0 WU X 45.00 SGD/h	270.00	
Material Cost	106.71	
<b>Total Paint Including Material</b>		<b>376.71</b>
<b>Repair Cost Excludes GST</b>		<b>692.71</b>
GST (+7.0%)		<b>48.49</b>
<b>Repair Cost Included GST</b>		<b>741.20</b>

**Comments**

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS