



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19006836/Kpa3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 06-04-2020



ATTN: CYNTHIA LOH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDW 9988Y	Veh. Inspected	SLC 5278A
Policy No.	GA431611/1	Coverage (\$)	0.00
Claim No.	S9M01KKL	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	17/04/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDGG20W20J004135	Colour	METALLIC GREY
Odometer	58001	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	GOODYEAR	4 mm
L/H Front Tyre	195/65 R15	GOODYEAR	4 mm
R/H Rear Tyre	195/65 R15	GOODYEAR	2 mm
L/H Rear Tyre	195/65 R15	GOODYEAR	2 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/04/2019	Inspection Date	17/04/2019
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 5278A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	220.00	-
1	L/F BUMPER BRACKET (CONSISTENT)	SERVICEABLE	28.00	-
15	BUMP CLIPS (CONSISTENT)	SERVICEABLE	15.00	-
	COST PLUS 10%		26.30	-
			289.30	-
	LABOUR			
	WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	CHECK WIRING.		40.00	10.00
	TOTAL LABOUR. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		306.00	306.00
	PAINT WORK: LABOUR COST.		328.50	270.00
	PAINT WORK: MATERIAL COST.		170.07	106.71
			924.57	692.71
	GRAND TOTAL		1,213.87	692.71
	RECOMMENDED COST OF REPAIRS			692.71

Report Ref No. CC4/ASM19006836/Kpa3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.